

ASS. REC. BY:

REF: CS/AIG/18017074/ ASD3ⁿ²

Special Instruction:

Surveyor
Menmen

Adrian
Mithoo Singh

ASSIGNMENT (Office)

From (Person):

of

AIG

Date/Time:

19/1/18 @ 11:10am

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGR 9815D

Insured:

SGV 35B

at Workshop m/s

Ho Auto Engineering

Tel:

9730 5013

of

Blk 3007, Ubi Rd 1 # 01-416

Policy No:

Claim No:

Sum Insured:

- Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/09/2018

21/09/2018 @ after 1pm

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

12:27pm @ 19/1/18

Person Contacted:

Tony

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SGR 9815D - x

SGV 35B - CC4/AIG/17008493/71ca3

DOA: 28/4/17

Adrian say of estimate

25/09/18

@ 12:02 p.m. revert pending estimate from repairer to
Chit Yan via me:mu.

WILL
Surrender

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGR981SD Yr Regn: 2007 / Feb 28
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: Mit Lances C.C. 1584
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 114560 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R15
 R: 195/60R15

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**
 GIA / PR Seen: _____ Consistent? : **Yes** or **No**
 Est. Repairs: _____ days Res.: **Yes** or **No**
 Lum Sum: _____ % 3 Val.: **Yes** or **No**
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Front 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 24/09/18

Survey held at Ho Anto.
 Des. of Damages: **Frt** / Rear / O/S / N/S / UIC / Rooftop or
front o/s.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Alq.
<u>25/10/18</u>	<u>Confirmed HS \$1.9K @ 4 days with Advien. (\$1,774.00 Red- 48%)</u>

RECEIVED 25 OCT 2018

Date/Time, File Pass to? 25/10/18
 1) Typ. 34
 Date/Time, File Return to?

: Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	<u>250</u>
	<u>30</u>
	<u>270</u>
TOTAL	

Report Format :
 Lump Sum / I.B.I: (\$ 1,900/- 45)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18017074/Asd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 19-09-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGV 35B	Veh. Inspected	SGR 9815D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MITHOOSINGH	Assign Date	19/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/09/2018	Inspection Date	24/09/2018
Survey held at	BLK 3007 UBI RD 1 #01-416		
Repairer	HO AUTO ENGINEERING		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

View Sent Message

This mail is associated with :

***SGR9815D (5746680770SG)
[SGV35B]**

TP

Sep 13 2018 12:00AM
[Chen Li Jiun]
HO AUTOGLOSS CENTRE

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/09/2018 17:02 PM.
To Chityan.Foo@aig.com
CC sur@lkkauto.com
Subject SGR9815D (5746680770SG) [SGV35B] TP

Dear Chit Yan,

Please be informed that we have inspected the vehicle SGR 9815D on 24/09/2018.

We are pending estimate from repairer.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

- Pre repair inspection request - SGR9815D VS SGV35B (OI) DOA: 13/09/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Sent: 19/9/2018 11:10:03 AM
Attachments: 0897_001.pdf; 0956_001.pdf

Hi,

Please refer to the enclosed request from VISION LAW LLC.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Mithoosingh, Aashweenjeetkaur
Sent: Tuesday, September 18, 2018 3:33 PM
To: jactan@visionlawllc.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi; Fan, Winnie-LW
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV35B AND SGR9815B ON 13/09/2018

Without Prejudice

Your Reference : AM.jt.Ins.H76.SGR9815B.18 (sj)
Our Reference : SGV35B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
JANICE HAN JIA LIN
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU

Unique Entity Number :200721148H

✓ **HEAD OFFICE:** 133 New Bridge Road

#18-01/02 Chinatown Point

Singapore 059413

Branch: 490 Toa Payoh Lorong 6

#03-11 HDB Hub

Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)

FAX ✓ : (65) 65356802 (General)

: (65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703

FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.H76.SGR9815B.18 (sj)

Your Ref: **SGV 35 B**

19 September 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attention: Motor Claims Department

BY FAX: 6415-3727

email: aashweenjeetkaur.mithoosingh@aig.com

Email: noormariesa.abukassim@aig.com

Dear Sirs,

ACCIDENT INVOLVING SGR 9815 D & SGV 35 B ON 13 SEPTEMBER 2018 ALONG JURONG WEST AVENUE 1 CARPARK NEAR BLK 423 AT ABOUT 1100 HOURS

We refer to your letter dated 18 September 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Adrian Ling from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue:

HO AUTO ENGINEERING

Blk 3007 Ubi Road 1

#01-416

Singapore 408701

Contact Person:

Mr Tony (9730-5013)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SGR 9815 B

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/09/2018 13:16
Date Of Accident	13/09/2018 11:00
Exact Location Of Accident	JURONG WEST AVE 1 - CARPARK NEAR BLK 423
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR9815D
Insured/Policyholder	
Name Of Registered Owner	CHUA CHOON CHYE
NRIC No	S1529712C
Email Address	JINHEHZY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97399379
Alternative Phone No	OFFICE-97399379

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80442212QMX
Cover Note Number	

Driver

Name of Driver	CHUA JIN HE
NRIC No	S9003456A
Date Of Birth	05/02/1990
Occupation	INDOOR
Date Of Driving Pass	27/09/2016
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97399379
Fax Number	
Contact Number	OFFICE-97399379
EMail Address	JINHEHZY@GMAIL.COM

Address	BLK 423 JURONG WEST AVE 1 #06-216
Postcode	640423
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	KHAIML
Phone Number	98575439
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV35B
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA

Address

NA
NA

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Jurong West Ave 1

Refer Police Report.
7/20180913/2143

DECLARATION


I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature

Driver's Signature

Witness's Signature

Police Officer's Signature


15/9/2018

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If Driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
SRK (1/1/2018)

Common Statement



POLICE FORCE



T/20180913/2143

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000

1 of 3

Report No. T/20180913/2143

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/09/2018 17:18	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: CHUA JIN HE		Address: APT BLK 423 JURONG WEST AVENUE 1 #06-216 SINGAPORE 640423	
ID Type / ID No.: NRIC NO / S9003456A		Contact No.: Home/Office: Mobile: 97399379	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 05/02/1990	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Shop sales assistant		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 13/09/2018 11:00	Type of Location: Car Park
Location: Along Road 1 JURONG WEST AVENUE 1 OPEN CARPARK BETWEEN BLOCK 423 JURONG WEST AVENUE 1 AND JURONG GREEN COMMUNITY CLUB				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGR9815D	Car				Slightly Damaged	0
SGV35B (Not Accurate)	Car					0

Common Statement



POLICE FORCE



T/20180913/2143

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408665
Tel No: 65470000

2 of 3

Report No. T/20180913/2143

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHUA JIN HE	ID No.	S9003456A
Related Vehicle	SGR9815D (Car)	Contact No.	97399379
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/09/2018 at about 1am, I parked my car (SGR9818D) in the parking lot at an open carpark between block 423 Jurong West Avenue 1 and Jurong Green Community Club. Everything was fine. Later that day at about 1.30pm I went down to my car and noticed a note that was left on my windscreen. In the note, it stated 'SGV35B hit your car and run. Timing range 11am - 11.20am. Lady driver. Saw by Macdonald riders'. However, no particulars of the witness was left.

I then made a check and saw some damages on the ~~left~~ ^{Right} side of the front bumper. The damages include scratches, dent and my car paint scrapped off. I have a in-car camera however it is not working.

Common Statement



POLICE FORCE

1/20180913/2143

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3



Report No. T/20180913/2143

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MASITA BINTE AZMAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 13/09/2018 17:18
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902  SINGAPORE POLICE FORCE	Classification Of Case: <div style="border: 1px solid black; width: 100px; height: 40px; margin-top: 5px;"></div>
Authentication Stamp NP168  SIGNATURE	

Common Statement

Witness
wrote note

SGV 35B

Hit your
car and run

Timing range
11 - 11:20 am

lady driver.

Saw by McDowell
rider's

owner S1529712 - E

Ho Auto Engineering

2 Kaki Bukit Ave 2, #02-18/23 (Kaki Bukit AutoHub), Singapore 417921
 Hoautoengineering@yahoo.com.sg (Kindly reply all correspondence via email)
 H/P: 97305013 (Tony Ho)

TP AIG Shirley

JMYSTCS3A74006888

Vehicle No.: SGR 9815 D

Model: Mitsubishi Lancer

QTY	List Price:	Prices \$
1	Front Bumper <i>Revised</i>	685 ✓
2	Front Bumper Retainer @42 each <i>Ret ma</i>	84 ✓ 42
2	Bumper Bracket @58 each <i>me</i>	115 +
1	Front Bumper Reinforcement <i>me</i>	385 +
1	Head Lamp (right) <i>cut 1619</i>	685 ✓ 572
1	Front Grilles <i>cracked less 10%: 1457.10</i>	320 ✓
Total:		2274
Nett Items		
QTY	List Price:	Prices \$
Total:		
Labor Charges		
To respray painting and etc.		600 — 500
Panel beating, remove and replacing above parts		650 — 400
To respray undercoating <i>930</i>		100 +
To check wiring		50 — 30
Total:		1400
ESTIMATE PARTS AND LABOR GRAND TOTAL \$		3674

Adrian Lim
 H/s 24/09/18

04 Days

Total: 2387.10

H/s: 19K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18017074/ASD3N2

Date: 29/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100328948
 Claimant Vehicle No : SGR9815D Insured Vehicle No : SGV35B
 Date of Loss: 13/09/2018 Nature of Claim: TP Claim No: 5746680770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGR9815D Engine No: 4G18HT3490
 Make & Model: MITSUBISHI LANCER, 1.6 (A) Chassis No: JMYSTCS3A7U006888
 Reg. Date: 28/02/2007 (Man. Year: 2006) Odometer: 114560 km
 Colour: Silver
 Engine Capacity: 1584 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,274.00	1,457.10	816.90	35.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	930.00	470.00	33.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,674.00	2,387.10	1,286.90	35.03
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	3,674.00	1,900.00	1,774.00	48.29

INSPECTION

Date of Assignment: 19/09/2018
 Date Inspected: 24/09/2018 Inspected At: 2 KAKI BUKIT AVENUE 2
 #02-18/23 KAK BUKIT AUTOHUB
 SINGAPORE 417921
 REPAIRER: HO AUTO ENGINEERING
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	685.00 F	*685.00 FL
2	1		*FRONT BUMPER RETAINER	O/s Necessary	84.00 F	*42.00 FL
3	2		*BUMPER BRACKET	Not Necessary	115.00 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	385.00 F	*- FL
5	1		*HEAD LAMP (RIGHT)	Cut	685.00 F	*572.00 FL
6	1		*FRONT GRILLES	Cracked	320.00 F	*320.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,274.00	1,619.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	161.90
Total Parts (S\$)	2,274.00	1,457.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY PAINTING AND ETC	New	600.00	500.00
2	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS	New	650.00	400.00
3	TO RESPRAY UNDERCOATING	New	100.00	-
4	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			1,400.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >