

45  
22/03/2003

ASS. REC. BY:

REF:

CS/AIG18017128/R/cd3<sup>SY</sup>

Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person):

Fong Andy

of

AIG

Date/Time: 19/9/18 @ 1:35pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 1327P

Insured:

SJW 3725H

at Workshop m/s

SMRT

Tel:

9296 0006

of

60 Woodlands Ind. Park E9

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 20/9/18 @ 10:07am

Person Contacted:

Derrick

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	FBL 1327P - X
	SJW 3725H - NA / INC 13011698 / m2
	DOA: 9/3/2013

Surveyor: Paul

REF: \_\_\_\_\_

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBL 1327Pat Workshop m/s SMART

of \_\_\_\_\_

Insured: AIK

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Denik 92960056Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBL 1327P Yr Regn: \_\_\_\_\_ /Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: YAMAHA c.c. 600Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 4621 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JYAR 3221 00000 4834Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120/70ZM7R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. 28/03/18 D.O.I. 20/9/18Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1/8</u>	<u>Submit final sig \$3318.70 (Red. 0%)</u> <u>Fair and reasonable</u>

RECEIVED 01 AUG 2019

1/8/2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 2

1)

☐ : Final ReportResurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS, \$

Photos

Others

TOTAL

Report Format : TPLump Sum / I.B.: (\$ 3318.70)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18017128/R1rd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 20-09-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 3725H	Veh. Inspected	FBL 1327P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	FONG ANDY	Assign Date	20/09/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	28/03/2018	Inspection Date	20/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E9 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**RE: - PD New Assignment - SJW3725H (OI) VS FBL1327P (TP) DOA 2...**

From: Fong, Andy-SY  
To: Catherine Chong (LKK Auto)  
Cc: Syed-Yusoff, Saliha, sur@lkkauto.com, Celine Fong, Olivia Lau (LKKAuto)  
Sent: 19/9/2018 1:35:41 PM

---

Celine

Representative from CNB has written to AIG. Did LKK get in touch with CNB??

**Andy Fong**

**AIG**

Claims Technical Control Manager

Singapore | Hong Kong

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1708|M: +(65) 9138 1785

[Andy-SY.Fong@AIG.com](mailto:Andy-SY.Fong@AIG.com) | [www.AIG.com.sg](http://www.AIG.com.sg)

**Follow us:**

Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

---

**From:** Fong, Andy-SY

**Sent:** Friday, September 14, 2018 12:26 PM

**To:** 'Catherine Chong (LKK Auto)'

**Cc:** Syed-Yusoff, Saliha

**Subject:** FW: aigencrypt - PD New Assignment - SJW3725H (OI) VS FBL1327P (TP) DOA 28/03/2018

Hi Catherine

Please take this email as our instruction to provide advice on the captioned third party claim. Kindly reach out to claimant.

We look forward to the necessary via Merimen.

Saliha, for your further instruction on third party claims administration

**Andy Fong**

**AIG**

Claims Technical Control Manager

Singapore | Hong Kong

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1708|M: +(65) 9138 1785

[Andy-SY.Fong@AIG.com](mailto:Andy-SY.Fong@AIG.com) | [www.AIG.com.sg](http://www.AIG.com.sg)

**Follow us:**

Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

---

**From:** Shirlene YEO (CNB) [mailto:Shirlene\_YEO@cnb.gov.sg]  
**Sent:** Wednesday, September 12, 2018 5:47 PM  
**To:** AIG SGP, CCU Referral  
**Cc:** Aden POT (CNB); Chris TAN (CNB)  
**Subject:** RE: -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

***Message Classification: Restricted***

Hi Varsha

We do not have a GIA report, our vehicles are self-insured.

The photographs of the vehicle are as attached.

The parts to be replaced/repared are as follows:

1. HANDLE BAR
2. BRAKE LEVER
3. BALANCER – RH
4. SIDE MIRROR – RH
5. FUEL TANK
6. FUEL TANK EMBLEM - LH/RH
7. FUEL TANK SIDE COVER – LH
8. SIDE COVER – RH
9. SIDE UNDER COVER – RH
10. FOOTREST BRACKET – RH
11. FRONT FOOTREST – RH
12. FRONT SIGNAL LAMP – RH
13. REAR BOX

The total cost of repairs is \$3,318.70 (excluding GST). We will also be claiming for loss of use of the vehicle after our workshop confirms on the number of days of repairs.

Our vehicle is currently at our workshop: SMRT 60 Woodlands Industrial Park E9, Singapore 757705. Contact person: 92960006 Derrick.

Please inform us by end of this week if you will be sending your assessor to view the vehicle. Otherwise, we will proceed with our repairs. Thanks.

Shirlene Yeo (Ms)  
Manager, Logistics Unit  
Corporate Services Division  
[Central Narcotics Bureau](#)  
DID: (65) 6325 6626

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

**From:** Shirlene\_YEO@cnb.gov.sg  
**To:** Andy-SY.Fong@aig.com  
**Cc:** AIGSGPCCUReferral@aig.com, Saliha.Syed-Yusoff@aig.com, Chris\_TAN@cnb.gov.sg  
**Subject:** RE: SJW3725H (OI) VS FBL1327P (TP) DOA 28/03/2018  
**Date:** Tue, 18 Sep 2018 15:20:46 +0000

***Message Classification: Restricted***

Hi Andy

Since we did not hear from you, we will proceed with the repairs.

Thanks.

Shirlene Yeo (Ms)  
Manager, Logistics Unit  
Corporate Services Division  
Central Narcotics Bureau  
DID: (65) 6325 6626

***Keeping Singapore Drug-Free***

Central Narcotics Bureau W [cnb.gov.sg](http://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://fb.com/CNB.DrugFreeSG) IG [instagram.com/cnb.drugfreesg](https://instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Shirlene YEO (CNB)  
**Sent:** Friday, 14 September 2018 12:42 PM  
**To:** 'Fong, Andy-SY' <Andy-SY.Fong@aig.com>  
**Cc:** AIG SGP, CCU Referral <AIGSGPCCUReferral@aig.com>; Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>;

Chris TAN (CNB) <Chris\_TAN@cnb.gov.sg>

**Subject:** RE: SJW3725H (OI) VS FBL1327P (TP) DOA 28/03/2018

***Message Classification: Restricted***

Hi Andy

Thanks for your phone call. As spoken, please let us know asap if AIG decides to view our vehicle before repairs. We wish to commence repairs very soon as we need this vehicle for deployment.

Please let us know by end of next Mon (17 Sep), otherwise, we will commence our repairs.

Thanks.

Shirlene Yeo (Ms)  
Manager, Logistics Unit  
Corporate Services Division  
Central Narcotics Bureau  
DID: (65) 6325 6626

*Keeping Singapore Drug-Free*

Central Narcotics Bureau W [cnb.gov.sg](http://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://www.facebook.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://www.instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>

**Sent:** Friday, 14 September 2018 11:46 AM

**To:** Shirlene YEO (CNB) <[Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)>

**Cc:** AIG SGP, CCU Referral <[AIGSGPCCUReferral@aig.com](mailto:AIGSGPCCUReferral@aig.com)>; Syed-Yusoff, Saliha <[Saliha.Syed-Yusoff@aig.com](mailto:Saliha.Syed-Yusoff@aig.com)>

**Subject:** SJW3725H (OI) VS FBL1327P (TP) DOA 28/03/2018

**Without Prejudice**

Dear Miss Yeo

As spoken on the phone earlier. LKK Auto Consultants Pte Ltd is also our appointed panel of Motor surveyor as such we will reach out to LKK for their recommendation of the matter.

Thank you

Andy Fong  
AIG

Claims Technical Control Manager  
Singapore | Hong Kong  
AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1708|M: +(65) 9138 1785  
[Andy-SY.Fong@AIG.com](mailto:Andy-SY.Fong@AIG.com) | [www.AIG.com.sg](http://www.AIG.com.sg)

**Follow us:**

Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

---

**From:** Shirlene YEO (CNB) [[mailto:Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)]  
**Sent:** Wednesday, September 12, 2018 5:47 PM  
**To:** AIG SGP, CCU Referral  
**Cc:** Aden POT (CNB); Chris TAN (CNB)  
**Subject:** RE: -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

***Message Classification: Restricted***

Hi Varsha

We do not have a GIA report, our vehicles are self-insured.

The photographs of the vehicle are as attached.

The parts to be replaced/repared are as follows:

1. HANDLE BAR
2. BRAKE LEVER
3. BALANCER – RH
4. SIDE MIRROR – RH
5. FUEL TANK
6. FUEL TANK EMBLEM - LH/RH
7. FUEL TANK SIDE COVER – LH
8. SIDE COVER – RH
9. SIDE UNDER COVER – RH
10. FOOTREST BRACKET – RH
11. FRONT FOOTREST – RH
12. FRONT SIGNAL LAMP – RH
13. REAR BOX

The total cost of repairs is \$3,318.70 (excluding GST). We will also be claiming for loss of use of the vehicle after our workshop confirms on the number of days of repairs.

Our vehicle is currently at our workshop: SMRT 60 Woodlands Industrial Park E9, Singapore 757705. Contact person: 92960006 Derrick.



Please inform us by end of this week if you will be sending your assessor to view the vehicle. Otherwise, we will proceed with our repairs. Thanks.

Shirlene Yeo (Ms)  
Manager, Logistics Unit  
Corporate Services Division  
Central Narcotics Bureau  
DID: (65) 6325 6626

*Keeping Singapore Drug-Free*

Central Narcotics Bureau W [cnb.gov.sg](http://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://fb.com/CNB.DrugFreeSG) IG [instagram.com/cnb.drugfreesg](https://instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** AIG SGP, CCU Referral <[AIGSGPCCUReferral@aig.com](mailto:AIGSGPCCUReferral@aig.com)>  
**Sent:** Friday, 7 September 2018 12:05 PM  
**To:** Shirlene YEO (CNB) <[Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)>  
**Cc:** Sylvester QUAH (MHA) <[Sylvester\\_QUAH@mha.gov.sg](mailto:Sylvester_QUAH@mha.gov.sg)>; AIG SGP, CCU Referral <[AIGSGPCCUReferral@aig.com](mailto:AIGSGPCCUReferral@aig.com)>  
**Subject:** RE: -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

Hi Shirlene,

Pls see attached email we replied on 21<sup>st</sup> June 2018.

Rgds,

*Varsha*  
Claims Care Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Fax +68357416  
[www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Shirlene YEO (CNB) [[mailto:Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)]  
**Sent:** Wednesday, September 05, 2018 3:33 PM  
**To:** AIG SGP, CCU Referral

**Cc:** Sylvester QUAH (MHA)

**Subject:** FW: -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

***Message Classification: Restricted***

AIG

We are unable to login to view the msg. Can you advise if you will be sending assessor to view the vehicle as we will be sending the vehicle for repair very soon?

Thanks.

Shirlene Yeo (Ms)  
Manager, Logistics Unit  
Corporate Services Division  
Central Narcotics Bureau  
DID: (65) 6325 6626

*Keeping Singapore Drug-Free*

Central Narcotics Bureau W [cnb.gov.sg](https://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://fb.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://Instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Sylvester QUAH (CNB)

**Sent:** Tuesday, 19 June 2018 10:58 AM

**To:** Shirlene YEO (CNB) <[Shirlene\\_YEO@cnb.gov.sg](mailto:Shirlene_YEO@cnb.gov.sg)>

**Subject:** FW: -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

***Message Classification: Restricted***

Are you able to open the email?

Sylvester Quah  
Senior Executive, Logistics  
Corporate Services Division  
Central Narcotics Bureau  
DID: (65) 6325 6625 | FAX: (65) 6224 3204

*Keeping Singapore Drug-Free*

Central Narcotics Bureau W [cnb.gov.sg](http://cnb.gov.sg) FB [fb.com/CNB.DrugFreeSG](https://fb.com/CNB.DrugFreeSG) IG [instagram.com/cnb.drugfreesg](https://instagram.com/cnb.drugfreesg)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

**From:** AIG SGP, CCU Referral [<mailto:AIGSGPCCUReferral@aig.com>]

**Sent:** Monday, 18 June, 2018 4:21 PM

**To:** Sylvester QUAH (CNB) <[Sylvester\\_QUAH@cnb.gov.sg](mailto:Sylvester_QUAH@cnb.gov.sg)>

**Cc:** AIGSGP, Claims <[claims.AIGsgp@aig.com](mailto:claims.AIGsgp@aig.com)>; AIG SGP, CCU Referral <[AIGSGPCCUReferral@aig.com](mailto:AIGSGPCCUReferral@aig.com)>

**Subject:** -RE: Ref No. CLM341222, Claims, Auto Insurance, Nil claim no 7188482354SG

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2018-06-25 03:20 CDT to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



## REPORT OF A TRAFFIC ACCIDENT

Date and Time Report Made: 28 MARCH 2018 2150HRS.		Vide Report No.: G/20180328/0160.	Station Diary No.:	
--	--	--------------------------------------	--------------------	--

Informant's Particulars			Address: B1K 416 Choa Chu Kang Ave 4 #05-362. Postal Code: 680416.	
Name of Informant: RAAM KUMAR S/O KANTHAMAN.		Contact No.: Mobile: 96664102. Home: - Office: -		
ID Type/No.: S9108583F.	Date of Birth: 07/03/1991.	Type of Informant: <input type="checkbox"/> Driver <input checked="" type="checkbox"/> Rider <input type="checkbox"/> Cyclist <input type="checkbox"/> Vehicle Owner <input type="checkbox"/> Pedestrian <input type="checkbox"/> Passenger <input type="checkbox"/> Pillion <input type="checkbox"/> Police Officer <input type="checkbox"/> Others (specify)		
Race: Indian.	Age: 27	Sex: M.	Occupation: (state name and address of work place if you are working or name of school/institution if you are a student) CNS officer.	

General Information on the Accident		Date of Accident: 28/3/2018	Type of Location:
Type of Accident:	<input type="checkbox"/> Fatal <input checked="" type="checkbox"/> Injury <input type="checkbox"/> Non-Injury For non-injury, involved: <input type="checkbox"/> Foreign vehicle <input type="checkbox"/> Pedestrian / Cyclist <input type="checkbox"/> Hit & Run <input type="checkbox"/> Police vehicle	Time of Accident: 3.30 PM.	<input type="checkbox"/> Bend <input type="checkbox"/> Flyover <input type="checkbox"/> Roundabout <input type="checkbox"/> Bridge <input type="checkbox"/> Gradient <input checked="" type="checkbox"/> Straight Road <input type="checkbox"/> Car Park <input type="checkbox"/> X-junction <input type="checkbox"/> T-junction <input type="checkbox"/> Y-junction <input type="checkbox"/> Private Property <input type="checkbox"/> Others (specify)
Location of Accident (state road name and specify landmark [if any]. If accident occurred at junction, state all road names that form the junction) PAYA LEBAR ROAD.			

Type of Collision:	Weather:
(i) Between moving vehicles <input type="checkbox"/> Head on <input type="checkbox"/> Side Swipe (same direction) <input type="checkbox"/> Head to Rear <input type="checkbox"/> Side Swipe (opposite direction) <input checked="" type="checkbox"/> Head to Side <input type="checkbox"/> Others (specify)	<input checked="" type="checkbox"/> Clear <input type="checkbox"/> Raining <input type="checkbox"/> Others (specify):
(ii) Moving Vehicle Against: <input type="checkbox"/> Parked Vehicle <input type="checkbox"/> Pedestrian <input type="checkbox"/> Animal <input type="checkbox"/> Lamp Post <input type="checkbox"/> Road Divider/Kerb <input type="checkbox"/> Others (specify)	

Traffic Flow:	Traffic Control:	Traffic Volume:	Road Surface:	Road Speed Limit:	Drink Drive:
<input type="checkbox"/> One-way <input type="checkbox"/> Two-way <input type="checkbox"/> Dual Carriageway	<input checked="" type="checkbox"/> Traffic Lights <input type="checkbox"/> Manual Control <input type="checkbox"/> Uncontrolled	<input type="checkbox"/> Heavy <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Light <input type="checkbox"/> No traffic	<input checked="" type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Others (specify):	..... km/h	Yes/No

Details Of Vehicle(s) & Driver(s) Involved									
Vehicle No.	Type/Make /Colour	Damage (serious, slight or no damage)	Name & ID of Driver	Class of D/Lic & Exp Date	Contact No	Degree of Injury & Days Given M/Leave	Name of Insurance Co.	Insurance Cert. No.	Validity Period of insurance
FBL1327P	X36 YAMAHA.	SLIGHT							
SJW3725H	NISSAN SILPHY.	SLIGHT.							

Details of Other Person(s) Involved (Passenger, Pedestrian, Pillion, etc.)							
Name	ID No.	Related Vehicle	Contact No.	Degree of Injury	Days Warded	Days given Medical Leave	Hospital/Clinic
DOROTHY PANG KAM LIN.	S0111876E.	NISSAN SILPHY. SJW3725H	98232128.	-	-	-	-







## CONTINUATION OF REPORT


<b>Information on Pedestrian(s) Involved</b>		
Any Pedestrian Involved: <u>Yes</u> / No		
No. of Pedestrians Injured:	Whether Pedestrian Crossing Was Used : <input type="checkbox"/> Used <input type="checkbox"/> Not Used <input checked="" type="checkbox"/> Not Available	Pedestrian's Degree of Injury : <input type="checkbox"/> Killed <input type="checkbox"/> Seriously Injured <input type="checkbox"/> Slightly Injured <input type="checkbox"/> Not Injured
<b>Information on Eyewitness</b>		
Any eyewitness available : <u>Yes</u> No	Eyewitness' Particulars Available <u>Yes</u> No (if Yes to both, please provide the eyewitness' particulars and contact number to the Investigation Officer)	


**Brief Details. This report shall be signed by the informant.**

On 28 March 2018 at about 3.30pm, I was alone on my bike (FBV1327P) travelling along Paya Lebar Road. I was on the third lane from the left. Suddenly, a car (SJW3725H) turned out into my lane from Jalan Afifi Road. The driver hit my motorcycle and I sustained a bone chip around my right shoulder. My motorcycle sustained damages on the tank (fuel) and box was dismantled. I had a 15 days MC, I was conveyed to CGH. I had advised the other party to lodge a police report as well. The gear lever and brake pad and side and rear lights, front number plate was damaged.

<b>Instructions</b> 1. Number each vehicle and show direction of travel by arrow.  2. Number each pedestrian and show direction by arrow.  3. Use solid line to show path of vehicle before accident  4. Show distance and direction to landmarks, identify by name. 5. Include road signs and any other important physical features.	<b>Sketch Plan</b> 
---	--

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to the Traffic Police at 65474749 stating the report number as reference.

Rank/Name/Signature Of Officer Recording The Report: W/SGT T150456 Taryn. 
Name/Signature Of Interpreter: —
Investigation Officer In-Charge Of Case:

Signature Of Informant: 
Date: 28 MARCH 2018.
Classification Of Case: —



**Scope Of Work  
Home Team Agency**

**SCOPE OF WORK**

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	E3	UNIT :	CNB / LOG2
VEH NO :	FBK9042M (FBL1327P)	REPAIR TYPE:	ACCIDENT		
VEH MAKE/MODEL:	YAMAHA XJ6N				

Reference No.
9042/CNB/2W/18/05/01

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	<b>Scope Of Repairs</b>					
1.1	Handle Bar	\$60.00	1	20%	72.00	72.00
1.2	Brake Lever	\$80.00	1	20%	96.00	96.00
1.3	Balancer - RH	\$20.00	1	20%	24.00	24.00
1.4	Side Mirror - RH	\$70.00	1	20%	84.00	84.00
1.5	Fuel Tank	\$860.00	1	20%	1032.00	1032.00
1.6	Fuel Tank Emblem - LH/RH	\$24.00	2	20%	28.80	57.60
1.7	Fuel Tank Side Cover - LH	\$80.00	1	20%	96.00	96.00
1.8	Side Cover - RH	\$110.00	1	20%	132.00	132.00
1.9	Side Under Cover - RH	\$100.00	1	20%	120.00	120.00
1.10	Footrest Bracket - RH	\$320.00	1	20%	384.00	384.00
1.11	Front Footrest - RH	\$70.00	1	20%	84.00	84.00
1.12	Front Signal Lamp - RH	\$28.00	1	20%	33.60	33.60
1.13	Rear Box	\$200.00	1	20%	240.00	240.00
2	<b>Additional Services</b>					
2.1	NA			0%	0.00	0.00
Remarks:					<b>Parts Total:</b>	<b>\$ 2,455.20</b>

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	<b>Scope Of Repairs</b>			
1.1	To Remove and Replace Handle Bar	59.00	2	118.00
1.2	To Remove and Replace Brake Lever & Balancer	59.00	1.5	88.50
1.3	To Remove and Replace Side Mirror - RH	59.00	0.5	29.50
1.4	To Remove and Replace Fuel Tank	59.00	2	118.00
1.5	To Remove and Replace Fuel Tank Cover - LH	59.00	0.5	29.50
1.6	To Remove and Replace Side Cover & Side Under Cover - RH	59.00	1.5	88.50
1.7	To Remove and Replace Footrest Bracket - RH	59.00	1	59.00
1.8	To Remove and Replace Front Footrest - RH	59.00	1	59.00
1.9	To Remove and Replace Front Signal Lamp - RH	59.00	0.5	29.50
1.10	To Remove and Replace Rear Box	59.00	2	118.00
2	<b>Additional Services</b>			
2.1	Towing from STN - WKSP, (SOR 8)	63.00	1	63.00
2.2	Towing from WKSP - STN, (SOR 8)	63.00	1	63.00
			<b>Labour Total:</b>	<b>\$ 863.50</b>
			<b>GRAND TOTAL :</b>	<b>\$ 3,318.70</b>
Contractor shall complete the entire repair within <u>60</u> working days upon quotation approved date. (Include parts awaiting time)				

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	04.05.2018	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	

All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018 <a href="#">Edit Reg</a>		19 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,318.70</b> <a href="#">Edit Estimates</a>	<b>S\$3,318.70</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>DOROTHY PANG KAM LIN</b> , ID: S0111876E		
Main Claimant:	-		
Vehicle Reg. No.:	<b>FBL1327P</b>	Date of Loss:	28/03/2018 00:00 - :59 [338 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 7188482354SG</b>	Policy/Cover Note No.:	2100199065 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SJW3725H</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 01/10/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (21/09/2018): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.





## Claim Documents

**\*FBL1327P (7188482354SG)  
[SJW3725H]  
TP**

**Mar 28 2018 12:00AM  
[DOROTHY PANG KAM LIN]  
SMRT Automotive Services Pte Ltd**

















[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

### Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/08/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>
2	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
3	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
4	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
5	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
6	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
7	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
8	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
9	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
10	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
11	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
12	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
13	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
14	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
15	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
16	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
17	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
18	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
19	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
20	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
21	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
22	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
23	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
24	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
25	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
26	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
27	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
28	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
29	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
30	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
31	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
32	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
33	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
34	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>
35	01/08/19 10:29	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	01/08/19 10:29	General View	 Load JPG	✓
37	01/08/19 10:29	General View	 Load JPG	✓
38	01/08/19 10:29	General View	 Load JPG	✓
39	01/08/19 10:29	General View	 Load JPG	✓
40	01/08/19 10:29	General View	 Load JPG	✓
41	01/08/19 10:29	General View	 Load JPG	✓
42	01/08/19 10:29	General View	 Load JPG	✓
43	01/08/19 10:29	General View	 Load JPG	✓
44	01/08/19 10:29	General View	 Load JPG	✓
45	01/08/19 10:29	General View	 Load JPG	✓
46	01/08/19 10:29	General View	 Load JPG	✓
47	01/08/19 10:29	General View	 Load JPG	✓
48	01/08/19 10:29	General View	 Load JPG	✓
49	01/08/19 10:29	General View	 Load JPG	✓
50	01/08/19 10:29	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/09/18 14:20	OI GIA REPORT	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18017128/R1CD3S2

Date: 02/08/2019

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100199065
Claimant Vehicle No :	FBL1327P	Insured Vehicle No :	SJW3725H
Date of Loss:	28/03/2018	Nature of Claim:	TP
		Claim No:	7188482354SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	FBL1327P	Engine No:	HIDDEN
Make & Model:	YAMAHA XJ6 DIVERSION F, 600cc	Chassis No:	JYARJ221000004834
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	4621 km
Colour:	Grey		
Engine Capacity:	600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	120/70 ZR17	Rear Tyre Size:	160/60 ZR17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,455.20	2,455.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	863.50	863.50	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,318.70</b>	<b>3,318.70</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>232.31</b>	<b>232.31</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>3,551.01</b>	<b>3,551.01</b>	<b>0.00</b>	<b>0.00</b>

## INSPECTION

Date of Assignment:	19/09/2018	
Date Inspected:	20/09/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	72.00 F	*72.00 F
2	1		*BRAKE LEVER	Scratched	96.00 F	*96.00 F
3	1		*BALANCER - RH	Scratched	24.00 F	*24.00 F
4	1		*SIDE MIRROR - RH	Cracked	84.00 F	*84.00 F
5	1		*FUEL TANK	Dented	1,032.00 F	*1,032.00 F
6	2		*FUEL TANK EMBLEM - LH/RH	Necessary	57.60 F	*57.60 F
7	1		*FUEL TANK SIDE COVER - LH	Cracked	96.00 F	*96.00 F
8	1		*SIDE COVER - RH	Scratched	132.00 F	*132.00 F
9	1		*SIDE UNDER COVER - RH	Scratched	120.00 F	*120.00 F
10	1		*FOOTREST BRACKET - RH	Bent	384.00 F	*384.00 F
11	1		*FRONT FOOTREST - RH	Scratched	84.00 F	*84.00 F
12	1		*FRONT SIGNAL LAMP - RH	Bent	33.60 F	*33.60 F
13	1		*REAR BOX	Cracked	240.00 F	*240.00 F
F=Franchise part.						
Total Parts (S\$)					2,455.20	2,455.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE HANDLE BAR.	New	118.00	118.00
2	TO REMOVE AND REPLACE BRAKE LEVER & BALANCER.	New	88.50	88.50
3	TO REMOVE AND REPLACE SIDE MIRROR - RH	New	29.50	29.50
4	TO REMOVE AND REPLACE FUEL TANK.	New	118.00	118.00
5	TO REMOVE AND REPLACE FUEL TANK COVER - LH.	New	29.50	29.50
6	TO REMOVE AND REPLACE SIDE COVER & SIDE UNDER COVER - RH.	New	88.50	88.50
7	TO REMOVE AND REPLACE FOOTREST BRACKET - RH.	New	59.00	59.00
8	TO REMOVE AND REPLACE FRONT FOOTREST - RH.	New	59.00	59.00
9	TO REMOVE AND REPLACE FRONT SIGNAL LAMP - RH.	New	29.50	29.50
10	TO REMOVE AND REPLACE REAR BOX.	New	118.00	118.00
11	TOWING FROM STN - WKSP, (SOR 8)	New	63.00	63.00
12	TOWING FROM WKSP - SYN, (SOR 8)	New	63.00	63.00
<b>Gross Labour Cost (S\$)</b>			<b>863.50</b>	<b>863.50</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >