

000000

INS. CASE OWNER

KC

CCV / AXA1801

7140, R1 p679

LEK

IDAC

Surveyor:

Rusul

DOI:

ASSIGNMENT

21/9/18

Date / Time:

20/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

SJD 677H

Name of Insured

TANG MUR KAT

Insured Tel No.

HP: 9694847

Excess Sec II :\$

D.O.A: 18/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

SEMOUWIA / 70604

Claim No.

Policy No.

Make / Model:

PERODUA

Place of Accident:

SLIP RD OF TAMPINES AVE 9  
TO TAMPINES AVE 10

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SVD 31979



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Chan's Customers



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

21/1/18  
HT

25/1/18

21/3/19

of amount claim

OI rechecked TP.

File pass to Shupei to close

STAGE	DATE / PIC
Non-Reporting 1st	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI	21/1/18
After call 1st to OI	
Documentation Check List:	Handler Typist
Notification 1st (if non-pickup)	
After call 1st to OI	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOI	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Assessed) BOLA S/N No.:	17.
Repair Cost:	\$5		
Loss of Rental (LOR):	\$5	(days)	
Loss of Use (LOU):	\$5	(days)	
Loss of Income (LOI):	\$5	(days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>			
GIA/LTA Search	\$5		
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/ Independent)	
Legal Cost:	\$5		
Total:	\$5	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5	Name 1:	Chan's Customers
Payee 2 (Strike if N.A.):	\$5	Name 2:	
Payee 3 (Strike if N.A.):	\$5	Name 3:	

Charn's Customcraft  
1010 Bukit Merah Lane 3  
Singapore 159724

LKK  
AXA

Claim Reference: THIRD PARTY  
Assessment Number: CC000015  
Version: CHARNCUS/1  
Date Calculated: 19/09/2018 08:50

Full Report - V1  
Registration: SLD7197G  
Printed: 19/09/2018 15:51

SLD71 97G

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	THIRD PARTY	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

#### Vehicle Details

##### Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SLD7197G
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

##### Model Specs

FROM MODEL 2016	TENS-/START SYS LINE
REAR COMBI LIGHT	REARVIEW CAMERA
REAR PARKING SYSTEM	1.5 LTR 88KW
TYRES 215/60 HR 16	WHEELS 7J X 17 ALLOY
SIDE AIRBAGS	HEAD AIRBAG
TWO COAT METALLIC	PREPARE OFF VEHICLE

#### Vehicle Condition

##### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	19/09/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

# Charn's Customcraft

Claim Reference: THIRD PARTY  
Assessment Number: CC000015  
Version: CHARNCUS/1  
Date Calculated: 19/09/2018 08:50

Full Report - V1  
Registration: SLD7197G  
Printed: 19/09/2018 15:51

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2711	REAR PANEL NEW PART PAINTING	19.0 ✓	
2931	BOOTLID/TAILGATE NEW PART PAINTING	19.0	
2587	L/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0 ✓	
2588	R/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0 ✓	
3900	FRONT BOOT FLOOR SURFACE PAINT	10.0 ✓	
<b>LABOUR COST - PAINT</b>			
<b>TIME(PAINT)</b>		<b>68.0</b>	
Preparation Main Work Plastic		8.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		<b>101.0</b>	
Total Paintwork Labour		<b>10.1HRS</b>	<b>\$454.50 ✓</b>
<b>MATERIAL COST - PAINT</b>			<b>Cost Price</b>
New Part Painting			\$80.76
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$30.63
Repair Painting Plastic			\$17.02
Material-Const Main Work Plastic			\$12.70
Total Excluding Pearlescent Uplift			\$169.71
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			<b>\$169.71</b>

## PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2977	1	BOOT/TAILGATE LOCK	74800T7AJ02		0%	83.00 ✓
2944	1	BOOT/TAILGATE SEAL	74440T7A003		0%	50.00 ✓
2931	1	BOOTLID/TAILGATE	68100T8PU10ZZ		0%	660.00 ✓
3171	4	CHECK	91501S70003	DEFAULT	0%	0.00F
3170	2	CHECK	91502S70003	DEFAULT	0%	0.00F
3173	2	CHECK	91536SS0J01	DEFAULT	0%	0.00F
4985	1	END PANEL TRIM	84640T8NT01ZA		0%	55.00 ✓
3167	1	L/R WINDOW SEAL	73254T7JH01		0%	17.00 ✓
3161	1	LWR REAR SCREEN SEAL	73226SZW000		0%	17.00 ✓
3168	1	R/R WINDOW SEAL	73214T7JH01		0%	17.00 ✓
2583	1	REAR BUMPER	71501T8NT50		0%	200.00 ✓
2711	1	REAR PANEL	66100T8NT10ZZ		0%	310.00 ✓
3160	1	REAR SCREEN BOND KIT	KNGKWI2	DEFAULT	0%	0.00F
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS		0%	0.00
3165	1	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161		0%	17.00 ✓
f: OEM Parts						
g: Original						
h: Secondhand						
p: Parallel						
x: Exchange						
Saving						\$83.40
Sub Total						\$1,426.00
Mark Up From Cost (15 %)						\$213.90
<b>Total Parts</b>						<b>\$1,639.90</b>

THIS ASSESSMENT CONTAINS UNPRICED PARTS

# Charn's Customcraft

Claim Reference: THIRD PARTY  
Assessment Number: CC000015  
Version: CHARNCUS/1  
Date Calculated: 19/09/2018 08:50

Full Report - V1  
Registration: SLD7197G  
Printed: 19/09/2018 15:51

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$200.00 Au ✓
<b>Total Extras</b>		<b>\$200.00</b>

## Final Calculation

<b>Total Parts</b>		<b>\$1,639.90</b> ✓
<b>Labour</b>		
Total Panel/Mechanical	\$607.50 178	
Total Paintwork	\$454.50 369	
<b>Total Labour</b>		<b>\$1,062.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$200.00	
<b>Total of Additional Costs</b>		<b>\$200.00</b>
<b>Total Paint/Material Costs</b>		<b>\$169.71</b> 148.81
<b>Grand Total Excludes GST</b>		<b>\$3,071.61</b>
GST @ 7 %		<b>\$215.01</b>
<b>Grand Total Includes GST</b>		<b>\$3,286.62</b>

## Assessment Notes

Resue

Hp 90010068

5 days

7/p or 4/s

21/09/18 @ 16:15

Recovery 34 or after repair



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Claim Reference: THIRD PARTY  
 Assessment Number: CC000015  
 Version: CHARNCUS/1  
 Date Calculated: 19/09/2018 08:50

Full Report - V1  
 Registration: SLD7197G  
 Printed: 19/09/2018 15:51



## Addresses

## Cost Summary

Total Labour	\$1,062.00
Total Paint/Material	\$169.71
Total Parts	\$1,639.90
Total of Additional Costs	\$200.00
Excess:	TBA
Grand Total Exc GST:	\$3,071.61
7 % GST:	\$215.01
Grand Total Inc GST:	\$3,286.62

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
 Price/Dent = \$45.00/HR

### Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	
NO NUMBER	REAR PANEL RUST PROOFING	1.0	
NO NUMBER	TAILGATE RUST PROOFING	1.0	
7141A0	R + R LEFT OUTER TAILLAMP	1.0	4.50
8131A8	R + R LEFT REAR WHEELHOUSE SHELL	3.0	13.50
7141A5	R + R RIGHT OUTER TAILLAMP	1.0	4.50
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL	3.0	13.50
8111A5 ZAX	RENEW REAR BUMPER	8.0	36.00
	INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.		
823100 ZAX	RENEW TAILGATE	33.0	148.50
	INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
NO NUMBER	RENEW REAR PANEL	42.0	189.00
8571C8)	R + R L/R SIDE PANEL TRIM	2.0	9.00
8571C9)	R + R R/R SIDE PANEL TRIM	2.0	9.00
2587	REPAIR L/R BUMPER CORNER	10.0*	45.00
2588	REPAIR R/R BUMPER CORNER	10.0*	45.00
3900	REPAIR FRONT BOOT FLOOR	20.0*	90.00
<b>LABOUR COST</b>			
Total Work Units		139.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		13.5HRS	\$607.50
Paint Labour		10.1HRS	\$454.50
Total Labour		23.6HRS	\$1,062.00

# Charn's Customcraft

Claim Reference: **THIRD PARTY**  
 Assessment Number: **CC000015**  
 Version: **CHARNCUS/1**  
 Date Calculated: **03/01/2019 07:06**

Full Report - V1  
 Registration: **SLD7197G**  
 Printed: **03/01/2019 15:06**

2931	BOOTLID/TAILGATE NEW PART PAINTING	19.0	
2587	L/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0	
2588	R/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0	
3900	FRONT BOOT FLOOR SURFACE PAINT	10.0	
<b>LABOUR COST - PAINT</b>			
	<b>TIME(PAINT)</b>	<b>49.0</b>	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	82.0	
	Total Paintwork Labour	8.2HRS	\$369.00
<b>MATERIAL COST - PAINT</b>			
	New Part Painting		Cost Price \$59.86
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$30.63
	Repair Painting Plastic		\$17.02
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$148.81
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$148.81

## PARTS

						Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)	
2977	1	BOOT/TAILGATE LOCK	74800T7AJ02		0%	83.00*	
2944	1	BOOT/TAILGATE SEAL	74440T7A003	BOOT RUBBER	0%	50.00F	
2931	1	BOOTLID/TAILGATE	68100T8PU10ZZ		0%	660.00*	
3171	4	CHECK	91501S70003	DEFAULT	0%	0.00F	
3170	2	CHECK	91502S70003	DEFAULT	0%	0.00F	
3173	2	CHECK	91536SS0J01	DEFAULT	0%	0.00F	
4985	1	END PANEL TRIM	84640T8NT01ZA	END PANEL TOP GARNISH	0%	55.00F	
3167	1	L/R WINDOW SEAL	73254T7JH01	WS MOULDING	0%	17.00F	
3161	1	LWR REAR SCREEN SEAL	73226SZW000	WS MOULDING	0%	17.00F	
3282	1	R/R OUTER LAMP	33502T7AH11	RR TAILLAMP RH	0% CFA	260.00F	
3168	1	R/R WINDOW SEAL	73214T7JH01	WS MOULDING	0%	17.00F	
2583	1	REAR BUMPER	71501T8NT50		0%	200.00*	
3160	1	REAR SCREEN BOND KIT	KNGKWI2	DEFAULT	0%	0.00F	
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS	DEFAULT	0%	0.00F	
1000	1	RR BP ANTENNA	Renew		0% NEC	55.00*	
2980	1	TAILGATE OPENER	74810T4NH01	SMART BUZZER	0% CRA	50.00F	
3165	1	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	WS MOULDING	0%	17.00F	

f: OEM Parts  
 g: Original  
 h: Secondhand  
 p: Parallel  
 x: Exchange

Saving \$253.05  
 Sub Total \$1,481.00  
 Mark Up From Cost (15 %) \$222.15  
**Total Parts \$1,703.15**

THIS ASSESSMENT CONTAINS UNPRICED PARTS  
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$200.00

Claim Reference: **THIRD PARTY**  
 Assessment Number: **CC000015**  
 Version: **CHARNCUS/1**  
 Date Calculated: **03/01/2019 07:06**

Full Report - V1  
 Registration: **SLD7197G**  
 Printed: **03/01/2019 15:06**

	<b>Total Extras</b>	<b>\$200.00</b>
<b>Final Calculation</b>		
<b>Total Parts</b>		<b>\$1,703.15</b>
<b>Labour</b>		
Total Panel/Mechanical	\$378.00	
Total Paintwork	\$369.00	
<b>Total Labour</b>		<b>\$747.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$200.00	
<b>Total of Additional Costs</b>		<b>\$200.00</b>
<b>Total Paint/Material Costs</b>		<b>\$148.81</b>
<b>Grand Total Excludes GST</b>		<b>\$2,798.96</b>
GST @ 7 %		<b>\$195.93</b>
<b>Grand Total Includes GST</b>		<b>\$2,994.89</b>

### Assessment Notes



Charn's Customcraft  
1010 Bukit Merah Lane 3  
Singapore 159724

Claim Reference: THIRD PARTY  
Assessment Number: CC000015  
Version: CHARNCUS/1  
Date Calculated: 03/01/2019 07:06

Full Report - V1  
Registration: SLD7197G  
Printed: 03/01/2019 15:06

### Summary Information

#### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	THIRD PARTY	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

#### Vehicle Details

##### Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	EX
Model Sheet Number:	HVE 06
Registration:	SLD7197G
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

##### Model Specs

FROM MODEL 2016	TENS-/START SYS LINE
REAR COMBI LIGHT	REARVIEW CAMERA
REAR PARKING SYSTEM	1.5 LTR 88KW
TYRES 215/60 HR 16	WHEELS 7J X 17 ALLOY
SIDE AIRBAGS	HEAD AIRBAG
TWO COAT METALLIC	PREPARE OFF VEHICLE

#### Vehicle Condition



##### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	19/09/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	



Claim Reference: THIRD PARTY  
 Assessment Number: CC000015  
 Version: CHARNCUS/1  
 Date Calculated: 03/01/2019 07:06

Full Report - V1  
 Registration: SLD7197G  
 Printed: 03/01/2019 15:06



## Addresses

## Cost Summary

Total Labour	\$747.00
Total Paint/Material	\$148.81
Total Parts	\$1,703.15
Total of Additional Costs	\$200.00
Excess:	TBA
Grand Total Exc GST:	\$2,798.96
7 % GST:	\$195.93
Grand Total Inc GST:	\$2,994.89

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR  
 Price/Dent = \$45.00/HR

### Repair /

### Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	
NO NUMBER	TAILGATE RUST PROOFING	1.0	
7141A5	R + R RIGHT OUTER TAILLAMP	1.0	4.50
8111A5 ZAX	RENEW REAR BUMPER	8.0	36.00
	INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.		
823100 ZAX	RENEW TAILGATE	33.0	148.50
	INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
848140	R + R REAR END PANEL TRIM	2.0	9.00
2587	REPAIR L/R BUMPER CORNER	10.0*	45.00
2588	REPAIR R/R BUMPER CORNER	10.0*	45.00
3900	REPAIR FRONT BOOT FLOOR	20.0*	90.00

### LABOUR COST

Total Work Units	87.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	8.4HRS	\$378.00
Paint Labour	8.2HRS	\$369.00
Total Labour	16.6HRS	\$747.00

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number Description	WU	Cost Price (\$)
- TWO COAT METALLIC		
- PREPARE OFF VEHICLE		

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 3618D

### Vehicle Details

Vehicle No.: SLD7197G  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 30 Sep 2018  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT  
Primary Colour: Silver  
Manufacturing Year: 2016  
Engine No.: L15B4034139  
Chassis No.: RU11114135  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$19,821.00  
Original Registration Date: 27 Jun 2016  
First Registration Date: 27 Jun 2016  
Transfer Count: 0  
Actual ARF Paid: \$9,821.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Jun 2026  
PARF Rebate Amount: \$7,365.00

### Intended COE Rebate Details

COE Expiry Date: 26 Jun 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$55,200.00  
COE Rebate Amount: \$42,718.00  
**Total Rebate Amount: \$50,083.00**

The information contained herein is correct as at 19 Sep 2018

OK




## Service Request Details

Claim

S8M00W1A

Reference

None 

Loss Date

September 18, 2018

Request Date

September 19, 2018

Due Date

September 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

20/9/2018 @ 937am  
Sharon veh not in.

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLD7197G

Make

TPVD HONDA

Model  
VEZEL-1.5 (A)

### Service Address

---

...

### Primary Contact/Insured

---

TANG MUN KIAT  
BLK 523B TAMPINES CENTRAL 7, #07-95, 522523, Singapore  
96954853  
KIATANG888@GMAIL.COM

### Claim Handler

---

CHAN Kian Chuan  
6568804269  
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



## <REQUEST FOR DS & SEEK MANDATE> - S8M00W1A [ACCIDENT INVOLVING SJD 677H(OI) & SLD 7197G(TP) ON 18/09/2018]

Type

Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$4,043.11(all-in). IA with mandate had been uploaded in Smartclaims. Kindly advise if we may proceed DS and let us have your mandate approval/instruction. Hsiao Tong - 25 Sept 2018

Reply



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25.09.2018

### Survey Details:

Date of loss	18.09.2018
Date of appointment	20.09.2018
Date of survey	21.09.2018
Location of survey	CHARN'S CUSTOMCRAFT

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLD 7197G
Make and Model	Honda Vezel (1496cc)
Date of registration	27.06.2016
Excess	NIL
Market Value/ Book Value	\$ 70,000.00 (est)
Parf/COE Rebate	\$ 50,083.00 (est)
Nett Loss	\$ 19,917.00 (est)

### Repair details:

Initial Estimate	\$ 3,071.61
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 2,009.61
Check items (estimate)	NIL
Labour	\$ 1,062.00
Supplementary	NIL
<b>Total</b>	<b>\$ 3,071.61</b>
<b>Lump Sum(if applicable)</b>	

Number of days for repair	<u>5</u>
---------------------------	----------



Auto  
Consultants  
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Date: 25.09.2018**

**Remarks:**

--

**Mandate:**

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 3,286.62	
Loss of use	NIL	
Loss of rental (w/GST)	\$ 749.00	(7days x \$100.00)
Loss of income	NIL	
LTA/GIA search fees	\$ 7.49	
Others	NIL	
Proposed Total	\$ 4,043.11	





**Re:<REQUEST FOR DS & SEEK MANDATE> -  
S8M00W1A [ACCIDENT INVOLVING SJD 677H(OI) &  
SLD 7197G(TP) ON 18/09/2018]**

Type

 Question

Message

PLS PROCEED FOR DS, QUANTUM AS PROPOSED

Reply

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 21 March 2019 4:19 PM  
**To:** 'Charn's Customcraft'  
**Cc:** Admin A  
**Subject:** RE: TP CASE / SLD 7197 G / SJD 677 H \*LKK REF: CC4/ASM18017140/R1pb3  
**Attachments:** AXA TPDS FORM\_SLD 7197G.pdf

**Sensitivity:** Confidential

### Without Prejudice

Dear Sirs/Mdm,

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,994.89
2. Loss of Use (5days x \$60.00)	\$ 300.00
<b>TOTAL</b>	<b><u>\$ 3,294.89</u></b>

If our offer is acceptable by your client, please duly sign the DV enclosed and return the together with your client's Authorisation to act to us (LKK) for our necessary action.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Charn's Customcraft <[charns@singnet.com.sg](mailto:charns@singnet.com.sg)>  
**Sent:** Thursday, 21 March 2019 1:54 PM  
**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: TP CASE / SLD 7197 G / SJD 677 H \*LKK REF: CC4/ASM18017140/R1pb3  
**Importance:** High  
**Sensitivity:** Confidential

Hi Hsiao Tong

Kindly find attached LOD for your necessary action.

Thanks & Regards,  
Sharon Lee  
Charn's Customcraft  
Tel: 6272 5429 Fax: 6273 6676  
Email: [charns@singnet.com.sg](mailto:charns@singnet.com.sg)  
GST Reg. No: M90367863L  
Company Reg No: 25151300M



## CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

21 March 2019

AXA Insurance Pte Ltd  
The Motor Claim Dept  
8 Shenton Way  
#27-01, AXA Tower  
Singapore 068811

Without Prejudices

Dear Sir

**ACCIDENT INVOLVING: SLD 7197 G & SJD 677 H on 18 SEPTEMBER 2018**  
**at/along TAMPINES AVE 9 TWDS TAMPINES AVE 10.**

We refer to the above matter.

We are helping the owner of vehicle no: **SLD 7197 G** to claim against your vehicle no: **SJD 677 H**, that the above accident was caused solely by the negligence of the driver of motor vehicle no: **SJD 677 H** which was insured by you at the material time. As a result of the said accident, we are claiming as follows:

1. Cost of Repair:	\$2994.89
2. Loss of Use @ \$80 x 5 days	\$ 400.00
<b>TOTAL</b>	<b><u>\$3394.89</u></b>

We forward copies of GIA reports, repair bill, certificate of insurance and driver's license for your attention. Please note that you should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter.

Thank You

Warmest Regards,

.....  
Sharon Lee  
Encl



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

02 OCT 2018

**TANG MUN KIT**  
BLK 523B TMPINES CENTRAL 7  
#07-95  
SINGAPORE 522523

Dear Sir/ Mdm

**OUR REF : CC4/ASM18017140/R1pb3**  
**YOUR REF : GA366008/1 (SJD 677H)**  
**ACCIDENT INVOLVING SJD 677H AND SLD 7197G ALONG/AT SLIP RD OF**  
**TAMPINES AVE 9 TO TAMPINES AVE 10 ON 18/09/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from CHARN'S CUSTOMCRAFT acting on behalf of the owner of SLD 7197G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [chewht@lkkauto.com](mailto:chewht@lkkauto.com) within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at [chewht@lkkauto.com](mailto:chewht@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

Cc     *AXA Insurance Pte Ltd*  
         *(Motor Claims Dept)*

**AXA INSURANCE PTE LTD**

8 Shenton Way

#26-01, AXA Tower

Singapore 068811

Attn: The Motor Claims Dept

**Without Prejudices**

**LETTER OF AUTHORITY**

I, TONY FAN YOW TANG, owner of SLD 7197 G hereby authorize CHARN'S CUSTOMCRAFT to act for me with respect to my claim for repair costs and/or rental and/or loss of use for my vehicle no: SLD 7197 G that was damaged pursuant to the accident which occurred on 18 SEPTEMBER 2018 at TAMPINES AVE 9 TWDS TAMPINES AVE 10 involving vehicle no/s: SJD 677 H.

---

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis in so far as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 06 (day) of 10 (month) 2018 (year)



Signature

Name: Tony Fan Yow Tang

NRIC: S1503618D



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJD 677H	(Insd veh)	Model: HONDA VEZEL 1.5X CVT
	SLD 7197G	(TP veh)	
Date of Accident/ Time:	18/09/2018		

Repair Estimate	\$ 3,735.76	
Final Repair Cost (w/GST)	\$ 2,994.89	
Loss of Use	\$ 300.00	5 days at \$ 60.00 per day
Rental (if any)	\$ -	days at \$ per day
LTA / GIA Search Fee	\$ -	
Others:	\$ -	
	\$ -	
Final Settlement Sum	\$ 3,294.89	

Payee Name : CHARN'S CUSTOMCRAFT

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: <u>1A</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:



#### NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: <u>Sharon Lee</u> Date: <u>30/04/19</u>  	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>Esther Kerk</u> Date: <u>30/04/19</u> 
Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date: <u>30/04/19</u>	





# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

## TAX INVOICE

*M/* AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01, AXA TOWER  
SINGAPORE 068811  
ATTN: THE MOTOR CLAIMS DEPT

2019036169

No. ....

TERM: .....

YOUR ORDER No. ....

OUR D/O No. 21/3/2019

DATE: .....

QUANTITY	DESCRIPTION	AMOUNT \$ CTS.
----------	-------------	-------------------

Vehicle No.	Make/Model	DOA	Reg. No.
SLD7197G	HONDA VEZEL 1.5X CVT	18/09/2018@1830	50372

Refer to Audatex report no: CC000015

2,798.96

CHARN'S CUSTOMCRAFT

Subtotal \$2,798.96

GST 7% \$195.93

Total \$2,994.89

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJD 677H (Insd veh)	Model:	HONDA VEZEL 1.5X
	SLD 7197G (TP veh)		
Date of Accident:	18/09/2018		

Global Sum Settlement	: [ ] Yes	[ X ] No	
Repair Estimate	: \$	3,735.76	
Final Repair Cost	: \$	2,994.89	
Loss of Use	: \$	300.00	5days at \$60.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	3,294.89

Is Third Party Workshop GIA Registered? [ X ] YES / [ ] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	27
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	CHARN'S CUSTOMCRAFT	: \$ 3,294.89

\_\_\_\_\_  
JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
09/05/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017140/R1pb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:KIAN CHUAN

Date : 09-05-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJD 677H	Veh. Inspected	SLD 7197G
Policy No.	GA366008/1	Coverage (\$)	0.00
Claim No.	S8M00W1A	Excess (\$)	0.00
Assign From		Assign Date	20/09/2018

**2. Vehicle Particulars & Condition**

Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11114135	Colour	GREY
Odometer	12767	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	18/09/2018	Inspection Date	21/09/2018
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 7197G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT /TAILGATE LOCK (CONSISTENT) (WCP)	BENT	83.00	83.00
1	BOOT/TAILGATE SEAL (CONSISTENT)(WCP)	NECESSARY	50.00	50.00
1	BOOTLID /TAILGATE (CONSISTENT)(WCP)	BENT	660.00	660.00
1	END PANEL TRIM (CONSISTENT)(WCP)	DEFORMED	55.00	55.00
1	L/R WINDOW SEAL (CONSISTENT)(WCP)	NECESSARY	17.00	17.00
1	LWR REAR SECREEN SEAL (CONSISTENT)(WCP)	NECESSARY	17.00	17.00
1	R/R WINDOW SEAL (CONSISTENT)(WCP)	NECESSARY	17.00	17.00
1	REAR BUMPER (CONSISTENT)(WCP)	DEFORMED	200.00	200.00
1	REAR PANEL (CONSISTENT)(WCP)	TO REPAIR SEE LABOUR	310.00	-
1	REAR SCREEN BOND KIT (CONSISTENT) (NPA)(WCP)	NOT NECESSARY	-	-
1	SET REAR SCREEN FIX (CONSISTENT) (NPA)(WCP)	NOT NECESSARY	-	-
1	UPP R-SCREEN SEAL (CONSISTENT)(WCP)	NECESSARY	17.00	17.00
1	R/R OUTER LAMP (CONSISTENT)(WCP)(ADDITIONAL)	CRACKED	260.00	260.00
1	RR BP ANTENNA (CONSISTENT)(WCP)(ADDITIONAL)	NECESSARY	55.00	55.00
1	TAILGATE OPENER (CONSISTENT)(WCP)(ADDITIONAL)	CRACKED	50.00	50.00
	COST PLUS 15%		268.65	222.15
			2,059.65	1,703.15
<b>SPECIAL NETT ITEMS</b>				
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	200.00	200.00
			200.00	200.00
<b>LABOUR</b>				
	PANEL /MECHANICAL INCLUSIVE OF THE REPAIR OF REAR PANEL .		607.50	378.00
	PAINTWORK.		454.50	369.00
	PAINT/MATERIAL COSTS.		169.71	148.81
			1,231.71	895.81
<b>GRAND TOTAL</b>			<b>3,491.36</b>	<b>2,798.96</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,798.96</b>

Report Ref No. CC4/ASM18017140/R1pb3q2



Report Ref No. CC4/ASM18017140/R1pb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

S61400W1A

Reference

ECA/ASM18017140/R14b3a2

Loss Date

18 September 2018

Report Date

19 Sep 2018 9:25:00 AM

Request Date

14 March 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (ITP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLD7197G

Make

TPWD HONDA

Model

VEZEL-1.5 IA

Service Address

Primary Contact/Insured

TANG MUN KIAT

BLK 523B TAMPINES CENTRAL 7, #07-95, 522523, Singapore

96954853

KIATANG88@GMAIL.COM

Claim Handler

CHAN Kian Chuan

65688042a9

kianchuan.chan@axa.com.sg

Actions















Next Step

Wait for Approve Invoice

Add Invoice

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type			Document SubType			
<div>Upload Documents</div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (ITP)	16 May 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 LKK Adjustment Lia.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 DS FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 DS FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 LETTER TO GI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	16 May 2019
 LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
 IA (with mandatal) dd 250918.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2018
 PAIRF_COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2018
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	24 September 2018



NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SLD677H INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE (Pragati)	19 September 2018
 EMAIL RECIEVED FROM WORKSHOP WITH TP GIA REPORT & ESTIMATE.png	Letters and Correspondence	Workshop	RATAN BHOSALE (Pragati)	19 September 2018
 SLD719TG TP GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE (Pragati)	19 September 2018