

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG18017163/KlCd302

Special Instruction:

Surveyor:
Nurman

Kalvin

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSG

Date/Time:

20/09/18 @ 3.44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 9655R

Insured:

SKV 1925D

at Workshop m/s

Michelin Engineering

Tel:

9797.3039

of

56 Jayang Way #06-07

Policy No:

29091274 AT2

Claim No:

570720

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/09/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4.12pm @ 20/9/18

Person Contacted:

Mas

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

GBG 9655R - X

SKV 1925D - X

(08/11/13)

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 686 9655R Yr Regn: 6 Dec 2012Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 22200 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MCE2620009604Gen. Cond: Good / Fair / Poor / BurntSteering: In order / 6 / Jammed / Leaked / Burnt orBrake: In order / 6 / Jammed / Leaked / Burnt orModi: Nil / S/Rim / 6 / STD / A/Rim orTyre Size: F: 195 R15C

R: _____

BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 12/1/1 D.O.I. 25/9/18 11.46Survey held at Miz Loh Engineering

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rear Bumper Striker repair book at the time of survey</u> <u>MS26</u> <u>PKS</u>
	<u>Range 1500/2 - 2000/2</u>
	<u>5/10/2018</u> <u>TRIM</u> <u>UMA</u>
	<u>5/10/18</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

120

2)

Transportation:

Photos

Others

10

TOTAL

130Report Format: PRS

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18017163/K1cd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-09-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKV 1925D	Veh. Inspected	GBG 9655R	
Policy No.	29091274AT2	Coverage (\$)	0.00	
Claim No.	570720	Excess (\$)	0.00	
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	20/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/09/2018	Inspection Date	25/09/2018	
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018		20 Sep 2018 15:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NGIAM MENG LANG, ID: S0073241I		
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R		
Vehicle Reg. No.:	GBG9655R	Date of Loss:	12/09/2018 09:00 - :59 [9 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570720	Policy/Cover Note No.:	29091274AT2 (Comprehensive) Coverage: 01/09/2018 - 31/08/2019
Vehicle Reg. No. (Insured):	SKV1925D	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/09/2018]		
Adj Asg. Remarks:	OI NOT REPORTED. CONTACT: RIZAN 8181 0737 / MAS 9797 3039		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1635R
Vehicle Details	
Vehicle No.:	GBG9655R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 SAT 5DR EURO V
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	YD25001950B
Chassis No.:	JN1MC2E26Z0009604
Maximum Power Output:	-
Open Market Value:	\$25,238.00
Original Registration Date:	06 Dec 2017
First Registration Date:	06 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,262.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$39,500.00
Total Rebate Amount:	\$39,500.00

The information contained herein is correct as at 28 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/09/2018 16:38
Date Of Accident	12/09/2018 09:45
Exact Location Of Accident	NO 2 GUAN SOON AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9655R
Insured/Policyholder	
Name Of Registered Owner	PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Co Reg No	201511635R
Email Address	PANPACIFICLEASING22@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64404428

Vehicle Particulars

Manufacturer	NISSAN
Model	NV 350
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5074863750-02
Cover Note Number	06/12/2017 TO 05/12/2018

Driver

Name of Driver	HANDAN BIN ABU BAKER
NRIC No	S1584685B
Date Of Birth	08/08/1963
Occupation	OUTDOOR
Date Of Driving Pass	06/04/2015
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98313045
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 59 MARINE TERRACE #05-85 (S) 440059
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV1925D
Vehicle Make/Model/Colour	TOYOTA CAMRY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

JIN PACIFIC VAN & TRUCK LEASING PTE. LTD.
CO. REG. NO: 201511635R
NO. 52 JOO CHIAI ROAD
SINGAPORE 427371
TEL: 6440 4426 FAX: 6345 0516

Policyholder's Signature: _____

Date & Time: _____

12/09/18 16:35 pm


Driver's Signature
(If driver is not the policyholder)
Date & Time: _____



Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Sketch Plan Pg. 1

SKETCH PLAN



A: GBA9655R

B: SKV1925B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 12/09/18, 09.45hrs. I was park my van GBA9655R front of unit no 3, 3A, for deliveries of items at unit no 02. While I searching the items my van sound loud of banging quickly I see the vehicles of SKV1725D trying to drive off, I stop the car, but he not so cooperative to me while asking the driving licence he gave me he say police also cannot ask my particulars and he offer me \$100 dollars Sug. I said no. I call police and make a oral statement, police and my Boss Company ask me to claim insurance as the driver of Toyota Camry SKV1725D drive of without leave any particulars.

DECLARATION

I/We hereby declare that the above particulars are true in every respect.

CO. REG. NO: 201511535R

NO. 52 JOO CHIAT ROAD

SINGAPORE 427371

TEL: 3440 4422 FAX: 6345 3516

Policyholder's Signature: [Signature]

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

Vehicle No: 4BG 9655 R

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT	R	X
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket	?		
1148	993068	Rear Bumper Side Retainer	?		
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		20 Sep 2018 15:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NGIAM MENG LANG , ID: S00732411								
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD , Co. Reg. No.: 201511635R								
Vehicle Reg. No.:	GBG9655R	Date of Loss:	12/09/2018 09:00 - :59 [9 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570720	Policy/Cover Note No.:	29091274AT2 (Comprehensive) Coverage: 01/09/2018 - 31/08/2019						
Vehicle Reg. No. (Insured):	SKV1925D	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Michelin Engineering Pte Ltd (HQ) 56 Loyang Way,, #06-07 Loyang Enterprise Building,, 508775 Loyang - Tel: 64404428								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Imm.Advice due 21/09/2018]								
Adj Asg. Remarks:	OI NOT REPORTED, CONTACT: RIZAN 8181 0737 / MAS 9797 3039								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG9655R (570720)

[SKV1925D]






































TP
























PAN PACIFIC VAN & TRUCK LEASING PTE LTD

Sep 12 2018 9:00AM

[NGIAM MENG LANG]

Michelin Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
2	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
3	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
4	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
5	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
6	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
7	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
8	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
9	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
10	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
11	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
12	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
13	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
14	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
15	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
16	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
17	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
18	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
19	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
20	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
21	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
22	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
23	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
24	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
25	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
26	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
27	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
28	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
29	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
30	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
31	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
32	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
33	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
34	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
35	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
36	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	
37	25/09/18 19:34	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/18 19:34	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	02/10/18 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/09/18 14:03	SURVEY DISAGREE ON SJE - ASSIGN LKK & PRI - EAST ASIA LAW CORPORATION	 Load PDF	
2	20/09/18 14:03	EMAIL FROM TP ON SURVEY LOCATION	 Load PDF	
3	20/09/18 14:03	GBG9655R TP E-FILE REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017163/K1CD3E2

Date: 10/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29091274AT2

Claimant Vehicle No : GBG9655R

Insured Vehicle No : SKV1925D

Date of Loss: 12/09/2018

Nature of Claim: TP

Claim No: 570720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG9655R

Make & Model: NISSAN NV350, 2.5 5AT 5DR EURO V (A)

Engine No: YD25001950B

Reg. Date: 06/12/2017 (Man. Year: 2017)

Chassis No: JN1MC2E26Z0009604

Colour: Grey

Odometer: 27290 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/09/2018

Date Inspected: 25/09/2018 Inspected At:

Michelin Engineering Pte Ltd (HQ)
56 Loyang Way., #06-07 Loyang
Enterprise Building,
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$2,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Oct 2018)	
Parts:	N/A	NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9655R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >