

Shenoy

Tanpin

REF: LPC

ASSIGNMENT

From: Date: 27/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 9KQ 3937H
at Workshop m/s: Falcon - Air
of: Blk 8 Pandan Loop

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Make of Veh:

Andy
11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Andy

Veh No: SKQ 3937H. Yr Regn: 2014, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf C.C. 1395

Colour: Blue A/C. Insured / Std / NI / NA

Sp. Reading: 56624 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVV ZZZ AM ZFW041392

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 2 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Houtlook

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 27/9/18 11am

Survey held at Falcon - Air Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report

1)

Date/Time: File Return to?

☐ : Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

☐ S + RS \$

☐ Photos

☐ Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL