

ASS. REC. BY:

REF:

CS3/CTI18017207/Gcd3²

Special Instruction:

Surveyor
menimenCmo @iang
Irene tay

ASSIGNMENT (Office)

From (Person):

of

CTI

Date/Time

21/9/18@

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGK 6211C

Insured:

GBH 4877 U

at Workshop in/s

Perfect Werkz

Tel:

8778 8855

of

No. 25 kaki Bkt Rd 4 # 06-51

Policy No:

DMCVSN1818571800

Claim No:

SNM18 D04405C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/09/2018

CA / REV / REP. / REV 24 HRS

(up)

21/9/18@ after 1pm

H.O.D. Endorsement:

Date/Time:

10:47am@ 21/9/18

Person Contacted:

Mr. Louis

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (X) Estimate

SGK 6211C - X

GBH 4877U - X

Dismantle: 25/9/2018

PPS
xal.

REF: CRI

ASSIGNMENT

From: Date: 20/11/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGK 6211C
at Workshop m/s: Perfect Werkz
of: No. 25 Kaki Bkt Rd 4 # 06-51

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

after 1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGK6211C Yr Regn: Aug / 06

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Airwave G.C. 1496

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 148503 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GJ11106752

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ N/R / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R14
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 24-09-18 4pm

Survey held at w/s

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: PRE

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18017207/Gcd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-09-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBH 4877U	Veh. Inspected	SGK 6211C
Policy No.	DMCVSN1818571800	Coverage (\$)	0.00
Claim No.	SNM18D04405C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/09/2018	Inspection Date	24/09/2018
Survey held at	PERFECT WERKZ-NO.25 KAKI BKT RD 4#06-51		
Repairer	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018		21 Sep 2018 10:21 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAY KIA KOON TRADING, Co. Reg. No.: B513137737K		
Main Claimant:	NG HAI LENG, ID: S1633410C		
Vehicle Reg. No.:	SGK6211C	Date of Loss:	11/09/2018 10:00 - :59
Claim Type:	TP / SNM18D04405C02	Policy/Cover Note No.:	DMCVSN1818571800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH4877U	Policy No. (Claimant):	DMPC185009137
		Excess:	S\$0.00
Repairer:	Perfect Werkz (HQ) NO. 25 KAKI BUKIT ROAD 4 #06-51 SYNERGY @ KB, 417800 Kaki Bukit - Tel: 87788855		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Driver/Custodian (Insured):	KU KOK FAN (27 / Male), NRIC: G6919561Q, Tel: +6586780850		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Anil Kumar <anil@htapartners.com.sg>
Sent: Thursday, 20 September, 2018 5:41 PM
To: Lucas Lee
Cc: Tay Khiang Wei (wei_845@icloud.com)
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - OUR REF: SNM18D04405C02 & YR REF: TCL.GCN.an.50354.18. - ACCIDENT INVOLVING SGK6211C & GBH4877U ON 11/09/18

Importance: High

Without Prejudice
Save As To Cost

Dear Lucas,

We refer to your email dated even date.

Our client regret to reject your list of surveyors and append below our client's list of surveyors for your consideration.

- 2. Kelvin - KAAS
- 3. Terrence - KAAS

If your end is not agreeable with the above list of surveyors, kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : Perfect Werkz
25 Kaki Bukit Road 4
#06-51 Synergy@KB
Singapore 417800
Contact Person : Mr Louis : 87788855

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: Lucas Lee [mailto:lucas.lee@sg.cntaiping.com]
Sent: Thursday, September 20, 2018 3:57 PM
To: Anil Kumar <anil@htapartners.com.sg>
Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - OUR REF: SNM18D04405C02 & YR REF: TCL.GCN.an.50354.18. - ACCIDENT INVOLVING SGK6211C & GBH4877U ON 11/09/18

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Thursday, 20 September, 2018 9:49 AM

To: Claims Dept of CTI

Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: GBH4877U & OUR REF: TCL.GCN.an.50354.18. - ACCIDENT INVOLVING SGK6211C & GBH4877U ON 11/09/18

Importance: High

Dear Sirs,

CLAIMANT: NG HAI LENG

ACCIDENT INVOLVING SGK6211C & GBH4877U ALONG / AT ANG MO KIO PARK 2 ON 11/09/18 @ TIME: 10:20 HRS

We are instructed by Ng Hai Leng to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number **SGK6211C** and vehicle registration number **GBH4877U** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MPA218117968 / Progressive Car Care Pte Ltd - HQ
 ENTRY DATE & TIME: 11/09/2018 15:58
 SUBMITTED BY: Lily Lim

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2018 15:58
Date Of Accident	11/09/2018 10:20
Exact Location Of Accident	ANG MO KIO PARK 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK6211C
Insured/Policyholder	
Name Of Registered Owner	NG HAI LENG
NRIC No	S1633410C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96192169
Alternative Phone No	Others-96192169

Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC185009137
Cover Note Number	

Driver

Name of Driver	NG HAI LENG
NRIC No	S1633410C
Date Of Birth	16/10/1964
Occupation	INDOOR
Date Of Driving Pass	17/02/1997
Driving Experience	21 YEARS AND 6 MONTHS

Gender MALE
Mobile Number (LOCAL) +65-96192169
Fax Number
Contact Number OTHERS-96192169
Email Address NOEMAIL
Address BLK 670 HOUGANG AVE 8 #04-753
Postcode 530670
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: REQUEST FROM OWNER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH4877U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG HAI LENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SGK6211C
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SGK6211C		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	AIRWAVE 1.5 A		
Chassis No. :	GJ11106752		
Propellant :	Petrol		
Engine No. :	L15A5108507		
Engine Capacity :	1496 cc		
Maximum Power Output :	81.0 kW (108 bhp)		
Maximum Laden Weight :	1435 kg		
Unladen Weight :	1160 kg		
Year Of Manufacture :	2006		
Original Registration Date :	18 Aug 2006		
Lifespan Expiry Date :	-		
COE Category :	E - Open Category		
PQP Paid :	\$24,760.00		
COE Expiry Date :	31 Jul 2021		
Road Tax Expiry Date :	17 Aug 2019		
Inspection Due Date :	17 Aug 2019		
Intended Transfer Date :	26 Sep 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

[OK](#)
[Print](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3410C
Vehicle Details	
Vehicle No.:	SGK6211C
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	L15A5108507
Chassis No.:	GJ11106752
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,686.00
Original Registration Date:	18 Aug 2006
First Registration Date:	18 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$17,255.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,760.00
COE Rebate Amount:	\$14,097.00
Total Rebate Amount:	\$14,097.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018		21 Sep 2018 10:21 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAY KIA KOON TRADING, Co. Reg. No.: B513137737K		
Main Claimant:	NG HAI LENG, ID: S1633410C		
Vehicle Reg. No.:	SGK6211C	Date of Loss:	11/09/2018 10:00 - :59 [144 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04405C02	Policy/Cover Note No.:	DMCVSN1818571800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH4877U	Policy No. (Claimant):	DMPC185009137
		Excess:	\$0.00
Repairer:	Perfect Werkz (HQ) NO. 25 KAKI BUKIT ROAD 4 #06-51 SYNERGY @ KB, 417800 Kaki Bukit - Tel: 87788855		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/10/2018]		
Driver/Custodian (Insured):	KU KOK FAN (27 / Male), NRIC: G6919561Q, Tel: +6586780850		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

*SGK6211C (SNM18D04405C02)
[GBH4877U]
TP
NG HAI LENG
Sep 11 2018 10:00AM
[TAY KIA KOON TRADING]
Perfect Werkz

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:32	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	11/09/18 16:32	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 14:02	General View	Load PDF	
2	26/09/18 14:13	Photographs of Damaged Parts	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:16	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	11/09/18 16:16	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/09/18 16:17	Owner Lic [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 10:20	PRS	Load PDF	
2	21/09/18 10:20	OI GIA	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:32	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	11/09/18 16:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	11/09/18 16:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
4	11/09/18 16:32	Accident Photo	 Load JPG	✓
5	11/09/18 16:32	Accident Photo	 Load JPG	✓
6	11/09/18 16:32	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 16:16	Sketch Plan	 Load JPG	✓
2	11/09/18 16:16	Sketch Plan #2	 Load JPG	✓
3	11/09/18 16:17	Owner Lic	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118017207/GCD3S2
 Date: 27/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1818571800
 Claimant Vehicle No: SGK6211C Insured Vehicle No: GBH4877U
 Date of Loss: 11/09/2018 Nature of Claim: TP Claim No: SNM18D04405C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGK6211C
 Make & Model: HONDA AIRWAVE, 1.5 (A) Engine No: L15A5108507
 Reg. Date: 18/08/2006 (Man. Year: 2006) Chassis No: GJ11106752
 Colour: Silver Odometer: 148503 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R14 Rear Tyre Size: 185/65R14
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/09/2018
 Date Inspected: 24/09/2018 Inspected At: Perfect Werkz (HQ)
 NO. 25 KAKI BUKIT ROAD 4 #06-51 SYNERGY @ KB
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2018)

Parts: M1-MPV HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGK6211C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >