Wenter	- INITIALITY	ASSIGN	MENT (Office)	vd3@proist instruct	
	Elouine Che	of _pr	Ctf	Date/Tim	2/9/18@ 2/17P
Estimated Co			Bill to:		
To Inspect V	/S/TP RES / OD RI	S/EVA/INV/MV	7 CS 389 S		NV ELICI
at Workshop of	m/s	Tan Chong N	1otor,	Tel: 670	DK 5445 L 3 8916
Policy No:_ Sum Insured	DMPCSN302	0231801	Claim No	SNMIEDO	4565002
Make of Veh (Client's Recen				D.O.A.	8108   2018
CA / REV	/ REP. / REV 24 I	RS lup	D SIDEPUFE	10am	ndorsespent
Date/Time:	236pmg 21/a/	Person Contacte	zuhn		~
Date/Time	Action/Instruction SMA 83845		te		
	8DK 5 4 4	SL-X			
11 10 16	@ 234pm ?	Zuhri said ranging for	vehicle ha	s not send	in for repair,
30/10/18			Linalised		

Bligging layer	CT
V ====================================	SSIGNMENT
From Date	Vell No SM 4 83895 Yr Regn. 20/1 7
Estimated Cost:	Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Traffer or
To inspect Vehicle No:	Make Nissin Gaskga 2 /1
at Workshop m/s	Golour Silver AC Insured / Std / NI
pt.	Sp.Reading 5375 TiRadio: Insured / Std / N
Insured	Eng/No.
Policy No.	CNO SJUFFA J142313583
Claires No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured. Excess:	Steering: Inorder / Jammed / Leaked / Burnt. or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Yeh	Modi Nil / S(R)m / STD A/Ring OF K()
	1,700.00
(Policy Condition)	R:
Remark. The veh had commenced its N/S C repair at the time of inspection.	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	Yoyo / Yoko or
Bat or Market Value	Front Bear R/Bal G mm R/Bal 6
IDAC Accident Rport. Consistent? : Yes or No  Consistent? : Yes or No	L/Bal 6 mm L/Bal 6
Section 1.11 Section 1	D.O.A D.O.I 3/10// 8
Est. Repers: days Res.: Yes or No  Lum Sum: % 3 Val. Yes or No	Survey held at TC BH Timeh
3pm	hy Des. of Damages : Frt. / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle IN /	
Date Person Contacted:	The U/C / Chassis frame / Body Structure affected due to o
	fumed by email (Red 13>>.36, 53%)
	ED 0 3 DEC 2018
RECEIV	
RECEIVI	Days Of Repair: 3
	CONTROL OF THE PARTY OF THE PAR
Cutoffens, File Pasa to? : Prell, Report : Final Report	Resurvey No. of Trip: Survey Fee 2
Cuto/Tanar, File Pasa to?  : Preli. Report : Final Report : Data/Tanar, File Raturn to?	Resurvey No. of Trip: Survey Fee 2

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	(Ad) Rot	Adt 50	binithiid	Ins Authind	Status	
Main	21 Sep 2018		21 Sep 2018 14:17 Assign				2.0 Adds 69	195	signment ase
	tain	Re	ference		Claim Details		Documer	nts	Show All
CLAIM SUE	FOLDER DE	TAILS				I Connet			
Insured:						Lcreati	ed by insurer]		
Main Claimant:	NOORSHI	RIN BINTE MUS	4						
Vehicle Reg. No.:	SMA8389S			Date of Loss:	07/09/2	7/09/2018 00:00 - :59			
Claim Type:	TP / SNM18D04565C02			Policy/Cover Note No.:	DMPCSN3020231801				
Vehicle Reg. No. (Insured):	SDK5445L				Policy No. (Claimant):				
Repairer:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road,				Excess:	\$50.00			
Handling Insurer:							54601594 dled by <b>Elaine Ch</b>	eongl	
Adjuster:		Consultants Pte							
Adj Asg. Remarks:		72, CASE WITH S.				000 0E/	10/2010]		
ASSOCIATE	D MAIL REC	EIVED						View All I	
There are no	mail for this o	ase,						VIEW AII	ompose Case Mail
ALL ASSOC	IATED TASK	(SE				View Al	II   Search Tasks	C	
Due Date	Priority	Type Task 6	iroup Subje	et Han	dler Assign	-	Completed On	Create New	
lo results.				22.0440		to all says	Compreted On	Creat	ed On Done

#### Lucas Lee

From: Sent:

160

Muhammad Zuhri <zuhri@tanchong.com> Friday, 21 September, 2018 12:41 PM

To:

Claims Dept of CTI

Subject:

ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018

INS/IC/ZHR/0407/2018 DIRECT SETTLEMENT - ANR

Attachments:

IC,DL&COLTIF; SAS2469511 (1).pdf; est.tif

Dear Office In Charge,

Our customer, Mdm NOORSHIRIN BINTE MUSA the owner of SMA8389S is insured with AXA Insurance at the material time of the accident. The 3rd party ,SDK5445L is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental \$150.00 / Use \$90.00. GIA Report / Estimate attached for your action.

Best Regards, ZUHRI Tan Chong Motor Sales Pte Ltd 913 Bukit Timah Road Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com



MTCJ18117288 / Tan Chong Motor Sales Pte Ltd - Build Timah ENTRY DATE & TIME: 10/09/2018 16/29 SUBMITTED BY: Muhammad Zuhn Bin lamali

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

Will Artiful		
	ACCIDENT STATEMENT	
Date Of Report	10/09/2018 16:29	
Date Of Accident	07/09/2018 10:40	
Exact Location Of Accident	CAUSEWAY LINK	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMA8389S	
Insured/Policyholder		
Name Of Registered Owner	NOORSHIRIN BINTE MUSA	
Work Permit No	S7124311G	

Email Address SHIRIN818@GMAIL.COM

Mobile Phone No (LOCAL) +65-81023106

Alternative Phone No OTHERS 81023105

Alternative Phone No OTHERS-81023106

Vehicle Particulars

Manufacturer NISSAN

Model QASHQAI-1.2 DIG-T (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800073782

Cover Note Number

Driver

Name of Driver ABDUL AZIZ BIN ROHANI

 NRIC No
 \$1808665D

 Date Of Birth
 31/05/1967

 Occupation
 INDOOR

 Date Of Driving Pass
 25/02/1993

Driving Experience 25 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-81023106

Fax Number

Contact Number

EMail Address SHIRIN818@GMAIL.COM

Address

818 WOODLANDS STREET 82#08-405

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

NOORSHIRIN BINTE MUSA

GENDER:

FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BUKIT PANJANG NORTH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 27 MARSILING DRIVE , POSTCODE: 730027 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-3689999 - FAX NO: 63682383

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer the attached

Attachment(s)

YES

Are accident photos available for attachment? Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number Vehicle Make/Model/Colour

SDK5445L

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

81993125

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **DETAILS OF INJURED PERSON 1**

Name

NOORSHIRIN BINTE MUSA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

8/2

Policyholder's Signature Date & Time: The

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

# Sketch Plan Pg. 2

#### SKETCH PLAN

leads immergration

#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date: 7 Supt 18 Accident Time: 10 46 AMPR
Accident Location: Cause way link
- Details of circumstances-
- Travelling on the second lane of counterway link toward
John Bahry
- when suddenly I felt a large impact from the rear
- Realize that a cur registration plate no. SDK5445L had
collided on my vear
- A Chinese man about 60 yis sid and myself both alighted
from our car and he admitted to his mustake
- The driver only provide the handphone number (81993125 hp)
- There is in car year view comera capture the accident.
- The weather - clear & along traffic volume - heavy.
3rd party details below:-
B) Veh No. SDKS445L Hp No. 81993125 Pax incl driver. Driver name:
C) Veh No: Pax incl driver: Driver name:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Policyholder's Signature Date & Time Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

#### Sketch Plan #2 Pg. 1



1/20180910/2074

Report No. T/20180910/2074

# Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No T/20180908/2064

Report Number

T/20180910/2074

Vide Report Number

T/20180908/2064

Date/Time of Report Made

10/09/2018 14:22

Place Report Lodged

Traffic Police Division HQ

Type of Informant

Driver

Name of Informant

ABDUL AZIZ BIN ROHANI

ID Type / ID No.

NRIC NO / S1808665D

Home/Office

Mobile

81023106

Email

Type of Accident

Injury / Others

Drink Drive

No

Anyone conveyed by

ambulance

No

Date/Time of Accident

07/09/2018 10:40

Details of Vehicle Involved							
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger	
SDK5445L	Car				Slightly Damaged	1	
SMA8389S	Car				Slightly Damaged	1	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL.	Use of Pedestrian Crossing: NA



7/20180910/2074

2 01 3

Report No. T/20180910/2074

#### Continuation of CSF For NP168

Name	ABDUL AZIZ BIN R	OHANI		ID No	e ·	S1808665D
Total Carlot				10.110		0.000000
Related Vehicle	SMA8389S (Car)			Conta	ect No.	81023106
Hospital/Clinic	MILLENNIUM MEDI	CAL GRO	UP	Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	08/09/2018		Date Dis	charge	08/09	/2018
No. of Days grant	ed Medical Leave	05	Degree o			

#### Brief Facts.

On 07/09/2018 at about 1040hrs, I was together with my wife and was travelling on the second lane of causeway link toward Johor Bahru. There was heavy traffic congestion, and every vehicles were moving slowly. I was also travelling at a very slow speed, when out of sudden I felt a large impact from the rear. I then came to realize that a vehicle bearing registration plate no. SDK5445L had collided onto my rear. The vehicle said driver, a male Chinese about 60yrs old, and I both alighted from our vehicle, the said driver admitted to his mistake, we do not sustained any injuries at the point of time. The said driver only provided his contact number to us and agreed to settle the matter when we returned back to Singapore. There was a slight dent and scratches on my rear rubber bumper area. There is in-car camera installed in my vehicle and recorded the whole accident and photo were taken too. On the same evening, we felt pain from the neck and back area and we went to seek medical treatment on the following morning, 08/09/2018 and was given 5 days of medical leave. I suspect that the driver was using his mobile phone while driving.

The following morning, on the 08/09/2018, I tried contacting the driver, but to no avail. And he did not replied back to me. I am lodging this report for my insurance claim purpose.

#### Sketch Plan #2 Pg. 3





Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027 Tel No: 1800-3689999 3 of 3 Report No. T/20180908/2064

CONTINUATION OF REPORT

#### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Staff Sgt LIN WUHUA	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 08/09/2018 12:28
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:
Authentication Stamp	

#### Sketch Plan #2 Pg. 4





Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027

1 of 3 Report No. T/20180908/2064

Tel No: 1800-3689999

REPORT	OF A TRAFFI	CACCIDENT			
	me Report / 018 12:28	Made:	Vide Report No.: Station 8		
Informa	nt's Partic	ulars	The second second		
	f Informant: AZIZ BIN F		Address: APT BLK 818 WOODLANDS SINGAPORE 730818	STREET 82 #08-405	
ID Type / ID No.: NRIC NO / S1808665D			Contact No.: Home/Office:	Mobile: 81023106	
National SINGAP	lity: PORE CITIZ	žEN.	Email:		
Sex: Male	Age: 51	Date of Birth: 31/05/1967	Type of Informant: Driver		
Race: Malay			Language: English	Institution / School Name:	
Occupat Other as	lion: ssistant eng	ineers	Driving Licence Information: Class: 2B,3	Date of Expiry:	

Type of Accident:	Cithore		Date/Time of Accident: 07/09/2018 10:4	Type of Location	
Location: Along Road 1 CAUSEWAY Causeway Lir	ik to Johor Bahru ci	ustom			
Weather: Clear		Road Surface: Dry			
Clear	Traffic Flow: One Way			Traffic Volume: Heavy	
21237		Traffic Control: Not Controlled		The state of the s	

T-71		Details of Vehicle Involved							
Make	Model	Color	Condition	No of Passenger					
				B					
			1 1	1					
	Make	Make Model	Make Model Color	Make Moder Color Condition					

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20180908/2064

Police Station Of Origin: Bukit Panjang North NPP 27 Marsiling Drive #01-237 SINGAPORE 730027

1040 W.

Report No. T/20180908/2064

Tel No: 1800-3689999

CONTINUATION OF REPORT

wife.

Driver	CARRIED SERVICE		THE PERSON NAMED IN	2.0	THE RE	The second second		
Name	ABDUL AZIZ BIN ROHANI			ID No	).	S1808665D		
Related Vehicle	SMA8389S (Car)			SMA8389S (Car)		Conta	act No.	81023106
Hospital/Clinic	MILLENNIUM MEDICAL GROUP			Class Drivin Licen Expin	ig	Class: 2B,3 Date of Expiry: NIL		
Date Treatment	08/09/2018		Date Disc	charge	08/09	/2018		
No. of Days gran	ted Medical Leave	05	Degree o	f Injury	NIL			

Brief Details.

On 07/09/2018 at about 2240hrs, I was together with my friend and was travelling on the second lane of causeway link toward seher bahru. There was heavy traffic congestion, and every vehicles were moving slowly. I was also travelling at a very slow speed, when out of sudden I felt a large impact from the rear. I then came to realise that a vehicle bearing registration plate no. SDK5445L had collided onto my rear. The vehicle said driver, a male Chinese about 60yrs old, and I both alighted from our vehicle, the said driver admitted to his mistake, we do not sustained any injuries at the point of time. The said driver only provide his contact number to us, and agreed to settle the matter when we returned back to Singapore. There was a slight dent and scratches on my rear rubber bumper area. There is in-car camera installed in my vehicle and recorded the whole accident. On the same night, we felt pain from the neck and back area, and we went to seek medical treatment on the following day, 08/09/2018 and was given 5 days of medical leave. I suspecting that the driver was using his mobile phone while driving.

The following day, on the 08/09/2018, I tried contacting the driver, but no to avail, and he did not replied back to me. I am lodging this report for my insurance claim purpose.

photo were taken too. 039

#### Sketch Plan #2 Pg. 6



T/20180910/2074

3 013 Report No. T/20180910/2074

### Continuation of CSF For NP168

#### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity

No

Officer-In-Charge of Case

TP/AEIT/


ONG YONG HOCK

Classification of Case

1) INJURY / OTHERS

Page 11 of 18










**Accident Photo** 



**Accident Photo** 





TAN CHONG NOTOR BALES PTE, LTD. 911, BUKIT TIMAH ROAD SINGAPORE 589623

ESTIMATE

· ACCIDENT/BODY REPAIRS

WORKSHOP

BURIT TIMAB

CONTACT NO

1 4694093

REFERENCE

: INS/IC/IHR/0407/2018

DATE

: 21-SEP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

5(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME

# MDM NOGREHIBIN BINTE MURA

ADDRESS

BLK 818 WOODLAND STREET 82

#08-405

S(730818)

TELEPHONE NO : 81023106 DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL: zuhri@tanchong.com

FAX: 64697472 OFFICE: 67038916

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO

TP-SDE5445L

VEHICLE NO

I SMAR389S

MODEL CODE

: FRLARDWJ11USA--A--

MODEL/YEAR

# NISSAN QASHQAI 1.2 MY2017

ENGINE NO CHASSIS NO

: HRA2640551A

MILEAGE

: SJNFEAJ11U2313563

1 806

DATE IN

: 21/09/2018

LIABILITY

0.00

EXCESS CLAUSE :

0.00

ESTIMATE BY

I HURAMMAD ZUHRI

ACCIDENT DATE : 07/09/2018

LKK Auto Consultants hence notify the Repairer of the following:

- \* To resurvey beforefafter spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Willhout Prejudice" basis
- No illegal modification(s) is allowed.
- · Supplementary (terms) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# TAN CHONG MOTOR SALES PTE. LTD. BUKIT TIMAH W/SHOP SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMAR389S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUET PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	^
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	55 V
3	SEALI	APPLY SEALANT TO ALL AFFECTED FAMEL JOINTS & HESEAL NECESSARY AREA	100.00	×
4	22/001	REFAIR REAR END PANEL , REAR TAILGATE , RENEW REAR BUMPER (2TONE)	560.00	280.
5	22/002	S/PAINT REAR BUMPER COVER(2 TONE), REAR TAILGATE REAR END PANEL	850.00	250
		TOTAL LABOUR CHARGES	1740.50	

#### TAN CHONG MOTOR SALES PTE. LTD. BURIT TIMAH W/SHOP SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMA83895

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST		REMARKS
1	SUNDRIES	HPN				/nn
2	ENBLEM-REAR	90890-4EA0A	59.70 K	nn		
3	ORNAMENT-BACK D	90892-4ER0A	87.00 ¥	nn		
:4	CLIP(10X1.2)	01553-05933	12.00 🗚	- V		
5	CLIF(7-2X3)	85284-JD00A	22.20 1	u- V		
6	CANGE RIVET(2X6.5)	76882-0M900	13.00 /4	ev		
7	FASCIA-RR SUMP	85022-HV00H	717.00 d	erv		
			**********			
	SUB TOTAL		910.90	0.00	50.00	
	LESS DISCOUNT (METT-20.00%, LIST-30.00%, S/NETT-	00%)	192.18	0.00	0.00	
	GRAND TOTAL		728.72	0.00	50.00	
			**********			
	OVERALL TOTAL		778.72			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

#### TAN CHONG MOTOR SALES PTE. LTD. BUKIT TIMAH W/SHOP SERVICE DEPARTMENT

#### SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMA83895

TOTAL LABOUR CHARGES

1740.00

TOTAL SPARE PARTS CHARGES 778.72

GRAND TOTAL

2518.72 +

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----

NAME

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

0.00

0.00

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further Imbour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD. 911, BUEIT TINAH BOAD SINGAPORE 589623

FINALIZED

ACCIDENT/BODY REPAIRS

MORKSHOP

. BUKIT TIMAN

CONTACT NO REFERENCE

1 4694091 : INS/IC/IMR/0407/2018

DATE

1 21-5EP-2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-80 SPRINGLEAF TOWER

S[079909]

TEL : 63896111

TAX : 62247175

DS => LKK Auto

OWNER'S MAME | MDM NOORSHIRIN BINTE HUSA

ADDRESS

# BLK 818 WOOGLAND STREET 82

108-405

S(730918)

TELEPHONE NO # 81023106

1 => DT (

TYPE OF CLAIM | DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO

i TP-SDK5445L

VEHICLE NO

1 SMAR3895

MODEL CODE

: FRLANDWJ11USA--A--

MODEL/YEAR

: NISSAN QASHQAI 1.2 HY2017

ENGINE NO

# HRA2640551A

CHASSIS NO

: SJNFEAJ11U2313563

HILEAGE

1 1 XM

DATE IN

1 21/09/2018

LIABILITY

0.00

EXCESS CLAUSE (

0.00

ESTIMATE BY

1 MUHAMMAD ZURRI

ACCIDENT DATE : 07/09/2018

#### TAN CHONG MOTOR SALES PTE. LTD. BURIT TIMAN W/SHOP SERVICE DEPARTMENT

### LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SHA83895

-----

3/110	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM BUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	-00
2	RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	55.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	-00
4	22/001	REPAIR REAR END PANEL , REAR TAILGATE , RENEW REAR BUMPER (2TONE)	560.00	280.00
5	ZZ/002	S/PAINT REAR BUMPER COVER(2 TONE), REAR TAILGATE REAR END PANEL	850.00	250.00
		TOTAL LABOUR CHARGES	1740.00	585.00

#### TAN CHONG HOTOR SALES PTE. LTD. BURIT TIMAH W/SHOP SERVICE DEPARTMENT

# MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SHARDSPS

DAMAGED PARTS & PRICES

s/NO	PARTS DESCRIPTION	FARTS NUMBER	NETT	LIST		REMARKS
1	SUNDRIES	NPN			50.00	x
2	EMBLEM-REAR	90890-4EA0A	59.70			х.
э	GRNAMENT-BACE D	90892-4EA0A	87.00			х
4	CLIP(10X1.2)	01553-05933	12.00			OK
5	CLIP(7.2X3)	85284-JD00A	22.20			OK.
6	CANGE RIVET(2X6.5)	76882-0M000	13.00			OK
7	FASCIA-RR BUMP	85022-HV00H	717.00			OK
			764.20	0.00	0.00	
	SUB TOTAL LESS DISCOUNT (METT-20.00%, LIST-30.00	0%, S/HETT00%)	152.84	0.00	0.00	
	GRAND TOTAL		631.36	0.00	0.00	
	OVERALL TOTAL		611.36			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

#### TAN CHONG MOTOR SALES FIE. LTD. 911, BUKIT TIHAH ROAD SINGAPORE 589623

# SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SHAB3898

NETT ITEM	764.20	
LESS 20.00%)	-152.84	
NETT AMOUNT	611.36	
LIST ITEM	0.06	
LESS 30.00%)	0.00	
LIST AMOUNT	0.00	
SPECIAL NETT ITEM	0.00	
LESS .00%)	0.00	
SPECIAL NETT AHOUNT	0.00	
TOTAL LABOUR CHARGES	585.00	
TOTAL SPARE PARTS CHARGES	611.36	
TOTAL CHARGES	1196.36	
ADD 7 % GST	83.75	
GRAND TOTAL	1280.11	

# Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 3 December 2018 10:12 AM

To:

'Muhammad Zuhri'; SUR

Cc:

Norsipah

Subject:

RE: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018

INS/IC/ZHR/0407/2018 DIRECT SETTLEMENT - (CTI REF: SNM18D04565C02)

Dear Zuhri,

# WITHOUT PREJUDICE

Confirmed amount \$1196.36 before GST @ 3 working days.

# Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Zuhri <zuhri@tanchong.com>

Sent: Saturday, 1 December 2018 11:32 AM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>; SUR < sur@lkkauto.com>

Cc: Norsipah <norsipah@tanchong.com>

Subject: RE: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT

SETTLEMENT - (CTI REF: SNM18D04565C02)

Dear Veron Chen,

Finalize attached .

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622 Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Veron Chen (LKKAuto) < veronchen@lkkauto.com >

Sent: 27 November 2018 16:49

To: Muhammad Zuhri < <a href="mailto:zuhri@tanchong.com">zuhri@tanchong.com</a>; SUR < <a href="mailto:sur@lkkauto.com">sur@lkkauto.com</a>>

Subject: RE: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT

SETTLEMENT - (CTI REF: SNM18D04565C02)

Dear Zuhri,

Kindly advise vehicle status.

# If vehicle has been repaired, please forward us finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 26 September 2018 8:03 AM

To: assignments <assignments@lkkauto.com> Subject: FW: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT

SETTLEMENT - (CTI REF: SNM18D04565C02)

Dear Assignment Team,

**FYNA** 

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Zuhri <zuhri@tanchong.com> Sent: Tuesday, 25 September 2018 4:16 PM

Subject: RE: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT

SETTLEMENT - (CTI REF: SNM18D04565C02)

Hi,

Kindly assist to arrange survey as follows:

Date: 27/09/2018 Day: Thursday

Time: 10:00AM (WAITING)

Best Regards, M.ZUHRI Tan Chong Motor Sales Pte Ltd 913 Bukit Timah Road Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Lucas Lee < lucas.lee@sg.cntaiping.com>

Sent: 21 September 2018 14:11

To: Muhammad Zuhri <zuhri@tanchong.com>

Subject: RE: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT

SETTLEMENT - (CTI REF: SNM18D04565C02)

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478 Email: <u>lucas lee@sq.cntaiping.com</u> Website: www.sg.cntaiping.com



This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately,

From: Muhammad Zuhri [mailto:zuhri@tanchong.com]

Sent: Friday, 21 September, 2018 12:41 PM

Subject: ACCIDENT INVOLVING SMA8389S & SDK5445L ON 07.09.2018 INS/IC/ZHR/0407/2018 DIRECT SETTLEMENT - ANR

Dear Office In Charge,

Our customer, Mdm NOORSHIRIN BINTE MUSA the owner of SMA8389S is insured with AXA Insurance at the material time of the accident. The 3rd party ,SDK5445L is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental \$150.00 / Use \$90.00. GIA Report / Estimate attached for your action.

Best Regards, ZUHRI Tan Chong Motor Sales Pte Ltd 913 Bukit Timah Road Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Merimen e-Claims

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	21 Sep 2018		21 Sep 2018 14:17 Edit Adj Rpt	S\$1,196.36 Edit Estimates	4 030	1,196.36 lew Rpt		Pendin Report Cance	
	Main	R	eference	Claim	etails		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created I	by insurer]		
Insured:	-, Co. Re	g. No.: -							
Main Claimant:	NOORSHI	RIN BINTE MUS	A						
Vehicle Reg No.:	SMA838	195		Date	of Loss:		8 00:00 - :59 and <b>17</b> Days From	LTA Reg Di	ate (Man Yr)]
Claim Type	TP / SNI	418D04565C02		Palic Note	/Cover	DMPC5N30	20231801		
Vehicle Reg No. (Insured):	SDK5445	L		Polic (Clair	No. nant):				
				Exce	5	5\$0.00			
Repairer:	Tan Chon	g Motor Sales (F	(Q) 913 Bukit Tima	h Road, 589622 B	ukit Tim	ah - Tel: 646	01694		
Handling Insurer:	Description of the second		(Singapore) Pte. I		(discount of	Callel Market Line	All of Productions in the State of	OTAN	
Adjuster:	02/10/2		Ltd (HQ) - Tel: 62	256-3561 [Han	fled by I	MOHD TAUF	(KH BIN HAMID)	[Final	Rpt due
Adj Asg. Remarks:	EST \$2518	1.72, CASE WITH	SJE						
ASSOCIAT	TED MAIL RE	CEIVED					View	v All Co	mpose Case Mai
There are n	o mail for this	case.							
ALL ASSO	CIATED TAS	iks⊟				View All S	Search Tasks C	reate New To	ask Complete
Due Dat	e Priority	Type Task	Group Subje	ct Handler	Assig	ned By	Completed On	Create	ed On Done

Merimen e-Claims Page 1 of 1

# Claim Documents

\*SMA8389S (SNM18D04565C02)

[SDK5445L]

TP

NOORSHIRIN BINTE MUSA

Sep 7 2018 12:00AM

[-]

Tan Chong Motor Sales

U	ioad Documents U	pload Photos   Compose New Letter	View	View in Brown	ser 🗸
Pho	tos/Images		3 per i	page v	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/12/18 10:02	General View	0	Load PDF	
2	03/12/18 10:02	Reinspection Photo	0	Load PDF	
Doc	umentation		1 per	page 🔽	2
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/09/18 14:16	EMAIL FM TANCHONG	0	Load PDF	
2	21/09/18 14:17	REPAIR EST	0	Load PDF	
3	21/09/18 14:17	TP GIA	0	Load PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			4
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18017229/T1VD3E2

Date:

04/12/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN3020231801

Claimant Vehicle

SMA8389S No:

Insured Vehicle No:

SDK5445L

Date of Loss:

07/09/2018

Nature of Claim: TP

Claim No:

SNM18D04565C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour

**SMA8389S** 

Make & Model:

NISSAN QASHQAI, 1.2 DIG-T (A)

Engine No:

HRA2640551A

5375 km

Reg. Date:

21/06/2018 (Man. Year: 2018) Silver

Chassis No: Odometer:

SJNFEAJ11U2313563

Engine Capacity:

1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	778.72	611.36	167.36	21.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	585.00	1,155.00	66.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,518.72	1,196.36	1,322.36	52.50
+ GST 7.00/7.00% (S\$)	176.31	83.75	92.56	52.50
Nett Amount (S\$)	2,695.03	1,280.11	1,414.92	52.50

INSPECTION

Date of Assignment:

21/09/2018

Date Inspected:

03/10/2018

Inspected At:

Tan Chong Motor Sales (HQ)

913 Bukit Timah Road Singapore 589622

Estimated Period of Repair:

3.0 days

MOHD TAUFIKH BIN HAMID Adjuster:

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)	
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMA8389S)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running panumbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.	

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	50.00FS	*-FS
2	1		*EMBLEM-REAR	Not Necessary	59.70 FN	*-FN
3	1		*ORNAMENT-BACK D	Not Necessary	87.00 FN	*- FN
4	1		*CLIP (10X1.2)	Necessary	12.00 FN	*12.00 FN
5	1		*CLIPS (7.2X3)	Necessary	22.20 FN	*22.20 FN
6	1		*CANOE RIVET (2X6.5)	Necessary	13.00 FN	*13.00 FN
7	1		*FASCIA-RR BUMP	Deformed	717.00 FN	*717.00 FN
F=Fn	anchise	part S=SpcNe	tt. N=NettItemDisc.		A12-100-1000	HACKEY SHOPPIN
				Sub Total (S\$)	960.90	764.20
		- Nett Item Discount on N Items 20.00/20.00% (S\$)			182.18	152.84
				Total Parts (S\$)	778.72	611.36

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	0.00
2	PANEL REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA		110.00	55,00
3		New	100.00	0.00
4	REPAIR REAR END PANEL, REAR TAILGATE, RENEW REAR BUMPER (2TONE)	New	560.00	280.00
5	S/PAINT REAR BUMPER COVER (2 TONE), REAR TAILGATE REAR END PANEL	New	850.00	250.00
	Gross Labou	r Cost (S\$)	1,740.00	585.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >