

22/03/2002

ASS. REC. BY:

REF:

CS3/SMD18017234/Gcd302

Special Instruction:

Surveyor
menimen

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Thelma Choo

of

SMD

Date/Time:

21/9/18 2:22pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 6579Y

Insured:

SLD 8438 E

at Workshop m/s

Bluwel Automotive

Tel:

6745 2088

of

1 Tekki Bkt Ave 6 # 01-28

Policy No:

D18MTPV01011716

Claim No:

CM7D1804095

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/09/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

2-29pm @ 21/9/18

Person Contacted:

Sally

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJH 6579Y - CS3/1PC18017159/d3

DOA: 19/9/18

SLD 8438 E - X.

Surveyor

Kne

REF: Sampo

05/26 /

(-2023)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TR / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Blumel
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$23k
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIH6579Y Yr Regn: 18 Aug 2008

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 C.C. 1498

Colour: Blue Grey A/C: Insured / Std / NI / NA

Sp.Reading: 81370 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IMODE10Y190122579

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ R/im or

Tyre Size: F: 205/50R16
 R: 11

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at w/s

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$6000 - \$7000

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation _____

Photos _____

Others _____

TOTAL

100

10

110

Report Format: PRG

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18017234/Gcd3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 21-09-2018		
		Code : SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLD 8438E	Veh. Inspected	SJH 6579Y	
Policy No.	D18MTPV01011716	Coverage (\$)	0.00	
Claim No.	CMTD1804095	Excess (\$)	0.00	
Assign From	MERIMEN (THELMA CHOO)	Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/09/2018	Inspection Date	21/09/2018	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		21 Sep 2018 14:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POON YOKE PUI, ID: S8508845I, Tel: +6590073430, Email: NOEMAIL		
Main Claimant:	THAM PEK HWA SHERINA @ SHAYLA THAM, ID: S8120372E		
Vehicle Reg. No.:	SJH6579Y	Date of Loss:	19/09/2018 19:00 - :59
Claim Type:	TP / CMTD1804095	Policy/Cover Note No.:	D18MTPV01011716 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD8438E	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Driver/Custodian (Insured):	POON YOKE PUI (33 / Female), NRIC: S8508845I, Tel: +6590073430		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 21 September 2018 2:21 PM
To: Sim Teo Koon; assignments@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1804095/THE- SUV(LKK)/ SLD8438E & SJH6579Y/ SLD5138R on 19-9-2018

Our Reference : CMTD1804095/THE
Your Reference: JEQ/180747/0918/BLU(zl)

Date: 21st September 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S JUSEQUITY LAW COPORATION

Dear Sir/ Madam,

ACCIDENT INVOLVING SLD8438E & SJH6579Y/ON 19.09.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Friday, September 21, 2018 12:39 PM

To: Teo, Grace

Cc: Choo, Thelma; Ye, Yong Kang Melvin

Subject: RE: CMTD1804095/THE- PRI/ SLD8438E & SJH6579Y/ SLD5138R on 19-9-2018

Dear Sir,

We refer to your email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) AEON Auto Consultants LLP,
- 3) Absolute Appraisal Services,
- 4) LCW APPRAISER PTE LTD
- 5) Treasure Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,
- 8) Prominent Appraiser Services,
- 9) Carlink Consultancy;
- 10) United Appraisal & Management Pte Ltd

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Bluwel Automotive Service Pte Ltd,

Autobay @ Kaki Bukit.

1, Kaki Bukit Ave 6, Blk C, #01-55, Singapore 417883

Person In-Charge: Ms. Sally. Tel: 6745 2088

*** Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.**

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.
E-mail: tk_sim@juseq.com.sg

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: 21 September 2018 12:28
To: Sim Teo Koon <tk_sim@juseq.com.sg>
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1804095/THE- PRI/ SLD8438E & SJH6579Y/ SLD5138R on 19-9-2018

Our Reference : CMTD1803712/AGC
Your Reference: JEQ/180747/0918/BLU(zl)

Date: 21st September 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S JUSEQUITY LAW COPORATION

Dear Sir/ Madam,

ACCIDENT INVOLVING SLD8438E & SJH6579Y/ON 19.09.2018

We refer to your Notice of Accident dated 20/09/2018.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Friday, September 21, 2018 11:31 AM

To: Claims - Motor Survey

Subject: Accident involving SJH6579Y / SLD8438E & SLD5138R on 19-9-2018

Dear Sir,

Please refer to our notice of accident.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6488 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0372E

Vehicle Details

Vehicle No.:	SJH6579Y
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 AT R
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	ZY494669
Chassis No.:	JMODE10Y190122579
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$13,433.00
Original Registration Date:	18 Aug 2008
First Registration Date:	18 Aug 2008
Transfer Count:	1
Actual ARF Paid:	\$13,433.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$16,749.00
Total Rebate Amount:	\$16,749.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/09/2018 15:03
Date Of Accident 19/09/2018 19:30
Exact Location Of Accident MCE TWDS ECP
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJH6579Y
Insured/Policyholder
Name Of Registered Owner THAM PEK HWA SHERINA @ SHAYLA THAM
NRIC No S8120372E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96398389
Alternative Phone No OFFICE-96398389

Vehicle Particulars

Manufacturer MAZDA
Model 2

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number Z18VP05019750
Cover Note Number

Driver

Name of Driver THAM PEK HWA SHERINA @ SHAYLA THAM
NRIC No S8120372E
Date Of Birth 17/07/1981
Occupation INDOOR
Date Of Driving Pass 19/08/2003
Driving Experience 15 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-96398389
Fax Number
Contact Number OFFICE-96398389
Email Address NOEMAIL

Address	BLK 106 BEDOK NORTH AVE 4 #13-1976
Postcode	460106
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 19/09/2018 AT ABOUT 7.30PM, I WAS DRIVING ALONG MCE ON THE MOST OUTER RIGHT LANE. SUDDENLY, I FELT A BANG AT THE BACK OF MY CAR AND THE GREAT IMPACT CAUSED MY CAR TO MOVE FORWARD AND HIT CAR C. I ALIGHTED FROM MY CAR AND FOUND OUT THAT CAR B HAS HIT THE REAR OF MY CAR AND THE GREAT IMPACT CAUSED MY CAR TO MOVE FORWARD AND HIT CAR C. I WAS INVOLVED IN A 3 CARS CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT136D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	THAM PEK HWA SHERINA @ SHAYLA THAM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJH6579Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 20/9/18, 1230p


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 20/9/18, 1234p


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19/11/18 at about 730pm, I was driving along MCE on the most outer right lane. Suddenly I felt a bang at the back of my car and the great impact caused my car to move forward and hit car 'C'. I alighted from my car and found out that Car 'B' has hit the rear of my car and the great impact caused my car to move forward and hit car 'C'. I was involved in a 3 cars chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 20/9/18, 123pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/9/18, 123pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		21 Sep 2018 14:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS						[Created by insurer]									
Insured:	POON YOKE PUI, ID: S85088451, Tel: +6590073430, Email: NOEMAIL														
Main Claimant:	THAM PEK HWA SHERINA @ SHAYLA THAM, ID: S8120372E														
Vehicle Reg. No.:	SJH6579Y			Date of Loss:	19/09/2018 19:00 - :59 [121 Months and 1 Days From LTA Reg Date (Man Yr)]										
Claim Type:	TP / CMTD1804095			Policy/Cover Note No.:	D18MTPV01011716 (Comprehensive)										
Vehicle Reg. No. (Insured):	SLD8438E			Policy No. (Claimant):											
				Excess:											
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088														
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]														
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/10/2018]														
Driver/Custodian (Insured):	POON YOKE PUI (33 / Female), NRIC: S85088451, Tel: +6590073430														

ASSOCIATED MAIL RECEIVED						View All	Compose Case Mail
There are no mail for this case.							

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH6579Y (CMTD1804095)

[SLD8438E]



































TP


























THAM PEK HWA SHERINA @ SHAYLA THAM

Sep 19 2018 7:00PM

[POON YOKE PUI]

Bluwel Automotive Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 14:23	Accident Statement From:SC - Reg. No: SLD8438E, Claimant: POON YOKE PUI	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 15:28	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 12:29	PRI	 Load PDF	
2	21/09/18 12:29	Third Party E-filed GIA report	 Load PDF	
3	21/09/18 14:21	Pre-Repair Survey - LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18017234/GCD3E2

Date: 25/09/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01011716

Claimant Vehicle No : SJH6579Y

Insured Vehicle No : SLD8438E

Date of Loss: 19/09/2018

Nature of Claim: TP

Claim No: CMTD1804095

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJH6579Y

Make & Model: MAZDA 2, 1.5 (A)

Reg. Date: 18/08/2008 (Man. Year: 2008)

Colour: Grey

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: ZY494669

Chassis No: JM0DE10Y190122579

Odometer: 81370 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Tyre Size: 205/50 R16

Rear Left Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/09/2018

Date Inspected: 21/09/2018 Inspected At:

Bluwei Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 Sep 2018)

Parts: 143 MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJH6579Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >