

ASS. REC. BY:

REF: CS31/CTI18017235/Gcd3br

Special Instruction:

Surveyor:
Menmen

Guo Chang

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time: 21/9/18 @ 1:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8KZ 2300D

Insured: XD 7251R

at Workshop m/s: 3 Jewel Automotive

Tel: 6745 2088

of: 1 Kaki Bkt Ave 6 # 01-28

Policy No: DMCVSN1655621802

Claim No: SNM18D04554C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 2:08pm @ 21/9/18

Person Contacted:

Sally

Vehicle IN / (OUT)

Date/Time	Action/Instruction (x) Estimate
	8KZ 2300D - x
	XD 7251R - x



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18017235/Gcd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 21-09-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 7251R	Veh. Inspected	SKZ 2300D
Policy No.	DMCVSN1655621802	Coverage (\$)	0.00
Claim No.	SNM18D04554C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	21/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/09/2018	Inspection Date	21/09/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		21 Sep 2018 13:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LIM THEAN HOCK STEPHEN		
Vehicle Reg. No.:	SKZ2300D	Date of Loss:	20/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04554C02	Policy/Cover Note No.:	DMCVSN1655621802
Vehicle Reg. No. (Insured):	XD7251R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1905Z
Vehicle Details	
Vehicle No.:	SKZ2300D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	SAAB
Vehicle Model:	9-3 CONV AERO 2.0TS AT ABS D/AB 2WD 2DR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	B207RCA39B782974
Chassis No.:	YS3FC7CY4B1303736
Maximum Power Output:	154.0 kW (206 bhp)
Open Market Value:	\$54,927.00
Original Registration Date:	17 Jan 2011
First Registration Date:	17 Jan 2011
Transfer Count:	1
Actual ARF Paid:	\$54,927.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2021
PARF Rebate Amount:	\$32,956.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,900.00
COE Rebate Amount:	\$10,310.00
Total Rebate Amount:	\$43,266.00

The information contained herein is correct as at 24 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2018 16:07
Date Of Accident	20/09/2018 13:15
Exact Location Of Accident	ALONG WOODLANDS ROAD TOWARDS JOHOR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ2300D
Insured/Policyholder	
Name Of Registered Owner	LIM THEAN HOCK STEPHEN
NRIC No	S1521905Z
Email Address	SLIM@NCS.COM.SG
Mobile Phone No	(LOCAL) +65-96860023
Alternative Phone No	OFFICE-96860023

Vehicle Particulars

Manufacturer	SAAB
Model	9-3 CONV AERO 2.0TS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28870279QMY
Cover Note Number	17/01/2018 - 16/01/2019

Driver

Name of Driver	LIM THEAN HOCK STEPHEN
NRIC No	S1521905Z
Date Of Birth	07/03/1962
Occupation	INDOOR
Date Of Driving Pass	08/01/1980
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96860023
Fax Number	
Contact Number	OFFICE-96860023
Email Address	SLIM@NCS.COM.SG

Address	15 VERDE AVENUE
Postcode	S688283
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7251R
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM GUAN BENG
NRIC/Passport Number	F1500741U
Contact Number	NA
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available from application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover or envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may and permit to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 20/9/18, 3:35 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/9/18, 3:35 pm


Reporting Centre Personnel's Signature

Name

NRIC: 980118-0

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/09/18 at about 1:15pm, I was driving along Woodlands Road towards Johor. Suddenly vehicle B came into my lane and hit the rear L/H side of my vehicle (A)

MS 116
 SKZ 23000
 Reporting Party
 Damaged Vehicle
 Not Damaged

Reporting Blurred Intentional Damage //

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
 Date & Time: 20/9/18, 3:35 PM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 20/9/18, 3:35 PM

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		21 Sep 2018 13:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LIM THEAN HOCK STEPHEN								
Vehicle Reg. No.:	SKZ2300D	Date of Loss:	20/09/2018 00:00 - :59 [92 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04554C02	Policy/Cover Note No.:	DMCVSN1655621802						
Vehicle Reg. No. (Insured):	XD7251R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKZ2300D (SNM18D04554C02)**
[XD7251R]
TP
LIM THEAN HOCK STEPHEN
Sep 20 2018 12:00AM
[-]
Bluwel Automotive Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser <input type="checkbox"/>		
Photos/Images							3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	25/09/18 12:47	General View				Load PDF		
2	25/09/18 12:49	Photographs of Damaged Parts				Load PDF		
Documentation							1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	21/09/18 13:25	PRS				Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017235/GCD3E2

Date: 27/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN1655621802	
Claimant Vehicle No : SKZ2300D	Insured Vehicle No : XD7251R	
Date of Loss: 20/09/2018	Nature of Claim: TP	Claim No: SNM18D04554C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ2300D	Engine No: B207RCA39B782974
Make & Model: SAAB 9-3, SPORTCOMBI 1.8T (A)	Chassis No: YS3FC7CY4B1303736
Reg. Date: 17/01/2011 (Man. Year: 2010)	Odometer: 108610 km
Colour: White	
Engine Capacity: 1998 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 235/40Z R18	Rear Tyre Size: 235/40Z R18
Front Left Side: Michelin 6 mm	Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm	Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/09/2018	
Date Inspected:	21/09/2018 Inspected At:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Sep 2018)

Parts: N/A SAAB 9-3 SPORTCOMBI 1.8T (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ2300D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >