

11/03/2011

ASS. REC. BY:

REF:

CS3/MSA18017302/Gcd3

Special Instruction:

Surveyor
Merimen

Guo Cheng

ASSIGNMENT (Office)

From (Person):

Chia Nyuk Pui

of

MSG

Date/Time: 21/9/18 @ 4:12pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 7081 T

Insured:

SJF 2515 T

at Workshop m/s

Prestige Auto

Tel: 9021 0057 / 6257 4781

of

191 Tanjong Katong Rd

Policy No:

A28958730 TMC

Claim No:

570710

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 14/09/2018

Insp: 3023A ubi Rd 1 # 01-64

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:36am @ 24/9/18

Person Contacted:

Mr. Chong

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (x) Estimate
	SJK 7081 T - X
	SJF 2515 T - CS / MSG 18012338 / rd3

DOA: 10/6/18

Signature

PRS
XKL

REF: MSG

ASSIGNMENT

From: _____ Date: 24/9/18
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJK 7081T
 at Workshop n/s: Prestige Auto
 of BK 3023A # 01-64 ubi Rd 1
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Mr-Chong-90210057

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^(up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJK 7081T Yr Regn: Oct 08
 Type: ☒ M/Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Ahtis c.c. 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 193621 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MA053 BEE 106121557
 Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.		D.O.I.	<u>24-09-18</u>

Survey held at w/s 1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Int
 The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18017302/Gcd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-09-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJF 2515T	Veh. Inspected	SJK 7081T
Policy No.	A28958730TMC	Coverage (\$)	0.00
Claim No.	570710	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	24/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/09/2018	Inspection Date	24/09/2018
Survey held at	BLK 3023A UBI RD1 # 01-64		
Repairer	PRESTIGE AUTO		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		21 Sep 2018 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	JCM RENTAL PTE LTD, Co. Reg. No.: 201711659M		
Main Claimant:	PLANNING FACTS, Co. Reg. No.: 53369734D		
Vehicle Reg. No.:	SJK7081T	Date of Loss:	14/09/2018 21:00 - :59 [118 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570710	Policy/Cover Note No.:	A28958730TMC (Third Party Only) Coverage: 17/05/2018 - 16/05/2019
Vehicle Reg. No. (Insured):	SJF2515T	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	Prestige Auto () 191 Tanjong Katong Road, 436993 Katong - Tel: 90210057/62574781		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/09/2018]		
Driver/Custodian (Insured):	ANG YUAN BIN (), NRIC: S9407011B, Tel: +6588223800		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT: MR CHONG 9021 0057/ 6257 4781		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/09/2018 15:04
Date Of Accident	14/09/2018 21:00
Exact Location Of Accident	SOUTH BRIDGE RD TWDS NEIL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK7081T
Insured/Policyholder	
Name Of Registered Owner	PLANNING FACTS
Co Reg No	53369734D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92288478
Alternative Phone No	OFFICE-92288478

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5094819552 (TP)
Cover Note Number	

Driver

Name of Driver	HOO TECK YONG
NRIC No	S7110210F
Date Of Birth	30/03/1971
Occupation	OUTDOOR
Date Of Driving Pass	02/05/1997
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83582424
Fax Number	
Contact Number	OTHERS-83582424
Email Address	NOEMAIL

Address	BLK 176 BISHAN STREET 13 #03-125
Postcode	570176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL VEHICLE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20180916/2057 ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF2515T
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	HOO TECK YONG
Approximate Age	47
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SJK7081T
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 176 BISHAN STREET 13 #31-25
Postcode	570176

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

17 SEP 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

17 SEP 2018



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A - SJK 7081
B - SJF 2515T
DOA - 14/9

Temple St
one way

South Bridge Rd

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.

~~Signature~~

17 SEP 2018



T/20180916/2057

1 of 3

Report No. T/20180916/2057

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No 1

Report Number T/20180916/2057

Vide Report Number T/20180916/2045

Date/Time of Report Made 16/09/2018 14:52

Place Report Lodged Traffic Police Division HQ

Type of Informant Driver

Name of Informant HOO TECK YONG

ID Type / ID No. NRIC NO / S7110210F

Home/Office 83582424

Mobile 83582424

Email

Type of Accident Injury / Conveyed By Ambulance

Drink Drive No

Anyone conveyed by ambulance Yes

Date/Time of Accident 14/09/2018 21:00

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJF2515T	Car					0
SJK7081T	Car				Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20180916/2057

2 of 3

Report No. T/20180916/2057

Continuation of CSF For NP168

Driver			
Name	HOO TECK YONG	ID No.	S7110210F
Related Vehicle	SJK7081T (Car)	Contact No.	83582424
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	14/09/2018	Date Discharge	15/09/2018
No. of Days granted Medical Leave	08	Degree of Injury	NIL

Brief Facts.

On 14/9/2018 at about 9pm, I was driving my vehicle (SJK7081T) along South bridge Road towards Neil Rd. It was a 4 lane road and I was driving on lane 3. Suddenly, one vehicle (SJF2515T) exited from Temple Street which was on my right. The vehicle (SJF2515T) drove to lane 3 and collided head-to side into my vehicle front right side. Subsequently, the vehicle (SJF2515T) clashes into the shop houses. Due to the accident, I was conveyed to Singapore General Hospital and was granted with 8 days of medical leave. I suffered from back pain and injuries on my left leg. The accident caused damages to my right bumper area and the driver's door. I have an in car CCTV which recorded the accident. I did not manage to exchange particulars as I was conveyed to the hospital. The traffic police were also at scene. I am lodging report for insurance claims and record purpose.



T/20180916/2057

3 of 3

Report No: T/20180916/2057

Continuation of CSF For NP168

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity	No
Officer-In-Charge of Case	TP / GIT / SUFIYAN BIN KHAIRI
Classification of Case	1) INJURY / CONVEYED BY AMBULANCE

Hoo Teck yong
871102107
[Signature]

[Signature]
BISHAN NPC
20 BISHAN STREET 2:
SINGAPORE 579737
TEL: 1800-5529999

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9734D
Vehicle Details	
Vehicle No.:	SJK7081T
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4804343
Chassis No.:	MR053ZEE106121557
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	30 Oct 2008
First Registration Date:	30 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2018
PARF Rebate Amount:	\$8,042.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$100.00
Total Rebate Amount:	\$8,142.00

The information contained herein is correct as at 26 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		21 Sep 2018 16:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JCM RENTAL PTE LTD , Co. Reg. No.: 201711659M		
Main Claimant:	PLANNING FACTS , Co. Reg. No.: 53369734D		
Vehicle Reg. No.:	SJK7081T	Date of Loss:	14/09/2018 21:00 - :59 [118 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570710	Policy/Cover Note No.:	A28958730TMC (Third Party Only) Coverage: 17/05/2018 - 16/05/2019
Vehicle Reg. No. (Insured):	SJF2515T	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	Prestige Auto () 191 Tanjong Katong Road, 436993 Katong - Tel: 90210057/62574781		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 22/09/2018]		
Driver/Custodian (Insured):	ANG YUAN BIN (), NRIC: S9407011B, Tel: +6588223800		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:100% CONTACT: MR CHONG 9021 0057/ 6257 4781		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



Claim Documents

***SJK7081T (570710)**
[SJF2515T]
TP
PLANNING FACTS
Sep 14 2018 9:00PM
[JCM RENTAL PTE LTD]
Prestige Auto

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)











[View](#)
[View in Browser](#)

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 14:49	Accident Statement From: SC - Reg. No: SJF2515T, Claimant: JCM RENTAL PTE LTD	 Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 12:31	General View	 Load JPG	
2	26/09/18 12:31	General View	 Load JPG	
3	26/09/18 12:31	General View	 Load JPG	
4	26/09/18 12:31	General View	 Load JPG	
5	26/09/18 12:31	General View	 Load JPG	
6	26/09/18 12:31	General View	 Load JPG	
7	26/09/18 12:31	General View	 Load JPG	
8	26/09/18 12:31	General View	 Load JPG	
9	26/09/18 12:31	General View	 Load JPG	
10	26/09/18 12:31	General View	 Load JPG	
11	26/09/18 12:31	General View	 Load JPG	
12	26/09/18 12:31	General View	 Load JPG	
13	26/09/18 12:31	General View	 Load JPG	
14	26/09/18 12:31	General View	 Load JPG	
15	26/09/18 12:31	General View	 Load JPG	
16	26/09/18 12:31	General View	 Load JPG	
17	26/09/18 12:31	General View	 Load JPG	
18	26/09/18 12:31	General View	 Load JPG	
19	26/09/18 12:31	General View	 Load JPG	
20	26/09/18 12:31	General View	 Load JPG	
21	26/09/18 12:31	General View	 Load JPG	
22	26/09/18 12:31	General View	 Load JPG	
23	26/09/18 12:31	General View	 Load JPG	
24	26/09/18 12:31	General View	 Load JPG	
25	26/09/18 12:31	General View	 Load JPG	
26	26/09/18 12:31	General View	 Load JPG	
27	26/09/18 12:31	General View	 Load JPG	
28	26/09/18 12:31	General View	 Load JPG	
29	26/09/18 12:31	General View	 Load JPG	
30	26/09/18 12:31	General View	 Load JPG	
31	26/09/18 12:31	General View	 Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	26/09/18 12:31	General View	 Load JPG	✓
33	26/09/18 12:31	General View	 Load JPG	✓
34	26/09/18 12:31	General View	 Load JPG	✓
35	26/09/18 12:31	General View	 Load JPG	✓
36	26/09/18 12:31	General View	 Load JPG	✓
37	26/09/18 12:31	General View	 Load JPG	✓
38	26/09/18 12:31	General View	 Load JPG	✓
39	26/09/18 12:31	General View	 Load JPG	✓
40	26/09/18 12:31	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 14:49	SJK7081T TP E-FILE REPORT From: SC - Reg. No: SJKF2515T, Claimant: JCM RENTAL PTE LTD	 Load PDF	
2	21/09/18 14:59	PRI - CATHERINE LIM LLC	 Load PDF	
3	21/09/18 14:59	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017302/GCD3S2
 Date: 27/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28958730TMC
 Claimant Vehicle No: SJK7081T Insured Vehicle No: SJF2515T
 Date of Loss: 14/09/2018 Nature of Claim: TP Claim No: 570710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK7081T
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4804343
 Reg. Date: 30/10/2008 (Man. Year: 2008) Chassis No: MR053ZEE106121557
 Colour: Silver Odometer: 193621 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/09/2018
 Date Inspected: 24/09/2018 Inspected At: Prestige Auto
 191 Tanjong Katong Road
 Singapore 436993
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK7081T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >