

20/03/2018

ASS. REC. BY

REP:

CS3/A1A18017 307/ Gcd3^{SV}

Special Instruction:

Surveyor

Guo Diang

ASSIGNMENT (Office)

From (Person):

ehin lee ying

of ALG

Date/Time

24/9/18 @ 12:56pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YL9340A

Insured:

SJ2 3345E

at Workshop in/:

QAS Auto

Tel:

8533 2822

of

Blk 3018A Ubi Rd 1 #01-23

Policy No:

Claim No:

1199019187SG

Sum Insured:

2100237127

Excess:

Make of Veh:
(Client's Record)

D.O.A

04/06/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:58pm @ 24/9/18

Person Contacted:

Doris

Vehicle IN OUT

Date/Time

Action/Instruction (x) Estimate

YL9340A - NJA/A1C09016876 /cl

DOA: 28/7/2009

SJ23345E - NBA/1NC13022573/y/s4

DOA: 28/11/13

INSURANCE

PAS Seal

REF:

CO145N

ASSIGNMENT

(-2020)

From: _____ Date: _____
 Estimated Cost: _____
 OD WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s **QAS Auto**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **YL934A** Yr Regn: **15 Feb 2005**
 Type: M.Car / M.Cycle / Bus / Van / Taxi / Prime Mover /
 Truck / Trailer or **Tanker**
 Make: **Mit FK617MSJR DEC**
 Colour: **Blue** A/C: Insured / Std / NI / NA
 Sp.Reading: **564158** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **FK 617M B 007 15**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Tyre Size: F: **8.25-16**
 R: **4 (D)**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. **5** mm R/Bal. **5/5** mm
 L/Bal. **5** mm L/Bal. **5/5** mm
 D.O.A. _____ D.O.I. **24-09-18**
 Survey held at **W/S** **1:20pm**
 Des. of Damages: Frt / Rear **LO/S** / N/S / UIC / Rooftop or
ht o/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	\$1500 \$1000
0/10	Submit DAR report.

RECEIVED 02 OCT 2018

T Grim Win
1/10/18

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: **3**
 Resurvey No. of Trip: **-** Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$) : S+RS \$
 : Interview (\$) : Photos
 : Tech. Invs (\$) : Other
 : Weekend (\$)
 Report Format: **DAR.**
 Lump Sum / I.B.I: (\$)
 TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18017307/Gcd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 24-09-2018	
		Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJZ 3345E	Veh. Inspected	YL 9340A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	24/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/06/2018	Inspection Date	24/09/2018
Survey held at	QAS AUTO PTE LTD 3018A UBI ROAD 1 #01-23 SINGAPORE 408711		
5a. Remarks			
<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>			

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 24/9/2018 12:56:44 PM
Attachments:  4088.pdf

Hi Nivitha,

As spoken, please contact Doris, 85332822, to arrange survey, owner waiting there.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼

UEN: 53159236K

133 New Bridge Road #13-05
Chinatown Point Singapore 059413
tel: 6533 3680 fax: 6533 3689
email: info@lawrencelee.com.sg

Your ref: please advise
Our ref: LWP/QAS/4088/18/wt

17 September 2018

AIG Asia Pacific Insurance Pte Ltd

EMAIL

Dear Sirs

**NOTICE OF ACCIDENT PURSUANT TO THE NIMA PROTOCOL
ACCIDENT AT T-JUNC OF PIONEER RD NORTH & JURONG WEST AVE 4
ON 04.06.18 INVOLVING YL9340A & SJZ3345E**

We are instructed by Rentokil Initial Singapore Pte Ltd to notify you of the abovementioned road traffic accident involving our client's vehicle registration number YL9340A and vehicle registration number SJZ3345E owned and driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

We do hereby notify you that our client's damaged vehicle may be inspected at the workshop at QAS Auto Pte Ltd at Blk 3018A Ubi Road 1 #01-23 Singapore 408711 (contact person: Mr Goh, mobile phone: 9857 9525).

Kindly revert within two (2) working days by fax only. Please do not email.

Yours faithfully



LEE WEE PENG LAWRENCE

Cc client

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 15:25
Date Of Accident	04/06/2018 12:35
Exact Location Of Accident	T-JUNCTION OF PIONEER RD NORTH & JURONG WEST AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YL9340A
Insured/Policyholder	
Name Of Registered Owner	RENTOKIL INITIAL SINGAPORE PTE LTD
Co Reg No	195900145N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96111003
Alternative Phone No	OFFICE-63478138

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FK617MSJRDEC
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	RAHMAN BIN JELAN
NRIC No	S0071837H
Date Of Birth	18/10/1952
Occupation	OUTDOOR
Date Of Driving Pass	21/02/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96111003
Fax Number	
Contact Number	
Email Address	NOEMAIL


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



Vehicle No
 A - YL93K0A
 B - 3JZ 3345E

Legend

 Vehicle Bike

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I come from Pioneer North Rd. toward to Pioneer Rd. Before toward Pioneer Rd. got traffic light function. My way that time is a green light. Then suddenly the car from the other side to turn right by the time green light for me I head then break I bang in front of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

16 & 18 Jalan Mesin
 Singapore 368815
 Policyholder's Signature
 Date & Time: 6347 8138 Fax: 6347 8105

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0145N
Vehicle Details	
Vehicle No.:	YL9340A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	MINISUBISHI
Vehicle Model:	FK617MSJRDEC
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	6D16972443
Chassis No.:	FK617MB00715
Maximum Power Output:	-
Open Market Value:	\$46,253.00
Original Registration Date:	15 Feb 2005
First Registration Date:	15 Feb 2005
Transfer Count:	0
Actual ARF Paid:	\$2,313.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$29,933.00
COE Rebate Amount:	\$8,078.00
Total Rebate Amount:	\$8,078.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 25 Sep 2018

OK

WY / MERRY (Frt)
TANKER

Vehicle No: **YL 9340A**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1004	991300	Frnt Bumper	BT	✓	
2001	991477	Frnt Bumper Upper			
2002	991387	Frnt Bumper Lower			
2003	991449	Frnt Bumper Side Cover			
2094	991443	Frnt Bumper Side Clip	NEC	✓	
1006	991325	Frnt Bumper Bracket	BT	✓	
1008	991433	Frnt Bumper Reinforcement	BT	✓	2
2005	991466	Frnt Bumper Signal Lamp			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
2006	990247	Frnt Grille Sticker			
1023	991799	Frnt Grille Chrome Moulding			
2007	991891	Frnt Panel			
2008	991874	Frnt Lower Panel			
2009	991328	Frnt Panel Emblem			
2010	990247	Frnt Panel Sticker			
2011	991893	Frnt Panel Garnish			
1024	991222	Frnt Apron Panel			
2012	991527	Frnt Corner Panel RH	CRA	✓	
2013	991532	Frnt Corner Panel Signal Lamp			
2014	995245	Frnt Signal Lamp LH			
2015	995246	Frnt Signal Lamp RH		?	
1029	995153	Frnt LH Headlamp Assy		?	
1030	991821	Frnt RH Headlamp Assy		?	
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
2016	992149	Frnt Wiper Panel			
2017	995043	Frnt Wiper Nozzle			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
2018	992145	Frnt Wiper Link			
2019	992148	Frnt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frnt Windscreen			
1115	992097	Frnt Windscreen Rubber			
1117	992098	Frnt Windscreen Sealant			
2020	992114	Frnt Windscreen Outer Pillar			
2021	992113	Frnt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frnt Side Mirror (Big)			
2023	991959	Frnt Side Mirror (Small)			
2024	991962	Frnt Side Mirror (Round)			
2025	995015	Frnt Wing Mirror Stay			
1025	992013	Frnt Support Panel			
1033	990248	Bonnet	SCR	R X	
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994331	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frnt Cabin Assy			
2028	991501	Frnt Cabin Mounting			
2029	991502	Frnt Cabin Rear Panel			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frnt RH Seat Belt Assy			
1135	995182	Frnt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
2035	994966	Frnt LH Wheel Guard			
1102	995170	Frnt LH Wheel Rim			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
2036	994966	Frnt RH Wheel Guard			
1111	992087	Frnt RH Wheel Rim			
1113	995065	Frnt RH Tyre			
1255	995326	Frnt LH Door			
1256	995140	Frnt LH Door Protector			
1257	995104	Frnt LH Door Hinge			
1258	995142	Frnt LH Door Wing Mirror			
1262	995103	Frnt LH Door Glass			
1263	991595	Frnt LH Door Glass Regulator			
1264	991596	Frnt LH Door Glass Regulator Motor			
1265	991662	Frnt LH Door Rubber			
1266	991636	Frnt LH Door Outer Handle			
1272	991617	Frnt LH Door Inner Trim Board			
1316	995327	Frnt RH Door	DD	R X	
1317	991654	Frnt RH Door Protector			
1318	991601	Frnt RH Door Hinge			
1319	991685	Frnt RH Door Wing Mirror			
1323	991584	Frnt RH Door Glass			
1324	991595	Frnt RH Door Glass Regulator			
1325	991596	Frnt RH Door Glass Regulator Motor			
1326	991662	Frnt RH Door Rubber			
1327	991636	Frnt RH Door Outer Handle			
1333	991617	Frnt RH Door Inner Trim Board			
2037	991644	Frnt Door Frnt Pillar			
2038	991657	Frnt Door Rear Pillar			
2039	992072	Frnt Wheel Arch Panel			
2040	992069	Frnt Wheel Arch Panel Garnish			
2041	991996	Frnt Step Panel			
2042	994498	Frnt Step Panel Top Garnish			
2043	994495	Frnt Step Panel Inner Garnish	RH	CRA	✓
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		Frnt Corner Panel moulding RH	SCR	R X	

Amn H
11/10/2018

No of Items: 6 Assessor: _____

TGim
11/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018 Edit Reg		24 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SOH ENG ANN , ID: S0236780G		
Main Claimant:	RENTOKIL INTIAL SINGAPORE PTE LTD		
Vehicle Reg. No.:	YL9340A	Date of Loss:	04/06/2018 00:00 - :59 [159 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1199019187SG	Policy/Cover Note No.:	2100237127 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ3345E	Policy No. (Claimant):	
		Excess:	
Repairer:	QAS AUTO PTE LTD (HQ) 3018A Ubi Road 1, #01-23, 408711 Ubi - Tel: 98579525		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/10/2018]		
Claimant's Solicitor:	LAWRENCE LEE & CO - Tel: 65333680		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (25/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YL9340A (1199019187SG)
 [SJZ3345E]
 TP
 RENTOKIL INTIAL SINGAPORE PTE LTD
 Jun 4 2018 12:00AM
 [SOH ENG ANN]
 QAS AUTO PTE LTD

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser ▾	
Assessment Reports										1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)							Thumbnail	Print	
1	25/09/18 16:24	Accident Statement From:SC - Reg. No: SJZ3345E, Claimant: SOH ENG ANN							 Load HTM		
Photos/Images										3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
2	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
3	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	26/09/18 15:10	General View							 Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017307/GCD3S2
Date: 02/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100237127
Claimant Vehicle No : YL9340A **Insured Vehicle No :** SJZ3345E
Date of Loss: 04/06/2018 Nature of Claim: TP Claim No: 1199019187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YL9340A**
Make & Model: MITSUBISHI FK617MSJRDEC, 7.5 D (M) Engine No: 6D16972443
Reg. Date: 15/02/2005 (Man. Year: 2004) Chassis No: FK617MB00715
Colour: Blue Odometer: 564158 km
Engine Capacity: 7545 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 8.25-16 Rear Tyre Size: 8.25-16 (D)
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5/5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/09/2018
Date Inspected: 24/09/2018 Inspected At: QAS AUTO PTE LTD (HQ)
3018A Ubi Road 1, #01-23
Singapore 408711
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	0.00 F	*-F
2	1		*FRT BUMPER CLIP	Necessary	0.00 F	*-F
3	2		*FRT BUMPER BRACKET	Bent	0.00 F	*-F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
5	1		*FRT CORNER PANEL RH	Cracked	0.00 F	*-F
6	1		*FRT SIGNAL LAMP RH	*Check	0.00 F	*-F
7	1		*FRT RH HEADLAMP ASSY	*Check	0.00 F	*-F
8	1		*FRT RH SIDE LAMP	*Check	0.00 F	*-F
9	1		*BONNET	Repair	0.00 F	*-F
10	1		*FRT RH DOOR	Repair	0.00 F	*-F
11	1		*FRT STEP PANEL	*Check	0.00 F	*-F
12	1		*FRT STEP PANEL TOP GARNISH	*Check	0.00 F	*-F
13	1		*FRT STEP PANEL INNER GARNISH RH	Cracked	0.00 F	*-F
14	1		*FRT CORNER PANEL MOULDING RH	Repair	0.00 F	*-F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >