

(08/11/43) wef

ASS. REC. BY: Merimen

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 3479Xat Workshop m/s Lf.

of _____

Insured: SLR 3479XPolicy No. 71594687 QMYClaims No. 571436

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

G/A / PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 45258

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR 3479X Yr Regn: 8.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 1A1Make: Mazda 3 hatchback 1496Colour: 3rd A/C: Insured / Std / NI / NASp. Reading: 22035 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN2FA8J0176030Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/9/18

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 24/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

have G.A26/9/18 Email G/A to Eileen15/10/18 confirmed L/S \$2700 with Alun (Red 5864.50, 687)15/10/18 Send preli revised via merimen

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 15/10 - typstDays Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

10

160

Report Format: merimenLump Sum / I.B.I. (\$) 2700/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Fievel Foo Wen Yao	Date: 15 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLK3179Z	Accident Date	: 21/09/2018
TP Vehicle No	: SLR3479X	Assignment Date	: 27/09/2018
Make	: MAZDA 3	Est. Duration of Repair	: 3.00
Date of Inspection	: 24/09/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,564.50
Revised Amount	:S\$	2,700.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,700.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2018		27 Sep 2018 09:29 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEE YING CHIN, ID: S8019024G, Tel: +6596630607, Email: YING_CHIN@HOTMAIL.COM			
Main Claimant:	SHAZLEE BIN NORDIN, ID: S8414238G			
Vehicle Reg. No.:	SLR3479X	Date of Loss:	21/09/2018 08:00 - :59 [13 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 571436	Policy/Cover Note No.:	71594687QMY (Comprehensive) Coverage: 12/01/2018 - 11/01/2019	
Vehicle Reg. No. (Insured):	SLK3179Z	Policy No. (Claimant):		
		Excess:		
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 28/09/2018]			
Driver/Custodian (Insured):	LEE YING CHIN (38 / Female), NRIC: S8019024G, Tel: +6596630607			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All] [Search Tasks] [Create New Task] [Complete]

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Eileen Ang <eileen_ang@sg.msig-asia.com>
Sent: Thursday, 27 September 2018 9:32 AM
To: Veron Chen (LKKAUTO); Fievel Foo
Cc: SUR; Accounts (LKKAUTO); KKLau
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 21/9/2018, SLR 3479X (TP VEHICLE), SLK 3179Z (OI VEHICLE)

Dear Veron,

Third Party folder created in merimen, claim ref is 571436.

Eileen Ang

Senior Admin Officer, Claims Services (Motor)
D: +65 6594 2561 | F: +65 6225 7402 | eileen_ang@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 26 September, 2018 8:43 AM
To: Eileen Ang <eileen_ang@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Accounts (LKKAUTO) <account@lkkauto.com>; KKLau <kklau@lkkauto.com>
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 21/9/2018, SLR 3479X (TP VEHICLE), SLK 3179Z (OI VEHICLE)

Dear Eileen,

Please be informed that we had inspected the vehicle SLR 3479X at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 24/9/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 26 September 2018 8:43 AM
To: Eileen Ang
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 21/9/2018, SLR 3479X (TP VEHICLE), SLK 3179Z (OI VEHICLE)
Attachments: GIA.pdf

Dear Eileen,

Please be informed that we had inspected the vehicle SLR 3479X at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 24/9/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2000 Downpayment Monthly
From \$638 Onwards. Lowest
3.18% P.A. @ Gv Cars Financing
GV Credit Pte Ltd StarAd

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

mazda 3 hb

Advanced Search Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
mazda 3 hb		Any	Any	2017	Any	Any	Any	Available



Mazda 3 HB 1.5A Deluxe

\$84,000

\$8,450 /yr

27-Oct-2017

1,496 cc

16,342 km

Hatchback

Available

Unique Soul Red Colour, Stable And Smooth Driving, Fuel Efficient, Stylish Exterior, Good Budget And Value For Money, Peace Of Mind, Agent Maintain And Warranty, Price Negotiable, Trade In Welcome.

Posted: 17-Sep-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 HB 1.5A Deluxe

\$88,000

\$9,070 /yr

18-Aug-2017

1,496 cc

12,000 km

Hatchback

Available

Down Payment \$9K Only! From \$1,300 Monthly. Fully Serviced With Agent With Valid 3 Years Warranty From Day 1! Very Under Utilized Unit With Very Low Mileage, Meticulously Maintained By Fervent Owner W...

Audax Auto Pte Ltd

Posted: 10-Sep-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 HB 1.5A Deluxe

\$80,800

\$8,720 /yr

28-Feb-2017

1,496 cc

15,000 km

Hatchback

Available

Posted: 19-Jul-2018 Tags: 2017 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used mazda 3 hb, mazda 3 hb Singapore, used mazda 3 hb Singapore, used vehicles Singapore or even buy used mazda 3 hb Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 4238G

Vehicle Details

Vehicle No.: SLR3479X

Vehicle to be Exported: No

Intended Deregistration Date: 03 Nov 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 HATCHBACK 1.5 AT DELUXE EU6

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: P520465904

Chassis No.: JM6BN24A8J0176030

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$19,232.00

Original Registration Date: 11 Aug 2017

First Registration Date: 11 Aug 2017

Transfer Count: 0

Actual ARF Paid: \$14,232.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Aug 2027

PARF Rebate Amount: \$10,674.00

Intended COE Rebate Details

COE Expiry Date: 10 Aug 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$44,002.00

COE Rebate Amount: \$38,584.00

Total Rebate Amount: \$49,258.00

The information contained herein is correct as at 24 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/09/2018 17:29
Date Of Accident	21/09/2018 08:50
Exact Location Of Accident	ALONG TPE TWDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR3479X
Insured/Policyholder	
Name Of Registered Owner	SHAZLEE BIN NORDIN
NRIC No	S8414238G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92311145
Alternative Phone No	OFFICE-92311145

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700046574-01
Cover Note Number	-

Driver

Name of Driver	SHAZLEE BIN NORDIN
NRIC No	S8414238G
Date Of Birth	28/05/1984
Occupation	INDOOR
Date Of Driving Pass	14/10/2008
Driving Experience	9 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92311145
Fax Number	
Contact Number	OFFICE-92311145
Email Address	NOEMAIL

Address	BLK 612 YISHUN ST 61 #12-189
Postcode	760612
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MARIE STELLA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK3179Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 21/9/18 at 8.50am, I was driving my vehicle A
along TPE towards Changi. Suddenly vehicle B cut
into my lane and hit on my L H side portion.

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

not Approved
1/5 \$2700
3 day
24/9/18

VEHICLE NO:SLR 3479X

QTY	PARTICULAR			
1 PCS	FRONT BUMPER	1031.00	Deep cut	\$1,245.30 ✓
1 PCS	FRONT BUMPER SIDE HOLDER N/S	37.40	Ref	\$85.00 ✓
1 PCS	FRONT BUMPER LOWER LIP		glue	\$205.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT		11	\$409.30 X
1 SET	FRONT BUMPER CLIPS	50.00	11	\$892.20 ✓
1 PCS	HEADLAMP N/S		11	\$1,048.20 ✓
1 PCS	FRONT FENDER N/S		10/Ref	\$230.00 ✓
1 PCS	FRONT FENDER INNER SHIELD N/S		To 1	\$98.20 ✓
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S	38.00	11	\$299.30 ✓
1 PCS	FRONT SPORT RIM '17 INCH' N/S		cut	\$450.50 ✓
1 PCS	FRONT LOWER ARM N/S		11	\$205.00 X
1 PCS	FRONT KNUCKLE ARM N/S		11	\$766.20 X
1 PCS	FRONT KNUCKLE ARM BEARING N/S		11	\$405.30 X
1 PCS	FRONT SHOCK ABSORBER N/S		11	\$85.00 X
				\$6,424.50

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	\$150.00	X
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO REFILL AIR CON GAS	\$120.00	X
TO SPRAY RUSF PROOFING	\$80.00	30
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS	\$680.00	300
TO PUTTY & SPRAY PAINTING	\$880.00	400
TOTAL	\$8,564.50	

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Prices are subject to confirmation
- To let party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3188.30
2548.24

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18017308/UVD3N2

Date: 22/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	71594687QMY
Claimant Vehicle No :	SLR3479X	Insured Vehicle No :	SLK3179Z
Date of Loss:	21/09/2018	Nature of Claim:	TP
		Claim No:	571436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3479X	Engine No:	P520465904
Make & Model:	MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A)	Chassis No:	JM6BN24A8J0176030
Reg. Date:	11/08/2017 (Man. Year: 2017)	Odometer:	22035 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,424.50	2,548.24	3,876.26	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	830.00	1,310.00	61.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,564.50	3,378.24	5,186.26	60.56
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	8,564.50	2,700.00	5,864.50	68.47
+ GST 7.00/7.00% (S\$)	599.52	189.00	410.52	68.47
Nett Amount (S\$)	9,164.02	2,889.00	6,275.02	68.47

INSPECTION

Date of Assignment: 27/09/2018

Date Inspected: 24/09/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
Parts:	144	MAZDA 3 1.5 HATCHBACK DELUXE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3479X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,245.30 F	*1,031.00 FL
2	1		*FRONT BUMPER SIDE HOLDER N/S	Bent	85.00 F	*37.40 FL
3	1		*FRONT BUMPER LOWER LIP	Grazed	205.00 F	*205.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	409.30 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	892.20 F	*50.00 FL
6	1		*HEADLAMP N/S	Cracked	1,048.20 F	*1,048.20 FL
7	1		*FRONT FENDER N/S	Dented/Bent	230.00 F	*230.00 FL
8	1		*FRONT FENDER INNER SHIELD N/S	Torn	98.20 F	*98.20 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	299.30 F	*35.00 FL
10	1		*FRONT SPORT RIM 17 INCH N/S	Cut	450.50 F	*450.50 FL
11	1		*FRONT LOWER ARM N/S	Not Necessary	205.00 F	*- FL
12	1		*FRONT KNUCKLE ARM N/S	Not Necessary	766.20 F	*- FL
13	1		*FRONT KNUCKLE ARM BEARING N/S	Not Necessary	405.30 F	*- FL
14	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	85.00 F	*- FL
					Sub Total (S\$)	6,424.50 3,185.30
					- List Item Discount on L Items 0.00/20.00% (S\$)	0.00 637.06
					Total Parts (S\$)	6,424.50 2,548.24

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	New	150.00	-
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO REFILL AIR CON GAS	New	120.00	-
5	TO SPRAY RUSF PROOFING	New	80.00	30.00
6	LABOUR FOR PANEL BEATING,CUT & REPLACING PARTS	New	680.00	300.00
7	TO PUTTY & SPRAY PAINTING	New	880.00	400.00
Gross Labour Cost (S\$)			2,140.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >