

RESTRICTED

**HQ Transport**

Kranji Camp III  
151 Choa Chu Kang Way  
Block 822 #01-04  
Singapore 688248

Tel : 6307 4511

Fax : 6307 4520

Date: 18 / 10 / 18

To: LKK Auto Consultants Pte Ltd  
Attn: Ms Joy Irene/Ms Chew Hsiao Tong

Our Ref: FY 18 / 19 / 0025

**Forwarding of Outstanding Document(s)**

Accident involving MID 33993 & SG 54355 on 12 / 09 / 18

We are faxing over / dispatching document(s) with regards to the above matter.

Kindly acknowledge upon receiving the below mentioned document(s) and revert back to us.

Acknowledgement from LKK Auto			
S/N	Documents	Received On	Received By
1	SAF 1201 ✓	19/11/18	
2	SAF 1202		
3	Police Report ✓	19/11/18	
4	Original Photographs ✓	23/11/18 (Email)	
5	Final Bill		

Thank You

Le  
PTE Joe Cheng

RESTRICTED



RESTRICTED


ANNEX H

**STATEMENT OF DRIVER/WITNESS**

**FIGURE H-1 – STATEMENT OF TRANSPORT OPERATOR (MID 33993)**

**SINGAPORE ARMED FORCES**

**STATEMENT OF DRIVER/WITNESS**

STATEMENT OF	LCP IVAN TANG WOO MING			ALIASES	-
NRIC NO	S9840244F	AGE	19	MALE/FEMALE	MALE
EMPLOYMENT	NSF	DRIVING LICENCE NO	SAF/TPT/N/0 2022/17	NATIONALITY	SINGAPORE
DIALECT	CANTONESE	LANGUAGE SPOKEN	ENGLISH	TEL NO	93829621
ADDRESS	BLOCK 175 BISHAN STREET 13 #09-157 S570175				
INTERPRETED BY	RANK		TIME	DATE	SIGN
RECORDED BY	RANK		TIME	DATE	SIGN
<p>I, S9840244F, LCP IVAN TANG WOO MING, am writing this statement regarding the traffic accident that occurred on 120918, 0625, at the junction along Jalan Anak Bukit, turning right into PIE (Changi). I was supposed to drive an SOUV, MID33993, to Bedok Reservoir this morning. At around 0625, I had reached the junction at Jalan Anak Bukit where I needed to perform a right turn at the junction in order to get up the ramp towards PIE(Changi). I had stopped behind a car in the right-turn pocket. After seeing that the car in front of me had moved off, I saw that the traffic light in front of me was green and followed. I failed to check for oncoming traffic. The SMRT Bus, SG 5435J, collided onto the left of my Vehicle, on the left-most lane just past stop line. After impact, I stopped my vehicle roughly 5 metres from the point of collision as I was dazed from the impact. After ensuring that my vehicle commander and the bus driver were not injured, I called MT Line to report to the Duty Transport Leader on the accident. I was told to leave the vehicle where it was and to wait for a Transport Leader to arrive. After a while, ISG Ben Chong reached the scene of the accident and took photos of the damaged vehicle. I was then instructed to shift the vehicle forward as I was obstructing traffic. I then contacted VRS hotline after being told to do so by Sergeant Ben. I then waited for my NSM and NC to arrive at the scene. I left the scene after the tow truck had arrived inside my Node Commander's car. That is all I have to say.</p>					
DATE :	12/09/18		SIGNATURE OF DRIVER/WITNESS		

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording to further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.  
Statements of witness must be signed by the witness.



RESTRICTED

ANNEX I

POLICE REPORT
**SINGAPORE  
POLICE FORCE**


T/20180912/2196

1 of 4

Report No. T/20180912/2196

Police Station Of Origin:  
Clementi N P C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
12/09/2018 21:29

Vide Report No.:

Station Diary No.:  
141

**Informant's Particulars**

Name of Informant:  
IVAN TANG WOO MING

Address:  
APT BLK 175 BISHAN STREET 13 #09-157 SINGAPORE  
570175

ID Type / ID No.:  
NRIC NO / S9840244F

Contact No.:  
Home/Office: Mobile: 93829621

Nationality:  
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:  
Male 19 02/12/1998

Type of Informant:  
Driver

Race:  
Chinese

Language:

Institution / School Name:

Occupation:  
SAF NSF

Driving Licence Information:  
Class:

Date of Expiry:

**General Information of the Accident**

Type of Accident: Non-Injury Government Vehicle

Drink Drive:  
No

Date/Time of Accident:  
12/09/2018 06:25

Type of Location:  
X-Junction

Location:  
Junction of Road 1 and Road 2  
JALAN ANAK BUKIT  
PAN ISLAND EXPRESSWAY  
Junction of Jalan Anak Bukit, turning into PIE Changi

Weather:  
Clear

Road Surface:  
Dry

Road Speed Limit:

Traffic Flow:  
One Way

Traffic Control:  
Traffic Light - Working

Traffic Volume:  
Light

Type of Collision:  
Between Moving Vehicles - Head To Side

Anyone conveyed by ambulance:  
No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
MID33993	OUV				Slightly Damaged	1
SG5435J	Bus/Coach/Minibus				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No  
No. of Pedestrians Injured: NIL  
Use of Pedestrian Crossing: NA





