

ASS. REC. BY:

REF:

CS3/CTI18017348/Gcd301

Special Instruction:

Surveyor:
Menimen

Gno Diono

ASSIGNMENT (Office)

FROM (Person):

Jowyn Tay

of

CTI

Date/Time:

24/9/18 @ 3:19pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLD 5304C

Insured:

CB 6350D

at Workshop m/s

Sheng Li Jui

Tel:

9111 9222

of

No. 2 Kaler Bkt Ave 2 # 01-36

Policy No.:

DMB1SN1659431701

Claim No.:

3NM1800440202

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/09/18

CA / REV / REP. / REV 24 HRS ^{1up}

25/9/18

H.O.D. Endorsement:

Date/Time:

4:40pm @ 24/9/18

Person Contacted:

Mr. Low

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	
	SLD 5304C - NA / CTI 18016581 / h 4	DoA: 10/9/18
	CB 6350D - NA / CTI 18016581 / h 4	DoA: 10/9/18
	Dismantle: 26/9/2018.	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18017348/Gcd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 24-09-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	CB 6350D	Veh. Inspected	SLD 5304C
Policy No.	DMB1SN1659431701	Coverage (\$)	0.00
Claim No.	SNM18D04402C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	24/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/09/2018	Inspection Date	25/09/2018
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2018		24 Sep 2018 15:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MR NG CHOON HUAT, ID: S1761039B		
Main Claimant:	CHUA SYEN SYEN SHAWNNA, ID: S8034487B		
Vehicle Reg. No.:	SLD5304C	Date of Loss:	10/09/2018 08:00 - :59
Claim Type:	TP / SNM18D04402C02	Policy/Cover Note No.:	DMB1SN1659431701 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	CB6350D	Policy No. (Claimant):	SD18V05207/VPC2/R00
		Excess:	S\$0.00
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/10/2018]		
Driver/Custodian (Insured):	CHAI AH ALI (67 / Male), NRIC: S2079860B, Tel: +6594780394		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Yvonne <yvonne@ealc.com.sg>
Sent: Monday, 24 September, 2018 2:58 PM
To: Lucas Lee; Jowyn Tay
Subject: PRI: China Taiping Insured CB6350D [EAL.2018.5947.MK.ya - SLD5304C]

Our ref : 2018.5947.MK.ya - **SLD5304C**
Your ref : **CB6350D**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

China Taiping Insurance (Singapore) Pte. Ltd.
No. 3 Anson Road,
#16-00 Springleaf Tower,
Singapore 079909
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s China Taiping Insurance (Singapore) Pte. Ltd. Vehicle SLD5304C inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: CHUA SYEN SYEN SHAWNNA

ACCIDENT INVOLVING SLD5304C & CB6350D ON 10 SEPTEMBER 2018 ALONG NEW UPPER CHANGI ROAD TOWARDS CHAI CHEE AT ABOUT 0835 HOURS

We refer to the above matter wherein we are instructed to act for **CHUA SYEN SYEN SHAWNNA**, the owner of vehicle no. **SLD5304C**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLD5304C** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Sheng Li Lai
No. 2 Kaki Bukit Ave 2,
#01-36 Autohub Kaki Bukit,
Singapore 417921.
Tel: 91119222 (Mr Low)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4487B
Vehicle Details	
Vehicle No.:	SLD5304C
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15Z14102195
Chassis No.:	MRHGM6660HP000005
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,511.00
Original Registration Date:	21 Jun 2016
First Registration Date:	21 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$12,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2026
PARF Rebate Amount:	\$9,383.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$36,589.00
Total Rebate Amount:	\$45,972.00

The information contained herein is correct as at 26 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2018 17:37
Date Of Accident	10/09/2018 08:35
Exact Location Of Accident	NEW UPPER CHANGI RD -> CHAI CHEE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD5304C
Insured/Policyholder	
Name Of Registered Owner	CHUA SYEN SYEN, SHAWNNA
NRIC No	S8034487B
Email Address	SHAWNNA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97928478
Alternative Phone No	OFFICE-97928478

Vehicle Particulars

Manufacturer	HONDA
Model	CITY-1.5 SV CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V05207/VPC2/R00
Cover Note Number	

Driver

Name of Driver	VALERIE OOI BEE CHOO
NRIC No	S2536927J
Date Of Birth	21/04/1949
Occupation	INDOOR
Date Of Driving Pass	10/12/1974
Driving Experience	43 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97900248
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 15A LENGKONG DUA
 Postcode 417692
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PARENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number CB6350D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver CHAI AH ALI
 NRIC/Passport Number S2079860B
 Contact Number 94780394
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

Vehicle No SLD 5304 C

Annex 1

Describe Circumstances of the Accident

On Monday, 10 September 2018 At 7:31am, I was driving along New Upper Changi Road in the centre lane going towards Kembangan. Traffic was very light at that time. Weather was good, visibility was clear.

Suddenly, a mini bus (CB 6350D) came very fast from the right and cut into my lane. This bus hit the front right of my vehicle as he tried to overtake and cut into the lane I was in. Upon hitting my car, he did not stop. He drove on to the left-most bus lane and stopped there. I then proceeded to follow and stop behind him.

The driver of the mini bus CB6350D admitted that he was in a hurry, late for school. The owner of the mini bus also appeared later and claimed they were in a hurry.

Declaration

We declare the foregoing particulars are true in every respect

[Signature]

Policyholder's Signature / Date & Time
10 Sept 2018, 4:00

[Signature] 10 Sept 2018 4:00

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 10 Sept 2018, 4pm

Driver's Signature


(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan #3

SKETCH PLAN



A) SLD 5304C
B) CB 6350D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along New Upper Changi Rd in the center lane. Veh (B) suddenly overtook me & cut in front of me & hit the front right of my vehicle. Traffic was very light at that time. The driver of Veh (B) admitted that he was in a hurry. The owner of the Veh (B) also appeared later.

Refer to attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time 10 Sept 2019, 4pm


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/ID No.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2018		24 Sep 2018 15:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MR NG CHOON HUAT , ID: S1761039B								
Main Claimant:	CHUA SYEN SYEN SHAWNNA , ID: S8034487B								
Vehicle Reg. No.:	SLD5304C	Date of Loss:	10/09/2018 08:00 - :59 [26 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04402C02	Policy/Cover Note No.:	DMB1SN1659431701 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	CB6350D	Policy No. (Claimant):	SD18V05207/VPC2/R00						
		Excess:	S\$0.00						
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/10/2018]								
Driver/Custodian (Insured):	CHAI AH ALI (67 / Male), NRIC: S2079860B, Tel: +6594780394								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD5304C (SNM18D04402C02)
[CB6350D]
TP
CHUA SYEN SYEN SHAWNNA
Sep 10 2018 8:00AM
[MR NG CHOON HUAT]
Sheng Li Lai

Upload Documents			Upload Photos			Compose New Letter			View View in Browser
Assessment Reports									1 per page <input type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)			Thumbnail			Print	
1	10/09/18 18:07	Accident Statement				Load HTM		<input type="checkbox"/>	
Photos/Images									3 per page <input type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)			Thumbnail			Print	
1	10/09/18 17:49	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
2	10/09/18 17:49	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
3	10/09/18 17:49	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
4	10/09/18 17:49	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
5	10/09/18 17:49	CHASSIS NO. [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
6	10/09/18 17:49	Accident Photo [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail			Print	
1	01/10/18 14:07	General View				Load PDF		<input type="checkbox"/>	
2	01/10/18 14:08	Photographs of Damaged Parts				Load PDF		<input type="checkbox"/>	
Documentation									1 per page <input type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail			Print	
1	24/09/18 15:18	PRS				Load PDF		<input type="checkbox"/>	
2	24/09/18 15:18	OI GIA				Load PDF		<input type="checkbox"/>	
No	Finalized On	Success United Pte Ltd (HQ)			Thumbnail			Print	
1	10/09/18 18:03	Sketch Plan [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
2	10/09/18 18:03	Sketch Plan #2 [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	
3	10/09/18 18:03	Sketch Plan #3 [Linked Accident Report Documents]				Load JPG		<input checked="" type="checkbox"/>	

Linked Accident Report Documents

						View View in Browser			
Assessment Reports									1 per page <input type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)			Thumbnail			Print	
1	10/09/18 18:07	Accident Statement				Load HTM		<input type="checkbox"/>	
Photos/Images									3 per page <input type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)			Thumbnail			Print	
1	10/09/18 17:49	Accident Photo				Load JPG		<input checked="" type="checkbox"/>	
2	10/09/18 17:49	Accident Photo				Load JPG		<input checked="" type="checkbox"/>	
3	10/09/18 17:49	Accident Photo				Load JPG		<input checked="" type="checkbox"/>	
4	10/09/18 17:49	Accident Photo				Load JPG		<input checked="" type="checkbox"/>	
5	10/09/18 17:49	CHASSIS NO.				Load JPG		<input type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
6	10/09/18 17:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Success United Pte Ltd (HQ)	Thumbnail	Print
1	10/09/18 18:03	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	10/09/18 18:03	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	10/09/18 18:03	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017348/GCD3E2

Date: 04/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1659431701
Claimant Vehicle No :	SLD5304C	Insured Vehicle No :	CB6350D
Date of Loss:	10/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04402C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD5304C	Engine No:	L15Z14102195
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660HP000005
Reg. Date:	21/06/2016 (Man. Year: 2016)	Odometer:	41027 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	24/09/2018	
Date Inspected:	25/09/2018 Inspected At:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
Parts: 143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD5304C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >