

ASS. REC. BY

REF

CS/ALG18017352/Ktd3

Action/Instructions

Surveyor

Mennen

Kenneth

ASSIGNMENT (Office)

From (Person)

Azlan, Syuzairidina

AIG

Date/Time

24/11/18 @ 2:29pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLG 551 Y

Insured

SKC 92675

at Workshop n/s:

RC Auto

Tel.

9761 9383

of

160 Sin Ming Drive # 06-20

Policy No.

Claim No.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/18

CA / REV / REP. / REV 24 HRS

rup

26/9/18

H.O.D. Endorsement

Date/Time: 3:32pm @ 24/11/18

Person Contacted:

Mr. Tan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 551 Y - CC1/ASM 18011755/71p93

D.O.A.: 22/6/18

SKC 92675 - x

1/11/18

L1 By B550d Carbur (Red: 2037, 27%)

REF: 416

ASSIGNMENT

From Date: 26/9/18

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLG 551 Y

at Workshop m/s

RC Auto

of

160 Sin Ming Drive # 06-20

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

05

days

Res: Yes or No

Lum Sum:

144

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date

Person Contacted

Vehicle IN / OUT

Veh No: SLG 551 Y Yr Regn: 09 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mr S500

G.C.

2996

Colour

M.D. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

41872

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

W00 2221622A 277166

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

245/45R19

R:

275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear

R/Bal:

4

mm

R/Bal:

6

mm

L/Bal:

4

mm

L/Bal:

6

mm

D.O.A.

26/9/18

D.O.I.

26/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/9 At north Corridor

RECEIVED 15 OCT 2018

Date/Time: File Pass in?



Preli. Report



Final Report

1) 15/10 Typist

Date/Time: File Return in?

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

1. S + RS. \$

) Photos

) Other

Report Format:

TP

Lump Sum / I.B.I. (\$) 5500/-

TOTAL

- Pre repair inspection request - SLG551Y VS SKC9267S (OI) DOA: 20/09/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariessa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur
Sent: 24/9/2018 2:29:56 PM
Attachments:  200709111

Hi,

Please refer to the enclosed request from **Legal Options LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: pinky@legaloptions.biz [mailto:pinky@legaloptions.biz]
Sent: Monday, September 24, 2018 12:24 PM
To: Azlan, Syazairdina
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariessa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKC9267S AND SLG551Y ON 20/09/2018

Dear Sirs,

We confirm

From: Azlan, Syazairdina
Sent: Mon, 24 Sep 2018 04:11:15 +0000
To: pinky@legaloptions.biz
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariessa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKC9267S AND SLG551Y ON 20/09/2018

Hi Pinky,

Please confirm that you are nominating Mr Kenneth Kong from LKK named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: pinky@legaloptions.biz [mailto:pinky@legaloptions.biz]
Sent: Monday, September 24, 2018 12:00 PM
To: Azlan, Syazairdina
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariessa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; pinky@legaloptions.biz
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKC9267S AND SLG551Y ON 20/09/2018

Dear Syaza,

Our client suggest Mr Kenneth Kong from LKK.

The said surveyor may contact Mr Tan at 9761 9383; M/s RC Auto at 160 Sin Ming Drive #06-20, Sin Ming Autocity, Singapore 575722

*If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Regards,

Pinky
M/s Legal Options LLC

From: Azlan, Syazairdina
Sent: Mon, 24 Sep 2018 02:50:27 +0000
To: pinky@legaloptions.biz
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Chan, Yoke Shi, Mithoosingh, Aashweenjeetkaur
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKC9267S AND SLG551Y ON 20/09/2018

Without Prejudice

Your Reference : 18-A18-MISC213L-VL.jp.sb
Our Reference : SKC9267S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

| Name of Surveyor | Company Name |
|--------------------------|--|
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Fong Soon Yee | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Quang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II
SQ Claims Operations | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS
Mediators - Commissioners for Oaths - Notary Public
法商律師事務所

Motor Accident & Personal Injuries
Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estates, Family
Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SKC 92675

Our Ref : 18-A18-MISC213L-VL.jp.sb

24th September 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way #07-16

AIG Building
Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : RT GROUP PTE LTD
ACCIDENT INVOLVING VEHICLE SLG 551Y AND SKC 92675 ALONG THOMSON ROAD
TOWARDS ANG MO KIO ON 20/09/2018

We are instructed by M/S RT GROUP PTE LTD to notify you of a road traffic accident on 20th SEPTEMBER 2018 at about 19:15 HOURS ALONG THOMSON ROAD TOWARDS ANG MO KIO involving our client's vehicle registration number SLG 551Y and vehicle registration number SKC 92675 driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully


cc/ Clients (SLG 551Y)

Directors
Joan Lim Phock Hoon LL.B (Hons)
Victor Leong Wai Mong LL.B (Hons)
Teo Lip Hua Benedict LL.B (Hons) LL.M

Jurisdiction Secretary's DID: 6513 2803
Direct Fax: 6438 8275
(Email: legaloptions@legaloptions.biz)

Mailing Address for Accident Claims
Documents Support:
23 Kallit Road Avenue 4 #01-01 South Wing
Singapore 415933

RECOMMENDATION

BY FAX: 6835 7416/POST



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--------------------------|---------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CS/AIG18017352/Ktd3 | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 24-09-2018 |  |
| | | Code : AIG | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SKC 9267S | Veh. Inspected | SLG 551Y |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | AZLAN SYAZAIRDINA | Assign Date | 24/09/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 20/09/2018 | Inspection Date | 26/09/2018 |
| Survey held at | 160 SIN MING DRIVE#06-20 | | |
| Repairer | R C AUTO | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------------|
| Date Of Report | 21/09/2018 15:47 |
| Date Of Accident | 20/09/2018 19:15 |
| Exact Location Of Accident | THOMSON RD (NEAR GOODWOOD FLORIST) |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|--|-----------------------|
| Vehicle Registration Number | SLG551Y |
| Insured/Policyholder | |
| Name Of Registered Owner | RT GROUP PTE LTD |
| Co Reg No | - |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-91078017 |
| Alternative Phone No | OFFICE-91078017 |
| Vehicle Particulars | |
| Manufacturer | MERCEDES-BENZ |
| Model | - |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | GA125158/1 |
| Cover Note Number | |
| Driver | |
| Name of Driver | AW GIM SAN |
| NRIC No | S1185891J |
| Date Of Birth | 03/09/1956 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/01/2016 |
| Driving Experience | 2 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91078017 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Thomson Rd towards Ang Mo Kio when a car on my right suddenly cut into my lane and hit onto my car. No one was injured during this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

RT GROUP PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

RT GROUP PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

| | |
|---|-------|
| Address | - |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------|
| Type Of Accident | SIDE SWIPE |
| Weather Conditions | CLEAR |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident


refer attached report.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------------------|
| Vehicle Registration Number | SKC9267S |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | HAS GUNAWAN BIN HARJUNA |
| NRIC/Passport Number | S8016862D |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |



Not Attached
1 lb
Pineapples 66 pms
5 day
11 Lms @ 550cl

Reg. No. 53199168K

Date : 24/9/2018

500 ✓
160
750

RC AUTO

Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 24 Sep 2018 Edit Reg | | 24 Sep 2018 00:00 Edit Adj Rpt | S\$5,500.00 Edit Estimates | S\$5,500.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | ID: - | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SLG551Y | Date of Loss: | 20/09/2018 00:00 - :59 [24 Months From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 6824785336SG | Policy/Cover Note No.: | (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SKC92675 | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | RC AUTO (HQ) 18 Sin Ming Industrial Estate Sector A, #01-43, 575676 Sin Ming - Tel: | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/10/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

















Claim Documents

*SLG551Y (6824785336SG)
[SKC92675]

TP

-
Sep 20 2018 12:00AM

[-]
RC AUTO

| | | | | | | | | | | | | | | |
|------------------|-----------------|-----------------------------------|---------------|--|--------------------|--|--------------|--|--------------|--|---|-----------|-------------------------------------|-------------------------------------|
| Upload Documents | | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View | | View in Browser | |
| Photos/Images | | | | | | | | | | | 3 per page | | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | Thumbnail | Print | |
| 1 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 15/10/18 11:38 | General View | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 15/10/18 11:43 | Reinspection Photo | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 15/10/18 11:43 | Reinspection Photo | | | | | | | | |  | Load JPG | <input checked="" type="checkbox"/> | |

Documents Checklist

| | | | |
|---|-------|------|-------|
| DOCUMENTS CHECKLIST | Reset | Save | Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18017352/KTD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle
No : SLG551Y

Insured Vehicle No : SKC9267S

Date of Loss: 20/09/2018

Nature of Claim: TP

Claim No: 6824785336SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG551Y

Make & Model: HYUNDAI SONATA, 2.0 (A)

Reg. Date: 20/09/2016 (Man. Year: 2016)

Colour: Metallic Dark Brown

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 27682430417198

Chassis No: WDD2221622A277168

Odometer: 41872 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Front Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm

Rear Tyre Size: 275/40 R19

Rear Left Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 5,454.00 | 5,454.00 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,020.00 | 1,490.00 | 530.00 | 26.24 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,474.00 | 6,944.00 | 530.00 | 7.09 |
| Approved Total (Overridden) (S\$) | | 5,500.00 | | |
| Nett Amount (S\$) | 7,474.00 | 5,500.00 | 1,974.00 | 26.41 |

INSPECTION

Date of Assignment: 24/09/2018

Date Inspected: 26/09/2018

Inspected At:

160 SIN MING DRIVE #06-20
Repairer: RC AUTO (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------|-----------------|--|-----------------|
| 1 | 1 | | *FRONT DOOR (ALUMINIUM) | Dented / Warped | 2,890.00 FL | *2,890.00 FL |
| 2 | 1 | | *REAR DOOR | Dented / Warped | 3,100.00 FL | *3,100.00 FL |
| 3 | 20 | | *DOOR BOARD RIVETS | Necessary | 70.00 FL | *70.00 FL |
| | | | | | Sub Total (\$\$) | 6,060.00 |
| | | | | | - List Item Discount on L Items 10.00/10.00% (\$\$) | 606.00 |
| | | | | | Total Parts (\$\$) | 5,454.00 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--------------------------------------|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | LABOUR CHARGES TO RENEW ABOVE PARTS | New | 800.00 | 500.00 |
| 2 | TO SCAN AND RESET DOOR MECHANISM | New | 80.00 | 80.00 |
| 3 | TO TRANSFER BOTH DOOR ACCESSORIES | New | 240.00 | 160.00 |
| 4 | SPRAY PAINTING ON ALL AFFECTED PARTS | New | 900.00 | 750.00 |
| Gross Labour Cost (S\$) | | | 2,020.00 | 1,490.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >