

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

CE/70/18017376/Used3 n2ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMC1093Eat Workshop m/s 3M

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 47

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A 34836

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMC1093E Yr Regn: 10, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: BMW 325i coupe c.c. 2497Colour: white A/C: Insured / Std / NI / NASp. Reading: 111545 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAKE32000E447064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ContinentalFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 19/9/18D.O.I. 24/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

NTAC FTA 2yrs incl.Dep 13k nett 12464L/S 920003/10/18 Confirmed HS \$9,200/- @ 6days with Marcus.(\$6,802.45 Red - 43%)Submit independent report.

Date/Time, File Pass to?

03/10/181) Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

6x15 = 90170 + 90505012480564

Report Format: _____

Lump Sum / I.B.I. (\$ 9,200/- L/S)

Ref. No : <u>CS/TP 18017376/USD3m2</u>	Res. Date: <u>1/10/8</u>	Date Received:
Veh. No : <u>SMC 1093E</u>	SP:	WKSP: <u>[Signature]</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page? YES / NO		Message:
If No, due to a) No authorisation b) Days of repair		
others:		
Final Re-inspection or Progress Photos		Inspected By:

MBWH16122341 / Ajax Mars Pro Ltd - Bukit Merah
ENTRY DATE & TIME: 20/09/2018 20:26
SUBMITTED BY: Boey Loke

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afterwards.

ACCIDENT STATEMENT

Date Of Report 20/09/2018 20:26
Date Of Accident 19/09/2018 19:10
Exact Location Of Accident MCE TOWARDS CHANGI
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC1093E
Insured/Policyholder
Name Of Registered Owner HONG HSIEH SHUEN LOUIS
NRIC No S9042792Z
Email Address HXXLOUIS@GMAIL.COM
Mobile Phone No (LOCAL) +65-86282886
Alternative Phone No OTHERS-86282886
Vehicle Particulars
Manufacturer BMW
Model 325 COUPE 2.5
Exact Purpose for which vehicle was being used at time of accident PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AVIVA LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 10849489
Cover Note Number N.A.
Driver
Name of Driver HONG HSIEH SHUEN LOUIS
NRIC No S9042792Z
Date Of Birth 15/11/1990
Occupation OUTDOOR
Date Of Driving Pass 18/04/2009
Driving Experience 9 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-86282886
Fax Number
Contact Number OTHERS-86282886
Email Address HXXLOUIS@GMAIL.COM

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : ETHELYN TIONG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was driving along MCE towards Changi when vehicle B suddenly rear ended my vehicle. My rear was badly damaged and no injury involved.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC6437Z
 Vehicle Make/Model/Colour KIA OPTIMA 1.7(A) DIESEL
 Details Of Properties NIL
 Vehicle Category TAXI
 Name of Driver HUANG HENG JIE
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 3

Passenger 1

NAME: : PASSENGER 1

GENDER: :

Passenger 2

NAME: : PASSENGER 2

GENDER: :

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

 VERIFIED BY ALAN MARS
 REPORTING OFFICER

Mohamed Sharil

 Witnessed by Reporting Centre
 Personnel

Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I as driving along MCE towards Changi when veh b suddenly rear ended my vehicle.
My rear was badly damage and no injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

20 September 2018 at 10:32 AM

Date/Time:

20 September 2018 at 10:32 AM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2792Z
Vehicle Details	
Vehicle No.:	SMC1093E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	325I COUPE AT HID ABS D/AB 2WD 2DR SR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	11707444N52B25AF
Chassis No.:	WBAKE32000E447064
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$42,055.00
Original Registration Date:	27 Oct 2010
First Registration Date:	27 Oct 2010
Transfer Count:	2
Actual ARF Paid:	\$42,055.00 21027
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2020
PARF Rebate Amount:	\$25,233.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$44,600.00
COE Rebate Amount:	\$9,303.00
Total Rebate Amount:	\$34,536.00

The information contained herein is correct as at 25 Sep 2018

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just


\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

V6 Engine Selling Cheaper Than Renting A Car!



Nice Bidded Number! Selling Cheaper Than Normal Sedan! Warranty Be Given! Direct Owner [StarAd](#)


[Browse by Category](#)
[Sort by](#)

4 vehicles

[Advanced](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage

Search Selection

bmw 325

Any

Any

2010

Any



BMW 3 Series 325i Sunroof

\$39,888

\$10,390 /yr

30-Sep-2010

2,497 cc

11

Well Taken Care By Owner. Full Servicing Record With TTS Eurocars. Done Up Unit With Sunroof. Accessories. PML Unit Depreciation Among All. Immaculate Condition. Call Us N...

TTS Eurocars

Posted: 22-Sep-2018 Tags: 2010 BMW 325i, 2010 bmw 325i, BMW 325i, bmw 325i, BMW, 325i, Used BMW



BMW 3 Series 325i Coupe Sunroof

\$51,000

\$13,810 /yr

08-Dec-2010

2,497 cc

\$5k Drive Away! Interest Rate From 2.98%! This Is Your Chance To Own This BMW 325i Coupe! Tastefully Done Up Unit Come With Bodykit, BMW Performance Exhaust, Gruppe M Air Int...

Dynamic Motoring

Posted: 19-Sep-2018 Tags: 2010 BMW 325i, 2010 bmw 325i, BMW 325i, bmw 325i, BMW, 325i, Used BMW



BMW 3 Series 325i Convertible

\$50,888

\$15,980 /yr

08-Jun-2010

2,497 cc

74

New Paint In June. Problem Free Car, Wear And Tear All Fixed! Low Mileage Only 74K Km! Viewing By Appointment Only

Posted: 25-Aug-2018 Tags: 2010 BMW 325i, 2010 bmw 325i, BMW 325i, bmw 325i, BMW, 325i, Used BMW



BMW 3 Series 325i Coupe XL

\$50,000

\$16,950 /yr

26-Feb-2010

2,497 cc

49

Very Low Mileage And Good Condition! Only Driven On Weekends. Price Negotiable! Please Call For Appointment To View

Posted: 25-Jul-2018 Tags: 2010 BMW 325i, 2010 bmw 325i, BMW 325i, bmw 325i, BMW, 325i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

[Compare](#)

Model Price Depreciation Reg Date Eng Cap Mileage



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-28-53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

SMC 1093E

To check wiring	S\$0.00	30
To Dismantle & replacing PAC sensor	S\$0.00	50
To Dismantle & refix Bootlid components	150.00	80
To Dismantle & refix seat cushion upholstery	150.00	80
To Dismantle & refix rear exhaust	150.00	80
To spray rust proofing	100.00	60
labour for panel beating & replacing parts	1080.00	800
To putty & spray painting	1500.00	1000
TOTAL		\$16102.45
		2180
		11506.57
<div><p>LKK Auto Consultants hence notify the Repairer of the following:</p><ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company<p>Acknowledged by Repairer</p><p>Signature:</p><p>Date:</p></div>		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18017376/Usd3n2

BLK 1 KAKI BUKIT AVE 6

#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 05-10-2018



ON BEHALF OF HONG HSIEH SHUEN LOUIS

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SMC 1093E
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	24/09/2018

2. Vehicle Particulars & Condition

Make & Model	BMW 325I COUPE (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAKE32000E447064	Colour	WHITE
Odometer	111545	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/09/2018	Inspection Date	24/09/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1093E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	DENTED / BENT	1,885.12	1,885.12
1	BOOTLID REAR LOGO	NECESSARY	62.50	62.50
1	BOOTLID INNER LOCK	TWISTED	299.08	299.08
1	BOOTLID WEATHERSTRIP	TWISTED	268.40	268.40
1	BOOTLID INNER TRIM	DEFORMED / TORN	295.43	295.43
2	BOOTLID HINGES @\$295.00	SERVICEABLE	590.00	-
2	BOOTLID REFLECTORS @\$425.00	SERVICEABLE	850.00	-
1	REAR BUMPER	DISTORTED	1,418.32	1,418.32
1	REAR BUMPER REINFORCEMENT	BENT	695.00	695.00
1	REAR BUMPER TOP RETAINER	CRACKED	188.20	188.20
2	REAR BUMPER SIDE HOLDER @\$135.00	BENT / CRACKED	270.00	270.00
4	REAR BUMPER PDC SENSORS @\$225.00	SHORTED (3 PCS ONLY)	900.00	675.00
1	REAR BUMPER LOWER GARNISH O/S	DISTORTED	366.05	366.05
1	REAR BUMPER UNDER COVER	TWISTED	182.00	182.00
1	REAR BUMPER TOW COVER	TORN	30.00	30.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	1,012.00	1,012.00
1	REAR END PANEL TOP GARNISH	TWISTED	265.30	265.30
1	REAR FENDER INNER TRIM O/S	DEFORMED / TORN	322.00	322.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,210.00	-
2	REAR EXHAUST MOUNTINGS @\$60.00	NOT NECESSARY	120.00	-
2	TAILLAMPS @\$625.00	CRACKED	1,250.00	1,250.00
1	REAR EXHAUST HEAT SHIELD	BENT	188.05	188.05
1	REAR END PANEL SEALER	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE W/HOLDER	SCRATCHED	45.00	45.00
	LESS 5% DISCOUNT		-	-490.87
			12,812.45	9,326.58
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX BOOTLID COMPONENTS.		150.00	80.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		150.00	80.00

Report Ref No. CS/TP18017376/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX REAR EXHAUST.		150.00	80.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,290.00	2,180.00
	GRAND TOTAL		16,102.45	11,506.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,200.00

Report Ref No. CS/TP18017376/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.