

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD F			Ref : CS3/ASM18015163/Upa3s2-1		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE HO			Date: 19-11-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLZ 6350X	Veh. Inspected	SKD 3502Y	
	Policy No.	VPA/P2119251	Coverage (\$)	0.00	
	Claim No.	S8M00SFK	Excess (\$)	0.00	
	Assign From	WINNIE HO	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN SCIROCCO (A)	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	WVWZZZ13ZCV013548	Colour	WHITE	
	Odometer	86191	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/40R18	CONTINENTAL	6 mm	
	L/H Front Tyre	235/40R18	CONTINENTAL	6 mm	
	R/H Rear Tyre	235/40R18	CONTINENTAL	6 mm	
	L/H Rear Tyre	235/40R18	CONTINENTAL	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/08/2018	Inspection Date	20/08/2018	
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				