

2/03/2003

ASS. REC. BY:

REF:

CS3/MSA18017394/Gcd347

Special Instruction:

Surveyor:

CNO Diana

From (Person):

Chhia Nyuk Pui

ASSIGNMENT (Office)

of MSG

Date/Time: 25/9/18 @ 9:37am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBD 5960B

Insured:

GBB 5291J

at Workshop m/s

Heng chye Motor

Tel:

6747 6845 / 9368 8075

of

3023A ubi Rd / # 01-57

Policy No:

A287 4019IMKC

Claim No:

571063

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/09/2018

CA / REV / REP: / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

10:35am @ 25/9/18

Person Contacted:

Ah chye

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	GBD 5960B - NA/AG18017016/K4
	GBB 5291J - NA/AG18017016/K4
	Dismantle: 26/9/2018

DOA: 17/9/18

Don: 17/9/18

PRS
Xnd.

REF: MSIG

B7385D /

ASSIGNMENT

From: Date: 25/1/18
Estimated Cost:
OD / P / VS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: GBD 5960B
at Workshop m/s: Heng Chye Motor
of 3023A Ubi Rd 1 # 01-57
Insured:
Policy No:
Claims Net:
Sum Insured: Excess:
(Client's Record)
Make of Veh: Ah chye: 9368 8075



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'
Date: Person Contacted: Vehicle: IN / OUT

Veh No: GBD 5960B Yr Regn: 15 Jan 2015
Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Hiace C.C. 2982
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 46398 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: JTFHT 02P 000159130
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: N / S / Rim / STD A / Rim or
Tyre Size: F: 15 R 15
R: 11
BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 25-01-18
Survey held at w/s 11AM
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
\$ 4000 - \$ 5000

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 7
Resurvey No. of Trip: 1

Report Format: PRS
Lump Sum / I.B.I. (\$

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:
Transportation:
S + RS: \$
Photos
Others

120
10
130

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG18017394/Gcd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 25-09-2018		
		Code : MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBB 5291J	Veh. Inspected	GBD 5960B	
Policy No.	A28740191MKC	Coverage (\$)	0.00	
Claim No.	571063	Excess (\$)	0.00	
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/09/2018	Inspection Date	25/09/2018	
Survey held at	HENG CHYE MOTOR WORKS BLK 3023A UBI ROAD 1 #01-57 SINGAPORE 408717			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		25 Sep 2018 09:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HO CANVAS MERCHANT, Co. Reg. No.: 09657800M, Tel: +6596873259, Email: HOCANVAS@HOTMAIL.COM		
Main Claimant:	BINSMART, Co. Reg. No.: 53217355D		
Vehicle Reg. No.:	GBD5960B	Date of Loss:	17/09/2018 13:00 - :59 [44 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 571063	Policy/Cover Note No.:	A28740191MKC (Comprehensive) Coverage: 17/06/2018 - 16/06/2019
Vehicle Reg. No. (Insured):	GBB5291J	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Heng Chye Motor Works - Ubi (HQ) 3023A UBI ROAD 1, #01-57, 408717 Ubi - Tel: 93688075 / 67476845		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/09/2018]		
Driver/Custodian (Insured):	HO CHOON BENG (45 / Male), NRIC: S72433591, Tel: +6596873259		
Adj Asg. Remarks:	LIABILITY : 100% / SJE : DISAGREED Kindly survey by tomorrow (URGENT REQUEST) And Please appoint LKK AUTO to conduct the survey . Please contact MR AH CHYE @ 9368 8075 or 6747 6845 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7355D
Vehicle Details	
Vehicle No.:	GBD5960B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2483740
Chassis No.:	JTFHT02P000159130
Maximum Power Output:	-
Open Market Value:	\$27,502.00
Original Registration Date:	15 Jan 2015
First Registration Date:	15 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$1,376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$63,701.00
COE Rebate Amount:	\$40,138.00
Total Rebate Amount:	\$40,138.00

The information contained herein is correct as at 26 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2018 16:57
Date Of Accident	17/09/2018 13:25
Exact Location Of Accident	AIRPORT RD TWDS EUNOS LINK RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD5960B
Insured/Policyholder	
Name Of Registered Owner	BINSMART
Co Reg No	-
Email Address	BINSUVKM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97713856
Alternative Phone No	OFFICE-97713856
Vehicle Particulars	
Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100498297-01
Cover Note Number	
Driver	
Name of Driver	THOMAS BINSU
Passport No/FIN	G0973816P
Date Of Birth	28/02/1980
Occupation	INDOOR
Date Of Driving Pass	18/12/2014
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97713856
Fax Number	
Contact Number	OTHERS-97713856
EMail Address	BINSUVKM@GMAIL.COM

Address	BINSMART
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB5291J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HO CHOON BENG
NRIC/Passport Number	S7243359I
Contact Number	96873259
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

18/9/2018

SKETCH PLAN



A - GBD5960B
B - GBB5291J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was Driving 170091018 Airport Road to Eunos Link Road, I am waiting to Enter Eunos link Road, Because ~~the~~ Heavy Traffic flow. After 15 seconds (B) GBB5291J They hit Behind my van (A) and vehicle (A) Back Door fully Damaged, and Back wind Screen broke and Back Brake light spoil and Back Bumper and Reverse sensor's also Damaged already to vehicle (A)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

18/9/2018

Reported on 15/11/2018
@ 1640 HRS

ACCIDENT STATEMENT

ACCIDENT DATE: 17/9/2018 (DD/MM/YYYY), TIME: 13:25 (HH:MM)

LOCATION: Airport Rd towards Eunus link Rd

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: GBD 5960 B
b) INSURANCE COMPANY: _____
c) POLICY NUMBER: _____
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: _____
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: _____
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
c) ADDRESS: _____

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: 97713856
c) ADDRESS: _____

*d) DATE OF BIRTH: (____/____/____) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: _____

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: GBB5291J MODEL: _____
b) DRIVER'S NAME: HO CHOO N BENG
c) NRIC/FIN/PASSPORT: 57243359 CONTACT: 96873259

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
e) DRIVER'S NAME: _____
f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

email = binsurkm@gmail.com

fax = binsurkm@gmail.com

VIDE.O =

REPUBLIC OF SINGAPORE
FIN G0973816P



Name
THOMAS BINSU

Date of Birth: 26-02-1980
Sex: M
Nationality: INDIAN

273816

REPUBLIC OF SINGAPORE DRIVING LICENCE
G0973816P

THOMAS BINSU

Birth Date: 26 Feb 1980
Issue Date: 28 Jul 2016
Valid Till: 07/08/2021

002593061J

F42041913

VISIT PASS
Immigration Regulations



FIN G0973816P

MULTIPLE JOURNEY VISA ISSUED

Date of Issue: 20-12-2017
Date of Expiry: 20-12-2019



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class	Vehicle Class	Effective Date
Class 2B	Motorcycles <= 200 cc	08 Aug 2011
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	18 Dec 2014

NP 428A



COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Name of Policyholder : BINSMART
 Period of Insurance : 16 Jan 2018 To 15 Jan 2019
 Engine No. : 1KD2483740
 Chassis No. : JTFHT02P000159130

Vehicle No. : GBD5960B
 Policy No. : 2100498297-01
 Endorsement No. :
 Issued Date : 12 Jan 2018

ABOUT THE COVER

Make/Model : TOYOTA HIACE 1 ton [Van]

Engine Capacity/Tonnage : 1 Tonnage

Sum Insured : Market Value

First Year of Registration : 2015

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) Any person who is driving on the Policyholder's order or with their permission.
 b) This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

- 1) Use in connection with the Policyholder's business.
 2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business.
 3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, and b) use whilst driving a trailer except the towing of anyone disabled using a mechanically propelled vehicle; c) use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out, at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0030210000

AIG ASIA PACIFIC INSURANCE PL
 78 SHENTON WAY #07-16 AIG BUILDING
 SINGAPORE 079120

Mobile

AIG Asia Pacific Insurance Pte. Ltd.



Policy/Reference No. 2100498297-01

12 Jan 2018

BINSMART
66 Kallang Bahru
#01-509
SINGAPORE 330066

Dear BINSMART

Your Policy Has Been Renewed

We are pleased to inform you that your COMMERCIAL AUTOPLUS COMMERCIAL has been renewed and details of your policy are below:

Policy number : 2100498297-01
Effective date : 16 Jan 2018
Expiry date : 15 Jan 2019

It is important that you review the enclosed policy documents to verify that all the information in these documents is accurate. If you wish to update us on any changes, please contact us.

For More Information

If you require more information about your policy, please contact our customer service representatives Monday through Friday between 9am to 5pm at +65 6419 3000. Alternatively, you can send us an email at www.aig.com.sg or a fax at +65 6415 3723.

Thank you for your support. We look forward to serving you in all your general insurance needs.

Yours sincerely

Bucha Manik
Head of Auto

PS: You can now enjoy round-the-clock access to selected AIG products and services with our easy-to-use Apple or Android smartphone app. Purchase new policies, renew your policies, access claims support or receive emergency assistance for motor and travel, anytime, 24-hours a day. Your AIG Mobile App can be downloaded for free at iTunes or Google Play.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		25 Sep 2018 09:37 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HO CANVAS MERCHANT , Co. Reg. No.: 09657800M, Tel: +6596873259, Email: HOCANVAS@HOTMAIL.COM									
Main Claimant: BINSMART , Co. Reg. No.: 53217355D									
Vehicle Reg. No.: GBD5960B		Date of Loss: 17/09/2018 13:00 - :59 [44 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 571063		Policy/Cover Note No.: A28740191MKC (Comprehensive) Coverage: 17/06/2018 - 16/06/2019							
Vehicle Reg. No. (Insured): GBB5291J		Policy No. (Claimant): Excess: S\$700.00							
Repairer: Heng Chye Motor Works - Ubi (HQ) 3023A UBI ROAD 1, #01-57, 408717 Ubi - Tel: 93688075 / 67476845									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 26/09/2018]									
Driver/Custodian (Insured): HO CHOON BENG (45 / Male), NRIC: S72433591, Tel: +6596873259									
Adj Asg. Remarks: LIABILITY : 100% / SJE : DISAGREED Kindly survey by tomorrow (URGENT REQUEST) And Please appoint LKK AUTO to conduct the survey . Please contact MR AH CHYE @ 9368 8075 or 6747 6845 to arrange for survey .									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD5960B (571063)**

[GBB5291J]

TP

BINSMART



































Sep 17 2018 1:00PM




































[HO CANVAS MERCHANT]

Heng Chye Motor Works - Ubi

Claim Documents

*GBD5960B (571063)
[GBB5291J]
TP
BINSMART
Sep 17 2018 1:00PM
[HO CANVAS MERCHANT]
Heng Chye Motor Works - Ubi

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	24/09/18 15:03	Accident Statement From: SC - Reg. No: GBB5291J, Claimant: HO CANVAS MERCHANT					 Load HTM		<input checked="" type="checkbox"/>	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
2	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
3	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
4	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
5	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
6	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
7	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
8	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
9	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
10	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
11	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
12	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
13	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
14	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
15	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
16	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
17	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
18	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
19	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
20	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
21	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
22	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
23	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
24	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
25	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
26	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
27	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
28	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
29	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
30	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
31	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
32	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	
33	01/10/18 11:02	General View					 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	01/10/18 11:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	01/10/18 11:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/09/18 15:03	TPD GBD5960B GIA REPORT From: SC - Reg. No: G885291J, Claimant: HO CANVAS MERCHANT	 Load PDF	
2	24/09/18 15:06	TPD GBD5960B - PRI	 Load DOC	
3	24/09/18 16:59	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017394/GCD3E2

Date: 02/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28740191MKC

Claimant Vehicle No : GBD5960B

Insured Vehicle No : GBB5291J

Date of Loss: 17/09/2018

Nature of Claim: TP

Claim No: 571063

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD5960B

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: 1KD2483740

Reg. Date: 15/01/2015 (Man. Year: 2014)

Chassis No: JTFHT02P000159130

Colour: Silver

Odometer: 46398 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/09/2018

Date Inspected: 25/09/2018 Inspected At:

Heng Chye Motor Works - Ubi (HQ)

3023A UBI ROAD 1, #01-57

Singapore 408717

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2018)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5960B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >