

MSIA/ CC3/MSH18017395/Utlb n2  
**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5JQ8220Xat Workshop m/s At

of \_\_\_\_\_

Insured: SDN 16785

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time | Action / Instruction LT A 4630X26/9/18 - Report & GIA via email to Yi Quan & MonicaEst. loss 1831.10 Rep. loss 1778.2015/10/18 confirmed f.no. of 8219.76 with Rtn. (Red: 11150.74, 57%)

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

1) 16/10/18 TP

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

200

10

210

Report Format: TPLump Sum / (B) (\$) 8219.76Veh No: 5JQ8220X Yr Regn: 3.18Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c. 1591Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 9658 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHD 841CMJU 647130Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KUMHO

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 25/5/18 D.O.I. 25/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

## **Denise Tay (LKKAuto)**

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 26 September 2018 2:11 PM  
**To:** 'yiqian\_low@sg.msg-asia.com'; 'Monica Chung'  
**Cc:** Accounts (LKKAuto); KKLau; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 25/9/2018, SJQ 8220X (TP VEHICLE), SDW 1678S (OI VEHICLE)  
**Attachments:** gia report SJQ 8220X.pdf

Dear Yi Qian/Monica,

Please be informed that we had inspected the vehicle SJQ 8220X at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 25/9/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Denise Tay (LKKAUTO)

**From:** Muhammad Asyraf Noor Azman <muhammad.asyraf@hyundaimotors.com.sg>  
**Sent:** Friday, 12 October 2018 8:07 AM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** RE: CHECK PART PRICE

Hi,

|                |                              |        |
|----------------|------------------------------|--------|
| 71504-F2C00    | PANEL ASSY-QUARTER OUTER,RH  | 1768.3 |
| 77004-F2000    | PANEL ASSY-REAR DOOR,RH      | 1775.2 |
| 76004-F2000    | PANEL ASSY-FRONT DOOR,RH     | 1831.1 |
| 83306-F2040UTE | PANEL ASSY-REAR DOOR TRIM,RH | 497.9  |
| 87131-F2000    | MOULDING-REAR WINDOW GLASS   | 74.2   |
| 81420-F2000    | LATCH ASSY-REAR DOOR,RH      | 191.5  |

**From:** Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]  
**Sent:** Thursday, 11 October, 2018 2:02 PM  
**To:** Muhammad Asyraf Noor Azman  
**Subject:** CHECK PART PRICE

Dear Asyraf,

Can help me check part price

Hyundai Elantra 2018 Model  
KMHD841CMJU647130

Rear Fender RH  
Rear Windscreen moulding  
Rear door RH  
Rear door inner lock RH  
Rear door inner board RH  
Front door RH

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Don't summit. keep*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                  |
|----------------------------|----------------------------------|
| Date Of Report             | 25/09/2018 15:26                 |
| Date Of Accident           | 25/09/2018 07:20                 |
| Exact Location Of Accident | AT YIO CHU KANG SECONDARY SCHOOL |
| Country/State of Loss      | SINGAPORE                        |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJQ8220X             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | MAH SENG NAM         |
| NRIC No                     | S6878098E            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-97695429 |
| Alternative Phone No        | OTHERS-97695429      |

### Vehicle Particulars

|  |                 |
|--|-----------------|
| Manufacturer   | HYUNDAI         |
| Model  | ELANTRA-1.6 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE     |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO              |
| If No, Please state action to be taken                                       | THIRD PARTY     |
| Vehicle Category   | PRIVATE CAR     |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5100291124                             |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | MAH SENG NAM          |
| NRIC No              | S6878098E             |
| Date Of Birth        | 30/10/1968            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 29/12/1995            |
| Driving Experience   | 22 YEARS AND 8 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97695429  |
| Fax Number           |                       |
| Contact Number       | OTHERS-97695429       |
| Email Address        | NOEMAIL               |

|   |                                |
|---|--------------------------------|
| Address   | BLK 410A #21-120 FERNVALE ROAD |
| Postcode  | 791410                         |
| Was driver an employee of the Insured's Company     | NO                             |
| If No, Relationship of the Driver with the Insured  | OWNER                          |
| Vehicle Registration Number of Driver's Own Vehicle | -                              |
|   | -                              |
|   | -                              |
| Insurance Company of Driver's Own Vehicle           | -                              |
|   | -                              |
|   | -                              |

#### General Information of the Accident

|                    |            |
|--------------------|------------|
| Type Of Accident   | SIDE SWIPE |
| Weather Conditions | CLEAR      |
| Road Surface       | DRY        |

#### Other Information

|   |                      |
|---|----------------------|
| Was any foreign vehicle involved in this accident?  | NO                   |
| Number of vehicles involved in the accident   | 2                    |
| Was any body injured in the Accident?   | YES                  |
| Was any injured conveyed to hospital by ambulance?  | NO                   |
| Was any other material or property damaged?   | YES                  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                   |
| Number of Passengers (Including Driver)   | 2                    |
| Passenger 1   | NAME: : LEE YOKE LAN |
|   | GENDER: : MALE       |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| Vehicle Registration Number         | SDN1678S                             |
| Vehicle Make/Model/Colour           | BMW                                  |
| Details Of Properties               |                                      |
| Vehicle Category                    | PRIVATE CAR                          |
| Name of Driver                      |                                      |
| NRIC/Passport Number                |                                      |
| Contact Number                      |                                      |
| Address                             |                                      |
| Postcode                            |                                      |
| Insurance Company Name              | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Nature Of Damage                    |                                      |
| No. Of Passenger (Including Driver) |                                      |

**DETAILS OF INJURED PERSON 1**

|   |                                |
|---|--------------------------------|
| Name  | MAH SENG NAM                   |
| Approximate Age                                     |                                |
| Injuries Sustain                                    |                                |
| Injured person in which vehicle?                    | SJQ8220X                       |
| Were seat belts worn?                               | YES                            |
| Was this injured conveyed to hospital by ambulance? |                                |
| Address   | BLK 410A #21-120 FERNVALE ROAD |
| Postcode  | 791410                         |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KARI BUKIT (VAC)**  
Reporting Centre Personnel's Signature  
Name: Singapore 415933  
Tel: 67416697  
NRIC/FIN No. Fax: 67492305  
Email: vackb@singnet.com.sg

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 25/2/18 at 7:00am, my car was stop at the  
 Hio Chu Keng Secondary school main gate. Suddenly  
 vehicle B hit on my RH side door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

IDAC KAKI BUKIT (VAC)  
 1 KAKI BUKIT AVE 4  
 Singapore 415533  
 Name: Reporting Centre Personnel's Signature  
 Tel: 67416697  
 NRIC/FIN No: 67492305  
 Fax: 67492305  
 Email: vuckb@singnet.com.sg



Date of Accident : 25/9/18 Accident Time: 7.20am (24-HR-Format)  
 Accident Place : At Yio Chu Keng secondary school  
 Vehicle. No. (Car Plate No.) : STX 8220X Make/Model: Hyundai Elantra 1.6  
 Insurance Company : NTUC Policy No: \_\_\_\_\_  
 Owner or Company Name /IC No. : Mah Seng Nam / 56878098E  
 Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
 DRIVER'S Name / IC No. : as above  
 DRIVER'S Date Of Birth : 30/10/1968 DRIVER'S License Pass Date 29/12/95  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
 DRIVER'S Address : B/K 410A Fervale Road #21-120  
 DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) 5791410  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : \_\_\_\_\_  
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): 2 person  
 Was there any video Captured by car camera: YES \ NO  
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
 Any Injury (If YES, Pls state): yes

**Other Party Driver's Particular (if any)**

|                                       |                              |
|---------------------------------------|------------------------------|
| Vehicle. No: <u>SDN 1678S (msl/G)</u> | Vehicle. No: _____           |
| Vehicle Make/Model: _____             | Vehicle Make/Model: _____    |
| Name Driver: _____                    | Name Driver: _____           |
| IC No. Driver/Contact: _____          | IC No. Driver/Contact: _____ |

**\* NEW - Passenger's name & gender:**

LEE YOE LAN (M)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

A - SJQ 8000X  
B - SDN 16785


Ang Mo Kio Ave


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


on 25/9/18 at 7.20am, my car was stop at the  
Yio Chu Kang Secondary school main gate. Suddenly  
vehicle B hit on my RH side door.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8098E

### Vehicle Details

Vehicle No.: SJQ8220X  
Vehicle to be Exported: No  
Intended Deregistration Date: 25 Sep 2018  
Vehicle Make: HYUNDAI  
Vehicle Model: ELANTRA AD 1.6 GLS AT (AMS)  
Primary Colour: Blue  
Manufacturing Year: 2018  
Engine No.: G4FGJU151348  
Chassis No.: KMHD841CMJU647130  
Maximum Power Output: 93.8 kW (125 bhp)  
Open Market Value: \$13,567.00  
Original Registration Date: 29 Mar 2018  
First Registration Date: 29 Mar 2018  
Transfer Count: 0  
Actual ARF Paid: \$13,567.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 28 Mar 2028  
PARF Rebate Amount: \$10,175.00

### Intended COE Rebate Details

COE Expiry Date: 28 Mar 2028  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$38,000.00  
COE Rebate Amount: \$36,130.00  
**Total Rebate Amount: \$46,305.00**

The information contained herein is correct as at 25 Sep 2018

OK

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-46/48/50  
SINGAPORE 417883

not Authorised  
25/3/18  
P/P \$219.76  
7 day.

VEHICLE NO: SJQ 8220X

| QTY   | PARTICULAR  |        |              |
|-------|---|--------|--------------|
| 1 PCS | FRONT DOOR O/S                                      | 10     | \$1,488.00   |
| 1 PCS | FRONT DOOR INNER LOCK O/S                           | 11     | \$315.00 X   |
| 1 PCS | FRONT DOOR INNER RUBBER O/S                         | 11     | \$219.00     |
| 1 SET | FRONT DOOR FRAME <del>BLACK</del> STICKER O/S Black | 11     | \$85.00      |
| 1 PCS | FRONT DOOR GLASS OUTER MOULDING O/S                 | 11     | \$110.00 X   |
| 1 PCS | CENTRE PILLAR O/S                                   | 11     | \$605.00 X   |
| 1 PCS | ROCKER PANEL O/S                                    | 11     | \$885.00 X   |
| 1 PCS | REAR DOOR O/S                                       | 30/300 | \$1,355.00   |
| 2 PCS | REAR DOOR HINGES @\$105.00                          | 11     | \$210.00 X   |
| 1 PCS | REAR DOOR OUTER HANDLE                              | 11     | \$195.00 X   |
| 1 SET | REAR DOOR FRAME <del>BLACK</del> STICKER O/S Black  | 11     | \$85.00      |
| 1 PCS | REAR DOOR INNER RUBBER O/S                          | 11     | \$215.00     |
| 1 PCS | REAR DOOR INNER TRIM BOARD O/S 497.50               | 11     | \$665.00     |
| 1 PCS | REAR DOOR GLASS REGULATOR MOTOR O/S 285.50          | 11     | \$388.50     |
| 1 PCS | REAR DOOR INNER LOCK O/S 191.50                     | 11     | \$315.00     |
| 1 PCS | REAR DOOR INNER STEP GARNISH O/S                    | 11     | \$60.00      |
| 1 PCS | REAR DOOR GLASS OUTER MOULDING                      | 11     | \$110.00 X   |
| 1 PCS | REAR FENDER O/S 1768.50                             | 30/300 | \$3,855.00   |
| 1 PCS | REAR FENDER UNDER COVER O/S                         | 11     | \$92.00      |
| 1 PCS | REAR FENDER UNDER COVER CLIPS O/S                   | 11     | \$30.00      |
| 1 PCS | REAR SHOCK ABSORBER O/S                             | 11     | \$299.00 X   |
| 1 PCS | REAR KNUCKLE ARM O/S                                | 11     | \$820.00 X   |
| 1 PCS | REAR WHEEL HUB BEARING O/S                          | 11     | \$350.00 X   |
| 1 PCS | REAR BUMPER   | 11     | \$660.00 X   |
| 1 SET | REAR BUMPER CLIPS                                   | 11     | \$39.00 X    |
| 1 PCS | REAR FENDER LOWER STICKER O/S                       | 11     | \$30.00      |
|       |   |        | \$13,480.50  |
|       | S.NETT  |        |              |
| 1 PCS | REAR SPORT RIM O/S                                  | 11     | \$680.00 350 |
| 1 PCS | REAR TYRE O/S                                       | 11     | \$300.00 X   |
| 1 PCS | REAR WINDSCREEN SEALANT                             | 11     | \$50.00 40   |
| 1 PCS | REAR WINDSCREEN INNER SEAL                          | 11     | \$50.00 30   |
| 1 SET | O/S DOOR VISOR                                      | 11     | \$200.00 120 |

LABOUR CHARGES:

|  |            |
|--|------------|
| TO CHECK WIRING                          | \$80.00 20 |
| TO DISMANTLE & REFIX REAR REVERSE SENSOR | \$80.00 50 |

|   |             |      |
|---|-------------|------|
| TO CONDUCT WHEEL ALIGNMENT  | \$120.00    | 60   |
| TO DISMANTLE & REFIX REAR WINDSCREEN                              | \$150.00    | 120  |
| TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY                     | \$150.00    | 80   |
| TO TRANSFER BOTH O/S DOOR MECHANISM                               | \$180.00    | 120  |
| TO SPRAY RUST PROOFING  | \$150.00    | 100  |
| TO DISMENTLE & REFIX REAR UNDERCARRIAGE                           | \$300.00    | X    |
| TO DISMANTLE & REFIX PETROL TANK                                  | \$100.00    | X    |
| LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS | \$1,800.00  | 1000 |
| TO PUTTY & SPRAY PAINTING   | \$1,500.00  | 1000 |
| TOTAL   | \$19,370.50 |      |

390

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18017395/UTBN2

Date: 17/10/2018

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | B27709425SMP |
| Claimant Vehicle No : | SJQ8220X                             | Insured Vehicle No : | SDN1678S     |
| Date of Loss:         | 25/09/2018                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 571375       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJQ8220X                     | Engine No:  | G4FGJU151348      |
| Make & Model:               | HYUNDAI ELANTRA, 1.6 (A)     | Chassis No: | KMHD841CMJU647130 |
| Reg. Date:                  | 29/03/2018 (Man. Year: 2018) | Odometer:   | 9658 km           |
| Colour:                     | Blue                         |             |                   |
| Engine Capacity:            | 1591 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/55R16  | Rear Tyre Size:  | 205/55R16  |
| Front Left Side:  | Kumho 9 mm | Rear Left Side:  | Kumho 9 mm |
| Front Right Side: | Kumho 9 mm | Rear Right Side: | Kumho 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                 | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--------------------------------|------------------|-----------------|------------------|--------------|
| Parts                          | 14,760.50        | 5,669.76        | 9,090.74         | 61.59        |
| Miscellaneous Items            | 0.00             | 0.00            | 0.00             |              |
| Labour                         | 4,610.00         | 2,550.00        | 2,060.00         | 44.69        |
| Paintwork Labour               | 0.00             | 0.00            | 0.00             |              |
| Towing                         | 0.00             | 0.00            | 0.00             |              |
| <b>Gross Total (\$\$)</b>      | <b>19,370.50</b> | <b>8,219.76</b> | <b>11,150.74</b> | <b>57.57</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b> | <b>1,355.94</b>  | <b>575.38</b>   | <b>780.56</b>    | <b>57.57</b> |
| <b>Nett Amount (\$\$)</b>      | <b>20,726.44</b> | <b>8,795.14</b> | <b>11,931.30</b> | <b>57.57</b> |

## INSPECTION

|                     |            |                                  |
|---------------------|------------|----------------------------------|
| Date of Assignment: | 27/09/2018 |                                  |
| Date Inspected:     | 25/09/2018 | Inspected At:                    |
|                     |            | Fastech Auto Pte Ltd (HQ)        |
|                     |            | 1 Kaki Bukit Ave 6, #01-46/48/50 |
|                     |            | Autobay                          |
|                     |            | Singapore 417883                 |

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 17 Oct 2018)  |
| <b>Parts:</b> 143  | HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJQ8220X) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

## Recommended Parts

| No. | Qty | Part No. Particulars                    | Condition     | Repairer's | Amount       |
|-----|-----|---|---------------|------------|--------------|
| 1   | 1   | *FRONT DOOR O/S                         | Dented        | 1,488.00 F | *1,488.00 FL |
| 2   | 1   | *FRONT DOOR INNER LOCK O/S              | Not Necessary | 315.00 F   | *- FL        |
| 3   | 1   | *FRONT DOOR INNER RUBBER O/S            | Necessary     | 219.00 F   | *219.00 FL   |
| 4   | 1   | *FRONT DOOR FRAME BLACK STICKER O/S SET | Necessary     | 85.00 F    | *85.00 FL    |
| 5   | 1   | *FRONT DOOR GLASS OUTER MOULDING O/S    | Not Necessary | 110.00 F   | *- FL        |
| 6   | 1   | *CENTRE PILLAR O/S                      | Repair        | 605.00 F   | *- FL        |
| 7   | 1   | *ROCKER PANEL O/S                       | Repair        | 885.00 F   | *- FL        |
| 8   | 1   | *REAR DOOR O/S                          | Badly Dented  | 1,355.00 F | *1,355.00 FL |
| 9   | 2   | *REAR DOOR HINGES                       | Serviceable   | 210.00 F   | *- FL        |
| 10  | 1   | *REAR DOOR OUTER HANDLE                 | Not Necessary | 195.00 F   | *- FL        |
| 11  | 1   | *SET REAR DOOR FRAME BLACK STICKER O/S  | Necessary     | 85.00 F    | *85.00 FL    |
| 12  | 1   | *REAR DOOR INNER RUBBER O/S             | Necessary     | 215.00 F   | *215.00 FL   |
| 13  | 1   | *REAR DOOR INNER TRIM BOARD O/S         | Deformed/Torn | 665.00 F   | *497.90 FL   |
| 14  | 1   | *REAR DOOR GLASS REGULATOR MOTOR O/S    | Shorted       | 388.50 F   | *295.50 FL   |
| 15  | 1   | *REAR DOOR INNER LOCK O/S               | Shorted       | 315.00 F   | *191.50 FL   |
| 16  | 1   | *REAR DOOR INNER STEP GARNISH O/S       | Twisted       | 60.00 F    | *60.00 FL    |
| 17  | 1   | *REAR DOOR GLASS OUTER MOULDING         | Not Necessary | 110.00 F   | *- FL        |
| 18  | 1   | *REAR FENDER O/S                        | Badly Dented  | 3,855.00 F | *1,768.30 FL |
| 19  | 1   | *REAR FENDER UNDER COVER O/S            | Torn          | 92.00 F    | *92.00 FL    |
| 20  | 1   | *REAR FENDER UNDER COVER CLIPS O/S      | Necessary     | 30.00 F    | *30.00 FL    |
| 21  | 1   | *REAR SHOCK ABSORBER O/S                | Not Necessary | 299.00 F   | *- FL        |
| 22  | 1   | *REAR KNUCKLE ARM O/S                   | Not Necessary | 820.00 F   | *- FL        |
| 23  | 1   | *REAR WHEEL HUB BEARING O/S             | Not Necessary | 350.00 F   | *- FL        |
| 24  | 1   | *REAR BUMPER                            | Repair        | 660.00 F   | *- FL        |
| 25  | 1   | *SET REAR BUMPER CLIPS                  | Not Necessary | 39.00 F    | *- FL        |
| 26  | 1   | *REAR FENDER LOWER STICKER O/S          | Necessary     | 30.00 F    | *30.00 FL    |
| 27  | 1   | *REAR SPORT RIM O/S                     | Cut           | 680.00 FS  | *350.00 FS   |
| 28  | 1   | *REAR TYRE O/S                          | Not Necessary | 300.00 FS  | *- FS        |
| 29  | 1   | *REAR WINDSCREEN SEALANT                | Necessary     | 50.00 FS   | *40.00 FS    |
| 30  | 1   | *REAR WINDSCREEN INNER SEAL             | Necessary     | 50.00 FS   | *30.00 FS    |
| 31  | 1   | *SET O/S DOOR VISOR                     | Necessary     | 200.00 FS  | *120.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                  |                 |
|---|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>14,760.50</b> | <b>6,952.20</b> |
| <b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b> | <b>0.00</b>      | <b>1,282.44</b> |
| <b>Total Parts (\$\$)</b>                                 | <b>14,760.50</b> | <b>5,669.76</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's      | Amount          |
|-------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>     |  |          |                 |                 |
| 1                       | TO CHECK WIRING  | New      | 80.00           | 20.00           |
| 2                       | TO DISMANTLE & REFIX REAR REVERSE SENSOR                       | New      | 80.00           | 50.00           |
| 3                       | TO CONDUCT WHEEL ALIGNMENT                                     | New      | 120.00          | 60.00           |
| 4                       | TO DISMANTLE & REFIX REAR WINDSCREEN                           | New      | 150.00          | 120.00          |
| 5                       | TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY                   | New      | 150.00          | 80.00           |
| 6                       | TO TRANSFER BOTH O/S DOOR MECHANISM                            | New      | 180.00          | 120.00          |
| 7                       | TO SPRAY RUST PROOFING   | New      | 150.00          | 100.00          |
| 8                       | TO DISMANTLE & REFIX REAR UNDERCARRIAGE                        | New      | 300.00          | -               |
| 9                       | TO DISMANTLE & REFIX PETROL TANK                               | New      | 100.00          | -               |
| 10                      | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS | New      | 1,800.00        | 1,000.00        |
| 11                      | TO PUTTY & SPRAY PAINTING                                      | New      | 1,500.00        | 1,000.00        |
| Gross Labour Cost (S\$) |  |          | <b>4,610.00</b> | <b>2,550.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >