

ASS. REC. BY:

REF: CS/AIG18017398/Aqd3

Special Instruction:

Surveyor  
Mennah

Adrian

ASSIGNMENT (Office)

From (Person):

Azlan, Syuzairidina

of

Aig

Date/Time:

24/9/18 @ 4.44pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

ER 662K

Insured:

81Y 4898A

at Workshop n/s

TICK HUI MOTOR

Tel:

6842 9089

of

1 Kaki Blk Ave 6 # 01-54 Autobay

Policy No:

2100227567

Claim No:

966159896956

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/09/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

25/09/18

Date/Time:

4.53pm @ 24/9/18

Person Contacted:

Connie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

ER 662K - CS / MSG18004790 / Agbn2

DoA: 9/3/18

81Y 4898A - CS / AIG16068056 / Agbn2

DoA: 27/4/16

1561800, 5 days cred to 400, 69%.

REF:

AIG

## ASSIGNMENT

From

Date:

25/9/18

Estimated Cost

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

ER 662 K

at Workshop m/s

Tick Hai Motor

of

1 Kaki Bkt Ave 6 #01-54

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

ER662K

Yr Regn:

1991 Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c 1343

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

446673.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMEC84200531344

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

195/50R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

25/09/18.

Survey held at

Tick Hai.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG.

COE Expiry: 30/04/19.

MV: 81K.

PV: 200

Nett: 7.8K.

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 19/11/18

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

250

20

S + RS \$

Photos

Others

TOTAL

270

Report Format:

NET-TP

Lump Sum / I.B.T. (\$

1800




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18017398/Aqd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 25-09-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJY 4898A	Veh. Inspected	ER 662K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	AZLAN SYAZAIRDINA	Assign Date	25/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	18/09/2018	Inspection Date	25/09/2018
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Pre repair inspection request - ER662K VS SJY4898A (OI) DOA: 18/09/2018

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi  
Sent: 24/9/2018 4:44:42 PM  
Attachments:  tmpD18E.TIF

---

Hi,

Please refer to the enclosed request from **ARIDAS & ASSOCIATES**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

---

**From:** aridasv@singnet.com.sg [mailto:aridasv@singnet.com.sg]  
**Sent:** Monday, September 24, 2018 3:47 PM  
**To:** Azlan, Syazairdina  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; aridasv@singnet.com.sg  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER 662 K ON 18/09/2018

Hi Syaza,

Yes its confirmed and please liase directly with Ms Connie at tel 68429089 of Tick Hai Motor & Welding Services Block 1 Kaki Bukit Avenue 6 #01-54 AutoBay @Kaki Bukit Singapore 417883.

Regards

Marina

---

**From:** Azlan, Syazairdina  
**Sent:** Mon, 24 Sep 2018 07:27:15 +0000  
**To:** aridasv@singnet.com.sg  
**Cc:** Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Chan, Yoke Shi, Mithoosingh, Aashweenjeetkaur  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER 662 K ON 18/09/2018

Hi Marina,

Please confirm that you are nominating Adrian Ling from LKK Auto Consultants Pte Ltd named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

---

**From:** aridasv@singnet.com.sg [mailto:aridasv@singnet.com.sg]  
**Sent:** Monday, September 24, 2018 2:59 PM  
**To:** Azlan, Syazairdina  
**Cc:** aridasv@singnet.com.sg  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER 662 K ON 18/09/2018

Hello Azlan, Syazairdina

My client has chosen Adrian Ling from LKK Auto Consultants Pte Ltd.

Regards,

Marina

---

**From:** Azlan, Syazairdina  
**Sent:** Mon, 24 Sep 2018 02:30:30 +0000  
**To:** aridasv@singnet.com.sg

Cc:

**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER 662 K ON 18/09/2018

Hi,

Ok this is noted.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

---

**From:** aridasv@singnet.com.sg [mailto:aridasv@singnet.com.sg]

**Sent:** Monday, September 24, 2018 10:20 AM

**To:** Azlan, Syazaidina

**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER662K ON 18/09/2018

Hi Azlan, Syazaidina,

Vehicle number should be ER 662 K

Regards,

Aridas & Associates

---

**From:** Azlan, Syazaidina

**Sent:** Mon, 24 Sep 2018 01:48:27 +0000

**To:** aridasv@singnet.com.sg

**Cc:** Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Chan, Yoke Shi, Mithoosingh, Aashweenjeetkaur

**Subject:** - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY4898A AND ER662K ON 18/09/2018

Without Prejudice

Your Reference : AA.21506.18.159

Our Reference : SJY4898A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**ARIDAS & ASSOCIATES**

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES &amp; SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #05-18, BOON SIEW BUILDING, SINGAPORE 229833  
 TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713  
 E-mail : aridasv @ singnet.com.sg

**VYTINGAM ARIDAS**  
 LLB (Hons) Lond. M.A.  
 Barrister, (Lincoln's Inn)

*Service of Court Documents  
 By Fax  
 Is Not Acceptable*

Our Ref : AA.21506.18.159

Your Ref : Please advise

21 SEPTEMBER 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

Dear Sirs

ACCIDENT INVOLVING MOTOR VEHICLES NOS. ER 662K AND SJY 4898A AT 1 KAKI BUKIT AVE 6  
 AUTOBAY @ KAKI BUKIT CP ON 18 SEPTEMBER 2018 AT 10:45.

We are instructed by GOH CHENG HAI to notify you of a road traffic accident on 18/9/18 at  
 10:45 involving our client's vehicle registration number ER 662K and vehicle registration  
 number SJY 4898A driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to  
 repair the damage vehicle, please let us know within 2 working days of your receipt of this  
 notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If  
 we do not receive any reply from you within the stipulated timeline, our client shall proceed to  
 repair the vehicle without further reference to you.

Our client's motor vehicle ER 662K can be inspected at:

M/s Tick Hai Motor & Welding Services, Block 1 Kaki Bukit Avenue 6, #01-54 Auto @ Kaki Bukit,  
 Singapore 417883.  
 Please contact Ms Connie at office number: 6842 9049.

Yours faithfully,  
 Aridas & Associates  
 75 Bukit Timah Road,  
 05-18 Boon Siew Building,  
 Singapore 229833  
 Tel : 63376359  
 Fax: 63382713





## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more



Post an Advertisement  
Sell it yourself! Advertise it at just  
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

## New 5 Years Coe Renewal Toyota Wish 1.8A



\$2000 Downpayment Monthly  
From \$638 Onwards, Lowest  
3.18% P.A. @ GV Cars Financing  
GV Credit Pte Ltd - StarAd



- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Save Search

Print

« Back ( 1 2 3 4 5 6 ) Next »

Sort by Date Posted

20 results/page

110 vehicles

Search civic

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection civic Any Any > 10 year(s) old Any Any Any Available



☐ Honda Civic 1.6M 3DR (COE till 03/2020)

\$20,000

\$13,200 /yr

06-Nov-1991

1,590 cc

Hatchback

Available

Rare! Honda Civic Si 3 Door EF Powered By A 1.6 Litre DOHC Engine, Newly Painted Pure White Color With Red Lower Trims, No Rust And Beautiful Chassis, EP9 Look Conversion, New Clutch System And Loads ...

PREMIUM AD

Posted: 24-Sep-2018 Tags: 1991 Honda Civic, 1991 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ Honda Civic 1.6M VTI 3DR (COE till 04/2019)

\$10,800

\$18,170 /yr

13-Nov-1991

1,590 cc

Hatchback

Available

1991 Honda Civic Si (EF3) 1.6 DOHC,

DIRECT OWNER

Posted: 25-Sep-2018 Tags: 1991 Honda Civic, 1991 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ Honda Civic VTI EG9 (New 10-yr COE)

\$55,088

\$5,500 /yr

02-May-1992

1,595 cc

Sports

Available

Accident Free Chassis EG9 In The Market, View With Your Experience Mechanic At SK Garage, Very New Engine, Harness/Wiring Full LTA Legal Civic, Very Cold Air Condition System, This Car Has Been Restored...

DIRECT OWNER

Posted: 23-Jul-2018 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ Honda Civic ESI EH9 (COE till 04/2021)

\$25,800

\$9,930 /yr

09-Jul-1992

1,590 cc

Sedan

Available

4-Dr Civic Vtec Coe Renewable 10 Years, Car Inspection Passed, Road Tax Expiry 22 April 2019. Option To Buy Not Include 26 Years Old Car Plate Number At \$20,800.

DIRECT OWNER

Posted: 23-Sep-2018 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

**TYREPAC**  
Buy Tyres Online!  
Latest Special Offers from Tyrepac!



☐ Honda Civic VTI EG9 (COE till 05/2019)

\$16,888

\$24,860 /yr

01-Dec-1992

1,595 cc

188,888 km

Sports

Available

Posted: 06-Sep-2018 Tags: 1992 Honda Civic, 1992 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda



☐ Honda Civic CRX (COE till 05/2019)

\$13,800

\$20,310 /yr

04-Jan-1993

1,595 cc

Sports

Available

Posted: 21-Sep-2018 Tags: 1993 Honda Civic, 1993 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda

PREMIUM AD



☐ Honda Civic VTI EG9 (COE till 04/2019)

\$29,000

\$48,780 /yr

02-Mar-1993

1,595 cc

Sports

Available

Full Rebuild Of The Bulletproof B16A Block With A Hondada Tune Ignition Coil-Pack Conversion New Legal Invidia Exhaust System Undercarriage Arms/Linkages/Bushings New C/F Fiber Bonnet And Boot Fresh N...

DIRECT OWNER

Posted: 30-Aug-2018 Tags: 1993 Honda Civic, 1993 honda civic, Honda Civic, honda civic, Honda, Civic, civic, Used Honda

SHORTLISTED HISTORY

Compare



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9494D
Vehicle Details	
Vehicle No.:	ER662K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 3DR A
Primary Colour:	White
Manufacturing Year:	1991
Engine No.:	D13B11603249
Chassis No.:	JHMECB4200S313441
Maximum Power Output:	-
Open Market Value:	\$13,253.00
Original Registration Date:	19 Sep 1991
First Registration Date:	19 Sep 1991
Transfer Count:	7
Actual ARF Paid:	\$19,880.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$3,864.00
COE Rebate Amount:	\$230.00
Total Rebate Amount:	\$230.00

The information contained herein is correct as at 25 Sep 2018

OK

MSME18121626-01 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 19/09/2018 15:05  
SUBMITTED BY: Ang Guo Bao

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

159 Tick Hai Motor

## ACCIDENT STATEMENT

Date Of Report 19/09/2018 15:05  
Date Of Accident 18/09/2018 10:45  
Exact Location Of Accident 1 KAKI BUKIT AVE 6 AUTOBAY @ KAKI BUKIT CP.  
Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ER662K  
**Insured/Policyholder**  
Name Of Registered Owner GOH CHENG HAI  
NRIC No S2589494D  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-82015292  
Alternative Phone No OFFICE-82015292

## Vehicle Particulars

Manufacturer HONDA  
Model CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage THIRD PARTY  
Fleet Policy NO  
Policy Number 5061489151  
Cover Note Number

## Driver

Name of Driver BERTRAND GILLES STEPHANE COLAS  
NRIC No G5249395T  
Date Of Birth 18/10/1990  
Occupation INDOOR  
Date Of Driving Pass 30/11/2015  
Driving Experience 2 YEARS AND 9 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-96197177  
Fax Number  
Contact Number  
Email Address NOEMAIL

Address 601 AMK AVE 5 #05-2611

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - FATHER IN LAW

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD, POSTCODE: 469676, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE POLICE REPORT NO. T/20180918/2047.

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WORKSHOP HOLDING ON TO THE VIDEO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJY4898A

Vehicle Make/Model/Colour

Details Of Properties VEH B

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

19/09/2018 10AM

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Accident Sketch Plan Pg. 1

ETCH PLAN

Vehicle A : ER662K

Vehicle B : 5374898A

Canteen



Block D

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 18 September at 10.45 AM, vehicle 5374898A left his parking lot and hit on to my vehicle ER662K that was parked just beside him. The driver did not check or leave any note. He only drove off.

Refer to Police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

19/09/2018  
10AM

TICK HERE

## Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180918/2047

1 of 3

Police Station Of Origin:  
Bedok North N.P.C.  
30 Bedok North Road SINGAPORE 489676  
Tel No: 1800-2449999

Report No. T/20180918/2047

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/09/2018 12:57	Vide Report No.:	Station Diary No.: 33
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: BERTRAND GILLES STEPHANE COLAS			Address: APT BLK 601 601 ANG MO KIO AVENUE 5 #05-2611 SINGAPORE 560601	
ID Type / ID No.: FIN NO / G5249395T			Contact No.:	Mobile: 96197177
Nationality: FRENCH			Home/Office:	
Sex: Male			Email:	
Age: 27	Date of Birth: 18/10/1990	Type of Informant: Vehicle Owner		
Race: Caucasian		Language:	Institution / School Name:	
Occupation: OPERATION AND BUSINESS MANAGER		Driving Licence Information: Class:		Date of Expiry:

## General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 18/09/2018 10:40	Type of Location: Car Park
Location: Along Road 1 KAKI BUKIT AVENUE 6				
Inside Autobay @ 1 Kaki Bukit ground floor opposite block D				
Weather:	Road Surface:		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle	Anyone conveyed by ambulance: No			

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
ER662K	Car					0
SJY4898A	Car					0

## Details of Person Involved

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		



## Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180918/2047

2 of 3

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

Report No. T/20180918/2047

## CONTINUATION OF REPORT

Vehicle Owner			
Name	BERTRAND GILLES STEPHANE COLAS	ID No.	G5249395T
Related Vehicle	ER662K (Car)	Contact No.	96197177
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 18th September 2018 at about 9.30am, I parked my father-in-law's car, ER662K, in the ground floor car park in Autobay @ 1 Kaki Bukit opposite block D and left for work.

On the same day at about 11.40am, I came back and discovered that my car's front right fender, right bumper, bonnet and light were dented. I looked through my in-car camera and discovered that at about 10.40am, a car, SJY4898A, hitting t the front right portion of my car just as the driver was about to leave the parking lot that was beside mine. The driver did not left a note nor did he alighted his car to make a check. The driver then drove off.

I wish to state that I have a footage of the whole incident in my thumb drive.

## Accident Sketch Plan Pg. 1

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999



T/20180918/2047

3 of 3

Report No. T/20180918/2047

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MOHAMED NASZRUL BIN MOHD HELMI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/09/2018 12:57

Officer In Charge Of Case:

TP / HRT /

SI KALESWARI PALANI

Contact No.: 65476902

Classification Of Case:

Authentication Stamp

NP168

**159 TICK HAI MOTOR**  
**1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883**  
**TEL: 6842 9089 FAX: 6841 2869**  
**REG NO : 53033608A**

TP ALG.  
Xiao Chun

Vehicle Number: ER662K

S/N.	Item Description	Amount (\$)
1	Front Bonnet <i>new</i>	\$ 780.00
2	Front Fender (RH) <i>Buckled</i>	\$ 450.00
3	Front Fender Inner Garnish (RH) <i>new</i>	\$ 158.00
4	Headlamp (RH) <i>new</i>	\$ 250.00
5	Headlamp Apron <i>delid</i>	\$ 230.00
6	Signal Lamp (RH) <i>cracked</i>	\$ 80.00
7	Front Bumper <i>Distorted</i>	\$ 580.00
8	Front Bumper Side Bracket x 2 pcs <i>RH new</i>	\$ 116.00
9	Front Bumper Signal Lamp (RH) <i>cracked</i>	\$ 80.00
10	Front Bumper Beam <i>best</i>	\$ 128.00
11	Horn <i>new</i>	\$ 128.00
	Amount :	\$ 2,980.00

1573  
1758.40

S/N	Special Nett Item	Amount (\$)
1	Front Tyre Rim (RH) <i>new</i>	\$ 480.00
	Amount :	\$ 480.00

Labour	Amount (\$)
To conduct 4-wheel alignment	\$ 80.00
To check front electrical wiring	\$ 80.00
Labour to remove, cut, change & panel beating	\$ 1,200.00
To putty and respray affected areas	\$ 980.00
Labour Total :	\$ 2,340.00
Total (Parts & Labour)	\$ 5,800.00

980

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to information
- Third party survey is on "without Prejudice" basis
- No illegal modifications allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 2238.40  
L/S: 1.8K  
05 Days

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18017398/AQD3N2

Date: 19/11/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100227567  
 Claimant Vehicle No: ER662K Insured Vehicle No: SJY4898A  
 Date of Loss: 18/09/2018 Nature of Claim: TP Claim No: 9661598969SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: ER662K Engine No: D13B11603249  
 Make & Model: HONDA CIVIC, 1.3 IMA (A) Chassis No: JHMEC84200S313441  
 Reg. Date: 19/09/1991 (Man. Year: 1991) Odometer: 446673 km  
 Colour: White  
 Engine Capacity: 1343 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,460.00	1,258.40	2,201.60	63.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	980.00	1,360.00	58.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,800.00</b>	<b>2,238.40</b>	<b>3,561.60</b>	<b>61.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	5,800.00	1,800.00	4,000.00	68.97
+ GST 7.00/7.00% (S\$)	406.00	126.00	280.00	68.97
<b>Nett Amount (S\$)</b>	<b>6,206.00</b>	<b>1,926.00</b>	<b>4,280.00</b>	<b>68.97</b>

## INSPECTION

Date of Assignment: 24/09/2018  
 Date Inspected: 25/09/2018 Inspected At: Tick Hai Motor (HQ)  
 AUTOBAY#01-54  
 Singapore 435435

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	780.00 F	*- FL
2	1		*FRONT FENDER (RH)	Buckled	450.00 F	*450.00 FL
3	1		*FRONT FENDER INNER GARNISH (RH)	Not Necessary	158.00 F	*- FL
4	1		*HEADLAMP (RH)	Not Necessary	250.00 F	*- FL
5	1		*HEADLAMP APRON	Deformed	230.00 F	*230.00 FL
6	1		*SIGNAL LAMP (RH)	Cracked	80.00 F	*80.00 FL
7	1		*FRONT BUMPER	Distorted	580.00 F	*580.00 FL
8	1		*FRONT BUMPER SIDE BRACKET	O/s Necessary	116.00 F	*25.00 FL
9	1		*FRONT BUMPER SIGNAL LAMP (RH)	Cracked	80.00 F	*80.00 FL
10	1		*FRONT BUMPER BEAM	Bent	128.00 F	*128.00 FL
11	1		*HORN	Not Necessary	128.00 F	*- FL
12	1		*FRONT TYRE RIM (RH)	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,460.00</b>	<b>1,573.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>314.60</b>
<b>Total Parts (\$\$)</b>	<b>3,460.00</b>	<b>1,258.40</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT 4-WHEEL ALIGNMENT	New	80.00	-
2	TO CHECK FRONT ELECTRICAL WIRING	New	80.00	30.00
3	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING	New	1,200.00	450.00
4	TO PUTTY AND RESPRAY AFFECTED AREAS	New	980.00	500.00
Gross Labour Cost (\$\$)			2,340.00	980.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;