

Your Ref: BK/17756.17.st

Date: 19th October 2018

Our Ref: CS1/LAW18017415/K1qbs2

M/s Bonnie Kwok LLC
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
GBC 9742T INSURED VEHICLE: GBF 1502G ACCIDENT DATE: 02/03/2017**

We thank you for your instruction on 31/07/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBC 9742T from M/s Automax Survey.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of GBC 9742T from M/s Eng Soon Painting Services.
- d) Singapore Accident Statement of Vehicles GBC 9742T and GBF 1502G.
- e) Colour damaged vehicle photographs of GBC 9742T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBC 9742T
Make & Model	: Nissan Cabstar 3.0
Year of Registration	: 2014
Chassis Number	: JN1SC2F24Z0855614
Engine Capacity	: 2953 cc
2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.