

2/003/2003

ASS. REC. BY:

REF:

CS/FCI18017438/T1+d312

Special Instruction:

Surveyor

CWS

Tudjih

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

25/9/18 @ 2:36pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8CX 2220G

Insured:

84D 6776P

at Workshop m/s:

Volkswagen

Tel:

63057176

of

247 Alexandra Road

Policy No:

Claim No:

D1800 6993MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/09/18

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

26/9/18 @ 4pm

owner nothing

Date/Time:

2:53pm @ 25/9/18

Person Contacted:

charmaine

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

8CX 2220G - X

84D 6776P - NS / INC 18014232 / Klgbn2

DOA: 3/8/18

23/9 @ 2:02pm - RERT via email preli advise.

Part by Part \$9,245.68 (Red: 2123.37, 18%)

Surveyor

Taylor

REF: FCI

ASSIGNMENT

From:

Date: 26/09/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SCX 22209

at Workshop m/s

Volkswagen

of

247 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

4pm

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SCX 22209 Yr Regn: 2014 NSW

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Sharan C.C. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 80017 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVVZZZ 7N2FV001 802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 21/9/2018

Survey held at 247 Alexandra Rd

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 OCT 2018



23/10/2018

Date/Time, File Pass to?

23/10 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 9245.68)

170 + 15

50

50

39

324



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017438/T1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-09-2018

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6776P	Veh. Inspected	SCX 2220G
Policy No.		Coverage (\$)	0.00
Claim No.	D18006993MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/09/2018	Inspection Date	26/09/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006993MFSH

Date: 28/9/2018

Our Ref: CS/FCI18017438/T1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SCX 2220G

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/09/2018 at the premises of M/s Volkswagen and have the following to report: -

Workshop Estimate Amount	: S\$ 10,957.96
Revised Estimate Amount	: S\$ 8,834.59
"Check" Items Amount	: S\$ 63.37
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No.	D18006993MFSH
Accident Date	21-09-2018	Claim Type.	Third Party
Insured Vehicle	SHD6776P	Third Party Vehicle.	SCX2220G
Survey Location	247 ALEXANDRA ROAD		
Contact Person.	CHARMAINE KONG		
Contact No.	63057176/ 63057299	Fax No.	64743643
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 28 September 2018 12:02 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006993MFSH/1
Attachments: PRELI ADVISED SCX 2220G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SCX 2220G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 25 September 2018 2:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006993MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 September 2018 2:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006993MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Sketch Plan #3



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel: +65 6827 7888 Fax: +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

VW DRIVEEASY
Comprehensive

Certificate No. A 80417800 AVW

Excess : SGD1,500
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SCX22200
2. Name of Policyholder
Kwan Chang Yew
3. Effective Date of the Commencement of Insurance for the purposes of the Act
11/11/2017
4. Date of Expiry of Insurance
10/11/2018
5. Persons or Classes of Persons entitled to drive*
Kwan Chang Yew
Jane Lee
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.
* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.


This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.


MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

thyl
for Chief Executive Officer

Sketch Plan #4



Sketch Plan #5



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



[illegible]

PDI TUAS

PDI TUAS

KWAN CHANG YEW (GUAN ZHENYAO)
132A HILLVIEW AVENUE
#09-06
Singapore, 669604
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV027081
Quote No. SER/QUO/1801591
QuoteDate 24/09/18
Salesperson Edmund Nai
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan NF 2.0 TSI (DSG6)+EQP	78,020	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SCX2220G	WVWZZZ7NZFV001802	11/11/14	Edmund Nai
Engine Code	Labor Type	Engine No.	Model Code
	10	CCZ 447265	7N14H3

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		1680 2,520.00
P B&P ALEX LABOUR	TRANSFER DOOR PARTS	1	UNIT		420 840.00
P B&P ALEX PAINT	SPRAY PAINTING	3	UNIT		1600 2,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				6,520.00
P 1K8837205F GRU	DOOR HANDLE RHR	1	Pieces		266.01
	Use Predecessor 1K8837205E GR				
P 7N0839718AD	SEAL RHR	1	Pieces		532.27
P 7N0843108AL	DOOR RHR	1	Pieces		2,943.13
P 7N0843470C 3Q7	WINDOW ALUMINIUM SEAL RHR	1	Pieces		224.32
P 7N0843696	WINDOW ALUMINIUM SEAL RHR	1	Pieces		63.37
P 7N0845206	WINDOW	1	Pieces		402.16
P 7N0863801	SOUND ABS	2	Pieces		6.70
	Sum Item				4,437.96

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

KWAN CHANG YEW (GUAN ZHENYAO)
132A HILLVIEW AVENUE
#09-06
Singapore, 669604
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV027081
Quote No. SER/QUO/1801591
QuoteDate 24/09/18
Salesperson Edmund Nai
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan NF 2.0 TSI (DSG6)+EQP	78,020	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SCX2220G	WVWZZZ7NZFV001802	11/11/14	Edmund Nai
Engine Code	Labor Type	Engine No.	Model Code
	10	CCZ 447265	7N14H3

Sum Labor	6,520.00
Sum Item	4,437.96
Total SGD	10,957.96
7% GST	10,957.96 767.06
Total SGD Incl. GST	11,725.02

Explanations

P = Proportionately Charged

Payment Terms

No Credit

11369.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Service Order Confirmation

SERVICE ORDER NO: 18IP2504
 CUSTOMER NO.: CV027081
 CUSTOMER NAME: KWAN CHANG YEW (GUAN ZHENYAO)
 TELEPHONE NO.:
 ADDRESS: 132A HILLVIEW AVENUE #09-06
 Singapore

VEH No.: SCX2220G

Order Date: 26/09/18
 Reg Date: 11/11/14 KM: 78,020
 VIN NO.: WVVZZZ7N2FV001802 ENGINE NO:
 MODEL: Sharan NF 2.0 TSi (DSG6)+EQP MODEL NO.: 7N14H3

SA: Cheong Pearlyn

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
2	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280
3	B&P ALEX LABOUR LABOUR	2	UNIT	840		1,680
4	B&P ALEX PAINT SPRAY PAINTING	2	UNIT	800		1,600
5	B&P ALEX LABOUR TRANSFER DOOR PARTS	0.5	UNIT	840		420
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
8	7N0843108AL DOOR RHR	1	PCS	2,943.13		2,943.13
9	7N0839718AD SEAL RHR	1	PCS	532.27		532.27
10	7N0845206 WINDOW	1	PCS	402.16		402.16
11	7N0863801 SOUND ABS	2	PCS	3.35		6.70
12	7N0843470C 3Q7 WINDOW ALUMINIUM SEAL RHR OUTER	1	PCS	224.32		224.32
13	1K8837205F GRU DOOR HANDLE RHR	1	PCS	266.01		266.01
14	7N0854950H GRU RHS SLIDING DOOR MLDG	1	PCS	288.40		288.40
15	7N0839886B SUPPORT DOOR HANDLE	1	PCS	122.69		122.69

Remarks : FIRST CAPITAL DIRECT SETTLEMENT

DOA 21.9.2018

SURVEYOR LKK

TP VEHICLE SHD6776P

Handwritten notes:
 CUT out 3/4/18
 266.01
 288.40
 122.69

Service Order Confirmation

SERVICE ORDER NO: 18IP2504
CUSTOMER NO.: CV027081
CUSTOMER NAME: KWAN CHANG YEW (GUAN ZHENYAO)
TELEPHONE NO.:
ADDRESS: 132A HILLVIEW AVENUE #09-06
Singapore

VEH No.: SCX2220G

Order Date: 26/09/18
Reg Date: 11/11/14 KM: 78,020
VIN NO.: WVWZZZ7NZFV001802 ENGINE NO:
MODEL: Sharan NF 2.0 TSI (DSG6)+EQP MODEL NO.: 7N14H3

SA: Cheong Pearlyn

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	9,245.68
GST AMOUNT	647.20
TOTAL AMOUNT	9,892.88

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

PDI TUAS

PDI TUAS

KWAN CHANG YEW (GUAN ZHENYAO)
132A HILLVIEW AVENUE
#09-06
Singapore, 669604
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV027081
Quote No. SER/QUO/1801736
QuoteDate 15/10/18
Salesperson Edmund Nai
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan NF 2.0 TSI (DSG6)+EQP	78,020	
License No.	VIN	Initial Registration	Sales Advisor
SCX2220G	WVWZZZ7NZFV001802	11/11/14	Edmund Nai
Engine Code	Labor Type	Engine No.	Model Code
	10	CCZ 447265	7N14H3

SUPPLEMENTARY

No.	Description	Qty.	UoM	Unit Price	Amount
7N0839886B	SUPPORT DOOR HANDLE	1	Pieces	122.69	cra 122.69 (A)
7N0854950H GRU	RHS SLIDING DOOR MLDG	1	Pieces	288.40	cut 288.40 (A)
	Sum Item				411.09

Sum Item **411.09**

Total SGD **411.09**
7% GST 28.78
Total SGD Incl. GST **439.87**

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No..:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017438/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6776P	Veh. Inspected	SCX 2220G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006993MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN SHARAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WWWZZZ7NZFV001802	Colour	BLACK	
Odometer	80017	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2018	Inspection Date	26/09/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCX 2220G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR HANDLE RHR (SN)	CUT	266.01	266.01
1	SEAL RHR (SN)	CUT	532.27	532.27
1	DOOR RHR (SN)	BENT	2,943.13	2,943.13
1	WINDOW ALUMINIUM SEAL RHR (SN)	BENT	224.32	224.32
1	WINDOW ALUMINIUM SEAL RHR (SN)	NOT NECESSARY	63.37	-
1	WINDOW (SN)	CUT	402.16	402.16
1	SOUND ABS (SN)	NECESSARY	6.70	6.70
1	RHS SLIDING DOOR MLDG (ADDITIONAL) (SN)	CUT	288.40	288.40
1	SUPPORT DOOR HANDLE (ADDITIONAL) (SN)	CRACKED	122.69	122.69
			4,849.05	4,785.68
LABOUR				
LABOUR.			2,520.00	1,680.00
TRANSFER DOOR PARTS.			840.00	420.00
SPRAY PAINTING.			2,400.00	1,600.00
PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.			480.00	480.00
CHECK WIRE HARNESS, ECU, S NETT.			280.00	280.00
			6,520.00	4,460.00
GRAND TOTAL			11,369.05	9,245.68
RECOMMENDED COST OF REPAIRS				9,245.68

Report Ref No. CS/FCI18017438/T1td3n2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.