

ASS. REC. BY:

REF:

CS/LPC18017447/At d3ⁿ²

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Gerald poh

of

LPC

Date/Time: 25/9/18 3.28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBE 8491 M

Insured:

GBC17875

at Workshop m/s:

Motoplex

Tel:

6747 6774

of

10 kaki Bkt Rd 2 # 01-24

Policy No:

Claim No: 18/18/18/VC05/020935

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

21/09/2018

27/9/18

R.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS lup

Date/Time:

3.46pm 25/9/18

Person Contacted:

Ah beng

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBC17875 - X

FBE 8491 M - X

Lump Sum \$900 (Cred: 927, 50%)

REF: LPC

ASSIGNMENT

From: Date: 27/09/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBE 8491 M

at Workshop m/s Motoplex

of 10 Kaki Bkt Rd 2 # 01-24 First East Centre

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBE8491M. Yr Regn: 2010 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda. ANF125 c.c 125

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NF125MM50014.16.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90 R17.

R: 90/80 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 27/09/18.

Survey held at: Motoplex

Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Lntec.

RECEIVED 08 JAN 2019

mv
TP 800
Net

Date/Time, File Pass to?

Birtupist

Date/Time, File Return to?

3)

Report Format :

Lump Sum / I.B.I. (\$) 900/-

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) S + RS SI

) Photos

) Other:

TOTAL

350




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC18017447/Atd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-09-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)			
Insured Veh.	GBC 1787S	Veh. Inspected	FBE 8491M
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020935	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	25/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/09/2018	Inspection Date	27/09/2018
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Tuesday, 25 September 2018 3:28 PM
To: assignments
Subject: FW: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: GBC 1787S // Our ref: L.18.1408.It(Ik)
Attachments: 18.1408 PRI.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 25 September 2018 3:20 PM
To: Admin A <admin-a@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Kuru & Co <kurulegal@yahoo.com.sg>
Subject: FW: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: GBC 1787S // Our ref: L.18.1408.It(Ik)

Dear Catherine/Nivitha,

Kindly proceed with the survey as proposed.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: Tuesday, 25 September, 2018 3:01 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: RE: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: GBC 1787S // Our ref: L.18.1408.It(Ik)

Dear Gerald,

Our client is agreeable to the following surveyor(s): **Adrian Ling**

Please arrange for your surveyor to survey our client's vehicle at the following address:

Motoplex Pte Ltd

10 Kaki Bukit Road 2

#01-24 First East Centre

Singapore 417868

Tel: 67476774

Please instruct your surveyor to conduct the pre-repair survey immediately and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Tuesday, 25 September 2018, 2:38:46 PM SGT, GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VC05/020935

Dear Lena,

Please see attached and revert to us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Tuesday, 25 September, 2018 2:08 PM

To: MT_Claim_SG

Subject: PRE-REPAIR INSPECTION NOTIFICATION - Yr ref: GBC 1787S // Our ref: L.18.1408.lt(lk)

Dear Sirs,

ACCIDENT INVOLVING FBE 8491M, GBC 1787S, SGM 7400G AND UNKNOWN ON 21.09.18

AT/ALONG BISHAN ROAD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Wong Kin Yip**, whose vehicle registration number **FBE 8491M** was damaged in the above accident.

A copy of the **Police Report** filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thanks / Rgds,

Lena

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

LKE

No.	Name of Surveyor	Please tick
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Mohammed Rasul	
5	Bryan Ang	
6	Adrian Ling	✓
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	2793I
Vehicle Details	
Vehicle No.:	FBE8491M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	ANF125MSS A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	NF125MME5001416
Chassis No.:	NF125MM5001416
Maximum Power Output:	-
Open Market Value:	\$1,692.00
Original Registration Date:	18 Oct 2010
First Registration Date:	18 Oct 2010
Transfer Count:	3
Actual ARF Paid:	\$254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	17 Oct 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,502.00
COE Rebate Amount:	\$308.00
Total Rebate Amount:	\$308.00

The information contained herein is correct as at 27 Sep 2018

OK

MVA318124180 / VAG - Kaki Bukit
ENTRY DATE & TIME: 25/09/2018 10:54
SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 25/09/2018 16:37

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/09/2018 10:54
Date Of Accident 21/09/2018 16:15
Exact Location Of Accident BISHAN ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBE8491M
Insured/Policyholder
Name Of Registered Owner WONG KIN YIP
NRIC No S0512793I
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96990283
Alternative Phone No OTHERS-96990283

Vehicle Particulars

Manufacturer HONDA
Model ANF125MSS A
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 5097881550
Cover Note Number

Driver

Name of Driver WONG KIN YIP
NRIC No S0512793I
Date Of Birth 10/03/1938
Occupation INDOOR
Date Of Driving Pass 01/07/1965
Driving Experience 53 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96990283
Fax Number
Contact Number OTHERS-96990283
Email Address NOEMAIL

Address BLK 223 #08-135 BISHAN STREET 23
 Postcode 570223
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 4
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name CHANGKAT NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 109 TAMPINES STREET 11 #01-261 , POSTCODE: 521109 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7819999 - FAX NO: 67832722
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20180923/2046

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC1787S
 Vehicle Make/Model/Colour NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD TURBO
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGM7400G
Vehicle Make/Model/Colour SKODA KODIAQ 2.0 TSI 4X4 (A)
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category NA/UNKNOWN
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG KIN YIP
Approximate Age 80
Injuries Sustain
Injured person in which vehicle? FBE8491M
Were seat belts worn? NO
Was this injured conveyed to hospital by ambulance? YES
Address BLK 223 #08-135 BISHAN STREET 23
Postcode 570223

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Wong
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre
 Name: Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN

Refer attached (FBE BH91M)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As Per Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Wong
Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Office
Singapore 415933

Name: Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

4-1-10 (c)

C



1. D - unknown
2. A - FBE-8491-M
3. B - GBC-1787-S
4. C - SGM-7400-G

TP Lon Pac

Denise.

97477223

FBE 8491M

wave 125

Date

No.

Front Fork	\$98 X 2	- \$196	X	N/A NEC
Front wheel	\$160	X	N/A NEC	
Front mudguard	\$38	✓	ut	
Brake lever	\$15	✓	ut	
Balancer	\$10	✓	ut	
handle bar	\$38	✓	Bent	
handle bar Bracket	\$25	✓	Bent	
Front signal RH	\$20	✓	ut	
Front inner side fairing RH	\$40	✓	Dmgd.	
Front outer side fairing RH	\$40	✓	ut	
tail fairing LH	\$45	X	N/A NEC	
tail fairing RH	\$45	X	Repair	
Rear mudguard	\$35	✓	ut	
Front footrest bar	\$38	✓	ut	
Front footrest rubber LH	\$12	X	N/A NEC	
Front footrest rubber RH	\$12	✓	ut	
gear pedal	\$30	X	N/A NEC	
Brake pedal	\$38	✓	ut	
Rear footrest LH	\$20	X	N/A NEC	
Rear footrest RH	\$20	X	N/A NEC	
Rear footrest bracket LH	\$48	X	N/A NEC	
Rear footrest bracket RH	\$48	X	N/A NEC	
Mirror RH	\$38	✓	Bent	
Front no. plate	\$15	✓	Bent	
Rear no. plate	\$28	X	N/A NEC	
Exhaust	\$180	X	N/A NEC	
Exhaust cover	\$45	✓	ut	
Box	\$150	✓	ut	
Box Bracket	\$98	✓	Bent	
Towing X 2	\$40 X 2	- \$80	40.	
Labour	\$300	250		
Spray Painting	\$300.	200.		

UKK Auto Consultants hence notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Repairs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Signature: _____
Date: _____

List: 695
 Len 10%: 625.50
 Labour: 490
 Total: 1115.5
 2/5: 900
 04 days.

2207

U-GRADE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18017447/Atd3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-01-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 1787S	Veh. Inspected	FBE 8491M
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020935	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	25/09/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ANF125	c.c	125
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	NF125MM5001416	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90 R17	WINGS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80 R17	WINGS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/09/2018	Inspection Date	27/09/2018
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 8491M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT FORK @\$98.00	NOT NECESSARY	196.00	-
1	FRONT WHEEL	NOT NECESSARY	160.00	-
1	FRONT MUDGUARD	CUT	38.00	38.00
1	BRAKE LEVER	CUT	15.00	15.00
1	BALANCER	CUT	10.00	10.00
1	HANDLE BAR	BENT	38.00	38.00
1	HANDLE BAR BRACKET	BENT	25.00	25.00
1	FRONT SIGNAL RH	CUT	20.00	20.00
1	FRONT INNER SIDE FAIRING RH	DAMAGED	40.00	40.00
1	FRONT OUTER SIDE FAIRING RH	CUT	40.00	40.00
1	TAIL FAIRING LH	NOT NECESSARY	45.00	-
1	TAIL FAIRING RH	TO REPAIR SEE LABOUR	45.00	-
1	REAR MUDGUARD	CUT	35.00	35.00
1	FRONT FOOTREST BAR	CUT	38.00	38.00
1	FRONT FOOTREST RUBBER LH	NOT NECESSARY	12.00	-
1	FRONT FOOTREST RUBBER RH	CUT	12.00	12.00
1	GEAR PEDAL	NOT NECESSARY	30.00	-
1	BRAKE PEDAL	CUT	38.00	38.00
1	REAR FOOTREST LH	NOT NECESSARY	20.00	-
1	REAR FOOTREST RH	NOT NECESSARY	20.00	-
1	REAR FOOTREST BRACKET LH	NOT NECESSARY	48.00	-
1	REAR FOOTREST BRACKET RH	NOT NECESSARY	48.00	-
1	MIRROR RH	CUT	38.00	38.00
1	FRONT NO PLATE	BENT	15.00	15.00
1	REAR NO PLATE	NOT NECESSARY	28.00	-
1	EXHAUST	NOT NECESSARY	180.00	-
1	EXHAUST COVER	CUT	45.00	45.00
1	BOX	CUT	150.00	150.00
1	BOX BRACKET	BENT	98.00	98.00
	LESS 10% DISCOUNT		-	-69.50
			1,527.00	625.50
LABOUR				
	TOWING.		80.00	40.00

Report Ref No. CS/LPC18017447/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR.INCLUSIVE OF THE REPAIR OF TAIL FAIRING RH. SPRAY PAINTING.		300.00	250.00
			300.00	200.00
			680.00	490.00
	GRAND TOTAL		2,207.00	1,115.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CS/LPC18017447/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.