

ASS. REC. BY:

REF

CS3/MSG18017463/Grd302

Special Instruction:

Surveyor  
MeimienQuo Orange  
Monica Chung

## ASSIGNMENT (Office)

From (Person):

of

MSIG

Date/Time:

25/9/18 @ 2:47pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 3880 R

Insured:

SGN 7208 R

at Workshop m/s

EM Solution

Tel:

6456 0226

of

160 Sin Ming Drive #03-19

Policy No:

A80 448262 QMX

Claim No:

571155

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/09/18

CA / REV / REP. / REV 24 HRS

1up?

26/9/18

H.O.D. Endorsement:

Date/Time:

5:27pm @ 25/9/18

Person Contacted:

Josephine

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 3880 R - X
	SGN 7208 R - X
	Dismantle: 27/9/2018

PRS  
Xel.

REF: MS16

6392B - /

(-2019)

30 Sep 2009

ASSIGNMENT

From: Date: 26/9/18

Estimated Cost:

OD ☒ TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 3880R

at Workshop m/s

EM solution

of

160 Sin Ming Drive # 03-19

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$18K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN3880R

Yr Regn:

30 Sep 2009

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

1.6

c.c. 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

110086

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

IM6BL10Z1A.011442

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

apollo

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26-09-18

Survey held at

W/S

1220pm

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The ☒ Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

Date/Time, File Pass to?

☐  
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

120

Transportation:

) S + RS. SI

) Photos

) Others

10

TOTAL

130

Report Format: PRS

Lump Sum / I.B.I. (\$)

Add Fee:

☐  
☐  
☐  
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG18017463/Gcd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 25-09-2018	
			Code : MSG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SGN 7208R	Veh. Inspected	SLN 3880R	
Policy No.	A80448262QMX	Coverage (\$)	0.00	
Claim No.	571155	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	25/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	21/09/2018	Inspection Date		
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018 09:56		25 Sep 2018 14:47 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN, PUAY HUEI, ID: S1568821A		
Main Claimant:	LEE YAN YI, ID: S9016392B		
Vehicle Reg. No.:	SLN3880R	Date of Loss:	21/09/2018 18:00 - :59 [107 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 571155	Policy/Cover Note No.:	A80448262QMX (Comprehensive) Coverage: 27/11/2017 - 26/11/2018
Vehicle Reg. No. (Insured):	SGN7208R	Policy No. (Claimant):	
		Excess:	
Repairer:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/09/2018]		
Driver/Custodian (Insured):	TAN, PUAY HUEI (56 / Male), NRIC: S1568821A		
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. LIAB 50/50%. Pls contact Tel: 6456 0226 - Bernard		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6392B
Vehicle Details	
Vehicle No.:	SLN3880R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN LUX
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	Z6808716
Chassis No.:	JM6BL10Z1A0114421
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$21,324.00
Original Registration Date:	30 Sep 2009
First Registration Date:	30 Sep 2009
Transfer Count:	2
Actual ARF Paid:	\$21,324.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2019
PARF Rebate Amount:	\$11,728.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,589.00
COE Rebate Amount:	\$1,567.00
<b>Total Rebate Amount:</b>	<b>\$13,295.00</b>

The information contained herein is correct as at 27 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/09/2018 17:46
Date Of Accident	21/09/2018 18:00
Exact Location Of Accident	JURONG EAST AVENUE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN3880R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE YAN YI
NRIC No	S9016392B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91850625
Alternative Phone No	OFFICE-91850625

### Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097442722
Cover Note Number	

### Driver

Name of Driver	LEE YAN YI
NRIC No	S9016392B
Date Of Birth	14/05/1990
Occupation	INDOOR
Date Of Driving Pass	10/03/2009
Driving Experience	9 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91850625
Fax Number	
Contact Number	OFFICE-91850625
EMail Address	NOEMAIL

Address	BLK 530 JURONG WEST STREET 52 #08-395
Postcode	640530
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SABRINA GENDER: : FEMALE
Passenger 2	NAME: : SU MING GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	<b>ROAD:</b> 700 CORPORATION ROAD , <b>POSTCODE:</b> 649818 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO: - FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN7208R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	LEE YAN YI
Approximate Age	
Injuries Sustain	REFER REPORT
Injured person in which vehicle?	SLN3880R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	




**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Attached Police Report NO: T/20180921/2197

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180921/2197

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

1 of 3

Report No. T/20180921/2197

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/09/2018 20:35	Vide Report No.:	Station Diary No.: 184
--	------------------	---------------------------

Informant's Particulars				
Name of Informant: LEE YAN YI			Address: APT BLK 530 JURONG WEST STREET 52 #08-395 SINGAPORE 640530	
ID Type / ID No.: NRIC NO / S9016392B			Contact No.: Home/Office: Mobile: 91850625	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Female	Age: 28	Date of Birth: 14/05/1990	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Accountant			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/09/2018 18:00	Type of Location: T-Junction
Location: Along Road 1 JURONG EAST AVENUE 1  near to the Mayfair Condominium				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGN7208R	Car	TOYOTA		Black	Slightly Damaged	1
SLN3880R	Car	MAZDA	MAZDA3 1.6L SDN	Silver	Seriously Damaged	2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLN3880R	NTUC Income Insurance Co-Operative Limited	5097442722	22/01/2018	21/01/2019



**SINGAPORE  
POLICE FORCE**



T/20180921/2197

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

2 of 3

Report No. T/20180921/2197

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEE YAN YI	ID No.	S9016392B
Related Vehicle	SLN3880R (Car)	Contact No.	91850625
Hospital/Clinic	ICON MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	21/09/2018	Date Discharge	21/09/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL

**Brief Details.**

On 21/09/2018 at about 1800hrs, I was driving SLN3880R with 02 passengers along Jurong East Ave 1 center lane towards Jurong West Ave 1 which consist of 03 lanes . While driving straight, I noticed a vehicle SGN7208R driving at the extreme right lane and the vehicle is driving coming closer towards my lane. I tried to avoid to the left however the vehicle still side swipe the right side of my vehicle. After the accident, both the driver exchange our particulars and left. At that point of time both my passengers informed that they are not in pain.

On 21/09/2018 at about 1830hrs, I felt pain on my right arm and went to seek treatment and was given 03 days of MC. Both of our vehicles are installed with in car camera.

Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180921/2197

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

3 of 3

Report No. T/20180921/2197

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 DESMOND CHIA WEN FENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/09/2018 20:35

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

SN 120

Classification Of Case:

Authentication Stamp

NP168






































### ...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018 09:56		25 Sep 2018 14:47 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>TAN, PUAY HUEI</b> , ID: S1568821A								
Main Claimant:	<b>LEE YAN YI</b> , ID: S9016392B								
Vehicle Reg. No.:	<b>SLN3880R</b>	Date of Loss:	21/09/2018 18:00 - :59 [107 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 571155</b>	Policy/Cover Note No.:	A80448262QMX (Comprehensive) Coverage: 27/11/2017 - 26/11/2018						
Vehicle Reg. No. (Insured):	<b>SGN7208R</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Em Solution Pte Ltd (160 Sin Ming) (HQ)</b> 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 26/09/2018]								
Driver/Custodian (Insured):	TAN, PUAY HUEI (56 / Male), NRIC: S1568821A								
Adj Asg. Remarks:	SJE DISAGREE APPOINT LKK. LIAB 50/50%. Pls contact Tel: 6456 0226 - Bernard								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLN3880R (571155)  
[SGN7208R]  
TP  
LEE YAN YI  
Sep 21 2018 6:00PM  
[TAN, PUAY HUEI]  
Em Solution Pte Ltd (160 Sin Ming)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
2	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
3	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
4	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
5	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
6	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
7	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
8	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
9	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
10	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
11	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
12	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
13	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
14	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
15	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
16	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
17	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
18	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
19	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
20	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
21	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
22	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
23	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
24	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
25	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
26	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
27	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
28	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
29	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
30	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
31	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
32	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
33	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
34	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
35	01/10/18 11:10	General View		Load JPG	<input checked="" type="checkbox"/>					
36	01/10/18 11:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
37	01/10/18 11:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	01/10/18 11:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/18 09:58	OI ACCIDENT REPORT	 Load PDF	
2	25/09/18 09:58	Third Party Accident Report	 Load PDF	
3	25/09/18 12:06	SJE DISAGREE APPOINT LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			



**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017463/GCD3E2

Date: 02/10/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80448262QMX

Claimant Vehicle No: SLN3880R

Insured Vehicle No: SGN7208R

Date of Loss: 21/09/2018

Nature of Claim: TP

Claim No: 571155

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN3880R

Make & Model: MAZDA 3, 1.5 (A)

Engine No: Z6808716

Reg. Date: 30/09/2009 (Man. Year: 2009)

Chassis No: JM6BL10Z1A0114421

Colour: Silver

Odometer: 110086 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: APOLLO 6 mm

Rear Left Side: APOLLO 6 mm

Front Right Side: APOLLO 6 mm

Rear Right Side: APOLLO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 25/09/2018

Date Inspected: 26/09/2018 Inspected At:

Em Solution Pte Ltd (160 Sin Ming) (HQ)  
160 Sin Ming Drive, #03-19 Sin Ming  
Autocity  
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 02 Oct 2018)

**Parts:** 144      MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLN3880R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >