



Your Ref: 18.24757.S.CK.xy

Date: 22nd October 2018

Our Ref: CS3/AXA17004768/Gqbs2-1

M/s AXA Insurance Pte Ltd

c/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GQ 9226J
INSURED VEHICLE: SKS 3438X
ACCIDENT DATE: 26/02/2017**

We thank you for your instruction on 25/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GQ 9226J from M/s CarLink Consultancy.
- b) Final Repair Bill of GQ 9226J from M/s N-51 Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles GQ 9226J and SKS 3438X.
- d) Colour damaged vehicle photographs of GQ 9226J.

Pre-Repair Inspection Date : 09/03/2017 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GQ 9226J
Make & Model	: Nissan Cabstar
Year of Registration	: 1999
Chassis Number	: JN1SFAF23Z0001721
Engine Capacity	: 3153 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.