

ASS. REC. BY:

REF: CS3/CTI180/7469/TIC d3^{sr} Special Instruction:Surveyor
Meiimen

From (Person):

Taufik
Irene tay

ASSIGNMENT (Office)

of CTI

Date/Time: 25/9/18 @ 3:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 8349G

Insured:

GBF 386G

at Workshop m/s

Bak Heng Motor

Tel:

9788 8579

of

5032, AMK Ind. park 2 # 01-291

Policy No:

DMCVSN3032401800

Claim No:

SNM18D04606C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/09/18

28/9/18 Morning

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

26/9/18 @ 25/9/18

Person Contacted:

Cindy

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

GBG 8349G - X

GBF 386G - CS/CTI18010825/Nrd3n2

DoA: 11/6/18

26/9/18 - VNI

Demandk: 28/9/2018

Signature: *Tamplin*

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GRG 83496 Yr Regn: 2017 Nov
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Tata Dylux c.c. 2482
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 38713 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT.35480K209171
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/75R15
 R: 155/R.2
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. _____ D.O.I. 28/9/18
 Survey held at Bak Hong Mnt
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$4800 - \$6,000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) \$ = RS. \$

) Photos

) Others

TOTAL

Report Format : PR8

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Signature
 10/10/2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018		25 Sep 2018 15:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	YAHONG ENGINEERING PTE LTD, Co. Reg. No.: 201216884H		
Main Claimant:	YLK CONSTRUCTION PTE LTD, Co. Reg. No.: 200710462W		
Vehicle Reg. No.:	GBG8349G	Date of Loss:	21/09/2018 19:00 - :59
Claim Type:	TP / SNM18D04605C02	Policy/Cover Note No.:	DMCVSN3032401800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF386G	Policy No. (Claimant):	5095371417
		Excess:	S\$0.00
Repairer:	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291, 569535 Ang Mo Kio - Tel: 9788 8579		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/10/2018]		
Driver/Custodian (Insured):	CHIU KAI MING (67 / Male), NRIC: S2554496Z, Tel: +6590606473		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors Commissioner For Oaths Notary Public

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/18
MANHATTAN HOUSE
SINGAPORE 160876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tcmg.com.sg

Our Ref : TCMG/GBG8349G/0918/BHM

Your Ref : GBF 386 G

24 September 2018

BY FAX NO. 6222 1033 ONLY

M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **M/s YLK Construction Pte Ltd**, the owner and/or driver of motor vehicle no. **GBG 8349 G**, which was involved in an accident along Woodlands Avenue 12 towards SLE/BKE on 21 September 2018 at 19:00 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **GBF 386 G** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Bak Heng Motor Repairing, (5032 #01-291, AMK Industrial Park 2, Singapore 569535 - Kelvin @ 9788 8579).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,

**MR LING LEONG HUI**

cc. M/s Bak Heng Motor
(Yref: GBG8349G)

BY FAX NO. 6481 6820 ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/09/2018 11:49
Date Of Accident	21/09/2018 19:00
Exact Location Of Accident	WOODLANDS AVE 12 TOWARDS SLE/BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8349G
Insured/Policyholder	
Name Of Registered Owner	YLK CONSTRUCTION PTE LTD
Co Reg No	200710462W
Email Address	ADMIN@YLK.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64568976

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095371417
Cover Note Number	09/11/2017 TO 08/11/2018

Driver

Name of Driver	TAN ZHEN QIANG
NRIC No	S9141500C
Date Of Birth	13/11/1991
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98226878
Fax Number	
Contact Number	
Email Address	NOEMAIL

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 24/09/2018 12:05pm



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0462W
Vehicle Details	
Vehicle No.:	GBG8349G
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2751805
Chassis No.:	JTFAT35Y80K209171
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,832.00
COE Rebate Amount:	\$32,577.00
Total Rebate Amount:	\$32,577.00

The information contained herein is correct as at 09 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2018		25 Sep 2018 15:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YAHONG ENGINEERING PTE LTD, Co. Reg. No.: 201216884H		
Main Claimant:	YLK CONSTRUCTION PTE LTD, Co. Reg. No.: 200710462W		
Vehicle Reg. No.:	GBG8349G	Date of Loss:	21/09/2018 19:00 - :59 [10 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04605C02	Policy/Cover Note No.:	DMCVSN3032401800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF386G	Policy No. (Claimant):	5095371417
		Excess:	S\$0.00
Repairer:	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291, 569535 Ang Mo Kio - Tel: 9788 8579		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/10/2018]		
Driver/Custodian (Insured):	CHIU KAI MING (67 / Male), NRIC: S2554496Z, Tel: +6590606473		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBG8349G (SNM18D04605C02)**
[GBF386G]
TP
YLK CONSTRUCTION PTE LTD
Sep 21 2018 7:00PM
[YAHONG ENGINEERING PTE LTD]
Bak Heng Motor Repairing

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:14	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	24/09/18 12:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/10/18 19:04	General View	Load PDF	
2	09/10/18 19:12	Photographs of Damaged Parts	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:14	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	24/09/18 12:14	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
3	24/09/18 12:14	certificate of insurance [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/18 15:56	PRS	Load PDF	
2	25/09/18 15:56	OI GIA	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:14	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	24/09/18 12:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/09/18 12:14	Accident Sketch Plan	 Load TIF	
2	24/09/18 12:14	Accident Sketch Plan	 Load TIF	
3	24/09/18 12:14	certificate of insurance	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017469/T1CD3S2

Date: 17/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3032401800
Claimant Vehicle No :	GBG8349G	Insured Vehicle No :	GBF386G
Date of Loss:	21/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04605C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8349G	Engine No:	1KD2751805
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y80K209171
Reg. Date:	13/11/2017 (Man. Year: 2017)	Odometer:	38713 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/09/2018	
Date Inspected:	28/09/2018	Inspected At: Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291 Singapore 569535
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 Oct 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG8349G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >