



Your Ref: 18.25138 PD-O

Date: 08th January 2019

Our Ref: CS3/ASM18014467/Gpa3s2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJS 6991G
INSURED VEHICLE: SDY 9911H
ACCIDENT DATE: 04/08/2018**

We thank you for your instruction on 25/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 6991G from M/s Prominent Appraiser Services Pte Ltd.
- b) Final Repair Bill of SJS 6991G from M/s Kum Chew Motor Workshop.
- c) Singapore Accident Statement of Vehicle SJS 6991G.
- d) Colour damaged vehicle photographs of SJS 6991G.

Pre-Repair Inspection Date : 08/08/2018 at M/s Kum Chew Motor Workshop, 160 Sin Ming Drive
#05-08 Sin Ming Autocity Singapore 575722.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJS 6991G
Make & Model	: B.M.W 730Li
Year of Registration	: 2013
Chassis Number	: WBAYE22080DZ20932
Engine Capacity	: 2996 cc
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.