

CS3/MSG/8015922/Uq6²⁷
 ASSIGNMENT (Office)
 From (Person) Monica chuney or MSIG Date/Time 25/09/2018
 Estimated Cost _____ Bill to _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No. GBB 4786E Insured GBC 2708P
 at Workshop no. Shuwei Automotive Tel. 6745 2088
 of 1 kcalci Bkt Ave 6 # 01-28
 Policy No. B29069129 MKF Claim No. 568746
 Sum Insured _____ Excess _____
 Make of Veh _____ DOA 29/8/18
 (Client's Record)
 CA / REV / REP. / REV 24 HRS up
 Date/Time 30/8/18 @ 5pm Person Contacted Sally H.O.D. Endorsement _____
 Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	DO NOT finalize
	GBB 4786E - CS/TP/7015642/Ur bn 2	DOA: 3/8/17
	GBC 2708P - X	
31/8/18	Turned in.	

28/9/18 Sumit L/S @ 2000 Hdy.
 Cred \$40, (7%)

RECEIVED 04 OCT 2018


 28/9/2018

REF:

MS6

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 6BB4786E

at Workshop m/s: BlueL Automotive

of 1 Kaki Bukit Ave 6 #01-22

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

31/8/2018

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 2 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or M /

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 29/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRE. NO OFFICE. UA 326

2500 - 4/6

19/8 submit PRE report

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S - RS - SI

) Photos

) Other

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) :

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

120

10

130

...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:02 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Gardenia Foods (S) Pte Ltd, Co. Reg. No.: 197801714R								
Main Claimant:	AIMS INSPECTION & TESTING SERVICES PTE.LTD, Co. Reg. No.: NA								
Vehicle Reg. No.:	GBB4786E	Date of Loss:	29/08/2018 08:00 - :59 [112 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 568746	Policy/Cover Note No.:	B29069129MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	GBC2708P	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwei Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/09/2018]								
Driver/Custodian (Insured):	WONG TEE JEE (64 / Male), NRIC: S0208776F								
Adj Asg. Remarks:	SJE DISAGREE ASSIGN LKK. PLS CONTACT SALLY @ 6745 2088. LIAB - 100%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (25/09/2018): Report Send Back Alerts - GBB4786E (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

M NEDUMARAN & CO

UEN NO. 53181067D

Advocates & Solicitors
Commissioner for Oaths



Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Branch Office: No. 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg

Our Ref : MN.IG.B1.1812613.st
Your Ref : GBC 2708P

19th September 2018

MSIG INSURANCE (SINGAPORE) PTE.LTD
4 Shenton Way
#21/23-01, SGX Centre 2
Singapore 068807

GARDENIA FOODS (S) PTE LTD
224 Pandan Loop
Singapore 128411

Dear Sir,

CLAIMANT : AIMS INSPECTION & TESTING SERVICES PTE LTD
ACCIDENT ON 29/08/2018 INVOLVING VEHICLES NO. GBB 4786E AND GBC 2708P ALONG AYE
EXITING NORMANTON PARK AT ABOUT 0850 HOURS

We act for AIMS INSPECTION & TESTING SERVICES PTE LTD, who was the owners of vehicle no. GBB 4786E.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 29/8/2018 ALONG AYE EXITING NORMANTON PARK involving our client's vehicle registration number GBB 4786E and vehicle registration number GBC 2708P driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01. Cost of Repair (inclusive of GST)	S\$ 2,568.00
02. Loss of Use for 4 days @ \$120.00 per day	S\$ 480.00
03. Pre-Repair Survey Loss of Use for 2 days	S\$ 240.00
04. Survey report fee	S\$ 548.00
05. GIA search/report & LTA search fees	S\$ 36.49
06. Costs & Incidentals	S\$ 1,060.00
	<u>S\$ 4,932.49</u>

"WITHOUT PREJUDICE"
BY HAND

CERTIFICATE OF POSTING
(for your information only)

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

Page 2

Our Ref : MN.IG.B1.1812613.st

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of GBB 4786E;
- (b) LTA Search;
- (c) Certificate of Insurance;
- (d) Enquire transfer fee;
- (e) Final Repair Bill;
- (f) Surveyor's report & invoice and
- (g) **68 black and white photographs** depicting the damages to motor vehicle GBB 4786E.
[coloured-print photos will be forwarded to insurance company upon request]

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that a Notice of accident dated 29th August 2018 was sent to your insurers. A pre-repair survey on our client's damaged vehicle was carried out by your insurer's appointed surveyor on 31/8/2018 and 1/9/2018.

Please also note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

M NEDUMARAN & CO

NEDUMARAN MUTHUKRISHNAN
(Branch Office)

Encls

cc. Client (By Fax 6841-2088 Only) – GBB 4786E

Enquire Vehicle & Owner Information (Vehicle No. GBC2708P As At 29 Aug 2018 / 08:50:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: B1.1812613

Current Owner Details

Owner ID Type: Company

Owner ID: 197801714R

Owner Name: GARDENIA FOODS (S) PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 224

Registered Street Name: PANDAN LOOP

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 128411

Current Vehicle Details

Vehicle No.: GBC2708P

Make Description/Model: NISSAN / URVAN 3.0 5MT ABS AB 5DR LWB PANEL

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD



Thank you

Lim Hwee Peng has successfully logged out.

Your last login date and time was 29 Aug 2018, 15:43:21.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (\$)	Log Date/Time
1	Vehicle	GBC2708P	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	29 Aug 2018 / 15:44:08

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.: GBB4786E
Vehicle Type: A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal
Vehicle Make: CITROEN
Vehicle Model: BERLINGO 1.6 M/T ABS AIRBAG 2WD 6DR
Chassis No.: VF77E9HXC67031161
Propellant: Diesel
Engine No.: 10JBCB0007616
Engine Capacity: 1560 cc
Maximum Power Output: -
Maximum Laden Weight: 2130 kg
Unladen Weight: 1500 kg
Year Of Manufacture: 2008
Original Registration Date: 13 Apr 2009
Lifespan Expiry Date: 12 Apr 2029
COE Category: C - Goods Vehicle & Bus
Quota Premium: \$5,300.00
COE Expiry Date: 12 Apr 2019
Road Tax Expiry Date: 12 Oct 2018
Inspection Due Date: 12 Apr 2019
Intended Transfer Date: 29 Aug 2018
CO2 Emission: -
CO Emission: -
HC Emission: -
NOx Emission: -
PM Emission: -

The current road tax expiry is 12 Oct 2018. You may renew the road tax from 13 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 12 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 13 Oct 2018 to 12 Apr 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	3.00	-	3.00
Total Amount Payable:			28.00
Message			

This vehicle has a road tax Over Payment of \$51.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Company) of AIMS INSPECTION & TESTING SERVICES PTE. LTD.
(201708085R)

Date: 23/03/2017

The Following Are The Brief Particulars of :

Registration No. : 201708085R
Company Name. : AIMS INSPECTION & TESTING SERVICES PTE. LTD.
Former Name if any :
Incorporation Date. : 23/03/2017
Company Type : EXEMPT PRIVATE COMPANY LIMITED BY SHARES
Status : Live Company
Status Date : 23/03/2017

Principal Activities

Activities (I) : BUILDING AND REPAIRING OF SHIPS, TANKERS AND OTHER OCEAN-GOING VESSELS
(INCLUDING CONVERSION OF SHIPS INTO OFF-SHORE STRUCTURES) (30110)
Description :
Activities (II) : PROCESS AND INDUSTRIAL PLANT ENGINEERING DESIGN AND CONSULTANCY
SERVICES (71122)
Description :

Capital

Issued Share Capital (AMOUNT)	Number of Shares *	Currency	Share Type
1000	1000	SINGAPORE, DOLLARS	ORDINARY

* Number of Shares includes number of Treasury Shares

Paid-Up Capital (AMOUNT)	Number of Shares	Currency	Share Type
1000		SINGAPORE, DOLLARS	ORDINARY

COMPANY HAS THE FOLLOWING ORDINARY SHARES HELD AS TREASURY SHARES

Number Of Shares	Currency
------------------	----------

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT, THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Company) of AIMS INSPECTION & TESTING SERVICES PTE. LTD.
(201708085R)

Date: 23/03/2017

Shareholder(s)

Name	ID	Nationality/Place of Incorporation/Origin	Source of Address	Address Changed
Address				
1 KAKARLAPUDI VENKATA MADHAVA VARMA	S6967577H	INDIAN	OSCARS	03/03/2017
236 WESTWOOD AVENUE #10-37 THE FLORAVALE SINGAPORE (648362)				
Ordinary(Number)	Currency			
700	SINGAPORE, DOLLARS			
2 KOLA VENKATARAMANA	S7962332F	INDIAN	OSCARS	18/07/2016
836 JURONG WEST STREET 81 #05-61 SINGAPORE (640836)				
Ordinary(Number)	Currency			
300	SINGAPORE, DOLLARS			

Abbreviation

UL - Local Entity not registered with ACRA

.F - Foreign Entity not registered with ACRA

AR - Annual Return

AGM - Annual General Meeting

A/C - Accounts

OSCARS - One Stop Change of Address Reporting Service by Immigration & Checkpoint Authority.

PLEASE NOTE THAT INFORMATION HEREIN CONTAINED IS EXTRACTED FROM FORMS/TRANSACTIONS FILED WITH THE AUTHORITY

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N



EQ Motor Cover Note

ORIGINAL

Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third Party Risks and Compensation) Rules 1960
Road Transport Act 1987 (Malaysia)
Motor Vehicles (Third Party Risks and Compensation) Rules 1959 (Malaysia)

Whereas the Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE


Agent / Broker Code:	A000342		
Policy No.		Cover Note no.:	41450
Name of Insured	AIMS INSPECTION & TESTING SERVICES PTE LTD		
Registration Number	GBB4786E		
Make / Model	Citroen Berlingo 1.6 m/T ABS AIRBAG 2W		
Year of Registration	2009		
Cubic Capacity	0.63 ton		
Engine Number	10JBCB 0007616		
Chassis Number	VF77EQHXC67031161		
Cover Type	Comprehensive		
Value	Market Value		
Period of Insurance	From:	(Time: 12 am/pm)	To: 12/10/2018
Hire Purchase Company	Abwin Pte Ltd		
Excess	\$500		
Type Of Plan	<input checked="" type="checkbox"/> Classic <input type="checkbox"/> Premier		

We hereby certify that this Cover Note is issued in accordance with the provisions of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless counter-signed by Authorised Agent		EQ Insurance Company Limited
ABWIN PTE LTD 8 KAKI BUKIT ROAD 2 RUBY WAREHOUSE COMPLEX #01-33 SINGAPORE 417841 TEL: 6042 3332 FAX: 6042 3301 (ADMIN OFFICE)		 Authorised Signatory
Signature / Date	15/5/2018	

Important Notice:

- This Cover Note is valid for 30 days from the first day of the Policy Period.
- Premium Warranty (for Individual Customers): Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7962332F



Name

KOLA VENKATARAMANA

Race

INDIAN

Date of birth

15-09-1979

Sex

M

Country of birth

INDIA



0178778



NRIC No. S7962332F

Nationality

INDIAN

Date of issue

07-09-2012

APT BLK 836 JURONG WEST STREET 61 #05-61
SINGAPORE 640836

NRIC No: S7962332F

Date: 18/07/2018



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Vehicle No : GBB 4786 E Date : 13-Sep-18
Make/Model : Citroen Berlingo
Name : Aims Inspection & Testing Services Pte Ltd
Address : c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

QTY	ITEM	AMT (\$)
-----	------	----------

Lump sum repair costs	\$	2,400.00
GST 7 %	\$	168.00
Grand-total	\$	2,568.00

Dollars : Two Thousand Five Hundred And Sixty Eight Only

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Billing Name & Address

Aims Inspection & Testing Services Pte Ltd
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Invoice No 18027-08/AY

Date 13 Sep 2018

Vehicle No : GBB 4786 E

Model : Citroen Berlingo

Item	Descriptions	Amount S\$
1	Date of inspection : <u>31 Aug 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>68</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 548.00</u>
	SDLS : FIVE HUNDRED AND FORTY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 18027-08/AY / 2018
Date of Report : 13 Sep 2018

Aims Inspection & Testing Services Pte Ltd
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 29 Aug 2018

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **31 Aug 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **GBB 4786 E**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: GBB 4786 E	Engine No	: 10JBCB0007616
Model	: Citroen Berlingo	Mileage	: 183063
Year / Capacity	: 2009/1560	Colour	: Black
Chassis No	: VF77E9HXC67031161		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 195/65 R15	Nexen	6.00 mm	Normal
REAR O/S	: 195/65 R15	Nexen	6.00 mm	Normal
FRONT N/S	: 195/65 R15	Nexen	6.00 mm	Normal
REAR N/S	: 195/65 R15	Nexen	6.00 mm	Normal



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 4 working days to complete.
5. Enclosed number of photograph : 68 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: GBB 4786 E
Report No: TP/ 18027-08/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear bumper	Damage	\$ 948.70	\$ 948.70 ✓
1	Rear bumper reinforcement	Damage	\$ 488.90	\$ 488.90 ✓
2	Rear bumper side retainers	Damage	\$ 275.92	\$ 275.92 ✓
1	Rear door rubber	Necessary	\$ 148.00	\$ 148.00 X
1	Rear end panel	Repair	\$ 475.00	\$ 1861.52 X
			\$ 2336.52	\$ 1861.52
	Discount	10.0%	\$ 233.65	\$ 186.15
			\$ 2102.87	\$ 1675.37
<u>Special Nett Items</u>				
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00 200
			\$ 280.00	\$ 280.00

1713.52
1542.66

Spare Parts Total \$ 2382.87 \$ 1955.37

Vehicle No: **GBB 4786 E**
Report No: **TP/ 18027-08/AY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 2382.87	\$ 1955.37
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 50.00	\$ 30.00 ✓
2	To remove and refit rear bumper sensor.	\$ 100.00	\$ 80.00 10
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 440.00 380
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 440.00 300
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 11 30.00 x
Total		\$ 4482.87	\$ 2975.37

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 2400.00

SDLS: TWO THOUSAND FOUR HUNDRED ONLY


Qualified/Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018		30 Aug 2018 15:02 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Gardenia Foods (S) Pte Ltd, Co. Reg. No.: 197801714R	
Main Claimant:	AIMS INSPECTION & TESTING SERVICES PTE.LTD, Co. Reg. No.: NA	
Vehicle Reg. No.:	GBB4786E	Date of Loss: 29/08/2018 08:00 - :59 [112 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568746	Policy/Cover Note No.: B29069129MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	GBC2708P	Policy No. (Claimant):
		Excess:
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/09/2018]	
Driver/Custodian (Insured):	WONG TEE JEE (64 / Male), NRIC: S0208776F	
Adj Asg. Remarks:	SJE DISAGREE ASSIGN LKK. PLS CONTACT SALLY @ 6745 2088. LIAB - 100%	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (25/09/2018): Report Send Back Alerts - GBB4786E (TP) 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Aug 2018		30 Aug 2018 15:02 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Gardenia Foods (S) Pte Ltd, Co. Reg. No.: 197801714R	
Main Claimant:	AIMS INSPECTION & TESTING SERVICES PTE.LTD, Co. Reg. No.: NA	
Vehicle Reg. No.:	GBB4786E	Date of Loss: 29/08/2018 08:00 - :59 [112 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 568746	Policy/Cover Note No.: B29069129MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	GBC2708P	Policy No. (Claimant):
		Excess:
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/09/2018]	
Driver/Custodian (Insured):	WONG TEE JEE (64 / Male), NRIC: S0208776F	
Adj Asg. Remarks:	SJE DISAGREE ASSIGN LKK. PLS CONTACT SALLY @ 6745 2088. LIAB - 100%	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (25/09/2018): Report Send Back Alerts - GBB4786E (TP) 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*GBB4786E (568746)

[GBC2708P]

TP

AIMS INSPECTION & TESTING SERVICES PTE.LTD

Aug 29 2018 8:00AM

[Gardenia Foods (S) Pte Ltd]

























Bluwel Automotive Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	30/08/18 09:57	Accident Statement <small>From: SC - Reg. No: GBC2708P, Claimant: GARDENIA FOODS (S) PTE LTD</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	31/08/18 14:35	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>	
2	31/08/18 14:35	Chassis Number	Load JPG	<input checked="" type="checkbox"/>	
3	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
4	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
5	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
6	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
7	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
8	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
9	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
10	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
11	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
12	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
13	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
14	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
15	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
16	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
17	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
18	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
19	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
20	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
21	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
22	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
23	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
24	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
25	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
26	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
27	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
28	31/08/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>	
29	31/08/18 14:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
30	31/08/18 14:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
31	31/08/18 14:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
32	31/08/18 14:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
33	31/08/18 14:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	31/08/18 14:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	07/09/18 09:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	07/09/18 09:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/18 09:57	PRI From:SC - Reg. No: GBC2708P, Claimant: GARDENIA FOODS (S) PTE LTD	 Load PDF	
2	30/08/18 09:57	Third Party Accident Report	 Load PDF	
3	30/08/18 10:02	Arrange Surveyor	 Load PDF	
4	30/08/18 10:27	SJE DISAGREE LKK	 Load PDF	
5	20/09/18 10:07	COLOURED SURVEY PHOTOS	 Load PDF	
6	22/09/18 12:31	LOD, GIA SEARCH, DRIVING LISCENCE, REPAIR BILL, SURVEY REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 15:05	PRS Invoice	 Load PDF	
2	05/10/18 15:07	COLOUR PHOTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015922/UQBE2-1

Date: 05/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29069129MKF
Claimant Vehicle No : GBB4786E **Insured Vehicle No :** GBC2708P
 Date of Loss: 29/08/2018 Nature of Claim: TP Claim No: 568746

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB4786E**
 Make & Model: CITROEN BERLINGO, 1.6 (A) Engine No: 10JBCB0007616
 Reg. Date: 13/04/2009 (Man. Year: 2008) Chassis No: VF77E9HXC67031161
 Colour: Black Odometer: 183063 km
 Engine Capacity: 1560 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,382.87	1,742.17	640.70	26.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	760.00	1,340.00	63.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,482.87	2,502.17	1,980.70	44.18
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,482.87	2,000.00	2,482.87	55.39
+ GST 7.00/7.00% (S\$)	313.80	140.00	173.80	55.39
Nett Amount (S\$)	4,796.67	2,140.00	2,656.67	55.39

INSPECTION

Date of Assignment: 30/08/2018
 Date Inspected: 31/08/2018 Inspected At: Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2018)
Parts:	M1-MPV	CITROEN BERLINGO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB4786E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	948.70 FL	*948.70 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	488.90 FL	*488.90 FL
3	2		*REAR BUMPER SIDE RETAINERS	Cracked	275.92 FL	*275.92 FL
4	1		*REAR DOOR RUBBER	Not Necessary	148.00 FL	*- FL
5	1		*REAR END PANEL	Repair	475.00 FL	*- FL
6	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,616.52	1,913.52
- List Item Discount on L Items 10.00/10.00% (\$\$)	233.65	171.35
Total Parts (\$\$)	2,382.87	1,742.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	30.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	900.00	380.00
4	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	900.00	300.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	0.00
Gross Labour Cost (\$\$)			2,100.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >