



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                        |                 |                               |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|-----------------|-------------------------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                        |                 | Ref : CC4/LPC18017488/R1ha3q2 |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE<br>199555                                                                           |                                                                                        |                 | Date : 22-07-2019             |  |
|                                                                                                                                        |                                                                                        |                 | Code : LPC2                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                        |                 |                               |                                                                                     |
| Insured Veh.                                                                                                                           | YN 1038R                                                                               | Veh. Inspected  | YP 2792D                      |                                                                                     |
| Policy No.                                                                                                                             | Z/18/VC10/102151-001                                                                   | Coverage (\$)   | 0.00                          |                                                                                     |
| Claim No.                                                                                                                              | 17/18/18/VC10/020937                                                                   | Excess (\$)     | 0.00                          |                                                                                     |
| Assign From                                                                                                                            |                                                                                        | Assign Date     | 25/09/2018                    |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                        |                 |                               |                                                                                     |
| Make & Model                                                                                                                           | mitsubishi canter feb71                                                                | c.c             | 2998                          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                 | Year of Reg.    | 2016                          |                                                                                     |
| Chassis No.                                                                                                                            | FEB71EA20217                                                                           | Colour          | RED                           |                                                                                     |
| Odometer                                                                                                                               | 72438                                                                                  | Steering        | IN ORDER                      |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                               | Modification    | NIL                           |                                                                                     |
| General                                                                                                                                | FAIR                                                                                   |                 |                               |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                        |                 |                               |                                                                                     |
|                                                                                                                                        | Size                                                                                   | Make            | Balance                       |                                                                                     |
| R/H Front Tyre                                                                                                                         | 215/75 R17.5                                                                           | BRIDGESTONE     | 7 mm                          |                                                                                     |
| L/H Front Tyre                                                                                                                         | 215/75 R17.5                                                                           | BRIDGESTONE     | 7 mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 215/75 R17.5 (D)                                                                       | BRIDGESTONE     | 7/7 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 215/75 R17.5 (D)                                                                       | BRIDGESTONE     | 7/7 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                        |                 |                               |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                         |                                                                                        |                 |                               |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                        |                 |                               |                                                                                     |
| Accident Date                                                                                                                          | 19/09/2018                                                                             | Inspection Date | 25/09/2018                    |                                                                                     |
| Survey held at                                                                                                                         | SIN SHENG ENGINEERING SERVICES<br>3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129 |                 |                               |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                        |                 |                               |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                        |                 |                               |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                        |                 |                               |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                        | 3 Working Days  |                               |                                                                                     |