

ASS. REC. BY:

REF: CS3/AIG18017504/Acd3e2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AIG

Date/Time:

26/9/18

Estimated Cost:

Bill to:

OD: TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 1462D

Insured:

GR 7700P

at Workshop m/s

Z-one Automotive

Tel:

6634 2112

of

1 Kelki Bldg Ave 6 #01-87

Policy No:

1700059550

Claim No:

805453116856

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:19am @ 26/9/18

Person Contacted:

Nancy

Vehicle:

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBC 1462D - X
	GR 7700P - NA / FC / 15007394/d2
	Disassemble: 27/9/2018

2A: 2/5/15

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC1462D Yr Regn: 2011 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 161085 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH T02PX 00073260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15

R: 195/80R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 26/09/18

Survey held at Z-one

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG PRS.

2/10 Submit DAR report.

MV: 80K

PV: 77K

Nett: 22.3K

Repair days 7

Trim 1/10/18

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 180

2)

Add Fee: ☐ : Site Insp (\$)

Transportation

☐ : Interview (\$)

S + RS, \$

☐ : Tech. Invs (\$)

Photos

☐ : Weekend (\$)

Others

Report Format: DAR

Lump Sum / I.B.I: (\$)

TOTAL

200




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG18017504/Acd3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 26-09-2018		
		Code : AIG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GR 7700P	Veh. Inspected	GBC 1462D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CHIN LEE YING	Assign Date	26/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/09/2018	Inspection Date	26/09/2018	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/9/2018 10:48:21 AM
Attachments:  Z-One - Pre-Repair Notice (AIG)(GBC1462D).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.Z (GBC1462D)
Your Ref: GR7700P

24 September 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6415 3727 & EMAIL

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR
CLAIMANT: CAR (S) PTE LTD
TRAFFIC ACCIDENT ON 22 SEPTEMBER 2018 AT 09:30 HRS ALONG JUNCTION OF TPE
EXIT TO LOYANG AVENUE INVOLVING VEHICLES NO. GBC1462D & GR7700P

We are instructed by Car (S) Pte Ltd to notify you of a road accident on 22 September 2018 at about 09:30 hrs along Junction of TPE Exit to Loyang Avenue involving our clients' vehicle registration number GBC1462D and vehicle registration number GR7700P driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Z-One Automotive Pte Ltd
Address: 1 Kaki Bukit Avenue 6
#01-87/85 Autobay @ Kaki Bukit
Singapore 417883
Contact: Nancy @ 6634 2112

Please liaise with the above workshop directly.

Yours faithfully

CrossBORDERS LLC

Crossborders LLC

Email: corene@crossbordersllc.com /

huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2524Z
Vehicle Details	
Vehicle No.:	GBC1462D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	1KD2094217
Chassis No.:	JTFHT02PX00073260
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	24 Jun 2011
First Registration Date:	24 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,189.00
COE Rebate Amount:	\$7,735.00
Total Rebate Amount:	\$7,735.00

The information contained herein is correct as at 26 Sep 2018

OK

CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOption of any
workshop

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Honda Odyssey With 10 Year New COE.



Upgrade To Pioneer Sound
System, German MAESTRO
Speaker Worth \$3k.
Direct Owner StarAd



**CERTIFIED PRE-OWNED
MERCEDES-BENZ**

[View our cars](#)

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

7 vehicles

Search hiace

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

hiace

Any

Any

2011

Any

Any

Any

Available


☐ Toyota Hiace

\$27,800

\$11,530 /yr

23-Feb-2011

2,982 cc

-

Bus

Available

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 21-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


☐ Toyota Hiace

\$28,800

\$11,920 /yr

25-Feb-2011

2,982 cc

-

Van

Available

Fuel Type: Diesel

Best Selling In Market, Price Negotiable! 1 Owner! Original Condition, Servicing No Repairs Needed, In-House, Welcome Trade In, And Call For Viewing.

ABWIN (1994) Pte Ltd

Posted: 13-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


☐ Toyota Hiace

\$31,800

\$11,600 /yr

24-Jun-2011

2,982 cc

167,500 km

Van

Available

Fuel Type: Diesel

Well Maintained! Engine And Gearbox In Very Mint Condition. Whole Vehicle Is In Pristine Condition! Serviced Regularly. High Loan And Trade In Welcomed! Call Now To Arrange An Appointment To View This...

Car (S) Pte Ltd

Posted: 25-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


☐ Toyota Hiace

\$31,800

\$11,600 /yr

24-Jun-2011

2,982 cc

-

Van

Available

Fuel Type: Diesel

All Wear & Tear Has Been Replaced.

Car (S) Pte Ltd

Posted: 19-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle

**Buying a pre-owned car, but
Unsure of its Condition?**
Get STA Car Evaluation


☐ Toyota Hiace

\$35,800

\$11,410 /yr

15-Nov-2011

2,982 cc

-

Van

Available

Fuel Type: Diesel

1 Owner, Well Maintained By Previous Owner And It's In Tip Top Condition, New Paintwork, Wear And Tear Changed, High Loan And High Trade In Offer, Call Now For Appointment.

ABWIN (1994) Pte Ltd

Posted: 17-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


☐ Toyota Hiace

\$34,800

\$10,810 /yr

15-Dec-2011

2,982 cc

-

Van

Available

Fuel Type: Diesel

1 Owner! Accident Free! One Of The Rarest Black Beauty In The Market. In Mint Condition! No Big Dent At All. Paintwork Is In Original Condition.

Car (S) Pte Ltd

Posted: 19-Sep-2018 Tags: 2011 Toyota Hiace, 2011 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

☐ Toyota Hiace

\$27,800

\$8,580 /yr

22-Dec-2011

2,494 cc

148,000 km

Van

Available

Fuel Type: Diesel

Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Compare [4]

Link One Automobile & Trading

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/09/2018 14:23
Date Of Accident	22/09/2018 09:30
Exact Location Of Accident	TPE EXIT TO LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC1462D
Insured/Policyholder	
Name Of Registered Owner	CAR (S) PTE LTD
Co Reg No	20162524Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85229333

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMTTHQ18-000006
Cover Note Number	

Driver

Name of Driver	CHIN KIM FOOK
NRIC No	S0091320J
Date Of Birth	27/06/1954
Occupation	OUTDOOR
Date Of Driving Pass	29/11/1980
Driving Experience	37 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97477118
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	BLK 247 TAMPINES ST 21 #04-289
Postcode	521247
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - CONTRACTOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GR7700P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAM KUM MENG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) to courts, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) in complying with requirements under any regulations, laws or court orders



Signature of Policyholder
Date: 2023/10/10

Signature of Authorised Driver
Date: 2023/10/10


Signature of Insurer
Date: 2023/10/10



Signature of Insurer
Date: 2023/10/10

Sketch Plan #2

SKETCH PLAN



Vehicle A: GBC1462D

Vehicle B: GR 7J00 R


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/09/2018 around 9:30 am. I was driving my vehicle GRCH46D from TPE exit to Logang Ave. I was driving slowly and stopped to waiting for the vehicle cross in front. Suddenly, I feeling an impact from my rear portion. I get off my vehicle and found that Vehicle B GR 7700R was collided on my rear portion. There is no injury in this accident.

DECLARATION



Sketch Plan #3



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



VAN / LORRY (Rear)

Vehicle No: GBC 1462 D

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT	✓	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket	BT	✓	2
1148	993068	Rear Bumper Side Retainer	BR	✓	2
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor	MIS	✓	
1159	993327	Rear End Panel	DD	✓	
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	SCR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	DD	✓	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish	CRA	✓	
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	CUT	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper	NN	X	
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket	BT	✓	
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper	DD	✓	
2070	992857	Rear Body Panel LH	DD	✓	
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker (70 km/h)	NEC	✓	
		Taillamp Lower Garnish	DD	✓	
		Rear Body Panel Step Panel	DIS	✓	

No of Items: 15

Assessor:

TGLim

11/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2018 Edit Reg		26 Sep 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	BUILDCOOL ENGINEERING SERVICES PTE LTD , Co. Reg. No.: 199505501G								
Main Claimant:	-								
Vehicle Reg. No.:	GBC1462D	Date of Loss:	22/09/2018 00:00 - :59 [86 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8054531168SG	Policy/Cover Note No.:	1700059550 (Comprehensive)						
Vehicle Reg. No. (Insured):	GR7700P	Policy No. (Claimant):							
		Excess:							
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/10/2018]								
Claimant's Solicitor:	CROSSBORDERS LLC - Tel: 64381323								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (27/09/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents






***GBC1462D (8054531168SG)**
[GR7700P]

TP

-

Sep 22 2018 12:00AM
[BUILDCOOL ENGINEERING SERVICES PTE LTD]
Z-one Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
2	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
3	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
4	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
5	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
6	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
7	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
8	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
9	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
10	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
11	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
12	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
13	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
14	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
15	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
16	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
17	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
18	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
19	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
20	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
21	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
22	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
23	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
24	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
25	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
26	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
27	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
28	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
29	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
30	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
31	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
32	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
33	28/09/18 17:34	General View														Load JPG	<input checked="" type="checkbox"/>			
34	28/09/18 17:35	General View														Load JPG	<input checked="" type="checkbox"/>			
35	28/09/18 17:35	General View														Load JPG	<input checked="" type="checkbox"/>			
36	28/09/18 17:35	General View														Load JPG	<input checked="" type="checkbox"/>			
37	28/09/18 17:35	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/09/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/09/18 17:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
94	28/09/18 17:35	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	27/09/18 10:57	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017504/ACD3E2

Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700059550
Claimant Vehicle No : GBC1462D **Insured Vehicle No :** GR7700P
 Date of Loss: 22/09/2018 Nature of Claim: TP Claim No: 8054531168SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC1462D**
 Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 1KD2094217
 Reg. Date: 24/06/2011 (Man. Year: 2011) Chassis No: JTFHT02PX00073260
 Colour: White Odometer: 161085 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/09/2018
 Date Inspected: 26/09/2018 Inspected At: Z-one Automotive Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6., Blk D #01-87,
 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	0.00 F	*- F
2	2		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Missing	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	1		*TAILGATE GARNISH	Cracked	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	1		*TAILGATE LOCK	Bent	0.00 F	*- F
13	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
14	1		*TAILGATE DAMPER	Not Necessary	0.00 F	*- F
15	1		*SPARE TYRE BRACKET	Bent	0.00 F	*- F
16	1		*SIDE STEP PANEL STOPPER	Dented	0.00 F	*- F
17	1		*REAR BODY PANEL LH	Repair	0.00 F	*- F
18	1		*STICKER (70KM/H)	Necessary	0.00 F	*- F
19	1		*TAILLAMP LOWER GARNISH	Dented	0.00 F	*- F
20	1		*REAR FLOOR PANEL STEP PANEL	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >