

ASS. REC. BY:

REF: cs/SM018017506/Uvd3¹²

Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

merimen

From (Person): Ghoh Pau Loung

of

SMO

Date/Time: 26/9/18 @ 2.06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 6139E

Insured:

SLB 3657H

at Workshop m/s

Fasteeh Auto

Tel:

67465405

of

Ikaki Bkt Ave 6 # 01-46

Policy No:

D18MTPV01005398

Claim No:

CMTD1804186

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS^{1up}

H.O.D. Endorsement:

Date/Time: 2.28pm @ 26/9/18

Person Contacted:

Nancy

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
27/9/18	Informed Pau Loung pending est from repairer via merimen
15/10/18	Send preli revised via merimen

(08/11/13) wef

ASS. REC. BY: MORAN

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 646139Eat Workshop m/s 24of 52B3657H

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 13800

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 72903

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 646139E Yr Regn: 6105

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)Make: Nissan Cabstar c.c. 3153Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 276540 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1SF4F2340854252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 195-R12 35R: 155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 26/9/18

Survey held at _____

Rear

R/Bal. 6/6 mmL/Bal. 6/6 mmD.O.I. 26/9/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 881830-4-2020 1745 7th. net 498215/10/18 4/5 2550 confab with Alan. CRed 5508-30, 6870

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

15/10-typtReport Format: merimenLump Sum / I.B.I. (\$) 2550/2Days Of Repair: 4Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

25010260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18017506/Uvd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 26-09-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 3657H	Veh. Inspected	GY 6139E
Policy No.	D18MTPV01005398	Coverage (\$)	0.00
Claim No.	CMTD1804186	Excess (\$)	0.00
Assign From	MERIMEN (GNOH PAU LOONG)	Assign Date	26/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/09/2018	Inspection Date	26/09/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: GNOH PAU LOONG	Date: 15 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLB3657H	Accident Date	: 26/09/2018
TP Vehicle No	: GY6139E	Assignment Date	: 26/09/2018
Make	:	Est. Duration of Repair	: 4.00
Date of Inspection	: 26/09/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,058.30
Revised Amount	:S\$	2,550.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,550.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ☒ Other comments : Vehicle survey on "Without Prejudice" basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		26 Sep 2018 14:06 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAM CHI KWONG, ID: S7871216C		
Main Claimant:	UNKNOWN4186		
Vehicle Reg. No.:	GY6139E	Date of Loss:	26/09/2018 00:00 - :59
Claim Type:	TP / CMTD1804186	Policy/Cover Note No.:	D18MTPV01005398 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB3657H	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/10/2018]		
Adj Asg. Remarks:	Please be informed that our insured has not reported the accident		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GY6139E (CMTD1804186)**
[SLB3657H]

TP
UNKNOWN4186
Sep 26 2018 12:00AM
[LAM CHI KWONG]
Fastech Auto Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **27/09/2018 12:43 PM.**

To PauLoong

Subject TP GY 6139E

Dear Pau Loong,

Please be informed that we have inspected the vehicle GY 6139E on 26/9/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.



Nissan Cabstar Price Range Depreciation > 10 year(Vehicle Type Submit

Advanced Search

Home » Used Cars » M.Y Commercial Pte Ltd » Nissan Cabstar (COE till 11/2020)

Resources

[Car Buying](#)

[Car Selling](#)

[Car Ownership](#)

[Car Aftermarket](#)

[On The Move](#)

[Lifestyle](#)

Car Leasing



Do you
know
your
home's
value?



mySG Home

Track now

Nissan Cabstar (COE till 11/2020)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$16,800	
Depreciation	\$7,750 /yr	?
Reg Date	26-Nov-2005 (2yrs 1mth 30days COE left)	
Lifespan	25-Nov-2025	
Manufactured	2005	?
Mileage	-	
Transmission	Manual	
Engine Cap	3,153 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	PQP Paid \$22,924. High Scrap Value! Well Maintenance By Previous Owner, Price Still Can Negotiable, High Loan With Lowest Interest Rate Available, Call Our Friendly Salesperson To View Now.	
COE	\$22,924	?
OMV	\$20,070	?
ARF	\$1,004	?
Dereg Value	\$9,936 as of today (change)	?
No. of Owners	2	?
Type of Veh	Truck	
Category	COE Car	
Availability	Available	

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)

Posted on: 14-Sep-2018 | Last Updated on: 15-Sep-2018

Tags: Nissan Cabstar, nissan cabstar, 2005 Nissan Cabstar, 2005 nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

Upfront Payment

* more Financial info

Transfer Fee	\$25	?
Down Payment	\$1,680 (change)	Maximum 90% Loan ?
1st Instalment	\$662	?
Total Upfront Payment	\$2,367 (excluding insurance)	?



Seller Information

Company	M.Y Commercial Pte Ltd * dealer's pricelist * 11 vehs sold 5 vehs available	
Address	7030 Ang Mo Kio Avenue 5 #02-16 Search cars nearby this location	
Location	Northstar @ AMK	
Office No	69093877	
Contact Person(s)	Kenny Tan Nicholas Lim MingYuan	91853232 88111535 93841509

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Nissan Cabstar

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » GF Motor Trading Enterprise » Nissan Cabstar (COE till 12/2020)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Nissan Cabstar (COE till 12/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$25,500

Depreciation \$11,250 /yr

Reg Date 02-Feb-2001
(2yrs 3mths 5days COE left)

Lifespan 01-Feb-2021

Manufactured 2000

Mileage -

Transmission Manual

Engine Cap 3,153 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories -

Description Please Call In Advance Before Viewing. Thanks.

COE \$31,269

OMV \$23,464

ARF \$1,174

Dereg Value \$7,085 as of today (change)

No. of Owners 4

Type of Veh Truck

Category COE Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 29-Aug-2018 | Last Updated on: 21-Sep-2018

Tags: Nissan Cabstar, nissan cabstar, 2001 Nissan Cabstar, 2001 nissan cabstar, Nissen, Cabstar, cabstar, Used Nissan

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$2,550 (change)	Maximum 90% Loan
1st Instalment	\$936	
Total Upfront Payment	\$3,511 (excluding insurance)	

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



Seller Information

Company	GF Motor Trading Enterprise » dealer's pricelist » 5 vehs sold 12 vehs available
Address	310 Thomson Road Search cars nearby this location
Location	Eng Aun Mansion
Office No	62567600

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 7290B

Vehicle Details

Vehicle No.: GY6139E

Vehicle to be Exported: No

Intended Deregistration Date: 26 Sep 2018

Vehicle Make: NISSAN

Vehicle Model: CABSTAR

Primary Colour: Gold

Manufacturing Year: 2005

Engine No.: QD32207808

Chassis No.: JN1SF4F23Z0854252

Maximum Power Output: -

Open Market Value: \$20,220.00

Original Registration Date: 10 Jun 2005

First Registration Date: 10 Jun 2005

Transfer Count: 1

Actual ARF Paid: \$1,011.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2020

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$27,653.00

COE Rebate Amount: \$8,818.00

Total Rebate Amount: \$8,818.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 26 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2018 15:22
Date Of Accident	26/09/2018 07:45
Exact Location Of Accident	ALONG UPPER THOMSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY6139E
Insured/Policyholder	
Name Of Registered Owner	KIAT SENG NURSERY
Co Reg No	52877290B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28740793
Cover Note Number	

Driver

Name of Driver	KOH AH KIAT
NRIC No	S1340258B
Date Of Birth	24/07/1958
Occupation	OUTDOOR
Date Of Driving Pass	19/01/1993
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97996638
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 483 ADMIRALTY LINK #07-29
Postcode	750483
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KOH SEOW YAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20180926/2053

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB3657H
Vehicle Make/Model/Colour	HONDA CRV 2.4 5AT 2WD S/R
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	KOH AH KIAT
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GY6139E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 483 ADMIRALTY LINK #07-29
Postcode	750483

DETAILS OF INJURED PERSON 2

Name	KOH SEOW YAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GY6139E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 483 ADMIRALTY LINK #07-29
Postcode	750483

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

KAT SENG BURNER

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

26 SEP 2018

IDAC KAKI BUKIT (VAC)

Reporting Centre Personnel's Signature
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305
Email: vackb@isignet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN

A - GY6139E
B - SLB365TH

A
B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report T/20180926/2053

DECLARATION

I/We declare the foregoing particulars are true in every respect.

KUAT BENG MURSET

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

26 SEP 2018

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180926/2053

Police Station Of Origin:

Jurong East N.P.C

92 Boon Lay Way SINGAPORE 609962

Tel No: 1800-8999999

1 of 3

Report No. T/20180926/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2018 12:08		Vide Report No.: F/20180926/0058		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: KOH AH KIAT			Address: APT BLK 483 ADMIRALTY LINK #07-29 SINGAPORE 750483		
ID Type / ID No.: NRIC NO / S1340258B			Contact No.: Home/Office: Mobile: 97996638		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 24/07/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GARDENER			Driving Licence Information: Class: 2B,3,4		Date of Expiry:

General information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/09/2018 07:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 UPPER THOMSON ROAD				
Along Upper Thomson Rd towards Ang Mo Kio				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GY6139E	Lorry	NISSAN	Cabstar	Gold	Slightly Damaged	1
SJV8644E	Car					0
SLB3657H	Car	HONDA		Black	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20180926/2053

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

2 of 3

Report No. T/20180926/2053

CONTINUATION OF REPORT

Driver			
Name	KOH AH KIAT	ID No.	S1340258B
Related Vehicle	GY6139E (Lorry)	Contact No.	97996638
Hospital/Clinic	THE CHONG FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	26/09/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the above mentioned date and time, I was driving the vehicle bearing the following details,

V1) GY 6139 E

Nissan

Cabstar

Grey

along Upper Thomson Rd towards Ang Mo Kio. I was driving along Lane 3.

While I was driving along the said lane behind one vehicle bearing registration plate SJV 8644 E, the vehicle suddenly performed a brake. I wish to state I was able to stop my vehicle on time behind the vehicle. However, during the process, the vehicle bearing the following details,

V2) SLB 3657 H

Honda

Black

collided the rear side of my vehicle. Due to the incident, my daughter who was the passenger and myself feel pain on my back. My daughter was conveyed to hospital to seek medical attention while I went to The Chong Family Clinic Pte Ltd to seek medical attention. The doctor then gave me 3 days of outpatient leave.

I wish to state that police and ambulance came down to scene. After the collusion, the vehicle bearing registration plate SJV 8644 E was seen leaving towards Springleaf Park direction. The driver did not on any signal light prior to turning as well. There is in vehicle video recording system in both my vehicle and V2's vehicle where the memory cards were seized by the Traffic Police at scene.

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



T/20180926/2053

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

3 of 3

Report No. T/20180926/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sr Staff Sgt TAN CHAI HEE

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt NOR FAIZAL BIN YAHYA
Contact No.: 65476202



Signature Of Informant:

Date/Time:
26/09/2018 12:08

Classification Of Case:

Date of Accident : 26/9/18 Accident Time: 7.30am (24-HR-Format)
Accident Place : Aloj upper Thomson Road
Vehicle No. (Car Plate No.) : AY 6139 E Make/Model: Nissan carster
Insurance Company : MSIG Policy No: A 28740793
Owner or Company Name /IC No. : Kiat Seng Nursery
Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Koh Ah Kiat
DRIVER'S Date Of Birth : 24/7/1958 DRIVER'S License Pass Date 19/1/1993
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : _____
DRIVER'S Contact No./ Alt No. : 1) 97996638 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : BIK 483 Admiralty Link #07-29
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET 5750483
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 2 person
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SLB 3657 H (somp0)</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

Koh seow Yan. (F)

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

not authorized
when
2/5 2550
26/9/18
427.

VEHICLE NO:GY 6139E

QTY	PARTICULAR (NETT ITEM)
1 PCS	TAILGATE
1 PCS	TAILGATE LOWER MEMBER
2 PCS	TAILLAMPS @\$366.10
2 PCS	TAILGATE LOCK LATCHS @\$148.50
2 PCS	TAILGATE 'L' LOWER PANELS @\$95.00
2 PCS	TAILGATE 'L' LOWER PANEL RUBBERS @\$20.00
1 PCS	REAR SPARE TYRE BRACKET & CHAIN
1 PCS	REAR EXHAUST PIPE
1 PCS	REAR CENTRE CROSS MEMBER
1 PCS	REAR LICENCE PLATE BRACKET

645.10
205 x 2 = 410

R	\$1,688.10	x
20/3ent	\$899.20	
320	\$732.20	
2	\$297.00	x
2	\$190.00	x
M/S 10.1	\$40.00	11.6
090/4m	\$355.30	
2	\$688.20	x
2	\$545.10	x
2	\$163.20	
	\$5,598.30	

(102)

	S.NETT
1 SET	REAR REVERSE SENSOR
1 PCS	TAILGATE '70 KM/H' STICKER
1 PCS	TAILGATE '5 PAX' STICKER
1 PCS	REAR LICENCE PLATE

shuld	\$280.00	200
ner	\$20.00	10
ner	\$20.00	10
ner	\$20.00	14

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	20
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR EXHAUST	\$80.00	60
TO SPRAY RUSF PROOFING	\$80.00	40
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS	\$900.00	750
TO PUTTY & SPRAY PAINTING	\$900.00	600

TOTAL

\$8,058.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1593.6
1734.24
3188

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017506/UVD3N2

Date: 17/10/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01005398
Claimant Vehicle No :	GY6139E	Insured Vehicle No :	SLB3657H
Date of Loss:	26/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1804186

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY6139E	Engine No:	QD32207808
Make & Model:	NISSAN CABSTAR, 3.2 D (M)	Chassis No:	JN1SF4F23Z0854252
Reg. Date:	10/06/2005 (Man. Year: 2005)	Odometer:	276540 km
Colour:	Gold		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R12	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Falken 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,938.30	1,668.24	4,270.06	71.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,520.00	600.00	28.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,058.30	3,188.24	4,870.06	60.44
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	8,058.30	2,550.00	5,508.30	68.36
+ GST 7.00/7.00% (S\$)	564.08	178.50	385.58	68.36
Nett Amount (S\$)	8,622.38	2,728.50	5,893.88	68.36

INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 26/09/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Oct 2018)	
Parts:	N/A	NISSAN CABSTAR 3.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY6139E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,688.10 F	*- FN
2	1		*TAILGATE LOWER MEMBER	Dented/Bent	899.20 F	*645.10 FN
3	2		*TAILLAMPS	Broken	732.20 F	*410.00 FN
4	2		*TAILGATE LOCK LATCHS	Repair	297.00 F	*- FN
5	2		*TAILGATE L LOWER PANELS	Repair	190.00 F	*- FN
6	1		*TAILGATE L LOWER PANEL RUBBERS	N/s Torn	40.00 F	*20.00 FN
7	1		*REAR SPARE TYRE BRACKET & CHAIN	Damaged/Jammed	355.30 F	*355.30 FN
8	1		*REAR EXHAUST PIPE	Repair	688.20 F	*- FN
9	1		*REAR CENTRE CROSS MEMBER	Repair	545.10 F	*- FN
10	1		*REAR LICENCE PLATE BRACKET	Bent	163.20 F	*163.20 FN
11	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
12	1		*TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
13	1		*TAILGATE 5 PAX STICKER	Necessary	20.00 FS	*10.00 FS
14	1		*REAR LICENCE PLATE	Bent	20.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,938.30	1,827.60
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	159.36
Total Parts (S\$)	5,938.30	1,668.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMENTLE & REFIX REAR EXHAUST	New	80.00	60.00
4	TO SPRAY RUSF PROOFING	New	80.00	40.00
5	LABOUR FOR PANEL BEATING,CUT & REPLACING PARTS	New	900.00	750.00
6	TO PUTTY & SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (S\$)			2,120.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >