

ASS. REC. BY:

REF: CS/SMO18017542/T1sd3

02

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 26/9/18 @ 3:35 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 2945J

Insured:

SKJ 5786A

at Workshop m/s

Mova Automotive

Tel:

6272 3892

of

Blk 1008, Blk Merah Lane 3 # 01-04

Policy No:

Claim No:

CMTD1804189 / NSW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/09/18

27/09/18 @ Morning

H.O.D. Endorsement:

CA / REV / REP: / REV 24 HRS

'up'

Date/Time:

4:40pm @ 26/9/18

Person Contacted:

Nitha

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 2945J - X

SKJ 5786A - X

09/10/18

@ 16:18 p.m. revised IA to Ngo Lau Wei Shawn via meimer.

12/10/18

Confirmed L1S \$2,500/- @ 3 days with Taufik.

(\$1,735.80 Rd - 41%)

Signature

Tanful

REF: SMO

ASSIGNMENT

From:

Date: 27/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKD 2945J

at Workshop m/s

Mova Automotive

of BIK 1008, Bkt Merah Jene 3 # 01-04

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKD 2945J

Yr Regn: 2011 / Nov.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot. 207cc.

cc 1598

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

83003

T/Radio: Insured / Std / NI / NA

Eng/No:

VF3WB5F59AE065197

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215 / 45 R17
R: 215 / 45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27/9/18 1650

Survey held at

Mova Bm.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 12 OCT 2018.

Date/Time, File Pass to?

12/10/18

1)

Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

: Photos

: Others

TOTAL

250
10

260

Report Format :

Lump Sum / I.B.I: (\$ 2,500/- L/S)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 01 Oct 2018

Preliminary Advice

Insured Vehicle No	: SKJ5786A	Accident Date	: 25/09/2018
TP Vehicle No	: SKD2945J	Assignment Date	: 26/09/2018
Make	: PEUGEOT 207	Est. Duration of Repair	: 3 days
Date of Inspection	: 27/09/2018		
Inspection At	: Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building Singapore 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,255.80
Revised Amount	:S\$	1,286.50
Check Items (Estimated)	:S\$	1,368.90
Total	:S\$	2,655.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		26 Sep 2018 15:36 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FAIYAAZ BASRAI, ID: S2621696F		
Main Claimant:	YAZID BIN ISMAIL, ID: S74121511		
Vehicle Reg. No.:	SKD2945J	Date of Loss:	25/09/2018 09:00 - :59
Claim Type:	TP / CMTD1804189	Policy/Cover Note No.:	D18MTPV01000185 (Comprehensive)
Vehicle Reg. No. (Insured):	SKJ5786A	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 12 October 2018 4:11 PM
To: 'Tan Yoong Wei'
Cc: SUR
Subject: RE: FINALISE SKD2945J

Hi Yoong Wei,

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei [mailto:tanyw@nova.com.sg]
Sent: Friday, 12 October 2018 4:13 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Subject: RE: FINALISE SKD2945J

Hi Shirley,
We accept the offer \$2500
THANK YOU.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 12 October 2018 1:54 PM
To: 'Tan Yoong Wei'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: FINALISE SKD2945J

Hi Yoong Wei,

Shirley Hiew (LKK Auto)

From: Tan Yoong Wei <tanyw@moval.com.sg>
Sent: Friday, 12 October 2018 4:13 PM
To: 'Shirley Hiew (LKK Auto)'
Subject: RE: FINALISE SKD2945J

Hi Shirley,
We accept the offer \$2500
THANK YOU.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 12 October 2018 1:54 PM
To: 'Tan Yoong Wei'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: FINALISE SKD2945J

Hi Yoong Wei,

Please Confirm final fig of \$2,500.00 (lump sum) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei [mailto:tanyw@moval.com.sg]
Sent: Wednesday, 10 October 2018 12:52 PM
To: taufikh@lkkauto.com
Cc: sur@lkkauto.com
Subject: FINALISE SKD2945J

Hi taufikh,
Please advice whether we can finalise cost of repair lumpsum \$3600 with 4 working days ?

Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 26 September 2018 3:35 PM
To: nitha; assignments@lkkauto.com; assignments@lkkauto.com
Cc: tanyw@movia.com.sg; crystal@movia.com.sg; 'Jia Yu'; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1804189/NSW - LIA(LKK)/ SKJ5786A & SKD2945J DOA 25/09/18 AT OLD TAMPINES ROAD TOWARDS LOYANG AVE

Our Claim Reference: CMTD1804189/NSW
Your Reference: SKD2945J

Hi Nitha,

We acknowledged receipt of your claim documents.

Please be informed that Shawn Ngo is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SKD2945J on a without Prejudice Basis and without any admission of liability basis.

Please submit with your report via merimen upon completion of survey.

Aside to Shawn,

Please refer to the liability request from Movia Automotive Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: nitha [mailto:nitha@nova.com.sg]

Sent: Wednesday, September 26, 2018 1:45 PM

To: Claims - Motor Survey

Cc: tanyw@nova.com.sg; crystal@nova.com.sg; 'Jia Yu'

Subject: TP CLAIMS - SKD2945J AGAINST SKJ5786A DOA 25/09/18 AT OLD TAMPINES ROAD TOWARDS LOYANG AVE

Importance: High

Dear Sir/Madam,
Good day

REF : SKJ5786A

Kindly assist revert officer in charge and liability for the above mention case.
Please arrange survey for SKD2945J at our workshop (Bukit Merah).

Thank you

Best Regards,

Nitha

Claims Officer

Nova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 21511

Vehicle Details

Vehicle No.: SKD2945J
Vehicle to be Exported: Yes
Intended Deregistration Date: 25 Sep 2018
Vehicle Make: PEUGEOT
Vehicle Model: 207CC 1.6 (A) EXTN. EUROV
Primary Colour: Red
Manufacturing Year: 2010
Engine No.: 10FHCK0891268
Chassis No.: VF3WVB5FS9AE065197
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$24,555.00
Original Registration Date: 17 Nov 2011
First Registration Date: 17 Nov 2011
Transfer Count: 0
Actual ARF Paid: \$24,555.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Nov 2021
PARF Rebate Amount: \$15,960.00

Intended COE Rebate Details

COE Expiry Date: 16 Nov 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$55,997.00
COE Rebate Amount: \$17,604.00
Total Rebate Amount: \$33,564.00

The information contained herein is correct as at 25 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2018 15:41
Date Of Accident	25/09/2018 08:35
Exact Location Of Accident	OLD TAMPINES ROAD TOWARDS LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD2945J
Insured/Policyholder	
Name Of Registered Owner	YAZID BIN ISMAIL
NRIC No	S7412151I
Email Address	REENSALLEH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97497977
Alternative Phone No	OTHERS-97497977

Vehicle Particulars

Manufacturer	PEUGEOT
Model	207CC 1.6 (A) EXTN. EUROV
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	NAZREEN BINTE MOHAMED SALLEH
NRIC No	S7425270B
Date Of Birth	17/08/1974
Occupation	INDOOR
Date Of Driving Pass	19/11/1997
Driving Experience	20 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97497977
Fax Number	
Contact Number	
Email Address	REENSALLEH@HOTMAIL.COM

Address	37 LOYANG RISE
Postcode	507564
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ5786A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKD 2945J	ACCIDENT DATE & TIME: 25th Sept. 18, 8.35am
CONTACT NUMBER: 97497977	E-MAIL ADDRESS: reensalleh@hotmail.com
LOCATION: OLD TAMPINES ROAD TOWARDS LOYANG AVE	
<p>Traffic light along Loyang avenue turn GREEN. I stopped car before continuous white line. Car B hit my car boot. The car did not stop and hit directly. My head It was a big bang that causes my head / whole body push forward and hit the bang of back of my head. I was wearing seat belt so I was safe. The accident causes my whole head, neck and back ache and pain. I went to the doctor to diagnose the injury.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- **XA018**

Page # :- 1
Veh # :- SKD2945J
Veh Model :- PEUGEOT
Estimate# :- CK418039
Claim # :-
ACC. Date :- 25/09/18
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER RETAINER L+R	2 PC	90.00	180.00
2.	REAR TAILLAMP LOWER BRACKET L+R	2 PC	54.00	108.00
3.	REAR TAILLAMP L+R - CHECK	2 PC		
4.	REAR BUMPER	1 PC	956.00	956.00
5.	REAR BUMPER PARKING SENSOR CENTRE	3 PC	296.00	888.00
6.	REAR BUMPER PROTECTOR	1 PC	485.00	485.00
7.	REAR REINFORCEMENT	1 PC	345.00	345.00
8.	REAR BOOT - REPAIR	1 PC		
LIST TOTAL S\$				2,962.00
10% DISCOUNT S\$				-296.20
				2,665.80

LABOUR :

TO REPAIR REAR BOOT, END PANEL, TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ACCIDENT DAMAGED PARTS

400 300 550.00

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

400 300 550.00

TO RUST PROOF ACCIDENT DAMAGED PARTS

X 40.00

TO INSPECT REAR LIGHTING & WATER LEAKAGE TEST

30 40.00

TO PROGRAMMING REAR ROOF TOP COUPE

150 250.00

TO REMOVE & REPLACE REAR PARKING SENSOR & CHECK WIRING

30 60.00

TO REMOVE REAR SIDE TRIM, SPARE TYRE, AND OTHER ATTACHMENT PARTS

40 100.00

LABOUR TOTAL S\$

1,590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

4,255.80

GST @ 7 %

297.91

AMOUNT DUE S\$

4,553.71

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Main Office:
Mova Building
No. 22, Jalan Kiang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

26/09/2018

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SKD2945J

Veh Model :- PEUGEOT

Estimate# :- CK418039

Claim # :-

ACC. Date :- 25/09/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER RETAINER L+R	2 PC	90.00	180.00
2.	REAR TAILLAMP LOWER BRACKET L+R	2 PC	54.00	108.00
3.	REAR TAILLAMP L+R - CHECK	2 PC		
4.	REAR BUMPER	1 PC	956.00	956.00
5.	REAR BUMPER PARKING SENSOR CENTRE	2 PC	200.00	400.00
6.	REAR BUMPER PROTECTOR	1 PC	485.00	485.00
7.	REAR REINFORCEMENT	1 PC	345.00	345.00
8.	REAR BOOT - REPAIR	1 PC		
LIST TOTAL S\$				2,962.00
10% DISCOUNT S\$				-296.20
				2,665.80
LABOUR :				
TO REPAIR REAR BOOT, END PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS AND REALIGN ACCIDENT DAMAGED PARTS				
TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS				400 300 550.00
TO RUST PROOF ACCIDENT DAMAGED PARTS				400 300 550.00
TO INSPECT REAR LIGHTING & WATER LEAKAGE TEST				X 40.00
TO PROGRAMMING REAR ROOF TOP COUPE				30. 40.00
TO REMOVE & REPLACE REAR PARKING SENSOR & CHECK WIRING				150. 250.00
TO REMOVE REAR SIDE TRIM, SPARE TYRE, AND OTHER ATTACHMENT PARTS				30 60.00
LABOUR TOTAL S\$				1,590.00

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$
GST @ 7 %

4,255.80
297.91

AMOUNT DUE S\$

4,553.71

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18017542/T1SD3N2

Date: 22/10/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01000185
Claimant Vehicle No :	SKD2945J	Insured Vehicle No :	SKJ5786A
Date of Loss:	25/09/2018	Nature of Claim:	TP
		Claim No:	CMTD1804189

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2945J	Engine No:	10FHCK0891268
Make & Model:	PEUGEOT 207, 1.6 CC (A)	Chassis No:	VF3WB5FS9AE065197
Reg. Date:	17/11/2011 (Man. Year: 2010)	Odometer:	83003 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,665.80	2,129.40	536.40	20.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	1,050.00	540.00	33.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,255.80	3,179.40	1,076.40	25.29
Approved Total (Overridden) (\$\$)		2,500.00		
	(\$\$)	4,255.80	2,500.00	1,755.80
+ GST 7.00/7.00% (\$\$)	297.91	175.00	122.91	41.26
Nett Amount (\$\$)	4,553.71	2,675.00	1,878.71	41.26

INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 27/09/2018 Inspected At:

Mova Automotive Pte Ltd (HQ)
No. 22 Jalan Kilang, #07-01, Mova
Building
Singapore 159419

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	PEUGEOT 207 1.6 CC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD2945J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER RETAINER L+R	Cracked	180.00 FL	*180.00 FL
2	2		*REAR TAILLAMP LOWER BRACKET L+R	Not Necessary	108.00 FL	*- FL
3	2		*REAR TAILLAMP L+R (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*REAR BUMPER	Deformed	956.00 FL	*956.00 FL
5	1		*REAR BUMPER PARKING SENSOR CENTRE	Not Working	888.00 FL	*400.00 FL
		(3 Pcs)				
6	1		*REAR BUMPER PROTECTOR	Deformed	485.00 FL	*485.00 FL
7	1		*REAR REINFORCEMENT	Bent	345.00 FL	*345.00 FL
8	1		*REAR BOOT (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,962.00	2,366.00
- List Item Discount on L Items 10.00/10.00% (S\$)	296.20	236.60

Total Parts (S\$)	2,665.80	2,129.40
-------------------	----------	----------

Report was unsubmitted during this print-out.