

ASS. REC. BY:

REF: CS3/CTI18017546/Gcd3⁴

Special Instruction:

Surveyor:

Gloria Ong

ASSIGNMENT (Office)

From (Person):

Catherine Chia

of

CTI

Date/Time: 26/9/18 @ 2.22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 8385B

Insured:

GBD 8129R

at Workshop m/s

Motor Int'l

Tel:

8838 3318

of

13 kaki Bukit Rd 1 # 01-20

Policy No:

DMCVSN3034041800

Claim No:

SNM18D04623C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/09/2018

CA / REV / REP. / REV 24 HRS^{up}

27/9/18

H.O.D. Endorsement:

Date/Time:

3.08pm @ 26/9/18

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBG 8385B - NA / AIG 18017464 / R3 DOA: 24/9/18
	GBD 8129 R - NA / AIG 18017464 / R3 DOA: 24/9/18
	Disassemble: 28/9/2018

DATE

PHS
Red

REF: CTI

34744

ASSIGNMENT

From: Date: 27/09/18

Estimated Cost

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBB 8385 B

at Workshop m/s Motor Intel

of 13 Kaki Bkt Rd 4 #01-20

Insured

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB 8385 B

Yr Regn:

07 Nov 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan cabstar

C.C 2953

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

11653

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNISC 2F24Z 0860326

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

175/80 R15

R:

155 R13

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27-09-18

Survey held at

w/s

3:20pm

Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

220

Transportation:

___ \$ + RS. ___ \$

Photos

Others

Report Format: PRE

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18017546/Gcd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-09-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBD 8129R	Veh. Inspected	GBG 8385B
Policy No.	DMCVSN3034041800	Coverage (\$)	0.00
Claim No.	SNM18D04623C02	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	26/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/09/2018	Inspection Date	27/09/2018
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Is Assigned	Status
Main	26 Sep 2018		26 Sep 2018 14:22 Assign			New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
<table style="width: 100%;"> <tr> <td style="width: 50%;">Insured: CADENZAUDIO LLP, Co. Reg. No.: T08LL0312F</td> <td style="width: 50%;"></td> </tr> <tr> <td>Main Claimant: P5 PTE LTD, Co. Reg. No.: 201802096E</td> <td></td> </tr> <tr> <td>Vehicle Reg. No.: GBG8385B</td> <td>Date of Loss: 24/09/2018 14:00 - :59</td> </tr> <tr> <td>Claim Type: TP / SNM18D04623C02</td> <td>Policy/Cover Note No.: DMCVSN3034041800 (Comprehensive)</td> </tr> <tr> <td>Vehicle Reg. No. (Insured): GBD8129R</td> <td>Policy No. (Claimant):</td> </tr> <tr> <td></td> <td>Excess: S\$0.00</td> </tr> <tr> <td colspan="2">Repairer: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:</td> </tr> <tr> <td colspan="2">Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]</td> </tr> <tr> <td colspan="2">Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]</td> </tr> <tr> <td colspan="2">Adj Asg. Remarks: NO EST, CASE W/O SJE.</td> </tr> </table>					Insured: CADENZAUDIO LLP , Co. Reg. No.: T08LL0312F		Main Claimant: P5 PTE LTD , Co. Reg. No.: 201802096E		Vehicle Reg. No.: GBG8385B	Date of Loss: 24/09/2018 14:00 - :59	Claim Type: TP / SNM18D04623C02	Policy/Cover Note No.: DMCVSN3034041800 (Comprehensive)	Vehicle Reg. No. (Insured): GBD8129R	Policy No. (Claimant):		Excess: S\$0.00	Repairer: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]		Adj Asg. Remarks: NO EST, CASE W/O SJE.	
Insured: CADENZAUDIO LLP , Co. Reg. No.: T08LL0312F																								
Main Claimant: P5 PTE LTD , Co. Reg. No.: 201802096E																								
Vehicle Reg. No.: GBG8385B	Date of Loss: 24/09/2018 14:00 - :59																							
Claim Type: TP / SNM18D04623C02	Policy/Cover Note No.: DMCVSN3034041800 (Comprehensive)																							
Vehicle Reg. No. (Insured): GBD8129R	Policy No. (Claimant):																							
	Excess: S\$0.00																							
Repairer: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:																								
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]																								
Adj Asg. Remarks: NO EST, CASE W/O SJE.																								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete																								
Due Date	Priority	Type	Task Group	Subject																				
<div style="display: flex; justify-content: space-between;"> Completed On Created On Done? </div>																								
No results.																								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2018 16:50
Date Of Accident	24/09/2018 14:05
Exact Location Of Accident	KING GEORGE AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8385B
Insured/Policyholder	
Name Of Registered Owner	P5 PTE LTD
Co Reg No	201802096E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92736887
Alternative Phone No	OFFICE-67719500

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	PARKED VEH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700074932
Cover Note Number	

Driver

Name of Driver	MOO YOOT LOY
Passport No/FIN	F0208842T
Date Of Birth	23/02/1967
Occupation	OUTDOOR
Date Of Driving Pass	30/04/2018
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98325082
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 134 BEDOK RESERVOIR RD #04-1227
Postcode	470134
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8129R
Vehicle Make/Model/Colour	NISSAN URVAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ALOYSIUS TANG BOHUI
NRIC/Passport Number	S9424756Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJP9160J
-----------------------------	----------

Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: 25/09/18
NRIC/FIN No.:

Individual Statement

SKETCH PLAN



A - GB68385B
B - GB08129R
C - SJ9160J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/09/2018 14 05 HRS, My vehicle A was stationary
park on the rd side of King George Ave. I was at
the hardware shop buying equipment. Out of sudden I heard a
loud bang. Vehicle B had collided onto the rear of my vehicle A.
Due to the strong impact my vehicle A jerked and hit onto the
front vehicle C.

DECLARATION

(/We) hereby declare that the above particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/PPN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3474H
Vehicle Details	
Vehicle No.:	GBG8385B
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	ZD30026500N
Chassis No.:	JN1SC2F24Z0860326
Maximum Power Output:	-
Open Market Value:	\$27,176.00
Original Registration Date:	07 Nov 2017
First Registration Date:	07 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$1,359.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,890.00
COE Rebate Amount:	\$42,707.00
Total Rebate Amount:	\$42,707.00

The information contained herein is correct as at 28 Sep 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		26 Sep 2018 14:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CADENZAUDIO LLP, Co. Reg. No.: T08LL0312F		
Main Claimant:	P5 PTE LTD, Co. Reg. No.: 201802096E		
Vehicle Reg. No.:	GBG8385B	Date of Loss:	24/09/2018 14:00 - :59 [10 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04623C02	Policy/Cover Note No.:	DMCVSN3034041800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD8129R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*GBG8385B (SNM18D04623C02)
[GBD8129R]
TP
P5 PTE LTD
Sep 24 2018 2:00PM
[CADENZAUDIO LLP]
Motor Intel Automo Pte Ltd - Kaki Bukit













































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:47	Accident Statement	Load HTM	
2	25/09/18 15:21	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 15:23	Accident Statement Addm. #1	Load HTM	

Photos/Images			3 per page	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:44	Scene Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	25/09/18 14:44	Scene Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	25/09/18 14:44	Scene Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	25/09/18 14:44	Scene Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	25/09/18 14:44	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
5	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
6	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
7	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
8	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>
9	01/10/18 15:16	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	✓
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
10	01/10/18 15:16	General View	 Load JPG	✓
11	01/10/18 15:16	General View	 Load JPG	✓
12	01/10/18 15:16	General View	 Load JPG	✓
13	01/10/18 15:16	General View	 Load JPG	✓
14	01/10/18 15:16	General View	 Load JPG	✓
15	01/10/18 15:16	General View	 Load JPG	✓
16	01/10/18 15:16	General View	 Load JPG	✓
17	01/10/18 15:16	General View	 Load JPG	✓
18	01/10/18 15:16	General View	 Load JPG	✓
19	01/10/18 15:16	General View	 Load JPG	✓
20	01/10/18 15:16	General View	 Load JPG	✓
21	01/10/18 15:16	General View	 Load JPG	✓
22	01/10/18 15:16	General View	 Load JPG	✓
23	01/10/18 15:16	General View	 Load JPG	✓
24	01/10/18 15:16	General View	 Load JPG	✓
25	01/10/18 15:16	General View	 Load JPG	✓
26	01/10/18 15:16	General View	 Load JPG	✓
27	01/10/18 15:16	General View	 Load JPG	✓
28	01/10/18 15:16	General View	 Load JPG	✓
29	01/10/18 15:16	General View	 Load JPG	✓
30	01/10/18 15:16	General View	 Load JPG	✓
31	01/10/18 15:16	General View	 Load JPG	✓
32	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
33	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
34	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
35	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
36	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
37	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
38	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
39	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
40	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
41	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
42	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
43	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
44	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
45	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
46	03/10/18 12:47	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 14:22	PRS	 Load PDF	
2	26/09/18 14:22	TP GIA	 Load PDF	
3	26/09/18 14:22	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	25/09/18 14:41	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
3	25/09/18 14:41	Identification Card [Linked Accident Report Documents]	 Load JPG	✓
4	25/09/18 14:41	Driving Licence [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:47	Accident Statement	Load HTM	
2	25/09/18 15:21	Addendum Sheet	Load JPG <input checked="" type="checkbox"/>	
3	25/09/18 15:23	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:44	Scene Photo	Load JPG <input checked="" type="checkbox"/>	
2	25/09/18 14:44	Scene Photo	Load JPG <input checked="" type="checkbox"/>	
3	25/09/18 14:44	Scene Photo	Load JPG <input checked="" type="checkbox"/>	
4	25/09/18 14:44	Scene Photo	Load JPG <input checked="" type="checkbox"/>	
5	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
6	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
7	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
8	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
9	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
10	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
11	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
12	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
13	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
14	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
15	25/09/18 14:44	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	25/09/18 14:41	Accident Sketch Plan	Load JPG <input checked="" type="checkbox"/>	
2	25/09/18 14:41	Accident Sketch Plan	Load JPG <input checked="" type="checkbox"/>	
3	25/09/18 14:41	Identification Card	Load JPG <input checked="" type="checkbox"/>	
4	25/09/18 14:41	Driving Licence	Load JPG <input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017546/GCD3S2

Date: 08/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3034041800
Claimant Vehicle No :	GBG8385B	Insured Vehicle No :	GBD8129R
Date of Loss:	24/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04623C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG8385B	Engine No:	ZD30026500N
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Chassis No:	JN1SC2F24Z0860326
Reg. Date:	07/11/2017 (Man. Year: 2017)	Odometer:	11653 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/80R15	Rear Tyre Size:	155 R13
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/09/2018	
Date Inspected:	27/09/2018	Inspected At: Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Oct 2018)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8385B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >