

† 22/03/2007

ASS. REC. BY:

REF: CS3/MSG18017555/Gcd302

Special Instruction:

Survivor: Guo Qiang

ASSIGNMENT (Office)

From (Person): Elaine Ng

of MS/G

Date/Time: 26/9/18 @ 4:24 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 684 Y

Insured: GBH 5430T

at Workshop m/s

Sat Motors

Tel: 9859 9677

of

24 Defu Seite 12

Policy No: A29088528 MKC

Claim No: 571321

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/09/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.34cm @ 27/9/18

Person Contacted:

Jessie

Vehicle IN/OUT

Date/Time

Action/Instruction	(✓) Estimate
--------------------	--------------

Estimate

1067-100
Surveyor

PRS
Knl

REF: MSG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Get Motor
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN684Y Yr Regn: 24 Oct 2006
Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or Carriera
Make: Porsche 911 C.C. 33596
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 133284 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: wpo282 992 75 700178
Gen. Cond: C / Fair / Poor / Burnt
Steering: C / Jammed / Leaked / Burnt or
Brake: C / Jammed / Leaked / Burnt or
Modi: Nil / C / STD A/Rim or
Tyre Size: F: 235/35 ZR18
R: 4
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / P / SUMI /
TOYO / YOKO or
Front
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 27-09-18
Survey held at w/s 1pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
TA o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$8000 - \$10k

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format : PRS

Lump Sum / I.B.I. (\$) _____

120

10

130



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18017555/Gcd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-09-2018



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 5430T	Veh. Inspected	SKN 684Y
Policy No.	A29088528MKC	Coverage (\$)	0.00
Claim No.	571321	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	26/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/09/2018	Inspection Date	26/09/2018
Survey held at	SAT MOTORS 24 DEFU LANE 12 SINGAPORE 539131		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018		26 Sep 2018 16:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG SHAN M&E SERVICES PTE LTD, Co. Reg. No.: -		
Main Claimant:	NG LEA SWEE, ID: S70401331		
Vehicle Reg. No.:	SKN684Y	Date of Loss:	22/09/2018 10:00 - :59 [142 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 571321	Policy/Cover Note No.:	A29088528MKC (Comprehensive) Coverage: 11/07/2018 - 10/07/2019
Vehicle Reg. No. (Insured):	GBH5430T	Policy No. (Claimant):	
		Excess:	
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/09/2018]		
Driver/Custodian (Insured):	GOH CHENG POCK (), NRIC: S1425555I, Tel: +6596615805		
Adj Asg. Remarks:	Liability 100%. Contact Person: Jonathan 9126 9987 / Jessie 9859 9677. TP disagree with SJE, proceed to appoint LKK.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0133I
Vehicle Details	
Vehicle No.:	SKN684Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	PORSCHE
Vehicle Model:	911 CARRERA 3.6 A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	M960569701272
Chassis No.:	WP0ZZZ99Z7S700178
Maximum Power Output:	239.0 kW (320 bhp)
Open Market Value:	\$65,471.00
Original Registration Date:	24 Oct 2006
First Registration Date:	10 Feb 2009
Transfer Count:	7
Actual ARF Paid:	\$65,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Feb 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$689.00
COE Rebate Amount:	\$25.00
Total Rebate Amount:	\$25.00

The information contained herein is correct as at 28 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/09/2018 17:10
Date Of Accident	22/09/2018 10:50
Exact Location Of Accident	BISHAN STREET 22 BLK 284 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN684Y
Insured/Policyholder	
Name Of Registered Owner	NG LEA SWEE
NRIC No	S7040133I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98777143
Alternative Phone No	OTHERS-98777143

Vehicle Particulars

Manufacturer	PORSCHE
Model	997
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V06398/VPS/R00
Cover Note Number	

Driver

Name of Driver	NG LEA SWEE
NRIC No	S7040133I
Date Of Birth	21/11/1970
Occupation	INDOOR
Date Of Driving Pass	12/04/1990
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98777143
Fax Number	
Contact Number	OTHERS-98777143
EEmail Address	NOEMAIL

Address	632 UPPER THOMSON ROAD #06-85
Postcode	787133
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5430T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A: 8KN684Y.
B: 6BH5430T.



I parked my car at Bishan street 22 Block 284 car park.
The van GBT543DT knocked into front bumper and ripped it while turning out of his lot. We decided to claim against his insurance.

I/We declare the foregoing particulars are true in every respect.

x 

x. r. *Ammonia*

Reporting Centre Personnel's Signature: _____
Name: _____
NRIC/FIN No.: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____


























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Sep 2018		26 Sep 2018 16:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HONG SHAN M&E SERVICES PTE LTD , Co. Reg. No.: -									
Main Claimant: NG LEA SWEE , ID: S70401331									
Vehicle Reg. No.: SKN684Y		Date of Loss: 22/09/2018 10:00 - :59 [142 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 571321		Policy/Cover Note No.: A29088528MKC (Comprehensive) Coverage: 11/07/2018 - 10/07/2019							
Vehicle Reg. No. (Insured): GBH5430T		Policy No. (Claimant):							
		Excess:							
Repairer: Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 27/09/2018]									
Driver/Custodian (Insured): GOH CHENG POCK (), NRIC: S14255551, Tel: +6596615805									
Adj Asg. Remarks: Liability 100%. Contact Person: Jonathan 9126 9987 / Jessie 9859 9677. TP disagree with SJE, proceed to appoint LKK.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKN684Y (571321)**
[GBH5430T]
TP
NG LEA SWEE
Sep 22 2018 10:00AM
[HONG SHAN M&E SERVICES PTE LTD]
Sat Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 14:49	Accident Statement From: SC - Reg. No: GBH5430T, Claimant: HONG SHAN M&E SERVICES PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/10/18 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 14:40	Notice of PRI	 Load PDF	
2	26/09/18 14:42	TP disagree with SJE, proceed to appoint LKK	 Load PDF	
3	26/09/18 14:49	SKN684Y GIA Rpt From: SC - Reg. No: GBH5430T, Claimant: HONG SHAN M&E SERVICES PTE LTD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017555/GCD3E2

Date: 02/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29088528MKC

Claimant Vehicle No: SKN684Y

Insured Vehicle No: GBH5430T

Date of Loss: 22/09/2018

Nature of Claim: TP

Claim No: 571321

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN684Y

Make & Model: PORSCHE 911, CARRERA

Engine No: M960569701272

Reg. Date: 24/10/2006 (Man. Year: 2006)

Chassis No: WP0ZZZ99Z7S700178

Colour: Red

Odometer: 133254 km

Engine Capacity: 3596 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19

Rear Tyre Size:

235/35Z R19

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/09/2018

Date Inspected: 27/09/2018

Inspected At:

Sat Motors (HQ)

24 Defu Lane 12

Singapore 539131

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2018)
Parts: M1-COUPE	PORSCHE 911 CARRERA (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKN684Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >