

22/03/2002

ASS. REC. BY:

REF:

CS / UOL18017562 / T1cd3<sup>52</sup>

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Chan Li Si

of

UOL

Date/Time:

27092018 @ 1032am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 207C

Insured:

Public Liability

at Workshop m/s

Cheng Auto

Tel:

6631 0707 / 8665 7775

of

1 Soon Lee St #06-41

Policy No:

DHOL110042527302

Claim No:

L11D55161809

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10-09-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

27092018 1032am

Person Contacted:

MUM

Vehicle IN / OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

SLE 207C - x

Public Liability - x

L1s \$2000 @ 4 days

15/4 5:04pm Confirmed L1 \$2000 and 4 days with Rachel. (Red 10, 144.25, 82%)

Tanpin

REF:

401

ASSIGNMENT

at 2026 July

From:

Date:

01-10-2018

Veh No:

SLE 207C

Yr Regn:

2006

Sp

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Murn

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mervack Benz E200K. cc 1796

Colour:

Beige

A/C:

Insured / Std / NI / NA

Sp. Reading

207 449

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDB2110412542826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/47R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

1/10/18 e1800

Survey held at

Cheng Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 16 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

22000

2x25.50  
30+250=300

Survey Fee:

300

Transportation:

60

Site Insp (\$

80

Interview (\$

40

Tech. Invs (\$

Weekend (\$

TOTAL

480

## Catherine Chong (LKK Auto)

---

**From:** CHAN LI SI <lisi@uoi.com.sg>  
**Sent:** Thursday, 27 September, 2018 10:34 AM  
**To:** claims@chengauto.com  
**Cc:** assignments@lkkauto.com; 'SUR'  
**Subject:** RE: SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : NEW

Dear Murugesan,

We refer to our telephone conversation of 27 September 2018. We have appointed LKK Auto to conduct a pre-repair inspection of your client's motor vehicle no.SLE207C

We are agreeable to explore a direct settlement on the following conditions:

- (1) That you would agree to abide by the recommendation provided by our appointed surveyor on the costs of repair; and
- (2) That we shall not be held liable for any delay caused at your end due to your inability to obtain the spare parts to carry out the repair to your client's vehicle within the reasonable period of time.

Regards,

**Chan Li Si**

Executive  
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** CHAN LI SI  
**Sent:** Monday, 24 September, 2018 10:52 AM  
**To:** 'claims@chengauto.com' <claims@chengauto.com>  
**Subject:** RE: SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : NEW

UOI's claim ref: L11D55161809

Without Prejudice

Dear Murugesan,

I refer to our telephone conversation just.

We are the public liability insurers of Secure Parking Singapore Pte Ltd and is currently investigating the matter.

We would like to appoint LKK Auto Consultants to conduct a WP survey. Please advise when the vehicle is in the workshop so that we can make the necessary arrangements.

Regards,

**Chan Li Si**

Executive

Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** [CLAIMS@CHENGAUTO.COM](mailto:CLAIMS@CHENGAUTO.COM) [mailto:[CLAIMS@CHENGAUTO.COM](mailto:CLAIMS@CHENGAUTO.COM)]

**Sent:** Monday, 24 September, 2018 9:39 AM

**To:** LEW JENNY <[jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)>

**Subject:** Fwd: SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : NEW

Dear Ms Jenny Lew,

CHENG AUTO : SLE207C / LIANG CLARENCE  
Ref. No.  
Insured Name : LIANG CLARENCE  
Policy Number : M0008649

Insurer/Policy : ETIQA /  
Type : INSURANCE

THIRD  
PARTY  
FIRE  
AND  
THEFT

Date of Loss : 10/09/2018  
Our Vehicle No. : SLE207C

We, the repairers for vehicle (SLE207C) is filing a Third Party Claim against your insured (Secure Parking), kindly please review the attached document.

Kindly please arrange for a pre-inspection survey.

We look forward to your prompt reply.

----- Forwarded Message -----

**Subject:** SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : NEW

**Date:** Fri, 21 Sep 2018 16:50:31 +0800

**From:** [CLAIMS@CHENGAUTO.COM](mailto:CLAIMS@CHENGAUTO.COM) <[CLAIMS@CHENGAUTO.COM](mailto:CLAIMS@CHENGAUTO.COM)>

**To:** CHUA JOHNSON <[johnsonchua@uoi.com.sg](mailto:johnsonchua@uoi.com.sg)>

Dear Mr Johnson,

CHENG AUTO : SLE207C / LIANG CLARENCE  
Ref. No.  
Insured Name : LIANG CLARENCE  
Policy Number : M0008649

Insurer/Policy : ETIQA  
Type : INSURANCE /

THIRD  
PARTY  
FIRE  
AND  
THEFT

Date of Loss : 10/09/2018  
Our Vehicle No. : SLE207C

We, the repairers for vehicle (SLE207C) is filing a Third Party Claim against your insured (Secure Parking), kindly please review the attached document.

Kindly please arrange for a pre-inspection survey.

We look forward to your prompt reply.

--

Thanks & Best Regards,

**CHENG AUTO BODYWORKS**

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

**Reporting Centre**

**Address:** 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

**Email:** [claims@chengauto.com](mailto:claims@chengauto.com)

**Workshop**

**Address:** 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

**Email:** [cab@chengauto.com](mailto:cab@chengauto.com)

**Spraypainting**

**Address:** 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

**Email:** [cab@chengauto.com](mailto:cab@chengauto.com)

## Celine Fong (LKKAUTO)

---

**From:** CLAIMS@CHENG AUTO.COM  
**Sent:** Monday, 15 April 2019 5:04 PM  
**To:** Celine Fong (LKKAUTO)  
**Cc:** SUR; Taufikh (LKKAUTO)  
**Subject:** RE: SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : L11D55161809

Dear Ms Celine,

We refer to your Re-offer L/S \$2,200.00 @ 4 DAYS, we accept offer.

Please advise if we should email LOD to you.

Thanks & Best Regards,  
Claims Department  
*Murugesan*



### CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

#### Reporting Centre

**Address:** 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

**Email:** [claims@chengauto.com](mailto:claims@chengauto.com)

#### Workshop

**Address:** 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

**Email:** [cab@chengauto.com](mailto:cab@chengauto.com)

#### Spraypainting

**Address:** 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

**Email:** [cab@chengauto.com](mailto:cab@chengauto.com)

---

**From:** Celine Fong (LKKAUTO) <celinefong@lkkauto.com>  
**Sent:** Monday, 15 April, 2019 11:54 AM  
**To:** CLAIMS@CHENG AUTO.COM  
**Cc:** SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Subject:** RE: SLE 207C - LIANG CLARENCE | DOA : 10/09/2018 | POLICY NO. : M0008649 | REF. NO. : L11D55161809

Dear Rachel,

My surveyor has further reviewed the price of frt rh door window and had re-adjusted to \$1,200.00.

Re-offer L/S \$2,200.00 @ 4 DAYS

Please confirm.

Best Regards,  
Celine Fong

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/09/2018 16:11
Date Of Accident	10/09/2018 10:05
Exact Location Of Accident	413A COMMONWEALTH AVE WEST CARPARK EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE207C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIANG CLARENCE
NRIC No	S7301161B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93662690
Alternative Phone No	OFFICE-93662690

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200K-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	M0008649
Cover Note Number	

### Driver

Name of Driver	LEE TSE YING
NRIC No	S7519296G
Date Of Birth	20/06/1975
Occupation	OUTDOOR
Date Of Driving Pass	14/05/2001
Driving Experience	17 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93662690
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 415 COMMONWEALTH AVENUE WEST #25-3009
Postcode	120415
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On the 10/09/2018 at 1005 hrs, I was at the multi storey carpark at 413A Commonwealth Ave West. The gantry opened and I moved forward. Before I could exit completely, I heard something drop on the roof of my car. I then realised that the gantry arm broke and dropped on my car when I exited the carpark. I moved out and parked my car and went back to take pictures of the gantry. The gantry arm had dropped off. The cable that had the arm secured was found on floor, snapped.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	GANTRY
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurers, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be processed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sites outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigations and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Insurer's Representative  
(Signature must be the policyholder)  
Date & Time:

Reporting Centre Representative Signature  
Name:  
NRIC/Fin No.:

I am fully aware that my insurer may have a 14-day period for me to decide on filing an Own Damage Claim.

# Accident Sketch Plan

SKETCH PLAN

Date of Accident: 10/09/18



A 15 L E 237 C

15 Gantry

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 10/09/18 at 1005hrs I was at the multi-storey carpark at 413A Commonwealth Ave West. The gantry opened and I moved forward. Before I could exit completely, I heard something drop on the roof of my car. I then realised that the gantry arm broke and dropped on my car when I exited the carpark. I moved out and parked my car and went back to take pictures of the gantry. The gantry arm had dropped off. The cable that had the arm secured was found on floor, snapped.

- ☐ Own Damage Claim
- ☐ Third Party Claim
- ☐ ODP/TP Claim at another workplace
- ☒ Reporting Only

## DECLARATION

I/We declare the foregoing particulars are true as stated.

Policyholder's signature  
Date & Time:

Driver's signature  
(If driver is not the policyholder)  
Date & Time:

11/09/2018  
0952



Reporting Officer's signature  
Name:  
NRC File No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1161B
<b>Vehicle Details</b>	
Vehicle No.:	SLE207C
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	27195630806882
Chassis No.:	WDB2110412B012826
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$54,102.00
Original Registration Date:	20 Sep 2006
First Registration Date:	20 Sep 2006
Transfer Count:	2
Actual ARF Paid:	\$59,513.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Jul 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$51,630.00
COE Rebate Amount:	\$37,639.00
<b>Total Rebate Amount:</b>	<b>\$37,639.00</b>

The information contained herein is correct as at 16 Apr 2019

OK

DATE: 21/9/2018

REPAIR DETAILS		
REFERENCE		
Vehicle Reg No.	SLE207C	
Make & Model	MERCEDES BENZ	E200K
Chassis No.	WDB21104128012826	
Engine No.	27195630806882	
Manufactured Year	2006	
Labour	REPAIRER'S	
TP Vehicle Reg No.		
DOA & Location	10/09/2018	413A COMMONWEALTH AVE WEST CARPARK EXIT
Our Ref	SLE207C	/ LIANG CLARENCE

## ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	ROOF		\$ 1,940.40
2	1	ROOF PANEL SIDE MOULDING		\$ 453.20
3	1	RH A-PILLAR		\$ 1,894.35
4	1	FRT RH DOOR FRAME		\$ 457.35
5	1	FRT RH DOOR WINDOW		\$ 1,653.50
6	1	REAR RH DOOR		\$ 2,506.05
7	1	FRT RH DOOR CHROME		\$ 109.86
8	1	ROCKER PANEL GARNISH RH		\$ 523.35
Sub-Total (\$\$)				\$ 9,538.06
SAAA List Item Discount - 10% (\$\$)				\$ 953.81
Sub-Total (\$\$)				\$ 8,584.25

## LABOUR

No.	Description	Price
1	LABOUR	\$ 1,500.00
2	SPRAYPAINTING	\$ 1,500.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 100.00
4	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	\$ 200.00
5	REMOVE AND REPLACE WINDOW GLASS / QUARTER GLASS	\$ 100.00
6	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	\$ 120.00
Total Labour (\$\$)		\$ 3,520.00

## MISCELLANEOUS ITEMS

No.	Description	Price
1	SOLAR FILM	\$ 150.00
2	ROCKER PANEL CLIPS (1 SET)	\$ 90.00
Total Miscellaneous Items (\$\$)		\$ 240.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts (\$\$) \$ 8,584.25  
Total Labour (\$\$) \$ 3,520.00

2810  
4592200

Total Miscellaneous (\$\$)	\$	240.00
Total (\$\$)	\$	12,344.25
GST 7% (\$\$)	\$	864.10
Grand Total (\$\$)	\$	13,208.35

Tanaka 97495749  
 'WP'  
 01/10/18 1800

  
 2/10/18

Resum after repair  
 sure lkkento.com  
 4 days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI18017562/T1cd3s2

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER SINGAPORE 079909

Date : 17-04-2019



Code : UOI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLE 207C
Policy No.	DHOL110042521302	Coverage (\$)	0.00
Claim No.	L11D55161809	Excess (\$)	0.00
Assign From	CHAN LI SI	Assign Date	27/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200K	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	WDB2110412B012826	Colour	BEIGE
Odometer	207499	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/47R17	MICHELIN	6 mm
L/H Front Tyre	245/47R17	MICHELIN	6 mm
R/H Rear Tyre	245/47R17	MICHELIN	6 mm
L/H Rear Tyre	245/47R17	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	10/09/2018	Inspection Date	01/10/2018
Survey held at	CHENG AUTO BODYWORKS 1 SOON LEE STREET #06-41 PIONEER CENTRE SINGAPORE 627605		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 207C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	ROOF	TO REPAIR SEE LABOUR	1,940.40	-
1	ROOF PANEL SIDE MOULDING	NOT NECESSARY	453.20	-
1	RH A-PILLAR	NOT NECESSARY	1,894.35	-
1	FRT RH DOOR FRAME	TO REPAIR SEE LABOUR	457.35	-
1	FRT RH DOOR WINDOW	CUT	1,653.50	1,200.00
1	REAR RH DOOR	TO REPAIR SEE LABOUR	2,506.05	-
1	FRT RH DOOR CHROME	TO REPAIR SEE LABOUR	109.86	-
1	ROCKER PANEL GARNISH RH	TO REPAIR SEE LABOUR	523.35	-
	LESS 10% DISCOUNT		-953.81	-120.00
			8,584.25	1,080.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SOLAR FILM (SN)	NECESSARY	150.00	100.00
1	SET ROCKER PANEL CLIPS (SN)	NOT NECESSARY	90.00	-
			240.00	100.00
	<b><u>LABOUR</u></b>			
	LABOUR.INCLUSIVE OF THE REPAIR OF ROOF,FRT RH DOOR FRAME,REAR RH DOOR,FRT RH DOOR CHROME AND ROCKER PANEL GARNISH RH.		1,500.00	700.00
	SPRAYPAINTING.		1,500.00	800.00
	DISCONNECT & CHECK ELECTRICAL WIRING HARNESS,WIRE SOCKETS,ETC.REMOVE & REINSTALL DAMAGED PARTS,TEST & RECTIFY FOR PROPER FUNCTIONING.		100.00	30.00
	ANTI-RUST COATING AND APPLY CORROSION PROTECTION.		200.00	40.00
	REMOVE AND REPLACE WINDOW GLASS/QUARTER GLASS.		100.00	60.00
	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR.	NOT NECESSARY	120.00	-
			3,520.00	1,630.00
	<b>GRAND TOTAL</b>		<b>12,344.25</b>	<b>2,810.00</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00
---	--	--	----------

Report Ref No. CS/UOI18017562/T1cd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.