

Surveyor
menmenGHO Giong
Junice Goh

ASSIGNMENT (Office)

of ICS

Date/Time: 26/9/18 @ 5.38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 5078P

Insured:

GBH 5109Y

at Workshop m/s:

Comfort Delgro

Tel:

6383 7362

of

205 Braddell Road

Policy No:

Claim No:

DMCV18000724

Sum Insured:

Excess:

Make of Veh:

D.O.A:

24/09/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:37am @ 27/9/18

Person Contacted:

Andrew

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLG 5078P-X

GBH 5109Y-X

26/10/18

@ 3:27pm Andrew said finalise not ready.

8/11/18

LS \$1950 confirmed by email (Ref 2178-24, 5373)

FORM 100

Xhe.

REF: ICS

C4597K

ASSIGNMENT

From

Date: 27092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

SLG 5078P

at Workshop n/s

Comfort Delgm

of

205 Bradeell Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

Andrew

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

- %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG5078P

Yr Regn:

03 oct 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle c.c 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

144379

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK 8100 6513

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: With S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KumHo

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27-09-18

Survey held at

w/s

4:20pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 08 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

8/11 - typist

Days Of Repair:

6

Resurvey No. of Trip:

-

Survey Fee:

Transportation

) S + PS) SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

merimen

Lump Sum / I.B.I. (\$

1950/-

250
10

260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18017572/Gvd3

10 EUNOS ROAD 8

SINGAPORE POST CENTRE #09-04A SINGAPORE Date : 27-09-2018

 408600



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5109Y	Veh. Inspected	SLG 5078P
Policy No.		Coverage (\$)	0.00
Claim No.	DMCV1800072H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	27/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/09/2018	Inspection Date	27/09/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 8 November 2018 10:18 AM
To: 'CDGE Braddell Private Cars Crash Repair Operation'; SUR
Subject: RE: LCR _ SLG5078P - Finalize

Dear Andrew,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,950.00 @ 6 working days.

Kindly send Final invoice and all supporting documents to ECICS

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Wednesday, 7 November 2018 4:23 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: LCR _ SLG5078P - Finalize

Dear Veron

The photos are being corrupted, hence we are unable to forward to you..

We proposed for Lumpsum finalize @ \$1,950.00

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Wednesday, 7 November 2018 2:33:36 PM
To: CDGE Braddell Private Cars Crash Repair Operation
Subject: FW: LCR _ SLG5078P - Finalize

Dear Andrew,

Kindly forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Wednesday, 7 November 2018 1:19 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Fw: LCR _ SLG5078P - Finalize

Dear Sir / Madam

Please refer to our email below.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

From: CDGE Braddell Private Cars Crash Repair Operation
Sent: Monday, 29 October 2018 5:12 PM
To: LKK Guo Qiang
Cc: Denis Teo Chin Chye; Kristy Tay Siew Hwa; CDGE Braddell Private Cars Crash Repair Operation
Subject: LCR _ SLG5078P - Finalize

Dear Guo Qiang

We forward the documents for your reference.

Please confirm the amount.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 November 2018 12:00 PM
To: CDGE Braddell Private Cars Crash Repair Operation
Cc: SUR
Subject: RE: SLG 5078P-DOA: 24/9/2018

Dear Andrew,

Kindly forward us finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 22 October 2018 2:16 PM
To: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLG 5078P-DOA: 24/9/2018

Dear Andrew,

As spoken.

Kindly forward us finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CDGE Braddell Private Cars Crash Repair Operation <braddell_operation@sparkcarcare.com>
Sent: Friday, 12 October 2018 3:45 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SLG 5078P-DOA: 24/9/2018

Hi

The vehicle has completed with repair.

We will finalize with you shortly.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Friday, 12 October 2018 3:42:59 PM

To: CDGE Braddell Private Cars Crash Repair Operation

Cc: SUR

Subject: SLG 5078P-DOA: 24/9/2018

Dear Andrew,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: CDGE Braddell Private Cars Crash Repair Operation
<braddell_operation@sparkcarcare.com>
Sent: Friday, 12 October 2018 3:45 PM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: Re: SLG 5078P-DOA: 24/9/2018

Hi

The vehicle has completed with repair.

We will finalize with you shortly.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

www.SPARKcarcare.com

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 12 October 2018 3:42:59 PM
To: CDGE Braddell Private Cars Crash Repair Operation
Cc: SUR
Subject: SLG 5078P-DOA: 24/9/2018

Dear Andrew,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 26 September 2018 5:38 PM
To: CDGE Braddell Private Cars Crash Repair Operation; 'assignments'
Cc: Denis Teo Chin Chye; CDGE Braddell Private Cars Crash Repair Counter; ECICS Claims
Subject: RE: LCR Fleet _ SLG5078P claim against GBH5109Y _ DOA 24.09.2018

Without Prejudice

Hi Andrew

Thank you for email.
We will appoint LKK for the TP survey.

Aside LKK

Please assist to arrange TP PRI.

Our claim no DMCV1800072H

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Wednesday, 26 September, 2018 2:28 PM
To: ECICS Claims; Lionel_Chua@ecics.com.sg
Cc: Denis Teo Chin Chye; CDGE Braddell Private Cars Crash Repair Counter; CDGE Braddell Private Cars Crash Repair Operation
Subject: Re: LCR Fleet _ SLG5078P claim against GBH5109Y _ DOA 24.09.2018

Dear Sir / Madam

Please arrange to survey the car at CDGE, Braddell.

Car in workshop ready for survey.

And to advice on the liability of the accident.

Andrew

Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com

From: CDGE Braddell Private Cars Crash Repair Operation
Sent: Tuesday, 25 September 2018 11:46 AM
To: ECIS
Cc: Denis Teo Chin Chye; CDGE Braddell Private Cars Crash Repair Counter; CDGE Braddell Private Cars Crash Repair Operation
Subject: LCR Fleet _ SLG5078P claim against GBH5109Y _ DOA 24.09.2018

Dear Sir / Madam

Please arrange to survey the car at CDGE, Braddell.

And to advice on the liability of the accident.

Car in workshop ready for survey.

Andrew
Best Regards
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)
Fax: 6281 5767
www.SPARKcarcare.com

follow us on  follow us on  visit our website 
facebook  twitter  ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLG5078P
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B3537655
Chassis No.:	GK81006513
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,465.00
Original Registration Date:	03 Oct 2016
First Registration Date:	03 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$8,465.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2026
PARF Rebate Amount:	\$6,348.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$42,725.00
Total Rebate Amount:	\$49,073.00

The information contained herein is correct as at 28 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/09/2018 15:43
 Date Of Accident 24/09/2018 13:30
 Exact Location Of Accident SIMS AVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG5078P
Insured/Policyholder
 Name Of Registered Owner LCRF PTE LTD
 Co Reg No 201624597K
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-31584769

Vehicle Particulars

Manufacturer HONDA
 Model SHUTTLE-1.5 (A)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy YES
 Policy Number
 Cover Note Number

Driver

Name of Driver WONG ZHI WEN
 NRIC No S8827114I
 Date Of Birth 26/06/1988
 Occupation OUTDOOR
 Date Of Driving Pass 09/06/2016
 Driving Experience 2 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93891473
 Fax Number
 Contact Number
 Email Address GEORGE.WONG.ZW@GMAIL.COM

Address	BLK 220 YISHUN ST 21 #05-411
Postcode	760220
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5109Y
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along Sims Ave towards Kedok. I driving straight on the 2nd lane from the left.
 Car B was on my right side, 3rd lane from the left.
 Car B swerve out to my lane while trying to overtake a moving lorry in front of him.
 Car B knock onto the right side of my door and fender.
 After the accident, there is 2 checklight on on my dashboard.

Video Attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIH No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S88271141



Name
WONG ZHI WEN

黄志文

Race
CHINESE

Date of birth
26-07-1988

Country/Place of birth
SINGAPORE

Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S88271141

WONG ZHI WEN

Birth Date: 26 Jul 1988
Issue Date: 09 Jun 2016

002576279F

5413882

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight \leq 2000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg 09 Jun 2016



NRIC No. S88271141



Date of issue
08-09-2015

APT BLK 220 YISHUN STREET 21 #05-411
SINGAPORE 760220

NRIC No: S88271141

Date: 19/11/2016

NP 426A





HOTLINE TEL: (65) 6419-3000
FAX: (65) 6416-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

AI 2.400

COMPREHENSIVE COMMERCIAL MOTOR CERTIFICATE NO. SLG5078P		(The below excess is subject to GST) ALL CLAIMS EXCESS S\$2000.00 WINDSCREEN EXCESS S\$100.00	
1) VEHICLE REGISTRATION NO.		SUM INSURED	Market Value
2) NAME OF INSURED		INSURING WITH COE/PARF	Yes
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		SLG5078P	
4) DATE OF EXPIRY OF INSURANCE		LCRF Pte Ltd	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*		25 February 2018	24 February 2019
<p>Any person who is driving on the insured's order or with their permission.</p> <p>If You or Your Authorised Driver is below the age of 21 years old and/or has less than 1 year driving experience, the excess is S\$3,500 (All Claims).</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p>			
6) LIMITATION AS TO USE*			
<p>1) Use for social, domestic, pleasure purposes and business purposes of Insured</p> <p>2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.</p> <p>3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.</p> <p>The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing; 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle; 3) Use for any purpose in connection with the Motor Trade.</p>			
LOSS OF USE		Not Included	
HIRE PURCHASE COMPANY		Refer to Policy Terms and Conditions	
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>			

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in Singapore 13 Feb 2018

AIG Asia Pacific Insurance Pte. Ltd.

030080-000
Aon Singapore Pte Ltd
2 Shenton Way
#26-01 SGX Centre 1
SINGAPORE 068804

Marib

AUTHORISED REPRESENTATIVE

SSPAHN

ORIGINAL



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLG5078PMake & Model : HONDA SHUTTLE 1.5G AYear of Manufacture : 2016Chassis No. : GK81006513Ins Company : AIG / ECICS

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 24/09/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items S -Plus/Less 20% S -Total of Cost / List S -(b) Nett Price Items S -

Less _____

Total of Nett Item _____

(c) Special Nett Items S -Total Parts Cost (Appendix A) S -Labour (Appendix B) S 3,360.00Total Repair Cost S 3,360.00

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor	: <u>Ang Qip . 82880282</u>
Company	: <u>ck/c</u>
Survey conducted on	: <u>27/9/18</u> at _____
Remarks By Surveyor	: <u>part by part. before paint photos. After paint photos.</u>
(a) The repair of this vehicle is authorized / is not authorized until further notice.	
(b) Recommended Days of Repair	: <u>6</u> day(s)
(c) Resurvey	: <u>Required</u> / Not Required
(d) Excess	: <u>S</u>
(e) Signature of surveyor	: _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG5078P Case Owner : Andrew

Make & Model : HONDA SHUTTLE 1.5G A Year Manufacture : 2016

Chassis No : GK81006513 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RH front fender <i>X Repair.</i>	1					
2	RH rocker panel garnish <i>/ Cut</i>	1	399.60				
3	RH wing mirror assy <i>X NN</i>	1					
4	RH wing mirror cover <i>Repair X</i>	1					
5	RH wing mirror lower cover <i>/ Cut</i>	1	409.60				
6	RH wing mirror signal lamp <i>X X NN</i>	1					
7	RH front rim cover <i>/ Cut</i>	1	151.10				
8	RH front rim <i>X X NN</i>	1					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLG5078P**
Make & Model : **HONDA SHUTTLE 1.5G A**

Case Owner : **Andrew**
Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	Labor charges to panel beat, repair on RH front door, RH rear door and to replace damaged parts (240)	\$960.00	480
2	To diagnose and reset electronic system on the anti skid and steering warning light	\$500.00	xx
3	To check wiring functions	\$80.00	x
4	To putty and spray paint front bumper, RH front fender, RH front door, RH rear door, RH rocker panel garnish, RH wing mirror and all affected areas (250)	\$1,500.00	1100
5	To apply rust proofing on repair and replace panels	\$200.00	x nn
6	To check and re-set steering geometry and wheel alignment	\$120.00	80
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Tel: 63837168 / 63837466 Fax:62815767

ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : M/s ECIS Vehicle Number : SLG5078P
 Attn to : M/s LKK - Guo Qiang Type Of Claim : TP

A. Spare parts	\$ 960.30	F. Total Parts	\$ 768.24
B. Supplementary	\$ -	G. Total Labour	\$ 1,660.00
C. Nett Price	\$ -	H. Total Repair	\$ 2,428.24
D. Supp Nett Price	\$ -	I. Excess	
E. S/Nett	\$ -	P/P Total	2,428.24

Total Spare Parts Price	\$ 960.30
Cost plus / List Down	20% 192.06
Total	768.24

Total Nett Price	\$ -
Nett Price Less	\$ -
Total	-

Lump Sum Less \$ -

Lump Sum Rounding

Total Finalized 1950

If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date in : _____	Total Repair Day <u>6</u>
Date Survey : _____	LOU/ Day _____
Date Out : _____	Total LOU _____
Sat/Sun/Ph. : _____	Rental/Day _____
Authorized Repair Day <u>6</u>	Total Rental _____

Submitted By / Date :

Andrew / 29.10.2018

Confirmed By / Date :

Guo Qiang

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG5078P Case Owner : Andrew
 Make & Model : HONDA SHUTTLE 1.5G A Year Manufacture : 2016
 Chassis No : GK81006513 Engine No : 0
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RH front fender	1					
2	RH rocker panel garnish	1		\$ 399.60			
3	RH wing mirror assy	1					
4	RH wing mirror cover	1					
5	RH wing mirror lower cover	1		\$ 409.60			
6	RH wing mirror signal lamp	1					
7	RH front rim cover	1		\$ 151.10			
8	RH front rim	1					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)

Labour

Case Owner
Year of Manufacture

: Andrew
: 2016

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18017572/GVD3N2

Date: 13/11/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLG5078P	Insured Vehicle No :	GBH5109Y
Date of Loss:	24/09/2018	Nature of Claim:	TP
		Claim No:	DMCV1800072H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG5078P	Engine No:	L15B3537655
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK81006513
Reg. Date:	03/10/2016 (Man. Year: 2016)	Odometer:	144379 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	768.24	768.24	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,660.00	1,700.00	50.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,128.24	2,428.24	1,700.00	41.18
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	4,128.24	1,950.00	2,178.24	52.76
+ GST 7.00/7.00% (S\$)	288.98	136.50	152.48	52.76
Nett Amount (S\$)	4,417.22	2,086.50	2,330.72	52.76

INSPECTION

Date of Assignment:	26/09/2018	
Date Inspected:	27/09/2018 Inspected At:	Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD Singapore 579701

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Nov 2018)
Parts:	N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG5078P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER (NPA)	Repair	0.00 FL	*- FL
2	1		*RH ROCKER PANEL GARNISH	Cut	399.60 FL	*399.60 FL
3	1		*RH WING MIRROR ASSY (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*RH WING MIRROR COVER (NPA)	Repair	0.00 FL	*- FL
5	1		*RH WING MIRROR LOWER COVER	Cut	409.60 FL	*409.60 FL
6	1		*RH WING MIRROR SIGNAL LAMP (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*RH FRONT RIM COVER	Cut	151.10 FL	*151.10 FL
8	1		*RH FRONT RIM (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	960.30	960.30
- List Item Discount on L Items 20.00/20.00% (S\$)	192.06	192.06

Total Parts (S\$)	768.24	768.24
-------------------	--------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR CHARGES TO PANEL BEAT,REPAIR ON RH FRONT DOOR,RH REAR DOOR AND TO REPLACE DAMAGED PARTS	New	960.00	480.00
2	TO DIAGNOSE AND RESET ELECTRONIC SYSTEM ON THE ANTI SKID AND STEERING WARNING LIGHT	New	500.00	-
3	TO CHECK WIRING FUNCTIONS	New	80.00	-
4	TO PUTTY AND SPRAY PAINT FRONT BUMPER,RH FRONT FENDER,RH FRONT DOOR,RH REAR DOOR,RH ROCKER PANEL GARNISH,RH WING MIRROR AND ALL AFFECTED AREAS	New	1,500.00	1,100.00
5	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	200.00	-
6	TO CHECK AND RE-SET STEERING GEOMETRY AND WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			3,360.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >