

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS14/

CC3/MR1

8017576

Uqbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 2686Rat Workshop m/s Pl.

of _____

Insured: SLT 89544Policy No. A29069766mkfClaims No. 57181

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 15k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJN 2686R Yr Regn: 10/2/09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Harde stream c.c. 1799Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 177870 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61092492

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. _____ mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/9/18 D.O.I. 27/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

_____ Perhaps 27710975_____ asky 4k. nett 4025

28/9/18 @ 2.03pm email GIA report to Jasmine Loh & Margaret Loh.

8/10/18 2/5 44000 confirmed with Plur. (Red to 11750.50, 75%)

09/10/18 @ 3.21pm revised to Chhia Nguk Ai via Mainman.

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 10/10 10/10

☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

10

210

Report Format :

MER-TPLump Sum / I.B.I. (\$) 4000

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 September 2018 2:00 PM
To: Jasmine Lok Kheng Kwei; Margaret Loh
Cc: KKLau; SUR; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 27/09/2018, SJN 2686R (TP VEHICLE), SLT 8954Y (OI VEHICLE)
Attachments: SJN2686 GIA.pdf

Dear Jasmine and Margaret,

Please be informed that we had inspected the vehicle SJN 2686R M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883 on 27/09/2018

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 09 Oct 2018

Preliminary Advice

Insured Vehicle No : SLT8954Y
TP Vehicle No : SJN2686R
Make : HONDA STREAM
Date of Inspection : 27/09/2018
Inspection At : FASTECH AUTO PTE LTD

Accident Date : 27/09/2018
Assignment Date : 02/10/2018
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,750.50
Revised Amount	:S\$	5,490.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,490.24

Lump Sum Repair	:S\$	4,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.



Honda Stream

Price Range

Depreciation

2009

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Dickson Automobile » Honda Stream 1.8A RSZ

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Stream 1.8A RSZ

Overview

Financial

Accessories

Similar

Research

Photos

Map



DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1988

PD 818/23
ISO 9001:2008

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$15,800**Depreciation** -**Reg Date** 08-Jan-2009
(3mths 11days COE left)**Manufactured** 2008**Mileage** 105,673 km (10.9k /yr)**Transmission** Auto**Engine Cap** 1,799 cc**Road Tax** \$978 /yr**Power** 103.0 kW (138 bhp)
View specs of the Honda Stream (2007-2014)**Curb Weight** 1,370 kg**Features** 1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Paddle Shifters, Sunroof, Auto Climatic Aircon Control, Knockdown Rear Seats.**Accessories** Sport Rims, Touchscreen Audio System, Tweeter Speakers, Roof Mount Monitor, Electric Retractable Side Mirrors With Indicator, Leather Seats.**Description** Very Low Mileage! Extended Warranty, Servicing And Grooming Package Available! Professional Evaluation Services Provided! Well Taken Care Stylish MPV, View And Test Drive It To Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come To Our Air-con Showroom To Appreciate It In Pristine Condition Now, Don't Miss It!**COE** \$1,551**OMV** \$23,621**ARF** \$17,656**Dereg Value** \$8,871 as of today (change)**No. of Owners** 4**Type of Veh** MPV**Category** PARF Car**Availability** Available

Location Map

Seller Information

Company

Dickson Automobile

» dealer's pricelist

» 88 vehs sold | 115 vehs available

Address

31 Kaki Bukit Road 3 #01-01

Search cars nearby this location

Location

Techlink

Website

dicksonauto.com.sg

Office No

68447667

Contact Person(s)

Jonathan Quah 91901666

Wayne Wong 91893632

Ricky Eng 91853390

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?

[Click here to see all Auspicious Numbers!](#)

+ SWISS

Geneva

SGD 1442.-

Conditions

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 2600K

Vehicle Details

Vehicle No.: SJN2686R

Vehicle to be Exported: No

Intended Deregistration Date: 27 Sep 2018

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8X A

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R18A1802311

Chassis No.: RN61092192

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$21,901.00

Original Registration Date: 10 Feb 2009

First Registration Date: 10 Feb 2009

Transfer Count: 3

Actual ARF Paid: \$21,901.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Feb 2019

PARF Rebate Amount: \$10,950.00

Intended COE Rebate Details

COE Expiry Date: 09 Feb 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$689.00

COE Rebate Amount: \$25.00

Total Rebate Amount: \$10,975.00

The information contained herein is correct as at 27 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2018 16:13
Date Of Accident	27/09/2018 07:45
Exact Location Of Accident	ADMIRALITY ROAD WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN2686R
Insured/Policyholder	
Name Of Registered Owner	VINCENT AUTO TRADING
Co Reg No	45542600K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96230628

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5099749626
Cover Note Number	

Driver

Name of Driver	PRASANTH RAJADORAI NAIDU
NRIC No	S9126179J
Date Of Birth	22/07/1991
Occupation	OUTDOOR
Date Of Driving Pass	29/09/2010
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91000721
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	73 MACKENZIE ROAD UNIT 1 MACKENZIE USED CAR CENTRE
Postcode	228729
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT8954Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF2256S
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBD6467C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PRASANTH RAJADORAI NAIDU
Approximate Age
Injuries Sustain BACK SPINE, NECK ACHE, ELBOW
Injured person in which vehicle? SJN2686R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 415913
Reporting Centre
Name: 
Tel: 67492305
Fax: 67492305
NRIC/FIN No:
Email: vacb@singnet.com.sg

SKETCH PLAN

Along Admiralty Road West	A	A: SJN 2686 R
	B	B: EIT 8954 N
	C	C: SLF 2256 S
	D	D: GBD 6467 C
	E	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/04/2018, at about 7:45am, I was
 travelling along Admiralty road west. I was
 stationary, due to front traffic. Suddenly
 I felt an impact. I was involved in a 4
 vehicle chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

ISAC KAKI BUKIT (VAC)
 23 KAKI BUKIT AVE 4
 Singapore 414533
 Reporting Centre Personnel's Signature
 Name: Tel: 67416697
 NRIC/FIN No.: Fax: 67492305
 Email: vackb@singnet.com.sg

1st A.
Date of Accident : 27/09/18 Accident Time: 7:45 am (24-HR-Format)
Accident Place : Admiralty road west.
Vehicle. No. (Car Plate No.) : SJN2686R, Make/Model: _____
Insurance Company : NTUC Policy No: _____
Owner or Company Name /IC No. : _____
Owner or Company Contact No. : 96230628 Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : S9126179 J R Prasanth Rajadurai Naidu.
DRIVER'S Date Of Birth : 22/07/1991 DRIVER'S License Pass Date 29/09/2010.
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Rental.
DRIVER'S Address : Blk 135 Cashew Rd #04-123 S670135.
DRIVER'S Contact No./ Alt No. : 1) 91000721 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): Driver only.

Was there any video Captured by car camera: YES \ NO .
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): Driver : Back (Spine) neck ache.

elbow : Pain.

Other Party Driver's Particular (if any)

2nd B:	3rd C:
Vehicle. No: SLT8954Y	Vehicle. No: SLF2256S.
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

4th D: GBD6467C.



[Signature]

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Along Admiralty road West	A	A: SJN 2686 R
	A	B: SLT 8954 Y
	A	C: SLF 2256 B
	B	D: GBD 6467 C
	A	
	C	
	A	
	D	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/04/2018 . at about . 7:45am . I was .

travelling along Admiralty road west . I was .

stationary . due to front to traffic . Suddenly

I felt an impact . I was involved in a 4

vehicle chain collision .

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Chop

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO) PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
Hak
27/9/18
2/s a Hood/-
Edy.

VEHICLE NO: SJN 2686R

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE 903.20
1 PCS	TAILGATE 'STREAM' EMBLEM 32.60
1 PCS	TAILGATE 'H' LOGO
1 PCS	TAILGATE OUTER HANDLE
1 PCS	TAILGATE INNER TRIM BOARD 315.20
1 SET	TAILGATE INNER TRIM BOARD CLIPS 30.80
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE WEATHERSTRIP 116.90
1 PCS	REAR BUMPER 665.40
1 SET	REAR BUMPER CLIPS 30.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.00
1 PCS	REAR END PANEL 306.10
1 PCS	REAR END PANEL LOWER MEMBER 182.30
1 PCS	REAR END PANEL TOP GARNISH 225.60
2 PCS	TAILLAMPS @\$485.20 338.60 x 2 = 677.20
2 PCS	TAILLAMP HOUSING PANELS @\$215.30
2 PCS	REAR FENDER INNER TRIMS @\$405.30
2 PCS	REAR FENDERS @\$971.20
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$30.60
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD

3750.30

(202)

neu	\$86.50	—
Body	\$1,285.10	—
na	\$45.80	—
11	\$45.00	X
11	\$288.20	X
del/dm	\$466.20	✓
neu	\$50.00	—
11	\$109.30	—
11	\$188.20	—
11	\$785.10	—
neu	\$39.00	—
Seat	\$70.00	—
Body	\$388.20	—
Body	\$185.40	—
11	\$305.20	—
11	\$970.40	—
11	\$430.60	X
11	\$810.60	X
11	\$1,942.40	X
11	\$866.20	X
11	\$61.20	X
11	\$911.40	X
11	\$310.50	X
	\$10,640.50	

S.NETT

1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 SET	REAR REVERSE CARMERA
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT
1 SET	REAR FLOOR PANEL INSULATOR

neu	\$50.00	40
neu	\$50.00	X
11	\$380.00	X
Sheld	\$300.00	200
neu	\$50.00	✓
11	\$220.00	X

LABOUR CHRAGES:

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$150.00	80

TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY RUSF PROOFING	\$100.00	60
TO DISMENTLE & REFIX REAR EXHAUST	1-1 \$100.00	x
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN &	\$1,800.00	800
REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,500.00	1000
TOTAL	\$15,750.50	

5450.24
4382

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18017576/UQBN2

Date: 11/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No :	SJN2686R	Insured Vehicle No :	SLT8954Y
Date of Loss:	27/09/2018	Nature of Claim:	TP
		Claim No:	571811

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN2686R	Engine No:	R18A1802311
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61092192
Reg. Date:	10/02/2009 (Man. Year: 2008)	Odometer:	177870 km
Colour:	Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,690.50	3,290.24	8,400.26	71.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	2,200.00	1,860.00	45.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,750.50	5,490.24	10,260.26	65.14
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	15,750.50	4,000.00	11,750.50	74.60
+ GST 7.00/7.00% (S\$)	1,102.54	280.00	822.54	74.60
Nett Amount (S\$)	16,853.04	4,280.00	12,573.04	74.60

INSPECTION

Date of Assignment: 02/10/2018

Date Inspected: 27/09/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN2686R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	86.50 F	*86.50 FL
2	1		*TAILGATE	Badly Dented	1,285.10 F	*903.20 FL
3	1		*TAILGATE STREAM EMBLEM	Necessary	45.80 F	*32.60 FL
4	1		*TAILGATE H LOGO	Not Necessary	45.00 F	*- FL
5	1		*TAILGATE OUTER HANDLE	Not Necessary	288.20 F	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed/Torn	466.20 F	*315.20 FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FL
8	1		*TAILGATE INNER LOCK	Dented	109.30 F	*109.30 FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	188.20 F	*116.90 FL
10	1		*REAR BUMPER	Dented	785.10 F	*665.40 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*30.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Bent	70.00 F	*70.00 FL
13	1		*REAR END PANEL	Badly Dented	388.20 F	*306.10 FL
14	1		*REAR END PANEL LOWER MEMBER	Badly Dented	185.40 F	*182.30 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	305.20 F	*225.60 FL
16	2		*TAILLAMPS	Cracked	970.40 F	*677.20 FL
17	2		*TAILLAMP HOUSING PANELS	Repair	430.60 F	*- FL
18	2		*REAR FENDER INNER TRIMS	Not Necessary	810.60 F	*- FL
19	2		*REAR FENDERS	Not Necessary	1,942.40 F	*- FL
20	1		*REAR EXHAUST	Not Necessary	866.20 F	*- FL
21	2		*REAR EXHAUST MOUNTINGS	Not Necessary	61.20 F	*- FL
22	1		*REAR FLOOR PANEL	Repair	911.40 F	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	310.50 F	*- FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
25	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS
26	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,690.50	4,040.30
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	750.06
Total Parts (S\$)	11,690.50	3,290.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX SEAT,CUSHION,UPHOLSTERY	New	150.00	80.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	TO DISMENTLE & REFIX REAR EXHAUST	New	100.00	-
8	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	1,800.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			4,060.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >