

2/03/2002

ASS. REC. BY:

REF: CS/AG118017597/Uqbnz

Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person): Albert Hong of AGI Date/Time: 27/09/2018 4:13pm

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 3866Y Insured: SKR 7771J

at Workshop m/s Fastech Auto Tel: 6746 5405

of Blk 1 Kaki Bukit Ave 6 #01-46

Policy No: Claim No: C10002050

Sum Insured: Excess:

Make of Veh: D.O.A. 27/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 27/09/2018 4:19pm Person Contacted: Nancy Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SKD 3866Y - CVI/VAL18017240/Bg
	SKR 7771J - CVI/OCB16023216/TTC

DCA: 27/09/2018

ASS. REC. BY: Marcus

REF:

AG.

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 38661at Workshop m/s LP

of \_\_\_\_\_

Insured: SGR 77711

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 52

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

71475

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKD 38661 Yr Regn: 11, 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMW X1 c.c. 1995Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 96315 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAVL32080VP 89994Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 27/9/18 D.O.I. 27/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 441815/10/18 L/S #5600 confirmed with Aler. (Red 61278797, 70%)

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

15/10/18

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 5600450

**Catherine Chong (LKK Auto)**

---

**From:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Sent:** Thursday, 27 September, 2018 4:13 PM  
**To:** 'assignments'  
**Cc:** 'SUR'  
**Subject:** Appoint LKK to conduct TP survey; Our Ref: C10002050

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Workshop chose Marcus Chua to survey the car.

Our insured's vehicle is SGR7771J.

Thank you.

Regards,

**Albert Hong**  
**Senior Executive, Claims**

T +65 6540 2182  
F +65 6725 0853  
E [albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)

**Budget  
Direct**  
insurance

**Customer Care:** +65 6221 2111  
**Claims:** +65 6221 2199  
**Claims (Int.):** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

---

**From:** Nancy Lam <nancy.lam@fastechno.com.sg>  
**Sent:** Thursday, 27 September, 2018 4:09 PM  
**To:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Subject:** RE: Request for prs SKD3866Y; Our Ref: C10002050

Hi Albert,

*Please arrange* Marcus Chua LKK Auto Consultants Pte Ltd to survey the car.

Regards,

Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

---

**From:** Nancy Lam <nancy.lam@fastechauto.com.sg>  
**Sent:** Thursday, 27 September, 2018 11:28 AM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Subject:** Request for prs SKD3866Y

*Hi Sir*

*My client claiming your insured SGR 7771Y.*

*Please kindly arrange PRS for SKD 3866Y.*

*Date of accident 27.09.2018*

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,  
Nancy Lam  
Fastech Auto Pte Ltd  
Tel: 6746 5405  
Fax: 6745 8520

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

2012 Golf For Sale At Only \$41500.



Low Mile Low Depreciation.  
Cheaper Than Japanese Car.  
Welcome Serious Offers.  
Straits Drive StarAd



Post an Ad

Advertiser Login

Ways of Selling


Browse by Category

Sort b

Advan

4 vehicles

bmw x1

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mil
Search Selection	bmw x1		Any	Any	2011	Any	
	BMW X1	sDrive18i	\$51,388	\$13,150 /yr	25-Jun-2011	1,995 cc	71
This BMW X1 Is The Perfect Vehicle For Those Who Want To Interpret Driving Pleasure In Line With Their Own Needs And Demonstrate Impressive Aplomb, Its Interior Enormous Fle...							
Posted: 26-Sep-2018 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW							
	BMW X1	sDrive18i	\$51,555	\$11,790 /yr	31-Oct-2011	1,995 cc	75
Lowest Pricing And Depreciation In Market! Low Mileage Done 11500km/year Only, Regularly Service/Well Maintain By P Condition, Flawless Exterior And Clean Interior, Accident Fre...							
Posted: 21-Sep-2018 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW							
	BMW X1	sDrive18i	\$51,300	\$11,720 /yr	31-Oct-2011	1,995 cc	75
Flexible Loan And Insurance Packages Available! STA Evaluation Available! No Chassis Or Structural Damages! Offer High It! Contact Today For Test Drive And Viewing, We Are...							
Posted: 21-Sep-2018 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW							
	BMW X1	sDrive18i	\$44,800	\$13,190 /yr	17-Jan-2011	1,995 cc	10
Regularly Serviced And Maintained By Meticulous Owner. No Repairs Needed. Very Clean And Neat Interior, View And Se Warranty And 1 Free Major Servicing! Witness Firsthand Fo...							
Posted: 15-Sep-2018 Tags: 2011 BMW X1, 2011 bmw x1, BMW X1, bmw x1, BMW, X1, x1, Used BMW							

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mil

For Compare

ed ads

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7147E
<b>Vehicle Details</b>	
Vehicle No.:	SKD3866Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I AT D/AB 2WD 5DR GAS/D SR
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	A496I932N46B20BD
Chassis No.:	WBAVL32080VP89994
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$30,567.00
Original Registration Date:	25 Nov 2011
First Registration Date:	25 Nov 2011
Transfer Count:	2
Actual ARF Paid:	\$30,567.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2021
PARF Rebate Amount:	\$19,868.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$24,317.00
<b>Total Rebate Amount:</b>	<b>\$44,185.00</b>

The information contained herein is correct as at 28 Sep 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/09/2018 20:11
Date Of Accident	27/09/2018 08:00
Exact Location Of Accident	SLIP RD TWDS TOH TUCK ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD3866Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE HWA KIAT
NRIC No	S7937147E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98522493
Alternative Phone No	OTHERS-98522493
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	X1 SDRIVE18I AT D/AB 2WD 5DR GAS/D SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA286390/1
Cover Note Number	

### Driver

Name of Driver	LEE HWA KIAT
NRIC No	S7937147E
Date Of Birth	26/11/1979
Occupation	INDOOR
Date Of Driving Pass	30/05/2000
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98522493
Fax Number	
Contact Number	OTHERS-98522493
Email Address	NOEMAIL



Address 471B UPPER SERANGOON CRESCENT #16-356 SPORE 532471

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGR7771J

Vehicle Make/Model/Colour CHEVROLET AVEO 1.4AUTO TH

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name LEE HWA KIAT

Approximate Age



Injuries Sustain

Injured person in which vehicle?

SKD3866Y

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

Report No. T/20180927/2068

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/09/2018 12:50	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: LEE HWA KIAT			Address: APT BLK 471B UPPER SERANGOON CRESCENT #16-356 SINGAPORE 532471		
ID Type / ID No.: NRIC NO / S7937147E			Contact No.: Home/Office: Mobile: 98522493		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 26/11/1979	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: QA MANAGER			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/09/2018 07:55	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 AYER RAJAH EXPRESSWAY TOH TUCK AVENUE AYE filter to Toh Tuck Avenue				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGR7771J	Car				Slightly Damaged	0
SKD3866Y	Car	BMW	X1 SDRIVE18I AT D/AB 2WD 5DR GAS/D SR	Grey	Slightly Damaged	0



Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

Report No. T/20180927/2068

**CONTINUATION OF REPORT**

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKD3866Y	AXA INSURANCE SINGAPORE PTE LTD	GA286390	25/11/2017	24/11/2018

**Details of Person Involved**

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

**Driver**

Name	Alvin Sia Cheong Wei	ID No.	S7608615Z
Related Vehicle	SGR7771J (Car)	Contact No.	93620155
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LEE HWA KIAT	ID No.	S7937147E
Related Vehicle	SKD3866Y (Car)	Contact No.	98522493
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/09/2018	Date Discharge	27/09/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 27/09/2018 at about 0757hrs I was driving my vehicle SKD3866Y. I exited AYE and I turned into the filter lane to turn left on to Toh Tuck Avenue. After the traffic have cleared I released my brakes and just started to accelerate I was hit from the back by a vehicle SGR7771J.

SGR7771J hit my vehicle from the back. Causing my vehicle bumper to drop off and damages on his bumper as well.

No one was injured at the point of time. Both of us alighted our vehicles to exchanges particulars and take pictures. No Police or Ambulance came to scene.

After the accident I felt uncomfortable and I went to Mount Alvernia Hospital to see a doctor and I was given 5 days of Medical Leave.



**SINGAPORE  
POLICE FORCE**



T/20180927/2068

3 of 4

Police Station Of Origin:

Teck Ghee NPP

321 Ang Mo Kio Street 31 SINGAPORE

560321

Tel No: 1800-4599999

Report No. T/20180927/2068

CONTINUATION OF REPORT



Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

Report No. T/20180927/2068

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Sgt 2 YAP PENG TING

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
27/09/2018 12:50

Classification Of Case:

SN 035



Signature

Singapore Police Force

Date of Accident : 07/9/18 Accident Time: 7:59am (24-HR-Format)  
Accident Place : Slip road towards Foh Tuck Rd  
Vehicle No. (Car Plate No.) : SKD 3866J Make/Model: BMW  
Insurance Company : AXA Policy No: GA286390/1  
Owner or Company Name /IC No. : Lee Hwa Kiat /S7937147E  
Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp 98522493 Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : as above  
DRIVER'S Date Of Birth : 26/11/1979 DRIVER'S License Pass Date 30/5/2000  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
DRIVER'S Address : BLK 471B Upper Serayun Crescent  
DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) #16-356-5532471  
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
Email Address : \_\_\_\_\_  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 1 Driver  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): yes

**Other Party Driver's Particular (if any)**

Vehicle No: <u>SGR 77715 (Direct)</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

**\* NEW - Passenger's name & gender:**

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 27/9/18 at 7.59am, I was driving my vehicle A along slip road towards Tok Tuk Rd. I stop my car to wait for on-coming vehicle to be clear. Suddenly vehicle B hit on my rear portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-46/48/50  
SINGAPORE 417883

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

VEHICLE NO: SKD 3866Y

QTY	PARTICULAR
1 PCS	TAILGATE
1 PCS	TAILGATE 'XI' EMBLEM
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE WEATHERSTRIP 266.50
1 PCS	TAILGATE INNER LOCK
2 PCS	TAILGATE REFLECTORS @\$650.50
1 PCS	REAR BUMPER 1245.32
1 PCS	REAR BUMPER PDC CENTRE 480.11
1 PCS	REAR BUMPER TOW COVER
1 PCS	REAR BUMPER LOWER GARNISH 466.50
2 PCS	REAR BUMPER SIDE RETAINERS @\$210.00 115
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER REFLECTORS @\$105.00
1 PCS	REAR BUMPER REINFORCEMENT 695
1 PCS	REAR BUMPER TOP RETAINER 185
2 PCS	REAR BUMPER PDC SENSORS @\$288.00 225
1 PCS	REAR END PANEL 820.10
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$866.05 685.00
1 PCS	REAR FENDER OUTER PROTECTOR O/S 285.00
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	REAR EXHAUST ASSY
1 PCS	REAR END PANEL SEALER
1 PCS	REAR WINDSCREEN SEALANT

LABOUR CHARGES:

TO CHECK WIRING  
TO DISMANTLE & REPLACING PDC SENSOR  
TO DISMANTLE & REFIX REAR WINDSCREEN  
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY  
TO SPRAY RUSF PROOFING  
TO DISMANTLE & REFIX REAR EXHAUST  
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

TOTAL

12	\$1,866.22	X
12	\$86.50	—
12	\$88.50	—
12	\$311.20	—
12	\$305.30	X
12	\$1,301.00	X
12	\$1,786.15	—
12	\$745.30	—
12	\$45.00	—
12	\$688.20	—
12	\$420.00	12
12	\$50.00	—
12	\$210.00	X
12	\$662.30	—
12	\$318.20	—
12	\$576.00	12
12	\$1,120.00	—
12	\$455.20	X
12	\$1,732.10	12
12	\$332.60	—
12	\$148.20	X
12	\$1,750.00	X
12	\$50.00	—
12	\$50.00	X
	\$15,097.97	

2.755.83

5468.03

	\$80.00	20
	\$80.00	50
12	\$150.00	X
	\$150.00	80
	\$100.00	30
12	\$150.00	X
	\$1,080.00	600
	\$1,500.00	800
	\$18,387.97	

Not Allowed  
Mai  
2/5 5500  
42.  
27/9/18



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18017597/Uqbn2

(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 16-10-2018



Code : AGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 7771J	Veh. Inspected	SKD 3866Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10002050	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	27/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	BMW X1 (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAVL32080VP89994	Colour	GREY
Odometer	96315	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	6 mm
L/H Front Tyre	225/45 R18	PIRELLI	6 mm
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	27/09/2018	Inspection Date	27/09/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 3866Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	TO REPAIR SEE LABOUR	1,866.22	-
1	TAILGATE "X1" EMBLEM	NECESSARY	86.50	86.50
1	TAILGATE REAR LOGO	NECESSARY	88.50	88.50
1	TAILGATE WEATHERSTRIP	NECESSARY	311.20	266.50
1	TAILGATE INNER LOCK	NOT NECESSARY	305.30	-
2	TAILGATE REFLECTORS @\$650.50	NOT NECESSARY	1,301.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,786.15	1,245.32
1	REAR BUMPER PAD CENTRE	DEFORMED / WARPED	745.30	480.11
1	REAR BUMPER TOW COVER	DEFORMED	45.00	45.00
1	REAR BUMPER LOWER GARNISH	TORN	688.20	466.50
2	REAR BUMPER SIDE RETAINERS @\$210.00	O/S BENT	420.00	115.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS @\$105.00	NOT NECESSARY	210.00	-
1	REAR BUMPER REINFORCEMENT	BENT	662.30	662.30
1	REAR BUMPER TOP RETAINER	CRACKED	318.20	185.00
2	REAR BUMPER PDC SENSORS @\$288.00	SHORTED	576.00	225.00
1	REAR END PANEL	DENTED	1,120.00	820.10
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	455.20	-
2	TAILLAMPS @\$866.05	O/S CRACKED	1,732.10	685.00
1	REAR FENDER OUTER PROTECTOR O/S	TORN	332.60	285.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	148.20	-
1	REAR EXHAUST ASSY	NOT NECESSARY	1,750.00	-
1	REAR END PANEL SEALER	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT	NOT NECESSARY	50.00	-
	LESS 5% DISCOUNT		-	-287.79
			15,097.97	5,468.04
<b>LABOUR</b>				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00

Report Ref No. CS/AGI18017597/Uqbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUSF PROOFING.	NOT NECESSARY	100.00	30.00
	TO DISMANTLE & REFIX REAR EXHAUST.		150.00	-
	LABOUR FOR PANEL BEATING,CUT & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE.		1,080.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,290.00	1,580.00
GRAND TOTAL			18,387.97	7,048.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,600.00

Report Ref No. CS/AGI18017597/Uqbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.