

CC | CC 4, ASM 180 17601, H jasyu | IDAC: 12084

Surveyor:

MASUL

DOI:

ASSIGNMENT

2/10/18

Date / Time:

20/9/18

Registered in Meriden:

Pre-assign / CCU / FTE

SKM 5627K

Soman 427



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

25/9/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final? Yes / No

SLU 1194P



INSRS: WSP: Volswagen
Tel:
Liability:
RMKS:



INSRS: WSP:
Tel:
Liability:
RMKS:



INSRS: WSP:
Tel:
Liability:
RMKS:



INSRS: WSP:
Tel:
Liability:
RMKS:

Date / Time

20/10
20/9

SLU 1194P X; SKM 5627K X

STAGE

DATE / PIC

Non-Reporting Itr (1st)
Non-Reporting Itr (2nd)
Non-Reporting Itr (Final)
Notification Itr (if non-pickup)
Call OI:
After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)		
After call Itr to OI:		
Authorisation To Act:		
Release Voucher:		
Final Repair Bill:		
Car Rental Invoice:		
Towing Invoice:		
LTA / GIA:		
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		✓
LOD:		
Payment Breakdown Form:		
Post-Repair Photos:		
Others: CM TO TP		✓

REJECTED. TP REVERSING AGAINST T.FLOW

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

0

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$\$

Loss of Rental (LOR):

\$\$

(

days)

Loss of Use (LOU):

\$\$

(\$

x

days)

Loss of Income (LOI):

\$\$

(\$

x

days)

LOR only LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search:

\$\$

Medical:

\$\$

Disbursement:

\$\$

(e.g. Tow/ Independent)

Legal Cost:

\$\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 350

Total:

\$\$

Global Sum \$\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$\$

Name 1:

Payee 2: (Strike if N.A.)

\$\$

Name 2:

Payee 3: (Strike if N.A.)

\$\$

Name 3:

20/6/2019

Paul

REF: ASM(AXA)

17601/R/jas

8127E

ASSIGNMENT

From: _____ Date: **02.10.2018**

Estimated Cost: _____

OD / TW / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: **SLU 1194P**

at Workshop n/s: **Volkswagen**

of: **217 Alexandra Rd**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **4pm**

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: **24K**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SLU 1194P** Yr Regn: **2010 July**

Type: **C** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: **Volkswagen Jetta 1.4 cc 1390**

Colour: **Grey** A/C: Insured / Std / NI / NA

Spl. Reading: **206379** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WUWZZZ1KZAM127045**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **S** In order / Jammed / Leaked / Burnt or _____

Brake: **S** In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **205/55ZR16**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / **MIC** / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal: **6** mm R/Bal: **6** mm


L/Bal: **6** mm L/Bal: **6** mm

D.O.A: **29/05/18** D.O.I: **02/10/18**

Survey held at: **Alexandra**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or **o/s Rear**

The U/C / Chassis frame / Body Structure affected due to collision



Date / Time	Action / Instruction
	4/5 \$ 6,100
	✓ \$ 894.23
	R (\$ 5,674.47 / 48%)

Date/Time: File Pass to/1: Prel. Report

1) Final Report

Date/Time: File Return to/2: _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Insp (\$ _____)

Weekend (\$ _____)

TOTAL: _____

PDI TUAS

PDI TUAS

YIP MUN TUCK
 ANDREW
 77 NIM ROAD
 #04-04
 Singapore, 807586
 Singapore

Phone No.
 Fax No.
 E-Mail

VAT Registration No. M20098505-2
 Tax No. 199101494Z

Service Quote

Customer No. CV003083
 Quote No. SER/QUO/1801610
 QuoteDate 26/09/18
 Salesperson Shawn Lim
 Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA 1.4 TSI 7 SPEED DSG 90KW	205,250	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SLU1194P	WVWZZZ1KZAM127045	01/07/10	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	M2	CAX 509586	1K23G5

No.	Description	Qty.	UoM	Unit Price	Amount
P	B&P ALEX LABOUR	1	UNIT		50.00
P	B&P ALEX LABOUR	4	UNIT		3,300.00
P	B&P ALEX PAINT	4	UNIT		3,200.00
P	B&P WHEEL ALIGNMENT	1			360.00
P	B&P DIAG	1	Time Un		480.00
P	B&P MECH	1	Time Un		280.00
	Sum Labor				7,730.00
P	311601361	1	Pieces		2.28
	Use Predecessor 281601361				
P	1K0601025CR8Z8	1	Pieces		2,232.03
	16" 'SEDONA' RIM ONLY				
	DIAMOND SILVER				
P	1K5807251A	1	Pieces		97.38
	FOAM				
P	1K5807305A	1	Pieces		640.40
	REAR CROSS MEMBER				
P	1K5807394	1	Pieces		63.60
	REAR BUMPER BRACKET RH				
P	1K5807417H GRU	1	Pieces		1,329.06
	REAR BUMPER				
	Use Predecessor 1K5807417E GR				
P	1K5807521A 9B9	1	Pieces		586.87
	REAR LOWER SPOILER				
P	1K5807863B	1	Pieces		92.85
	REAR CENTER GUIDE				
	Use Predecessor 1K5807863A				
	Sum carried forward				11,774.47

Payments to: - BBN: - Acc.-No.:

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

PDI TUAS

YIP MUN TUCK
ANDREW
77 NIM ROAD
#04-04
Singapore, 807586
Singapore

Service Quote

Customer No. CV003083
Quote No. SER/QUO/1801610
QuoteDate 26/09/18
Salesperson Shawn Lim
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA 1.4 TSI 7 SPEED DSG 90KW	205,250	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SLU1194P	WVWZZZ1KZAM127045	01/07/10	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	M2	CAX 509586	1K23G5

Continued 11,774.47

Sum Item 4,044.47

Sum Labor 7,730.00

Sum Item 4,044.47

Total SGD 11,774.47

7% GST 824.21

Total SGD Incl. GST 12,598.68

Explanations

P = Proportionately Charged

Payment Terms No Credit

UKK Auto Consultants hence notify the Repairer of the following:

- To reserve particular spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
5 \$ days
02/10/18 P 1630
Resy & paint

Payments to: - BBN - Acc.-No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	81271
Vehicle Details	
Vehicle No.:	SLU1194P
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1K23G5 MX
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	CAX509586
Chassis No.:	WVWZZZ1KZAM127045
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,571.00
Original Registration Date:	01 Jul 2010
First Registration Date:	01 Jul 2010
Transfer Count:	0
Actual ARF Paid:	\$20,571.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2020
PARF Rebate Amount:	\$11,314.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$26,102.00
COE Rebate Amount:	\$4,546.00
Total Rebate Amount:	\$15,860.00

The information contained herein is correct as at 03 Oct 2018

OK

24,000
 15,860

 8,140

◀ Re:VNI

Type

📍 Question

Message

PLS PROCEED TO REJECT TP CLAIM, TP REVERSING AGAINST TRAFFIC FLOW

Reply

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 2 October 2018 5:56 PM
To: 'Kong, Charmaine (VWG Singapore)'
Cc: Wong, Meiy (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore); Admin A
Subject: RE: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18 *** LKK REF: CC4/ASM18017601/ja3
Attachments: E-FILE.pdf

WITHOUT PREJUDICE

Dear Charmaine,

We refer to the subject.

We note that your client was reversing against the traffic flow. Our principal have reviewed the matter, and we regret to inform you that we are instructed by our principal to deny liability.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Kong, Charmaine (VWG Singapore) [<mailto:charmaine.kong@vw.com.sg>]
Sent: Tuesday, 2 October 2018 4:47 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>
Subject: RE: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18 *** LKK REF: CC4/ASM18017601/ja3

Dear Joy,

Please revert on liability.

Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Thursday, 27 September, 2018 3:42 PM
To: Kong, Charmaine (VWG Singapore)
Cc: Wong, MeiY (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore); Joy Irene (LKKAuto); Asher Sng (LKKAuto); Admin A; assignments
Subject: RE: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18 ***
LKK REF: CC4/ASM18017601/ja3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.


Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

Sketch Plan Pg. 2

Date of accident: 25/9/2018 Time: 1300hrs Location: Broadway Plaza Hotel open car park.
My Vehicle A: SKM5627K Vehicle B: SLU1194P Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting my carpark lot, halfway out I saw
vehicle B reversing, vehicle B reversing direction is
moving against the traffic flow, it was fast and I
immediately halted my vehicle. My intention is to turn
left, while vehicle B is reversing from my right side.
Despite sounding my horn, vehicle B continue reversing
which collided into my front bumper. My car is
stationary at the point of impact

Please provide us evidence i.e. video and scene photo

Please note that for liability, claim negotiation and settlement, please contact Joy at 6841 2409.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 27 September, 2018 1:16 PM

To: 'Kong, Charmaine (VWG Singapore)' <charmaine.kong@vw.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Wong, Mei (VWG Singapore)' <meiy.wong@vw.com.sg>; 'Cheong, Pearlyn (VWG Singapore)'

<Pearlyn.cheong@vw.com.sg>; 'Goh, Edmund (VWG Singapore)' <edmund.goh@vw.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18

Dear Charmaine,

Appointment confirmed.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kong, Charmaine (VWG Singapore) [<mailto:charmaine.kong@vw.com.sg>]

Sent: Thursday, 27 September, 2018 12:19 PM

To: assignments (assignments@lkkauto.com) <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>

Subject: FW: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18

Dear Catherine,

Please arrange survey on coming Tuesday 2.10.18 4pm.

Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: Kong, Charmaine (VWG Singapore)

Sent: Wednesday, 26 September, 2018 3:15 PM

To: motor.survey@axa.com.sg

Cc: Wong, Meiy (VWG Singapore) (meiy.wong@vw.com.sg); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore)

Subject: REQUEST FOR DIRECT SETTLEMENT FOR ACCDT INVOLVING SLU1194P & SKM5627K ON 25.9.18

Dear Claims,

Please revert on liability & survey arrangements.

Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: charmaine.kong@vw.com.sg [<mailto:charmaine.kong@vw.com.sg>]

Sent: Wednesday, 26 September, 2018 3:10 PM

To: Kong, Charmaine (VWG Singapore)

Subject: Scan von MyMFP

Scan from MyMFP

◀ Service Request Details

Claim

S8M00WZZ

Reference

None ✎

Loss Date

September 25, 2018

Request Date

September 26, 2018

Due Date

October 3, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*27/09/2018 @ 9:27am
Charminal wh not in*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLU1194P

Make

TPVD VOLKSWAGEN

Model

JETTA 1.4 TSI 7 SPEED DSG 90KW

Service Address

...

Primary Contact/Insured

WANG HAIXIA

BLK 546A SEGAR ROAD, #16-71, 671546, Singapore

hedy2796@gmail.com

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017601/R1ja3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 09-07-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKM 5627K	Veh. Inspected	SLU 1194P
Policy No.	GA133703	Coverage (\$)	0.00
Claim No.	S8M00WZZ	Excess (\$)	0.00
Assign From		Assign Date	26/09/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN JETTA 1.4	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ1KZAM127045	Colour	GREY
Odometer	206379	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55Z R16	MICHELIN	6 mm
L/H Front Tyre	205/55Z R16	MICHELIN	6 mm
R/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
L/H Rear Tyre	205/55Z R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/09/2018	Inspection Date	02/10/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1194P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RUBBER VALVE (SN) (CONSISTENT)	NECESSARY	2.28	2.28
1	16 'SEDONA' RIM ONLY DIAMOND SILVER (SN) (CONSISTENT)	CUT	1,232.03	1,232.03
1	FOAM (SN) (CONSISTENT)	* CHECK	97.38	-
1	REAR CROSS MEMBER (SN) (CONSISTENT)	* CHECK	640.40	-
1	REAR BUMPER BRACKET RH (SN) (CONSISTENT)	* CHECK	63.60	-
1	REAR BUMPER (SN) (CONSISTENT)	SCRATCHED	1,329.06	1,329.06
1	REAR LOWER SPOILER (SN) (CONSISTENT)	SCRATCHED	586.87	586.87
1	REAR CENTER GUIDE (SN) (CONSISTENT)	* CHECK	92.85	-
			4,044.47	3,150.24
LABOUR				
	R&R RIM & BALANCE.		50.00	50.00
	LABOUR.		3,360.00	1,680.00
	SPRAY PAINT.		3,200.00	1,600.00
	B&P WHEEL ALIGNMENT.		360.00	360.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	CHECK WIRE HARNESS ,ECU,S.		280.00	280.00
			7,730.00	4,450.00
GRAND TOTAL			11,774.47	7,600.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$894.23 NETT)				6,100.00

Report Ref No. CC4/ASM18017601/R1ja3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKinspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 LKKadjudgment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 July 2019
 SLU 1194F - TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	7 November 2018
 SKM5627K INSO GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL, Raghav	26 September 2018
 TP PRI FROM WORKSHOP WITH GIA AND ESTIMATE.msg	Letters and Correspondence	Workshop	DHAKAL, Raghav	26 September 2018