

ASS. REC. BY:

REF: 083/SMO18017605/Gcd3 Special Instruction:

Surveyor: Guo Qiang ASSIGNMENT (Office)

From (Person): Chan su Hui Agnes of SMO Date/Time: 26/9/18 @ 3:47pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 8322Z Insured: SKH 9604B

at Workshop m/s The Mechanic Pte. Ltd Tel: 9333 0611

of Blk 29 Kaki Bkt Rd 4# 05-85

Policy No: DIEMTPV01002746 Claim No: CMTD1804073

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/09/18
(Client's Record)

CA / REV / REP. / REV 24 HRS 'up' H.O.D. Endorsement: _____

Date/Time: 9:55am @ 27/9/18 Person Contacted: Peter Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLJ 8332Z - CC2/MIDA17018311/P DOA: 8/9/17
	SKH 9604B - X
	Dismantle: 28/9/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO18017605/Gcd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-09-2018



Code : SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKH 9604B	Veh. Inspected	SLJ 8322Z
Policy No.	D18MTPV01002746	Coverage (\$)	0.00
Claim No.	CMTD1804073	Excess (\$)	0.00
Assign From	MERIMEN (CHAN SU HUI AGNES)	Assign Date	27/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/09/2018	Inspection Date	27/09/2018
Survey held at	THE MECHANIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-85 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Sep 2018		26 Sep 2018 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DEL ROSARIO IGNACIO FEDERICO LII DONATO , ID: S7562562F								
Main Claimant:	RANK VENTURE PTE LTD , Co. Reg. No.: 200716751R								
Vehicle Reg. No.:	SLJ8322Z	Date of Loss:	18/09/2018 16:00 - :59						
Claim Type:	TP / CMTD1804073	Policy/Cover Note No.:	D18MTPV01002746 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKH9604B	Policy No. (Claimant):							
		Excess:							
Repairer:	The Mechanic Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD, # 05-85 SYNERGY @KB (S), 417800 Kaki Bukit - Tel: 92712214								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/10/2018]								
Driver/Custodian (Insured):	DEL ROSARI ANNA KATRINA KATIGBAK (), NRIC: S7463810D, Tel: +6591054599								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

VEHICLE CLAIMS SPECIALIST PTE LTD
UEN 201802773H

Date: 26th September 2018

Your ref: CMTD1804073 (SKH 9604B)

BY EMAIL ONLY

Our ref: VCS/SLJ 8322Z/TM/PDPI

To: SOMPO INSURANCE (S) PTE LTD

Attn: Motor Claims Dept

Dear Sirs,

**CORRESPONDANCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION
PROTOCOL FOR NIMA CASES.**

We refer to your email dated 26th September 2018.

Please note that the said vehicle can be inspected at:

THE MECHANIC PTE LTD

25 KAKI BUKIT ROAD 4

#05-85

SINGAPORE 417800

Contact No: 9733 0611

**Please call for to arrange for an appointment before conducting the pre-repair
inspection.**

Please note that the vehicle will be available for pre-repair inspection within the next 2 days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without further notice or reference to you. All our client's right are expressly reserved.

PLEASE REPLY BY EMAIL ONLY : VCSSG01@GMAIL.COM

DO NOT REPLY BY FAX

Yours faithfully

VCS

Vehicle Claims Specialist Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2018 15:31
Date Of Accident	18/09/2018 16:10
Exact Location Of Accident	BRADDELL ROAD / UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ8322Z
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	RANK VENTURE PTE. LTD.
Co Reg No	200716751R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92210808

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091548396 CLASSIC
Cover Note Number	

Driver

Name of Driver	LIM KEE CHING
NRIC No	S1450075H
Date Of Birth	17/06/1960
Occupation	INDOOR
Date Of Driving Pass	27/02/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92210808
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	24B JALAN TELITI
Postcode	537322
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE PROPRIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY CAR WAS STATIONARY AT THE SLIP ROAD FROM BRADDELL ROAD INTO UPPER SERANGOON ROAD, WAITING FOR CLEAR TRAFFIC. SUDDENLY A CAR(SKH9604B) CAME FROM BEHIND, HIT ONTO THE REAR PORTION OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH9604B
Vehicle Make/Model/Colour	VOLKSWAGEN TOURAN 1.4 TSI AT 1T32B4
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten Signature]

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305

Policyholder's Signature: *[Signature]*
Date & Time: 19 SEP 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19 SEP 2018

Email: carbk@singnet.com.sg
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer

C-File

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

19 SEP 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLJ8322Z		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	COROLLA ALTIS CLASSIC 1.6 CVT		
Chassis No. :	MR053REH104555535		
Propellant :	Petrol		
Engine No. :	1ZR588348		
Engine Capacity :	1598 cc		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1640 kg		
Unladen Weight :	1205 kg		
Year Of Manufacture :	2016		
Original Registration Date :	28 Dec 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$50,951.00		
COE Expiry Date :	27 Dec 2026		
Road Tax Expiry Date :	27 Dec 2018		
PARF Eligibility Expiry Date :	27 Dec 2026		
Inspection Due Date :	27 Dec 2019		
Intended Transfer Date :	01 Oct 2018		
CO2 Emission :	151.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 27 Dec 2018. You may renew the road tax from 28 Sep 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Dec 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 28 Dec 2018 to 27 Jun 2019)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	371.00	-	371.00
Total Amount Payable :			396.00
Amount Payable (From 28 Dec 2018 to 27 Dec 2019)			

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6751R
Vehicle Details	
Vehicle No.:	SLJ8322Z
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRX588348
Chassis No.:	MR053REH104555535
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	28 Dec 2016
First Registration Date:	28 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2026
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$41,966.00
Total Rebate Amount:	\$55,452.00

The information contained herein is correct as at 01 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Sep 2018		26 Sep 2018 15:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	DEL ROSARIO IGNACIO FEDERICO LII DONATO , ID: S7562562F		
Main Claimant:	RANK VENTURE PTE LTD , Co. Reg. No.: 200716751R		
Vehicle Reg. No.:	SLJ8322Z	Date of Loss:	18/09/2018 16:00 - :59 [20 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804073	Policy/Cover Note No.:	D18MTPV01002746 (Comprehensive)
Vehicle Reg. No. (Insured):	SKH9604B	Policy No. (Claimant):	
		Excess:	
Repairer:	The Mechanic Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD, # 05-85 SYNERGY @KB (S), 417800 Kaki Bukit - Tel: 92712214		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/10/2018]		
Driver/Custodian (Insured):	DEL ROSARI ANNA KATRINA KATIGBAK (), NRIC: S7463810D, Tel: +6591054599		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ8322Z (CMTD1804073)**

[SKH9604B]

TP

RANK VENTURE PTE LTD

Sep 18 2018 4:00PM

[DEL ROSARIO IGNACIO FEDERICO LII DONATO]

The Mechanic Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 15:52	Accident Statement From: SC - Reg. No: SKH9604B, Claimant: DEL ROSARIO IGNACIO FEDERICO LII DONATO	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
5	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
6	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
7	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
8	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
9	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
10	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
11	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
12	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
13	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
14	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
15	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
16	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
17	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
18	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
19	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
20	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
21	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
22	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
23	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
24	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
25	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
26	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
27	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
28	01/10/18 15:17	General View	Load JPG	<input checked="" type="checkbox"/>
29	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	03/10/18 12:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 08:31	TPPD Pre-Repair Survey	Load PDF	
2	26/09/18 08:32	Third Party E-filed GIA report	Load PDF	
3	26/09/18 15:46	WS - THE MECHANIC	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18017605/GCD3S2
Date: 05/10/2018REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01002746
Claimant Vehicle No :	SLJ8322Z	Insured Vehicle No :	SKH9604B
Date of Loss:	18/09/2018	Nature of Claim:	TP
			Claim No: CMTD1804073

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8322Z	Engine No:	1ZR588348
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104555535
Reg. Date:	28/12/2016 (Man. Year: 2016)	Odometer:	153943 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/09/2018	
Date Inspected:	27/09/2018 Inspected At:	The Mechanic Pte Ltd (HQ) BLK 25 KAKI BUKIT ROAD, # 05-85 SYNERGY @KB (S) Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 - \$2,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ8322Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >