

ASS. REC. BY:

REF:

CS3/CTI18017606/ Gcd32

Special Instruction:

Survivor:

Mun men

From (Person):

Guo Qiang

Catherine Chia

ASSIGNMENT (Office)

of

CTI

Date/Time:

27/9/18 @ 2:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 9167S

Insured:

SKL 9869H

at Workshop m/s

MSM Logistics

Tel: 91074212

of

160 Sin Ming Drive # 03-08

Policy No:

DMPCSN 3058501704

Claim No:

9NM18D04644C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/09/18

CA / REV / REP. / REV 24 HRS / up

1/10/18 @ after 10am

H.O.D. Endorsement:

Date/Time:

3:09pm @ 27/9/18

Person Contacted:

chen

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SKW 9167S - X

SKL 9869H - X

Dismantle: 2/10/2018

PHS  
XRL

REF: CTI

44651

ASSIGNMENT

(-2019)

From: Date: 01/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 9167S  
at Workshop m/s MSM Logistics  
of 160 Sg Ming Drive # 03-08  
Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 10am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

\$15k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / wps

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKW 9167S Yr Regn: 25 May 2008

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda3 C.C. 1999

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 140077 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: IM6BL10F1A0100847

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 ZR17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achille

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 01-10-18

Survey held at w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$ )

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018		27 Sep 2018 14:03 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LIM HAN, ID: S7721532H		
Main Claimant:	ERH JIAN WEI(YU JIANWEI)		
Vehicle Reg. No.:	SKW9167S	Date of Loss:	25/09/2018 21:00 - :59
Claim Type:	TP / SNM18D04644C02	Policy/Cover Note No.:	DMPCSN3058501704 (Comprehensive)
Vehicle Reg. No. (Insured):	SKL9869H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS ▢

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Lucas Lee**

---

**From:** Natalie Ng <natalie\_ng@rssolomon.com>  
**Sent:** Thursday, 27 September, 2018 1:50 PM  
**To:** Lucas Lee  
**Cc:** khian hen Chen  
**Subject:** Re: PRS of SKW9167S (CTI REF: SNM18D04644C02)  
**Attachments:** image001.png

Dear Mr. Lee,


We thank you for your email of even date.

We have our client's instruction to appoint Mr. Adrian Ling as the SJE.

In this premises, please contact Mr Chen of MSM Logistics Pte Ltd at mobile no. 94896649 (1st prior) /91074212 for a pre-repair survey of our client's vehicle locate at No. 160 Sin Ming Drive #01-12 Sin Ming Autocity Singapore 575722.

Thank you and Best Regards,

**Natalie Ng** | Office Manager 人事与行政经理



**R. S. Solomon LLC | 正氣律師事務所**

Head Office: 300 Beach Road The Concourse #12-03/04 Singapore 199555 | Branch: Blk 184 Toa Payoh Central #02-354 Singapore 310184

t +65 6817 7498 | f +65 6292 2665 | e [natalie\\_ng@rssolomon.com](mailto:natalie_ng@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

---

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

---

On Thu, 27 Sep 2018 at 13:09, Lucas Lee <[lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)> wrote:

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
'Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Catherine Thia

Lucas Lee

Claims Department (Motor)

**China Taiping Insurance (Singapore) Pte. Ltd.**


3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4403I
Vehicle Details	
Vehicle No.:	SKW9167S
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 2.0L SDN
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	LF10777745
Chassis No.:	JM6BL10F1A0100847
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$23,856.00
Original Registration Date:	25 May 2009
First Registration Date:	25 May 2009
Transfer Count:	4
Actual ARF Paid:	\$23,856.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2019
PARF Rebate Amount:	\$11,928.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$9,180.00
COE Rebate Amount:	\$589.00
<b>Total Rebate Amount:</b>	<b>\$12,517.00</b>

The information contained herein is correct as at 02 Oct 2018

OK

MS1118124828 / STA INSPECTION PTE LTD - Sin Ming  
ENTRY DATE & TIME: 26/09/2018 12:21  
SUBMITTED BY: Wong Lip Yong

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	26/09/2018 12:21
Date Of Accident	25/09/2018 21:50
Exact Location Of Accident	112A WHAMPOA ROAD MSCP DECK 4A
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SKW9167S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ERH JIAN WEI (YU JIANWEI)
NRIC No	S8944403I
Email Address	ERHJIANWEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91546474
Alternative Phone No	OTHERS-91546474
<b>Vehicle Particulars</b>	
Manufacturer	MAZDA
Model	3-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100047724
Cover Note Number	
<b>Driver</b>	
Name of Driver	ERH JIAN WEI (YU JIANWEI)
NRIC No	S8944403I
Date Of Birth	22/11/1989
Occupation	OUTDOOR
Date Of Driving Pass	17/07/2009
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91546474
Fax Number	
Contact Number	OTHERS-91546474
Email Address	ERHJIANWEI@GMAIL.COM



Address BLK 112 WHAMPOA ROAD #09-79  
SINGAPORE

Postcode 321112

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKL9869H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LIM HON

NRIC/Passport Number S7721532H

Contact Number 91667577

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name ERH JIAN WEI (YU JIANWEI)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SHOULDER PAIN

SKW9167S

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting from stated multi-storey carpark, when I went down to level 4A, I saw vehicle B was in front of me moving slowly, I followed him as well. Suddenly vehicle B engaged reverse gear and reversed without noticing my vehicle and hit into my front portion.

Video footage was captured, vehicle B didn't put on hazard light or anything.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

QIARM SketchPlanForm\_v3

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018		27 Sep 2018 14:03 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LIM HAN</b> , ID: S7721532H									
Main Claimant: <b>ERH JIAN WEI(YU JIANWEI)</b>									
Vehicle Reg. No.: <b>SKW9167S</b>		Date of Loss: 25/09/2018 21:00 - :59 [112 Months From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM18D04644C02</b>		Policy/Cover Note No.: DMPCSN3058501704 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKL9869H</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>Msm Logistics Pte Ltd- Sin Ming (HQ)</b> 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 08/10/2018]</b>									
Adj Asg. Remarks: NO EST, ASSIGN ADRIAN LING AS SJE.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKW9167S (SNM18D04644C02)  
[SKL9869H]  
TP  
ERH JIAN WEI(YU JIANWEI)  
Sep 25 2018 9:00PM  
[LIM HAN]  
Msm Logistics Pte Ltd- Sin Ming

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	26/09/18 15:02	Accident Statement	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	26/09/18 15:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	26/09/18 15:01	SCENE PHOTO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	26/09/18 15:01	SCENE PHOTO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	26/09/18 15:01	SCENE PHOTO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	26/09/18 15:01	SCENE PHOTO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/09/18 14:02	PRS	Load PDF	
2	27/09/18 14:02	TP GIA	Load PDF	
3	27/09/18 14:03	OI GIA	Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	26/09/18 15:00	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	26/09/18 15:00	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 15:00	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	26/09/18 15:02	Accident Statement	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	26/09/18 15:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
2	26/09/18 15:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 15:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	26/09/18 15:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	26/09/18 15:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	26/09/18 15:01	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	26/09/18 15:01	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
8	26/09/18 15:01	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
9	26/09/18 15:01	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
10	26/09/18 15:01	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	26/09/18 15:00	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	26/09/18 15:00	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	26/09/18 15:00	Sketch Plan #3		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017606/GCD3E2

Date: 04/10/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3058501704

Claimant Vehicle  
No : SKW9167SInsured Vehicle  
No : SKL9869H

Date of Loss: 25/09/2018

Nature of Claim: TP

Claim  
No: SNM18D04644C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKW9167S

Make &amp; Model: MAZDA 3, 2.0 (A)

Reg. Date: 25/05/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: LF10777745

Chassis No: JM6BL10F1A0100847

Odometer: 140077 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: Achilles 6 mm

Rear Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm

Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 27/09/2018

Date Inspected: 01/10/2018 Inspected At:

Msm Logistics Pte Ltd- Sin Ming (HQ)  
160 Sin Ming Drive #03-08 Sin Ming Auto  
City  
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2018)
<b>Parts:</b> 144	MAZDA 3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW9167S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >