

COMFORTDELGRO ENGINEERING PTE LTD

Date: 25.09.2018

REPAIR ESTIMATE

China Taiping  
CLS)

Time: 17:04:33

Page: 1/2 IS

LKE - kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305217453  
REGN NO : SHC7881S  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 04.09.2014  
DATE/TIME IN : 25.09.2018 12:35  
ACCIDENT DATE : 25.09.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	/
0002	04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	35.60	20.00	28.48	?
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60	/
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	X
0005	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	/

SUB-TOTAL : 806.58

JOB NATURE

0000	L	PANEL BEATING					
0001	23-502	SPRAYPAINT ON AFFECTED AREA					
0002	L	R/I REVERSE SENSOR					

~~280.00~~ 200

~~250.00~~ 200

~~120.00~~ 30

SUB-TOTAL : 650.00

China Taiping (US)

LKK-Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305217453  
REGN NO : SHC7881S  
MILEAGE : 000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 04.09.2014  
DATE/TIME IN : 25.09.2018 12:35  
ACCIDENT DATE : 25.09.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,456.58

*[Signature]*

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

*Kalvin (LKK)  
26/9/18 1040 hrs.  
2 hrs  
L/s  
After Report p LKK*

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before final spray painting  
• To display damaged parts during resurvey  
• Parts prices are subject to resurvey  
• Third party survey is on a "Without prejudice" basis  
• No illegal modification is allowed  
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: