

ASS. REC. BY:

REF:

003 / II 18017610 / R1cb37

Special Instruction:

Surveyor:

RACIA

ASSIGNMENT (Office)

From (Person):

Joel Nah

of

II

Date/Time:

27/09/2018 3:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 3224A

Insured:

SHD 3112A

at Workshop m/s

Hoe Kong Motor

Tel:

6268 1111

of

Bik 7 Pioneer Rd North #01-43

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

22-10-2018 @ after 1pm

H.O.D. Endorsement:

Date/Time:

27/09/2018 4:23pm

Person Contacted:

Sabana

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKW 3224A - X
	SHD 3112A - 003 / A1615007423 / R12y372

DOA: 230415

Surveyor:

Faru

REF:

25652

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 3224A

at Workshop m/s HOE KENG

of 7/10/18 AS NATH #01-43

Insured: III / PRS

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKW 3224A Yr Regn: 2015 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALNS 1.6 G.C. 1598

Colour: GREEN A/C: Insured / Std / NI / NA

Sp.Reading: 65197 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053RKH1045411.68

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKE or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/09/18 D.O.I. 23/10/18

Survey held at HOE KENG

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format : PRS.

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 27 September, 2018 3:51 PM
To: Catherine Chong (LKK Auto); 'sur@lkkauto.com'; Olivia Lau (olivialau@lkkauto.com)
Cc: accident@kscgp.com; jiapei@kscgp.com; Mekavathanan Sarangapani; Sherini Pillai
Subject: FW: Notice to Conduct Pre-Repair Survey – Your insured veh: SHD 3112A Our ref: SKW 3224A/HK/jp/ca
Attachments: 2nd PRS.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKW 3224A
III INSURED VEHICLE NO. : SHD 3112A
DATE OF LOSS :21/09/2018

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK to conduct the pre-repair survey.

This claim is handled by **sherini**

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Joel Nah

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: accident@kscgp.com [mailto:accident@kscgp.com]
Sent: Thursday, 27 September, 2018 3:46 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jiapei@kscgp.com; Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Subject: RE: Notice to Conduct Pre-Repair Survey – Your insured veh: SHD 3112A Our ref: SKW 3224A/HK/jp/ca

Dear Joel,

We refer to your email of even date.

We enclose herewith our 2nd Notice to conduct pre-repair survey. Our client is not agreeable to your proposed motor surveyor as Single Joint Expert.

Thank you.

Regards,
Candice
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

To: accident@kscgp.com

Cc: jiapei@kscgp.com, mekavathanan@iii.com.sg

Sent: Thu, 27 Sep 2018 07:18:14 +0000

Subject:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Joel Nah

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: accident@kscgp.com [mailto:accident@kscgp.com]

Sent: Thursday, 27 September, 2018 2:24 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: jiapei@kscgp.com

Subject: Notice to Conduct Pre-Repair Survey – Your insured veh: SHD 3112A Our ref: SKW 3224A/HK/jp/ca

Dear Sirs,

Please find enclosed our notice to conduct pre-repair survey / inspections for your necessary action.

Thank you.

Regards,

Candice

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including

the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Your Ref : SHD 3112A
Our Ref : SKW 3224A/HK/jp/ca
Date : 27 September 2018

Fax : 6538 3708
Tel : 3152 0981
Email : accident@kscgp.com

India International Insurance Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 21 SEPTEMBER 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email on even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no	Name of Surveyor	Company Name
1.	Errol Tan	Pro Plus Automobile Engineers
2.	Dave Chang	Sincere Appraisal Services
3.	Lee Kok Weng	Lee Automobile Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Hoe Keng Motor Service & Trading
Blk 7 Pioneer Road North
#01-43 Lokyang Light Industrial Park
Singapore 628459

Contact Person/Tel : Sabrina / Tel: 6268 4111

Yours faithfully,

CA

Your Ref : SHD 3112A

Our Ref : SKW 3224A/HK/jp/ca

Date : 27 September 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of _____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/09/2018 10:56
Date Of Accident	21/09/2018 17:45
Exact Location Of Accident	ALONG AYE TWD TUAS AFTER BUONA VISTA EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW3224A
Insured/Policyholder	
Name Of Registered Owner	SIA CHOON HOO
NRIC No	S7972565Z
Email Address	ALEXSIA79@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90067718
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80445457ATT
Cover Note Number	

Driver

Name of Driver	SIA CHOON HOO
NRIC No	S7972565Z
Date Of Birth	03/01/1979
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2001
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90067718
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	ALEXSIA79@YAHOO.COM

Address	BLK 283 CHOA CHU KANG AVE 3 #06-398
Postcode	680283
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 21/09/2018 AT ABOUT 1745 HRS. WHILE I WAS TRAVELLING ALONG AYE TOWARDS TUAS AFTER BUONA VISTA EXIT. VEHICLE IN FRONT OF ME SUDDENLY APPLY BRAKE. I ALSO APPLY BRAKE AND STOP IN TIME. SUDDENLY I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF VEHICLE HAD HIT BY VEHICLE B. NO ONE WAS INJURED. THAT ALL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3112A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	92700778
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Address	BLK 283 CHOA CHU KANG AVE 3
	#06-398
Postcode	680283
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 21/09/2018 AT ABOUT 1745 HRS. WHILE I WAS TRAVELLING ALONG AYE TOWARDS TUAS AFTER BUONA VISTA EXIT. VEHICLE IN FRONT OF ME SUDDENLY APPLY BRAKE. I ALSO APPLY BRAKE AND STOP IN TIME. SUDDENLY I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF VEHICLE HAD HIT BY VEHICLE B. NO ONE WAS INJURED. THAT ALL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3112A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	92700778
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A-SKW3224K

B-SHD3112A

AVE Aft Bouna Vista Exit
TWD Tuas

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- ☐ Claim own policy
- ☐ Claim third party
- ☐ Claim OD / TP at other works hop
- ☒ For record purpose

Policy No. A80445457ATT
Insurer MSIG Veh. No. SC

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2565Z
Vehicle Details	
Vehicle No.:	SKW3224A
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	1ZRY224274
Chassis No.:	MR053REH104541168
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2025
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$39,215.00
Total Rebate Amount:	\$53,906.00

The information contained herein is correct as at 24 Oct 2018

OK



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

Toyota DriveElite
Comprehensive

Certificate No. A 80445457 ATT

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle

SKW3224A

2. Name of Policyholder

Sia Choon Hoo

3. Effective Date of the Commencement of Insurance for the purposes of the Act

26/10/2017

4. Date of Expiry of Insurance

25/10/2018

5. Persons or Classes of Persons entitled to drive*

Sia Choon Hoo

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT BORNEO MOTORS (S) PTE LTD OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.


Signature / Date

Counter-Signatory:

Inchcape Automotive Services Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers



Amy Ler
Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XINCHAZD2017101317390570

Np 428A



License No. S7972565Z

Class 2D Motorcycles not exceeding 200 cc
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms
16 Nov 2001
PACS DATE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

NRIC No: S7972565Z
Date: 20/03/2011
No: 6070813

APT BLK 283 CHOA KANG AVENUE 3 #06-39B
SINGAPORE 680283

O+ 13-12-2000

MALAYSIAN



S7972565Z



8381683

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7972565Z



SIA CHOON HOO

谢俊和

RACE
CHINESE

Date of Birth: 03-01-1979 Sex: M

Country of Birth
MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7972565Z

Name:

SIA CHOON HOO

Birth Date: 03 Jan 1979

Issue Date: 07 Jan 2004



...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018 14:26 Edit Reg		27 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	SIA CHOON HOO , ID: S7972565Z		
Vehicle Reg. No.:	SKW3224A	Date of Loss:	21/09/2018 17:00 - :59 [34 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHD3112A	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

***SKW3224A**
[SHD3112A]
TP
SIA CHOON HOO
Sep 21 2018 5:00PM
[-]
Premium Automobiles Pte Ltd

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=755899&extid=286151&... 1/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18017610/R1CBS2

Date: 25/10/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKW3224A

Insured Vehicle No : SHD3112A

Date of Loss: 21/09/2018

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW3224A

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRY224274

Reg. Date: 26/10/2015 (Man. Year: 2015)

Chassis No: MR053REH104541168

Colour: Grey

Odometer: 65197 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/09/2018

Date Inspected: 23/10/2018 Inspected At:

HOE KENG MOTOR SERVICE & TRADING
BLK 7 PIONEER ROAD NORTH
#01-43
SINGAPORE 628459

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Oct 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW3224A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >