

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18017616 / 11 vber

Special Instruction:

Surveyor  
MerimenASSIGNMENT (Office)

From (Person):

Eng Huey Ni

of

MSH

Date/Time:

27/09/2018 358pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 5649R

Insured:

WC 27858

at Workshop m/s

SC Auto

Tel:

67588828

of

51 Senoko Rd

Policy No:

28985078 MKF

Claim No:

527730

Sum Insured:

Excess:

17

Make of Veh:

D.O.A.

20082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

28-09-2018 @ 10.30am

H.O.D. Endorsement:

Date/Time:

27/09/2018 4:40pm

Person Contacted:

Hamimah

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

PC 5649R - X

WC 27858 - X

2/10/18

Rvert 1A thru merimen

11/10/18

@ 3:30pm Mei Lin said vehicle has not send in for repair

30/10/18

@ 3:11pm Mei Lin said vehicle has not send in for repair

30/10/18

Submit preli report

Signature: *Taufik*

REF:

MSIG

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *PC 5649R* Yr Regn: *2017 Feb.*  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Isuzu LT 434P* C.C. *7790*  
Colour: *White* A/C: Insured / Std / NI / NA  
Sp. Reading: *98476* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: *JHLLT434PH 7000093*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *11R22.5*  
R: *7- (17)*

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front		Rear	
R/Bal. <i>0</i>	mm	R/Bal. <i>B/S</i>	mm
L/Bal. <i>0</i>	mm	L/Bal. <i>0/S</i>	mm
D.O.A. _____		D.O.I. <i>28/9/10</i>	

Survey held at *SC Mkt*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*o/s minor*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 OCT 2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) *30/10 - typist*

Report Format : *meimen*

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Days Of Repair: *1*

Resurvey No. of Trip: *-*

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_ )

☐ : Interview (\$ \_\_\_\_\_ )

☐ : Tech. Invs (\$ \_\_\_\_\_ )

☐ : Weekend (\$ \_\_\_\_\_ )

Survey Fee:

Transportation:

\_\_\_\_\_ S + RS. \_\_\_\_\_ SI

) Photos

) Others

TOTAL

*150*

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2017		27 Sep 2018 15:58 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	ALLIANCE CONCRETE SINGAPORE PTE LTD, Co. Reg. No.: 200516266D								
Main Claimant:	TAN BUS TRANSPORT Co Reg, Co. Reg. No.: 53068308C								
Vehicle Reg. No.:	PC5649R	Date of Loss:	20/08/2017 00:00 - :59 [6 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 527730	Policy/Cover Note No.:	28985078MKF (Comprehensive) Coverage: 01/07/2017 - 30/06/2018						
Vehicle Reg. No. (Insured):	WC2785S	Policy No. (Claimant):							
		Excess:							
Repairer:	SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road, #03-01, 758133 Woodlands - Tel: 67582222/65719972								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eng Huey Ni - 6643 1314]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/09/2018]								
Adj Asg. Remarks:	ON WP. Survey appointment on 28/09/2018 11.30AM, Owner waiting. SURVEY AGREE ON SJE - ASSIGN LKK. LIABILITY:UNCLEAR. CONTACT: HAMIMAH 6758 8828.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
• MSIG_SG (27/09/2018): Cancellation of Assignment: PC5649R									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eng Huey Ni

Date: 02 Oct 2018

## **Preliminary Advice**

Insured Vehicle No	: WC2785S	Accident Date	: 20/08/2017
TP Vehicle No	: PC5649R	Assignment Date	: 27/09/2018
Make	: ISUZU LT434P 7.8 SMT	Est. Duration of Repair	: 1.00
Date of Inspection	: 28/09/2018		
Inspection At	: SC AUTO INDUSTRIES (S) PTE LTD (HQ) 51 SENOKO ROAD, #03-01 SINGAPORE 758133		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s mirror and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,120.00
Revised Amount	:S\$	2,710.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,710.00

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/08/2017 13:04
Date Of Accident	20/08/2017 23:45
Exact Location Of Accident	HEAVY VEHICLE CARPARK OF BLK 218 BEDOK NORTH ST 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC5649R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN BUS TRANSPORT
Co Reg No	53068308C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98510044

### Vehicle Particulars

Manufacturer	ISUZU
Model	LT434P 7.8 SMT-7.8 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA161470/1
Cover Note Number	

### Driver

Name of Driver	TAN CHEK MING
NRIC No	S0955095Z
Date Of Birth	07/06/1946
Occupation	OUTDOOR
Date Of Driving Pass	31/01/1969
Driving Experience	48 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan





The Quality Coach Builder

# 狮城机动工业(新)私营有限公司 SC Auto Industries (S) Pte Ltd

51 Senoko Road, Singapore 758133  
Tel: 67582222 Fax: 62576931  
Email: sales@scauto.com.sg  
Website: www.scauto.com.sg



Co. Reg. No. 199800107D

M/S TAN BUS TRANSPORT  
Blk 117 Bedok North Road, #08-219  
SINGAPORE 460117  
Insured TAN BUS TRANSPORT  
Policy CB1/GA161470/I

## ESTIMATE Bill

GST Reg. No: 19-9800107D  
Date: 28/8/2017  
Our Case Ref. SC17/08/188/4TC-TP  
Accident Date 20/8/2017

Damaged Vehicle No: PC5649R 02/02/17

S/no	Description	QTY	Price	Disc	Amount
<b><u>Replaced Parts</u></b>					
1	RHS REAR VIEW MIRROR	1 PC	\$1,980.00	crn ✓	\$1,980.00
<b><u>Labour Charges</u></b>					
1	LABOUR FOR WIRING	1	\$150.00	80.	\$150.00
2	LABOUR FOR REAR VIEW MIRROR	1	\$640.00	350.	\$640.00
3	SPRAY PAINTING	1	\$350.00	300.	\$350.00
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div> <div> <p>Tan Jia 97495749 wp 28/9/18 @ 1020 Resurvey before paint / new parts surv @ lkkauto.com 01 day part by part.</p> </div>					
Sub Total					S 3,120.00

Authorised Signature

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Aug 2017		27 Sep 2018 15:58 <a href="#">Edit Adj Rpt</a>	<b>S\$2,710.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,710.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>






















  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured:	<b>ALLIANCE CONCRETE SINGAPORE PTE LTD</b> , Co. Reg. No.: 200516266D								
Main Claimant:	<b>TAN BUS TRANSPORT Co Reg</b> , Co. Reg. No.: 53068308C								
Vehicle Reg. No.:	<b>PC5649R</b>	Date of Loss:	20/08/2017 00:00 - :59 [6 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 527730</b>	Policy/Cover Note No.:	28985078MKF (Comprehensive) Coverage: 01/07/2017 - 30/06/2018						
Vehicle Reg. No. (Insured):	<b>WC2785S</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>SC Auto Industries (S) Pte Ltd (HQ)</b> 51 Senoko Road, #03-01, 758133 Woodlands - Tel: 67582222/65719972								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Eng Huey Ni</b> - 6643 1314]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 27/10/2018]</b>								
Adj Asg. Remarks:	ON WP. Survey appointment on 28/09/2018 11.30AM, Owner waiting. SURVEY AGREE ON SJE - ASSIGN LKK. LIABILITY:UNCLEAR. CONTACT: HAMIMAH 6758 8828.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (27/09/2018): <b>Cancellation of Assignment: PC5649R</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*PC5649R (527730)  
[WC2785S]  
TP  
TAN BUS TRANSPORT Co Reg  
Aug 20 2017 12:00AM  
[ALLIANCE CONCRETE SINGAPORE PTE LTD]  
SC Auto Industries (S) Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View View in Browser	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/17 09:39	<b>Accident Statement</b> From: SC - Reg. No: WC2785S, Claimant: TAN BOON KIAU	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/18 10:36	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	03/10/18 10:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/08/17 11:10	<b>PC5649R GIA RPT</b>	 Load PDF	
2	28/08/17 11:11	<b>ESTIMATE</b>	 Load PDF	
3	13/09/17 10:39	<b>OT's police report</b>	 Load PDF	
4	26/09/18 15:41	<b>SURVEY AGREE ON SJE - REQ TO ASSIGN LKK</b>	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017616/T1VBE2

Date: 01/11/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28985078MKF

Claimant Vehicle No : PC5649R

Insured Vehicle No : WC2785S

Date of Loss: 20/08/2017

Nature of Claim: TP

Claim No: 527730

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC5649R

Make &amp; Model: ISUZU LT434P 7.8 SMT, 7.8 D (M)

Engine No: 6HK1685792

Reg. Date: 02/02/2017 (Man. Year: 2016)

Chassis No: JALLT434PG7000093

Colour: White

Odometer: 98476 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 11 R22.5

Rear Tyre Size: 11 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,980.00	1,980.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	730.00	410.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,120.00</b>	<b>2,710.00</b>	<b>410.00</b>	<b>13.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>218.40</b>	<b>189.70</b>	<b>28.70</b>	<b>13.14</b>
<b>Nett Amount (S\$)</b>	<b>3,338.40</b>	<b>2,899.70</b>	<b>438.70</b>	<b>13.14</b>

### INSPECTION

Date of Assignment: 27/09/2018

Date Inspected: 28/09/2018 Inspected At:

SC Auto Industries (S) Pte Ltd (HQ)  
51 Senoko Road, #03-01  
Singapore 758133

Estimated Period of Repair: 1.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Nov 2018)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5649R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS REAR VIEW MIRROR	Cracked	1,980.00 F	*1,980.00 F
						F=Franchise part.
<b>Total Parts (S\$)</b>					<b>1,980.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR WIRING	New	150.00	80.00
2	LABOUR FOR REAR VIEW MIRROR	New	640.00	350.00
3	SPRAY PAINTING	New	350.00	300.00
Gross Labour Cost (\$\$)			1,140.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >