

ASS. REC. BY:

REF: CS3/AIG/18017620/Ged301

Special Instruction:

Supervisor:  
Mamen

*Handwritten initials*

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time:

27/9/18 @ 12:08pm

Estimated Cost:

Bill to:

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 1668K

Insured:

SGB 1379H

at Workshop m/s

Green Star Spray Painting

Tel:

6546 3092

of

Blk 3011 Bedok north ave 4 # 01-2004

Policy No:

0100589273.

Claim No:

H042841081SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/09/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

28/9/18 @ morning

Date/Time:

12:58pm @ 27/9/18

Person Contacted:

Debbie

Vehicle

IN /  OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKX 1668K - X
	SGB 1379H - X
	Dismantle: 28/9/2018

Pres Xhd.

REF: AIG

B87C /

ASSIGNMENT

From: \_\_\_\_\_ Date: 28/9/18

Estimated Cost: \_\_\_\_\_

OD  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 1668K

at Workshop m/s: Green Star Spray painting

of: Blk 3011 Bedok North Ave # 01-2004

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>wp</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKX1668K Yr Regn: 08 Dec 2015

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or **Picasso**

Make: Citroen **CC** C.C. 1560

Colour: Red A/C Insured / Std / NI / NA

Chassis Reading: 43318 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF73DBH2TFJ761491

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD  Rim or

Tyre Size: F: 205/60 R16  
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA /  MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. _____	D.O.I. 28-9-18

Survey held at: **W/S** 12:40pm

Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<del>\$1500 - \$2500</del>
4/10	Submit DAR report.

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: DAR

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 180

Transportation: \_\_\_\_\_



) S + RS: \_\_\_\_\_

) Photos: \_\_\_\_\_

) Others: 20

TOTAL: 200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 27/9/2018 12:08:20 PM  
Attachments:  24092018162007.pdf  GIA Report SKX 1668K.PDF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Sales-GreenStarSP [mailto:sales@greenstarsp.com]  
**Sent:** Monday, September 24, 2018 5:25 PM  
**To:** Mithoosingh, Aashweenjeetkaur  
**Cc:** admin@greenstarsp.com  
**Subject:** FW: REF: ACCIDENT INVOLVING YOUR REF: SGB1379H & OUR REF: SKX1668K

Without Estimate

Dear Sirs,

Please find the attached GIA report and PRI letter for your attention and further action.  
To avoid delay, please let us know if you want to conduct the pre-repair inspection within 2 working days.

Thank you and looking forward to your prompt response.

Kind Regards,

Kind Regards,

*Jane*

**GREEN STAR SPRAY PAINTING**

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: [www.greenstarsp.com](http://www.greenstarsp.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

*Jane*

**GREEN STAR SPRAY PAINTING**

Blk 3011 Bedok North Ave 4

#01-2004 Bedok Ind Park E Singapore 489977

Tel: +6546 3092 | Fax: 6545 2066 | Website: [www.greenstarsp.com](http://www.greenstarsp.com)

**From:** Chan, Yoke Shi [mailto:yokeshi.chan@aig.com]  
**Sent:** Monday, September 24, 2018 4:38 PM  
**To:** Sales-GreenStarSP <sales@greenstarsp.com>  
**Subject:** Automatic reply: ACCIDENT INVOLVING YOUR REF: SGB1379H & OUR REF: SKX1668K

*Thank you for your email. I am away on leave and will be back on 01/10/2018 hence please expect a delay in my email response.*

*In my absence please feel free to reach out to my colleague:*

*TP task-Syaza - [Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)*

*LOD- Imran - [Imran.Ishak@aig.com](mailto:Imran.Ishak@aig.com)*

*WS - Sheng Yang - [ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)*

*PRI -Aashween - [Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)*

*Alternatively for urgent matters please free to reach out to my line manager, Baljit [Baljit.Kaur@aig.com](mailto:Baljit.Kaur@aig.com)*

*Otherwise will revert to your email the soonest when I return to work.*

---

**From:** Sales-GreenStarSP [mailto:sales@greenstarsp.com]  
**Sent:** Monday, September 24, 2018 4:36 PM  
**To:** 'Chan, Yoke Shi' <yokeshi.chan@aig.com>; 'Tan, Lily (AIG)' <Lily.Tan@aig.com>  
**Cc:** 'admin@greenstarsp.com' <admin@greenstarsp.com>  
**Subject:** REF: ACCIDENT INVOLVING YOUR REF: SGB1379H & OUR REF: SKX1668K

Without Estimate

Dear Sirs,

Please find the attached GIA report and PRI letter for your attention and further action. To avoid delay, please let us know if you want to conduct the pre-repair inspection within 2 working days.

Thank you and looking forward to your prompt response.

24. 09. 2018

To: Defendant's Insurers *AIG Asia Pacific Insurance Pte Ltd*  
Address *BY FAX & POST*

Dear Sir

We are instructed by (name of claimant) to notify you of a road traffic accident on (date) at about (time) at (place of accident which must be sufficiently detailed to establish location) involving our client's vehicle registration number (*SK 166 8K*) and vehicle registration number (*SG 61379H*) insured by you at the material time. A copy of the Singapore Accident Statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Green Star Spray Painting  
Blk 3011 Bedok North Ave 4  
#01-2004 Bedok Industrial Park E  
Singapore 489977

Tel: 65468092  
Fax: 65452066  
email: sales@greenstar.sp.com

Enc

Cc 1. Defendant's name

Address

2. Other Defendant and his insurers

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1387C
Vehicle Details	
Vehicle No.:	SKX1668K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	CITROEN
Vehicle Model:	C4 PICASSO 1.6 BLUEHDI EAT6
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	10JBHD3013720
Chassis No.:	VF73DBHZTFJ761491
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$23,246.00
Original Registration Date:	08 Dec 2015
First Registration Date:	08 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$9,545.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Dec 2025
PARF Rebate Amount:	\$7,158.00
Intended COE Rebate Details	
COE Expiry Date:	07 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,200.00
COE Rebate Amount:	\$42,522.00
<b>Total Rebate Amount:</b>	<b>\$49,680.00</b>

The information contained herein is correct as at 01 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/09/2018 15:41
Date Of Accident	16/09/2018 09:55
Exact Location Of Accident	MSCP OF BLK 248 SIMEI ST 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX1668K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG KOK CHUAN
NRIC No	S8201387C
Email Address	DANIEL.NKC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91807990
Alternative Phone No	OFFICE-91807990

### Vehicle Particulars

Manufacturer	CITROEN
Model	C4 PICASSO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10785022
Cover Note Number	

### Driver

Name of Driver	NG KOK CHUAN
NRIC No	S8201387C
Date Of Birth	26/01/1982
Occupation	INDOOR
Date Of Driving Pass	02/11/2001
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91807990
Fax Number	
Contact Number	OFFICE-91807990
EMail Address	DANIEL.NKC@GMAIL.COM



Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

At the block 248 Simei Street 5 multi-storey carpark, a grey Toyota Allis vehicle bearing car plate number SGB1379H reversed and hit the front of my stationary vehicle. Consequently, the front of my vehicle was damaged. Only driving license and contact number was exchanged with the Toyota car owner.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO UPLOADED INTO FILE ZILLA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGB1379H
Vehicle Make/Model/Colour	TOYOTA / COROLLA / DARK GRAY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANDREW HUNG
NRIC/Passport Number	S0016350C
Contact Number	91528854
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
  - I understand, acknowledge, agree and consent that:
    - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
      - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
    - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHAMAD HELMI BIN  
ALEHAM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

At the block 248 Simei Street 5 multi-storey carpark, a grey Toyota Altis vehicle bearing car plate number SGB1379H reversed and hit the front of my stationary vehicle. Consequently, the front of my vehicle was damaged. Only driving license and contact number was exchanged with the Toyota car owner.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

Aviva Motor Insurance Policy No: 10785022  
Car Vehicle No: SKX1668K  
Name: Ng Kok Chuan  
NRIC: S8201387C


Date of accident: 16 Sep 2018

Time of accident: 9:55am

Traffic accident location: Block 248 Simei St 5 Multi-Storey Carpark


Traffic accident description: At the block 248 Simei Street 5 multi-storey carpark, a grey Toyota Altis vehicle bearing car plate number SGB1379H reversed and hit the front of my stationary vehicle. Consequently, the front of my vehicle was damaged. Only driving license and contact number was exchanged with the Toyota car owner.

Damage caused to the front of my vehicle:



A video captured on my front car camera is available as supporting evidence.

Damage of his vehicle:



(08)Skipped (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn  
 (14)Unconfirmed (15)Not Working

**MOTOR CAR (Fr)**

Aug 2005  
 (1)Replace (✓) (2)Repair (X) (3)Check (?)  
 (4)Not Consistent (NC)

**Front Portion**

Vehicle No: **SKX 1668K**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate	SCR	✓	
1002	991887	Frnt Number Plate Base			
1003	991889	Frnt Number Plate Garnish			
1004	991300	Frnt Bumper	SCR	R	X
1005	992341	Frnt Bumper Clips			
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement			
1009	991318	Frnt Bumper Beam			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1012	991420	Frnt Bumper Pad			
1013	991363	Frnt Bumper Grille	BR	✓	
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler			
1016	991438	Frnt Bumper Sensor			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
1023	991799	Frnt Grille Chrome Moulding			
1024	991222	Frnt Apron Panel			
1025	992013	Frnt Support Panel			
1026	992025	Frnt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frnt Brace Panel			
1029	995153	Frnt LH Headlamp Assy			
1030	991821	Frnt RH Headlamp Assy			
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frnt Exhaust Manifold			
1064	991713	Frnt Exhaust Manifold Cover			
1065	991054	Frnt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1098	995147	Frnt LH Fender Lamp			
1099	995148	Frnt LH Fender Protector			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
1102	995170	Frnt LH Wheel Rim			
1103	994025	Frnt LH Rim Cover			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender			
1106	991739	Frnt RH Fender Inner Panel			
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector			
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
1111	992087	Frnt RH Wheel Rim			
1112	994025	Frnt RH Rim Cover			
1113	995065	Frnt RH Tyre			
1114	992093	Frnt Windscreen Glass			
1115	992117	Frnt Windscreen Rubber			
1116	992108	Frnt Windscreen Moulding			
1117	992098	Frnt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frnt Driver Seat			
1133	991922	Frnt RH Seat Belt Assy			
1134	991899	Frnt Passenger Seat			
1135	995182	Frnt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: 3

Accession: \_\_\_\_\_

TGrim Wm 3/10/18

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Sep 2018 <a href="#">Edit Reg</a>		27 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>HUNG MOW NGIAP ANDREW</b> , ID: S0016350C								
Main Claimant:	<b>NG KOK CHUAN</b> , ID: S8201387C								
Vehicle Reg. No.:	<b>SKX1668K</b>	Date of Loss:	16/09/2018 00:00 - :59 [33 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4042841081SG</b>	Policy/Cover Note No.:	0100589273 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SGB1379H</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>GREEN STAR SPRAY PAINTING (HQ)</b> BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 08/10/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (28/09/2018): <b>Request To Upload TP GIA Report</b>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SKX1668K (4042841081SG)  
 [SGB1379H]  
 TP  
 NG KOK CHUAN  
 Sep 16 2018 12:00AM  
 [HUNG MOW NGIAP ANDREW]  
 GREEN STAR SPRAY PAINTING

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser</span>		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
2	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
3	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
4	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
5	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
6	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
7	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
8	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
9	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
10	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
11	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
12	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
13	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
14	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
15	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
16	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
17	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
18	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
19	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
20	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
21	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
22	02/10/18 12:00	General View							Load JPG	<input checked="" type="checkbox"/>		
23	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
24	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
25	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
26	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
27	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
28	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
29	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
30	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
31	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
32	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
33	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
34	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
35	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
36	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
37	02/10/18 12:01	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/10/18 12:01	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
39	02/10/18 12:01	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
40	02/10/18 12:01	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
41	02/10/18 12:01	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/09/18 08:44	<b>OI GIA REPORT</b>	Load PDF	<input type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017620/GCD3E2

Date: 04/10/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100589273  
 Claimant Vehicle No: SKX1668K Insured Vehicle No: SGB1379H  
 Date of Loss: 16/09/2018 Nature of Claim: TP Claim No: 4042841081SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKX1668K  
 Make & Model: CITROEN C4 PICASSO, 1.6 BLUEHDI EAT6 (A) Engine No: 10JBHD3013720  
 Reg. Date: 08/12/2015 (Man. Year: 2015) Chassis No: VF73DBHZTFJ761491  
 Colour: Red Odometer: 43318 km  
 Engine Capacity: 1560 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 27/09/2018  
 Date Inspected: 28/09/2018 Inspected At: GREEN STAR SPRAY PAINTING (HQ)  
 BLK 3011 BEDOK NORTH AVENUE 4  
 #01-2004 BEDOK INDUSTRIAL PARK E  
 Singapore 489977  
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRT BUMPER	Repair	0.00 F	*- F
3	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >