

ASS. REC. BY:

REF:

CS/CTU 8017621 / Rlsbn2

Special Instruction:

Survivor

Muhun

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTU

Date/Time:

27/07/18 3:12 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 4323 R

Insured:

SLU 4822 R

at Workshop m/s

Goldbell

Tel:

8816 2798

of

Blk K Pandan Loop Ind Est #01-12

Policy No:

OMP CSN 1768451700

Claim No:

SNM18DD4 642 CS.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

28092018

H.O.D. Endorsement:

Date/Time:

27/07/2018 5:03pm

Person Contacted:

Andy

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 4323 R - X

SLU 4822 R - X

11/10/18

Confirmed P/P \$1,285.36 @ 3 days with Resul.
(P \$1,299.84 Red - 50%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2018		27 Sep 2018 15:12 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CHEN DINGZHOU		
Vehicle Reg. No.:	SKW4323R	Date of Loss:	23/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04642C02	Policy/Cover Note No.:	DMPCSN1768451700
Vehicle Reg. No. (Insured):	SLU4822R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tuas - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/10/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg No: 198003963G

DATE: 27/09/2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD #16-00 SPRINGLEAF TOWER


SINGAPORE 079909

Dear Sir,

We are instructed by CHEN DINGZHOU to notify you of a road traffic accident on 23/09/2018 at about 15:55HRS at CLEMENTI AVE 5 involving our client's/customer's vehicle registration number SKW4323R and vehicle registration number SLU4822R driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client/customers' vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days from Date: 27/09/2018 on your receipt of this notice whether you (vehicle insurer) would like to conduct a pre-repair survey of the vehicle by providing to GOLDBELL Engineering Pte Ltd a list of at least 10 motor surveyors. We will reply you our decision to agree or object your named surveyor as a Single Joint Expert following Apr 2016 NIMA Protocol process flow. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Mr ANDY OOI 
GOLDBELL Motor Claim Officer

bizSAFE
S T A R



Certificate No: AJA/S11Q1243

Certificate No: 14471324

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 11 October 2018 11:20 AM
To: 'Andy Ooi Lee Keong'
Cc: SUR; Rasul (LKKAuto)
Subject: RE: PLEASE CONFIRMED FINALISED AMOUNT - SKW4323R

Dear Andy,

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Andy Ooi Lee Keong [mailto:AndyOoiLK@goldbell.com.sg]
Sent: Thursday, 11 October 2018 11:09 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: PLEASE CONFIRMED FINALISED AMOUNT - SKW4323R

Dear Shirley ,

Amount confirmed .

Thank & regards

Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 11 October 2018 11:06 AM
To: Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>
Cc: SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: PLEASE CONFIRMED FINALISED AMOUNT - SKW4323R

Dear Andy,

Please confirm final fig of \$1,285.36 (part by part) @ 3 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Andy Ooi Lee Keong [<mailto:AndyOoiLK@goldbell.com.sg>]

Sent: Friday, 5 October 2018 10:34 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>


Cc: SUR <sur@lkkauto.com>

Subject: PLEASE CONFIRMED FINALISED AMOUNT - SKW4323R


Hi Rasul ,

Kindly find the above attached check item & before paint photo & accident scene photo ,
Please closed @ Part by Part Repairs @ \$ 1285.36 B4 GST with 05 days .

Thank & regards

 **Andy Ooi Lee Keong | Goldbell Engineering Pte Ltd**
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6773 0073 | Fax: +65 6458 7172 |
Mobile: +65 8816 2798 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Ind. Estate, #01-12 Singapore 128230



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/09/2018 15:07
Date Of Accident	23/09/2018 15:55
Exact Location Of Accident	CLEMENTI AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW4323R
Insured/Policyholder	
Name Of Registered Owner	CHEN DINGZHOU
NRIC No	S7183553G
Email Address	CHEN.DINGZHOU@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90217067
Alternative Phone No	OTHERS-90217067

Vehicle Particulars

Manufacturer	SUBARU
Model	XV-1.6 I-S AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100435846-02
Cover Note Number	

Driver

Name of Driver	CHEN DINGZHOU
NRIC No	S7183553G
Date Of Birth	23/09/1971
Occupation	INDOOR
Date Of Driving Pass	14/08/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90217067
Fax Number	
Contact Number	OTHERS-90217067
Email Address	CHEN.DINGZHOU@GMAIL.COM

Address	BLK 311B CLEMENTI AVE 4 #36-173
Postcode	122311
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZHUANG XUNHUA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE KINDLY REFER TO THE ACCIDENT STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU4822R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name: Ng Boon Swee, Eric
NRIC/FIN No.: 3741263361

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23rd Sep around 3:57pm, I drive my car from Clementi Ave 2 turn left to Clementi Ave 5. I stop and wait for right angle car to clear, suddenly my behind car SLU4822R hit my back side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name: Ng Boon Swee, Eric
 NRIC/PIN No.: S781265369

Owner Certificate Of Insurance



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : CHEN DINGZHOU
Period of Insurance : 29 Oct 2017 To 28 Oct 2018
Engine No. : FB16Y051649
Chassis No. : JF1GP3KCSFG158465

Vehicle No. : SKW4323R
Policy No. : 2100435846-02
Endorsement No. :
Issued Date : 09 Oct 2017

ABOUT THE COVER

Makes/Model	SUBARU XV 1.6	Sum Insured	Market Value	First Year of Registration	2015
Engine Capacity/Tonnage	1,600.00 CC	Off Peak Car	No	Insuring with COE/PARF	Yes
Driver Restriction	NA				

Person or Classes of Persons Entitled to Drive*

As The Policyholder
If any other person, who is taking on the Policyholder's name or with holder permission,
this Policy will normally only fully indemnify the insured driver only. It does not cover the licensed age condition.
You have to pay an additional sum of \$1,200 for "Impaired Driver Excess" (IDPE) if You are a "New Authorized Driver" (not an experienced driver) who has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for local domestic and business purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving whilst intoxicated, racing, speed testing, reliability trial or speed testing, the damage of goods other than samples or merchandise with any trade or business or use for any purpose in connection with trade trials.

Class of Use : 1000cc - 1600cc (Optional)

*Incidents incurred irrespective by Section 8 of the Motor Vehicle (Third Party Rules and Compensation) Act (Cap. 188) and Section 16 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 (Own Damage) - \$800 (Third - \$0 (New Driver) - \$0
Section 2
Theft - \$0
Section 3
Collision - \$100
Windscreen - \$100

Named Driver and Excess (where applicable)

CHEN DINGZHOU : \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

Approved Reporting Centres/Authorised Repairers offer claims-related repairs.
Any accident repairs to the Vehicle must be carried out by one of our Approved Repairers within the first 3 years of the first registration of the Vehicle in Singapore. You have the option of having the accident repairs carried out at the AIG Approved Repairer.
For other approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 1200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG 5.0 Mobile App. Sleeping while in work involves AIG 5.0, Suni, Suni or Suni, Suni.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan : DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicle (Third Party Rules and Compensation) Act (Cap. 188) and the Road Transport Act 1987 (Malaysia) and Motor Vehicle (Third Party Rules) Rules 1989 (Malaysia).

003094000

ZHUANG XUE HUA WANG
3 TAMPAKES GRANDE #05-02 AIA TAMPAKES
SINGAPORE 628708 SP-TAMPKES-ANGSING
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mank

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 10 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 198903963G

Page 1 / 2

ESTIMATE

Date	: 26/09/2018	Reg No	: SKW4323R
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: XV 1.6I-S AWD CVT
Attn.	:	Chassis No	: JF1GP3KC5FG158465
Office / Mobile	:	Engine No	: FB16Y051849
Email Address	:	Quotation No.	: 72169
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 23/09/2018
Attn.	: ANDYOOILK	Policy No.	: 2100435846-02
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER	1	594.20	-20	475.36	475.36
2		REAR BUMPER GARNISH RH	1	25.30	-20	20.24	20.24
3		REAR BUMPER REINFORCEMENT	1	187.00	-20	149.60	149.60
PARTS TOTAL :							645.20

SPECIAL NETT ITEMS

1	REAR BUMPER REVERSE SENSOR	1	280.00	200.00
PARTS TOTAL:				280.00

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS , CUT , WELD , PANEL BEAT , STRAIGHTEN & REALIGN , ETC	880.00	280.00
2	TO PUTTY , CLEAN , SPRAY PAINT & POLISH , ETC , AFFECTED AREAS	650.00	280.00
3	CHECK & REPAIR WIRING SYSTEM	280.00	60.00
4	SUNDRIES	50.00	20.00

LABOUR TOTAL : 1,660.00

SUB-TOTAL : 2,585.20

GST @ 7% for \$ 2,585.20 180.96

GRAND TOTAL (S\$) : 2,766.16



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No. 198003963G

Page 2 / 2

ESTIMATE

Date	: 26/09/2018	Reg No	: SKW4323R
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: XV 1.6I-S AWD CVT
Attn.	:	Chassis No	: JF1GP3KC5FG158465
Office / Mobile	:	Engine No	: FB16Y051849
Email Address	:	Quotation No.	: 72169
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 23/09/2018
Attn.	: ANDYOOILK	Policy No.	: 2100435846-02
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOoiLK@goldbell.com.sg	Workshop	: PANDAN

PREPARED BY : ANDYOOILK

DATE / TIME : 28/09/18 @ 1425

SURVEYOR : same

MOBILE NO : 90010068

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART ~~LUMP SUM~~

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 3 days

REMARKS : _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

5, First Avenue, #8 Singapore 439854
Tel: +65 6773 0007 Fax: +65 6561 0500 (b.k.w.c)
Tel: +65 6773 0007 (technical) +65 6862 1247 (toll-free)
Website: www.goldbell.com.sg
Reg No: 150015635

Page 1 / 2

ESTIMATE

Date	: 26/09/2018	Reg No	: SKW4323R
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: XV 1.6I-S AWD CVT
Attn.	:	Chassis No	: JF1GP3KC5FG158465
Office / Mobile	:	Engine No	: FB16Y051849
Email Address	:	Quotation No.	: 72169
		Ref. No.	: GBE/SVC/SALES
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 23/09/2018
Attn.	: ANDYOOILK	Policy No.	: 2100435846-02
Office / Mobile	: +65 67730073	Claim Type	: THIRD PARTY CLAIM
Email / Fax No.	: AndyOilK@goldbell.com.sg	Workshop	: PANDAN

N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BUMPER	1	594.20	-20	475.36	475.36
2		REAR BUMPER GARNISH RH	1	25.30	-20	20.24	20.24
3		REAR BUMPER REINFORCEMENT	1	187.00	-20	149.60	149.60
PARTS TOTAL :							645.20

SPECIAL NETT ITEMS

1	REAR BUMPER REVERSE SENSOR	1				280.00	280.00
PARTS TOTAL:							280.00

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN , ETC					880.00	300
2	TO PUTTY ,CLEAN ,SPRAY PAINT & POLISH ,ETC ,AFFECTED AREAS					650.00	250
3	CHECK & REPAIR WIRING SYSTEM					80.00	60
4	SUNDRIES					50.00	XM
LABOUR TOTAL :							1,660.00

SUB-TOTAL : 2,585.20
GST @ 7% for \$ 2,585.20 180.96
GRAND TOTAL (S\$) : 2,766.16

P-475-36
S/N-200-00
L-610-00

FINALISED-1285-36 PART BY PART REPAIR

WEEK 5 DAY

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18017621/R1SBN2

Date: 11/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1768451700	
Claimant Vehicle No :	SKW4323R	Insured Vehicle No :	SLU4822R	
Date of Loss:	23/09/2018	Nature of Claim:	TP	Claim No: SNM18D04642C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW4323R	Engine No:	FB16Y051849
Make & Model:	SUBARU XV, 1.6 I-S AWD CVT (A)	Chassis No:	JF1GP3KC5FG158465
Reg. Date:	29/10/2015 (Man. Year: 2015)	Odometer:	45088 km
Colour:	Blue		
Engine Capacity:	1600 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	975.20	675.36	299.84	30.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	610.00	1,000.00	62.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,585.20	1,285.36	1,299.84	50.28
+ GST 7.00/7.00% (\$\$)	180.96	89.98	90.98	50.28
Nett Amount (\$\$)	2,766.16	1,375.34	1,390.82	50.28

INSPECTION

Date of Assignment:	27/09/2018	
Date Inspected:	28/09/2018 Inspected At:	Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12 Singapore 128219

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts: 144	SUBARU XV 1.6 I-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW4323R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	594.20 FL	*594.20 FL
2	1		*REAR BUMPER GARNISH RH	Not Necessary	25.30 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	187.00 FL	*- FL
4	1		*REAR BUMPER REVERSES ENSOR	Not Working	280.00 FS	*200.00 FS
5	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
Sub Total (S\$)						1,136.50 794.20
- List Item Discount on L Items 20.00/20.00% (S\$)						161.30 118.84
Total Parts (S\$)						975.20 675.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC	New	880.00	300.00
2	TO PUTTY,CLEAN,SPRAY PAINT & POLISH,ETC,AFFECTED AREAS	New	650.00	250.00
3	CHECK & REPAIR WIRING SYSTEM	New	80.00	60.00
Gross Labour Cost (S\$)			1,610.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >