

ASS. REC. BY:

REF:

CS3/MSG18017624/Gcd3<sup>52</sup>

Special Instruction:

Survivor  
MAMOR

## ASSIGNMENT (Office)

From Person:

Chhia Nyuk Rui

of

MS1G

Date/Time:

27/9/18 @ 9:35am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 7951Y

Insured:

FQ 7655D

at Workshop m/s

Ong Motor

Tel:

8380 2233

of

No. 464 Macpherson Rd

Policy No:

MSD/VMS/18-38270

Claim No:

MSC/v/18-001273

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/09/18

CA / REV / REP. / REV 24 HRS

(up)

28/09/18

H.O.D. Endorsement:

Date/Time:

5:09pm @ 27/9/18

Person Contacted:

jaeky

Vehicle

IN/OUT

Date/Time	Action/Instruction ( X ) Estimate	
	FBL 7951Y - NA/INC18017058/r3	DOA: 17/9/18
	FQ 7655D - NA/INC18017058/r3	DOA: 17/9/18
	Dismantle: 2/10/2018	



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		27 Sep 2018 09:35 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KENNEDY KWOK JUN AN, ID: S9632237B, Tel: +6584484520, Email: NOEMAIL		
Main Claimant:	LIM AI GEOK, ID: S1406474E		
Vehicle Reg. No.:	FBL7951Y	Date of Loss:	17/09/2018 02:00 - :59 [18 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001273	Policy/Cover Note No.:	MSD/VMS/18-382170 (TP, Fire & Theft) Coverage: 24/04/2018 - 23/04/2019
Vehicle Reg. No. (Insured):	FQ7655D	Policy No. (Claimant):	
		Excess:	
Repairer:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/09/2018]		
Driver/Custodian (Insured):	KENNEDY KWOK JUN AN (22 / Male), NRIC: S9632237B, Tel: +6584484520		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:50%/50% CONTACT: JACKY SIAH 8380 2233		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/09/2018 14:34
Date Of Accident	17/09/2018 02:00
Exact Location Of Accident	BKE TWDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL7951Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM AI GEOK
NRIC No	S1406474E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97122384
Alternative Phone No	OTHERS-97122384

### Vehicle Particulars

Manufacturer	YAMAHA
Model	XABRE TFX150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5088593378-01
Cover Note Number	

### Driver

Name of Driver	TAY YU HENG
NRIC No	S9633335H
Date Of Birth	19/09/1996
Occupation	OUTDOOR
Date Of Driving Pass	11/01/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97122384
Fax Number	
Contact Number	
Email Address	TAYYUHENG88@GMAIL.COM

Address	BLK 259 BOON LAY DRIVE #12-523
Postcode	640259
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20180918/2001

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FQ7655D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	KENNEDY KOWK JUN AN
NRIC/Passport Number	S9632237B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	TAY YU HENG
Approximate Age	
Injuries Sustain	LEFT LEG,RIGHT WRIST & LEFT ELBOW
Injured person in which vehicle?	FBL7951Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 19/09/18

 19/09/18  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to the police report: 5/20180918/2001

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 19/09/18

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Individual Statement



**SINGAPORE  
POLICE FORCE**



T/20180918/2001

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

2 of 3

Report No. T/20180918/2001

**CONTINUATION OF REPORT**

**Brief Details.**

On 17/9/2018 at around 0200hrs, i was riding my bike(FBL7951Y) along BKE towards PIE. I was riding on the second left most lane. While on my left there was another rider however, i do not remember what is the plate number however, the model of the bike is Yamaha R15, black color with the rider namely: Keanedy Kowk Jun An, S9632237B.

Ahead of the rider was a vehicle going to make a stop as it flashes hazard light. the rider then make a lane change towards his right side without signaling before hand. As a resulted, the other rider crash along the left side of my bike. I then lost my balance and fell towards the left of my bike. Passerby then stop on the road to help me out. Both of us then exchange our particulars. After that, i then make a check on my bike and discovered that the gear, hand guard and mirror was damaged. There's ambulance on scene.

On the same date at round 0600hrs, i went to Ng Teng Fong to seek treatment and i was given medical leave from 17/9/2018 to 24/9/2018. I sustained injuries on left leg, cuts on my right wrist and left elbow.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6474E
Vehicle Details	
Vehicle No.:	FBL7951Y
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	XABRE TFX150
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	G3G8E0030352
Chassis No.:	MH3RG3710HK024327
Maximum Power Output:	-
Open Market Value:	\$2,727.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$410.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,801.00
COE Rebate Amount:	\$5,747.00
<b>Total Rebate Amount:</b>	<b>\$5,747.00</b>

The information contained herein is correct as at 01 Oct 2018

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Sep 2018		27 Sep 2018 09:35 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>KENNEDY KWOK JUN AN</b> , ID: S9632237B, Tel: +6584484520, Email: NOEMAIL		
Main Claimant:	<b>LIM AI GEOK</b> , ID: S1406474E		
Vehicle Reg. No.:	<b>FBL7951Y</b>	Date of Loss:	17/09/2018 02:00 - :59 [18 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / MSC/V/18-001273</b>	Policy/Cover Note No.:	MSD/VMS/18-382170 (TP, Fire & Theft) Coverage: 24/04/2018 - 23/04/2019
Vehicle Reg. No. (Insured):	<b>FQ7655D</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Ong Motor Trading (MACPHERSON RD)</b> No. 464 Macpherson Road, 368182 Macpherson - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 28/09/2018]		
Driver/Custodian (Insured):	<b>KENNEDY KWOK JUN AN</b> (22 / Male), NRIC: S9632237B, Tel: +6584484520		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:50%/50% CONTACT: JACKY SIAH 8380 2233		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*FBL7951Y (MSC/V/18-001273)**  
**[FQ7655D]**  
**TP**  
**LIM AI GEOK**  
**Sep 17 2018 2:00AM**  
**[KENNEDY KWOK JUN AN]**  
**Ong Motor Trading**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports


























1 per page ▼ ☒


No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 16:41	<b>Accident Statement</b> From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	Load HTM	<input checked="" type="checkbox"/>
2	26/09/18 16:41	<b>Addendum Sheet</b> From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	Load TIF	<input checked="" type="checkbox"/>
3	26/09/18 16:41	<b>Accident Statement Addm. #1</b> From:SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	Load HTM	<input checked="" type="checkbox"/>

### Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	03/10/18 11:57	<b>General View</b>	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	03/10/18 11:57	General View	 Load JPG	✓
31	03/10/18 11:57	General View	 Load JPG	✓
32	03/10/18 11:57	General View	 Load JPG	✓
33	03/10/18 11:57	General View	 Load JPG	✓
34	03/10/18 11:57	General View	 Load JPG	✓
35	03/10/18 11:57	General View	 Load JPG	✓
36	03/10/18 11:57	General View	 Load JPG	✓
37	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
38	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
39	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
40	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
41	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
42	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
43	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
44	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
45	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
46	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
47	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
48	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
49	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
50	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
51	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
52	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
53	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓
54	03/10/18 11:57	Photographs of Damaged Parts	 Load JPG	✓

Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/18 16:41	<b>FBL7951Y TP E-FILE REPORT</b> From: SC - Reg. No: FQ7655D, Claimant: KENNEDY KWOK JUN AN	 Load PDF	
2	26/09/18 16:46	<b>EMAIL FROM TP TO ARRANGE SURVEY</b>	 Load PDF	
3	26/09/18 16:46	<b>SURVEY DISAGREE ON SJE - ASSIGN LKK</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
 Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017624/GCD3S2

Date: 05/10/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/18-382170  
 Claimant Vehicle No: FBL7951Y Insured Vehicle No: FQ7655D  
 Date of Loss: 17/09/2018 Nature of Claim: TP Claim No: MSC/V/18-001273

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL7951Y**  
 Make & Model: YAMAHA XABRE, 150cc TFX150 Engine No: G3G8E0030352  
 Reg. Date: 15/03/2017 (Man. Year: 2017) Chassis No: MH3RG3710HK024327  
 Colour: Black Odometer: 0 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 130/70-17  
 Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 27/09/2018  
 Date Inspected: 28/09/2018 Inspected At: Ong Motor Trading (MACPHERSON RD)  
 No. 464 Macpherson Road  
 Singapore 368182  
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Oct 2018)	
Parts:	N/A	YAMAHA XABRE 150cc TFX150 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL7951Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >