



Your Ref: LSP/RSS/11049/17/ff

Date: 26th November 2018

Our Ref: CS1/LAW18017629/Avbs2

M/s Lee Shergill LLP

111 North Bridge Road
#07-07 Peninsula Plaza
Singapore 179098

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJH 919P INSURED VEHICLE: WSX 9617 ACCIDENT DATE: 19/03/2015**

We thank you for your instruction on 27/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJH 919P from M/s Prominent Appraiser Services Pte Ltd.
- b) Final Repair Bill of SJH 919P from M/s New Hock Teck Motor Workshop.
- c) Singapore Accident Statement of Vehicle SJH 919P.
- d) Colour damaged vehicle photographs of SJH 919P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJH 919P
Make & Model	: Honda Fit (A)
Year of Registration	: 2008
Chassis Number	: GE61080049
Engine Capacity	: 1339 cc

2. We recommend that the repairs of the entire damage require about 18 (Eighteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.