

ASS. REC. BY:

REF:

CS 1CTI18017641/Nsd362

Special Instruction:

Surveyor:

Naz

From (Person):

catherine thia

ASSIGNMENT (Office)

of CTI

Date/Time: 28/9/18 @ 11.05am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

GW 1883H

Insured:

PA 8122 J

at Workshop m/s

zhong cheng Enterprise

Tel:

9 338 2859

of

Blk 6 - Yew Tee Ind. Est 399J

Policy No:

DMB1SN 303 G 78 1800

Claim No:

SM18D04646C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/09/18

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

11:17am @ 28/9/18

Person Contacted:

Ms. Sini

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	GW 1883H - NA (AWA17065524/r3
	PA 8122J - X
	Pending estimate from Repairer

DOA: 17/03/17

REF: CTI

ASSIGNMENT

From: Date: 28/09/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GW1883H

at Workshop m/s Zhong cheng Enterprise

of BKG, Yew Tee Ind. Est 399 J

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Ms. Sini @ 9338 2859

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GW 1883 H Yr Regn: 29 NOV 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HILUX 3.0 AUTO C.C. 2,982

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 107, 465 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KD12015023958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STDA/Rim or

Tyre Size: F: 195R15C

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE (P), MIC (R)

Front

Rear

R/Bal. 6 mm R/Bal. 4 mm

L/Bal. 6 mm L/Bal. 4 mm

D.O.A. 26/9/18 D.O.I. 28/9/18

Survey held at ZHONG CHENG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/1/19 FINALIZED LUMP SUM REPAIR \$5400.00 / 5 DAYS

25/01/19 Confirmed L/S \$5,400/- @ 5 days with Nae
(\$7,266.50 Red. 57%)

RECEIVED 28 JAN 2019

Date/Time, File Pass to?

23/01/19

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 5,400/- L/S)

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2018		28 Sep 2018 11:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SMH TRADING & TRANSPORTATION SERVICES , Co. Reg. No.: 53212598C		
Main Claimant:	H-TM CARPENTRY WORKS , Co. Reg. No.: 53241704J		
Vehicle Reg. No.:	GW1883H	Date of Loss:	26/09/2018 17:00 - :59
Claim Type:	TP / SM18D04646C02	Policy/Cover Note No.:	DMB1SN3036781800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	PA8122J	Policy No. (Claimant):	5095874771
		Excess:	S\$0.00
Repairer:	Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD, 678008 Woodlands - Tel: 9826-4959		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2018]		
Driver/Custodian (Insured):	HAMED BIN ASMIN (46 / Male), NRIC: S7133156C, Tel: +6582234226		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Cheonghoh Law <mail@cheonghoh.sg>
Sent: Friday, 28 September, 2018 10:46 AM
To: Lucas Lee
Subject: Re: PRS for GW 1883 H involving vehicle PA 8122 H on 26 September 2018 along Teck Whye Avenue (Our ref: LCH.lg/W6ZC-80893.18) (CTI REF: SNM18D04646C02)

Dear Sirs,

We refer to the above matter and to your email of 27 September 2018.

Our client hereby nominate LKK Auto Consultants Pte Ltd named in your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, Zhong Cheng Enterprise, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008 for the said survey of GW 1883 H.

Contact Person : Mr Tan / Sini / Winson
Telephone : 9826 4959 / 9338 2859 / 9750 6777

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 27 Sep 2018, at 4:09 PM, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.
Case Handler: Catherine Thia

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com
<image001.png>

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Thursday, 27 September, 2018 2:36 PM
To: Claims Dept of CTI; Lucas Lee
Subject: Re: PRS for GW 1883 H involving vehicle PA 8122 H on 26 September 2018 along Teck Whye Avenue (Our ref: LCH.lg/W6ZC-80893.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: c364@cheonghoh.sg
Subject: Message from KMBT_C364e
Date: 27 September 2018 at 2:30:21 PM SGT
To: mail@cheonghoh.sg
Reply-To: c364@cheonghoh.sg



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Zhong Cheng <zhongchengauto@gmail.com>
Sent: Wednesday, 23 January 2019 4:26 PM
To: Naz (LKKAUTO)
Cc: Shirley Hiew (LKK Auto); SUR
Subject: Re: GW 1883H Finalization

Dear All,

Ok to accept COR \$5400 and repair days 5.

Thank you

Best Regards
Sini Tan
Zhong Cheng Enterprise Pte Ltd
Blk 6, 399J
Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Wed, Jan 23, 2019 at 4:19 PM Naz (LKKAUTO) <Naz@lkkauto.com> wrote:

Dear Ms Cheng,

Apologies for the late reply. Attached herewith is the amended marked estimate. We will proceed to finalize if you are agreeable with the amended COR;

PARTS - \$7354.00
LESS 25% - \$5515.50
SPECIAL NET ITEMS - \$35
LABOUR - \$1230.00
LESS LUMP SUM 20% - \$5424.40
TOTAL - \$5400.00 / 5 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Naz (LKKAuto)

Sent: Monday, 21 January 2019 6:14:47 PM

To: Zhong Cheng

Cc: Shirley Hiew (LKK Auto); SUR

Subject: Re: GW 1883H Finalization

Dear Ms Cheng,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS - \$6254.00

LESS 25% - \$4690.50

SPECIAL NET ITEMS - \$35

LABOUR - \$1230.00

LESS LUMP SUM 20% - \$4764.40

TOTAL - \$4750.00 / 5 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhong Cheng <zhongchengauto@gmail.com>

Sent: Friday, 11 January 2019 12:11:25 PM

To: Naz (LKKAuto)

Subject: Fwd: GW1883H GIA REPORT

Dear Naz,

This is lump sum repair not part by part.

Thank you

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883

----- Forwarded message -----

From: Zhong Cheng <zhongchengauto@gmail.com>

Date: Mon, Nov 5, 2018 at 1:24 PM

Subject: Re: GW1883H GIA REPORT

To: <Naz@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Dear Naz,

Attached estimate & pics for finalization, please.

Thank you



GW1883H.zip

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est
S678008
HP: 93382859 Fax: 68942883

On Fri, Sep 28, 2018 at 6:55 PM Zhong Cheng <zhongchengauto@gmail.com> wrote:
Hi Naz,

GIA fyi.

Thanks

Sent from my iPhone

Begin forwarded message:

From: "YT\ (HQ\)" <info@yewteegroup.com>
Date: 27 September 2018 at 1:09:01 PM SGT
To: "'Zhong Cheng'" <zhongchengauto@gmail.com>
Cc: "YT\ (HQ\)" <info@yewteegroup.com>
Subject: GW1883H GIA REPORT

Hi ,

Kindly find attached.

Thank you

Best Regards

Vinnie Lim

Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID:62562081

Email: info@yewteegroup.com



Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2018 12:55
Date Of Accident	26/09/2018 17:40
Exact Location Of Accident	ALONG TECK WHYE AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GW1883H
Insured/Policyholder	
Name Of Registered Owner	H-TM CARPENTRY WORKS
Co Reg No	53241704J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90108820

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095874771
Cover Note Number	

Driver

Name of Driver	ANG KIM HUAT
NRIC No	S0955547A
Date Of Birth	11/10/1952
Occupation	OUTDOOR
Date Of Driving Pass	21/04/1970
Driving Experience	48 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90108820
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 226 PENDING ROAD #09-193
Postcode	670226
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA8122J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A) G10 1883 H

B) PA 8922

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At mentioned details, I was driving along Teek Wye Ave
 & going straight when suddenly vehicle B turn out from
 slip road & hit onto my vehicle's front part.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature

Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Vehicle no. : GW1883H
Model : TOYOTA HIACE

Estimate - Spare Part(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

1	front bumper	\$ 400	535.00 / CRK
1	front bumper upper chrome grille	\$ 700	795.00 / DEF
1set	front bumper upper chrome grille fasteners	\$	38.00 / NEC
1	front bumper lower grille	\$	265.00 XSVL
1set	front bumper lower grille fasteners	\$	38.00 XNN
1	front bumper RH side retainer	\$	170.00 / DIS
1	front bumper reinforcement	\$	425.00 ? / BT
2	front RH & LH headlamp	\$	1,530.00 RH ? / JLR
2	front headlamp bracket	\$	110.00 LH ? / CRK
2set	front headlamp fasteners	\$	50.00 ? / CRK
1	front panel	\$	895.00 / DB
1set	front panel fasteners	\$	38.00 / NEC
1	front panel inner lock	\$	125.00 / BT
1	front bonnet toyota emblem logo	\$	58.00 / NEC
1	front support panel mounting	\$	695.00 / BT
1	radiator assy	\$ 1,100	1,250.00 ? / BT
1	air condensor assy	\$	1,020.00 ? / BT
1	air cleaner box assy	\$	650.00 ?
1	air cleaner blower sensor	\$	255.00 ?
1	air cleaner inlet	\$	255.00 ?
1	front brake pump	\$	840.00 ?
1	front wiper motor	\$	770.00 ?
1	wiper garnish	\$	395.00 ?
		7354	\$ 11,202.00
		5515.50	\$ 2,800.50
	Less 25%		\$ 8,401.50

SPECIAL NETT ITEMS:-

20	1 pc carplate w housing	\$ 35	60.00 / DD / CRK
21	1 pc windscreen sealant	\$	60.00 XNN
		35	\$ 120.00

Estimate - Labour

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	\$ 1,800.00 500
2		Check wiring & lightings	\$ 120.00 50
3		To anti-rust	\$ 150.00 50
4		to realign headlamp focus	\$ 35.00 30
5		to remove and reinstall radiator and condensor	\$ 100.00 ? / nec
6		to remove and reinstall front windscreen	\$ 120.00 XNN
7		to top up coolant and air con gas	\$ 80.00 ? XNN
8		to realign or conduct front support panel / chassic alignment	\$ 300.00 XNN
9		to remove & refix dashboard components	\$ 240.00 XNN
10		To putty and spray-paint of affected areas	\$ 1,200.00 500
			1230 \$ 4,145.00

NAZ LKK 28/9/18

PIP

5 X DAYS

CHECK ITEMS PHOTO
BEFORE PRINT PHOTO


18/11/19

12,666.50

PARTS \$ 7,354
LESS 25% \$ 5,515.50

S/NET \$ 35

LABOUR \$ 1,230

TOTAL \$ 6,780.50

LESS 21% 20% \$ 5,424.40

L/D TOTAL: \$ 5,400 / 5 DAY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018		28 Sep 2018 11:05 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SMH TRADING & TRANSPORTATION SERVICES , Co. Reg. No.: 53212598C									
Main Claimant: H-TM CARPENTRY WORKS , Co. Reg. No.: 53241704J									
Vehicle Reg. No.: GW1883H		Date of Loss: 26/09/2018 17:00 - :59 [21 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SM18D04646C02		Policy/Cover Note No.: DMB1SN3036781800 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): PA8122J		Policy No. (Claimant): 5095874771							
		Excess: S\$0.00							
Repairer: Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD, 678008 Woodlands - Tel: 9826-4959									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/10/2018]									
Driver/Custodian (Insured): HAMEDI BIN ASMIN (46 / Male) , NRIC: S7133156C, Tel: +6582234226									
Adj Asg. Remarks: NO EST, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GW1883H (SM18D04646C02)
[PA8122J]

TP


















































H-TM CARPENTRY WORKS

Sep 26 2018 5:00PM

[SMH TRADING & TRANSPORTATION SERVICES]









Zhong Cheng Enterprise

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)		Thumbnail	Print					
1	27/09/18 13:00	Accident Statement		1 Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)		Thumbnail	Print					
1	27/09/18 13:00	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
2	27/09/18 13:00	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
3	27/09/18 13:00	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
4	27/09/18 13:00	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
5	27/09/18 13:00	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
2	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
3	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
4	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
5	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
6	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
7	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
8	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
9	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
10	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
11	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
12	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
13	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
14	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
15	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
16	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
17	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
18	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
19	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
20	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
21	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
22	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
23	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
24	23/01/19 17:45	General View		1 Load JPG	<input checked="" type="checkbox"/>					
25	23/01/19 17:46	General View		1 Load JPG	<input checked="" type="checkbox"/>					
26	23/01/19 17:46	General View		1 Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
27	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
65	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
66	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
67	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
68	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
70	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
71	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
72	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
73	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
74	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
75	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
76	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
77	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
78	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
79	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
80	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
81	23/01/19 17:46	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 11:05	PRS	 Load PDF	
2	28/09/18 11:05	TP GIA	 Load PDF	
3	28/09/18 11:05	OI GIA	 Load PDF	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:00	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 13:00	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:00	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 13:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 13:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 13:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/09/18 13:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 13:00	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 13:00	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017641/NSD3E2

Date: 28/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3036781800
Claimant Vehicle No :	GW1883H	Insured Vehicle No :	PA8122J
Date of Loss:	26/09/2018	Nature of Claim:	TP
		Claim No:	SM18D04646C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW1883H	Engine No:	1KD2641855
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2015023958
Reg. Date:	29/11/2016 (Man. Year: 2016)	Odometer:	107465 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	West Lake 6 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,521.50	5,550.50	2,971.00	34.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,145.00	1,230.00	2,915.00	70.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,666.50	6,780.50	5,886.00	46.47
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	12,666.50	5,400.00	7,266.50	57.37

INSPECTION

Date of Assignment:	28/09/2018	
Date Inspected:	28/09/2018 Inspected At:	Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD Singapore 678008
Estimated Period of Repair:	5.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jan 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW1883H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	535.00 FL	*400.00 FL
2	1		*FRONT BUMPER UPPER CHROME GRILLE	Deformed	795.00 FL	*700.00 FL
3	1		*SET FRONT BUMPER UPPER CHROME GRILLE FASTENERS	Necessary	38.00 FL	*38.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Serviceable	265.00 FL	*- FL
5	1		*SET FRONT BUMPER LOWER GRILLE FASTENERS	Not Necessary	38.00 FL	*- FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	170.00 FL	*170.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	425.00 FL	*425.00 FL
8	2		*FRONT RH & LH HEADLAMP	O/S Scratched / N/S Cracked	1,530.00 FL	*1,530.00 FL
9	2		*FRONT HEADLAMP BRACKET	Cracked	110.00 FL	*110.00 FL
10	2		*SET FRONT HEADLAMP FASTENERS	Cracked	50.00 FL	*50.00 FL
11	1		*FRONT PANEL	Dented	895.00 FL	*895.00 FL
12	1		*SET FRONT PANEL FASTENERS	Necessary	38.00 FL	*38.00 FL
13	1		*FRONT PANEL INNER LOCK	Bent	125.00 FL	*125.00 FL
14	1		*FRONT BONNET TOYOTA EMBLEM LOGO	Necessary	58.00 FL	*58.00 FL
15	1		*FRONT SUPPORT PANEL MOUNTING	Bent	695.00 FL	*695.00 FL
16	1		*RADIATOR ASSY	Bent	1,250.00 FL	*1,100.00 FL
17	1		*AIR CONDENSOR ASSY	Bent	1,020.00 FL	*1,020.00 FL
18	1		*AIR CLEANER BOX ASSY	Not Necessary	650.00 FL	*- FL
19	1		*AIR CLEANER BLOWER SENSOR	Not Necessary	255.00 FL	*- FL
20	1		*AIR CLEANER INLET	Not Necessary	255.00 FL	*- FL
21	1		*FRONT BRAKE PUMP	Not Necessary	840.00 FL	*- FL
22	1		*FRONT WIPER MOTOR	Not Necessary	770.00 FL	*- FL
23	1		*WIPER GARNISH	Not Necessary	395.00 FL	*- FL
24	1		*CARPLATE W HOUSING	Dented / Cracked	60.00 FS	*35.00 FS
25	1		*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,322.00	7,389.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,800.50	1,838.50
Total Parts (S\$)	8,521.50	5,550.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,800.00	500.00
2	CHECK WIRING & LIGHTINGS	New	120.00	50.00
3	TO ANTI-RUST	New	150.00	50.00
4	TO REALIGN HEADLAMP FOCUS	New	35.00	30.00
5	TO REMOVE AND REINSTALL RADIATOR AND CONDENSOR	New	100.00	100.00
6	TO REMOVE AND REINSTALL FRONT WINDSCREEN	New	120.00	0.00
7	TO TOP UP COOLANT AND AIR CON GAS	New	80.00	0.00
8	TO REALIGN OR CONDUCT FRONT SUPPORT PANEL / CHASSIC ALIGNMENT	New	300.00	0.00
9	TO REMOVE & REFIX DASHBOARD COMPONENTS	New	240.00	0.00
10	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,200.00	500.00
Gross Labour Cost (S\$)			4,145.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >