

ASS. REC. BY:

REF: es/FCI/18017644/Utbn Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

CWS

From (Person):

Lurene yuw

of

FCIDate/Time: 28/9/18, 2.31pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 3511 E

Insured:

SHC 00175

at Workshop m/s

SME Motor

Tel:

6741 6106

of

1 Kaki Bkt Ave 6 # 02-15

Policy No:

Claim No:

018007061MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

2.29pm @ 28/9/18

Person Contacted:

Pei YingVehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

1/10-Revertvia email preli advise

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN3511 Eat Workshop m/s Sum

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

SIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

3/10/18 L7A858K full plus.
confirmed m/s 2450 with AH ying.
cred: 814 25:24%

Veh No: SJN3511 E Yr Regn: 2109Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota conlla Altis c.c 1598Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 209498 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO532EE106139349Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 25/9/18

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 28/9/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 5/10 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

130

50

50

40

270

Report Format: TPLump Sum / I.B.I: (\$ 2450)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017644/Utb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 17S	Veh. Inspected	SJN 3511E
Policy No.		Coverage (\$)	0.00
Claim No.	D18007061MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	28/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/09/2018	Inspection Date	28/09/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007061MFSH

Date: 1/10/2018

Our Ref: CS/FCI18017644/Utb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 3511E

Please be informed that we had conducted the inspection of the abovementioned vehicle
28/09/2018 at the premises of M/s SME MOTOR and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,264.25</u>
Revised Estimate Amount	: S\$ <u>3,094.25</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-09-2018	Our Ref No.	D18007061MFSH
Accident Date	25-09-2018	Claim Type.	Third Party
Insured Vehicle	SHC0017S	Third Party Vehicle.	SJN3511E
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT		
Contact Person.	PEIYING		
Contact No.	67476106/ 0	Fax No.	67442368
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244521)



PRI Documents



Close X

PRI Header Details

Claim No	D18007061MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SME MOTOR
Workshop Name	SME MOTOR PTE LTD (Contact Person : PEIYING)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY (Mobile: 0 , Phone: 67476106 , Fax: 67442368 EmailId: PEIYING@SMEMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0017S	TP Vehicle No	SJN3511E
PRI Recieved Date	27-09-2018 07:54:31 PM	Surveyor Appointed Date	28-09-2018 02:30:03 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-09-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 1 October 2018 5:42 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007061MFSH/1
Attachments: PRELI ADVISED SJN 3511E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJN 3511E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 28 September 2018 2:43 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007061MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 28 September 2018 2:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007061MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 7694B

Vehicle Details

Vehicle No.: SJN3511E

Vehicle to be Exported: No

Intended Deregistration Date: 28 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4859492

Chassis No.: MR053ZEE106139349

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,990.00

Original Registration Date: 12 Feb 2009

First Registration Date: 12 Feb 2009

Transfer Count: 1

Actual ARF Paid: \$16,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Feb 2019

PARF Rebate Amount: \$8,495.00

Intended COE Rebate Details

COE Expiry Date: 11 Feb 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$2,693.00

COE Rebate Amount: \$100.00

Total Rebate Amount: \$8,595.00

The information contained herein is correct as at 28 Sep 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Toyota Corolla altis

Price Range

Depreciation

2009

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Tan Motor Car Enterprise » Toyota Corolla Altis 1.6A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



High yield

10.0%

10%!! High-yield
and safe Japanese
real estates.
Don't miss!



Property LIFE

Compare

Toyota Corolla Altis 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$14,800

Depreciation

Reg Date 12-Feb-2009

(4mths 14days COE left)

Manufactured 2009

Mileage

Transmission Auto

Engine Cap 1,598 cc

Road Tax \$742 /yr

Power 80.0 kW (107 bhp)

View specs of the Toyota Corolla Altis (2008-2013)

Curb Weight 1,195 kg

Features

Fuel Efficient Economical 16 Valves DOHC VVT-I 1.6L Engine, Climatic Control Aircon, Dual Airbags, ABS, Multi Function Steering Control, Disc Brake.

Accessories

Reverse Sensors, Fog Lights., Factory Fitted 15" Sports Rims, Auto Retractable Mirror With Indicator, Solar Films, Original MP3/WMA Player.

Description

Option To Renew 5 Years COE Or 10 Years COE, Tip Top Condition, Low Depreciation And Best Price In Town, View To Believe, Fast Delivery. Call Us Now Before It's Gone!

COE \$1,020

OMV \$16,990

ARF \$16,990

Dereg Value \$8,533 as of today (change)

No. of Owners 1

Type of Veh Mid-Sized Sedan

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21-Sep-2018 | Last Updated on: 26-Sep-2018

Tags: Toyota Corolla, toyota corolla, 2009 Toyota Corolla, 2009 toyota corolla, Toyota, Corolla, corolla, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee

\$25



Price Analysis

Seller Information

Company

Tan Motor Car Enterprise

» dealer's pricelist

» 3 vehs sold | 19 vehs available

Address

61 Ubi Avenue 2 #04-11

Search cars nearby this location

Location

Automobile Megamart

Office No

64577328

Contact Person(s)

Joseph Tan

82288908

Sunny

97524000

Terence

97876217

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-191 (09)

Claim Type: Third Party

Accident Date: 25/09/2018

TP Veh Reg No: SHC17S

Estimate No: EST0004405

Date: 27 Sep 2018

Policy No: 5098276213

Veh Reg No: SJN3511E

Make/Model: TOYOTA ALTIS

Chasis No: MR053ZEE106139349

Engine No: 3ZZ4859492

Reg. Date: 12/02/2009

Estimate Repair Cost to Vehicle No :SJN3511E

Description	Quantity	List Price SS	Amount SS
List Price			
1 RH SIDE MIRROR ASSY	1 PC	1,157.00	
2 RH SIDE MIRROR COVER	1 PC	60.00	
3 FRT RH DOOR	1 PC	1,200.00	
4 FRT RH DOOR GLASS	1 PC	447.00	
5 FRT RH DOOR OUTER MOULDING	1 PC	135.00	
6 FRT RH DOOR OUTER HANDLE	1 PC	185.00	
7 FRT RH DOOR OUTER HANDLE COVER	1 PC	35.00	
		3,219.00	
	Less 25%	804.75	2,414.25
Labour			
8 WIRE CHECKING	1 UNIT	30.00	
9 TRANSFER DOOR COMPONENTS FROM OLD TO NEW	1 UNIT	120.00	
10 LABOUR CHARGE	1 UNIT	300.00	
11 SPRAY PAINTING	1 UNIT	400.00	
		850.00	850.00
	Total		SS 3,264.25
	Add GST @ 7%		228.50
	Total Amount Payable		SS 3,492.75

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED NINETY TWO AND CENTS SEVENTY FIVE ONLY

Not Allowed
 28/9/18
 2450/-
 300/-
 2150/-
 The photo above

For SME Motor Pte Ltd

Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- AUTHORISED SIGNATURE**
- Two party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3094.25



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017644/Utn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 17S	Veh. Inspected	SJN 3511E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18007061MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106139349	Colour	GREY	
Odometer	209498	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/55 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/55 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/55 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2018	Inspection Date	28/09/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3511E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH SIDE MIRROR ASSY	BROKEN	1,157.00	1,157.00
1	RH SIDE MIRROR COVER	BROKEN	60.00	60.00
1	FRT RH DOOR	BADLY DENTED	1,200.00	1,200.00
1	FRT RH DOOR GLASS	DEEP CUT	447.00	447.00
1	FRT RH DOOR OUTER MOULDING	SCRATCHED	135.00	135.00
1	FRT RH DOOR OUTER HANDLE	CRACKED	185.00	185.00
1	FRT RH DOOR OUTER HANDLE COVER	CRACKED	35.00	35.00
	LESS 25% DISCOUNT		-804.75	-804.75
			2,414.25	2,414.25
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	TRANSFER DOOR COMPONENTS FROM OLD TO NEW.		120.00	60.00
	LABOUR CHARGE.		300.00	200.00
	SPRAY PAINTING.		400.00	400.00
			850.00	680.00
	GRAND TOTAL		3,264.25	3,094.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS/FCI18017644/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.